

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-059-20455
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-6228
7. Lease Name or Unit Agreement Name: Bravo Dome Carbon Dioxide Gas Unit 2333
8. Well Number 252
9. OGRID Number 16696
10. Pool name or Wildcat Bravo Dome Carbon Dioxide Gas 640

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other CO2 Supply Well <input type="checkbox"/>	7. Lease Name or Unit Agreement Name: Bravo Dome Carbon Dioxide Gas Unit 2333
2. Name of Operator OXY USA Inc.	8. Well Number 252
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250	9. OGRID Number 16696
4. Well Location Unit Letter <u>N</u> : <u>504</u> feet from the <u>south</u> line and <u>1454</u> feet from the <u>west</u> line Section <u>25</u> Township <u>23N</u> Range <u>33E</u> NMPM County <u>Union</u>	10. Pool name or Wildcat Bravo Dome Carbon Dioxide Gas 640
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4972.1'	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: Completion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE David Stewart TITLE Sr. Regulatory Analyst DATE 6/10/05
Type or print name David Stewart E-mail address: david_stewart@oxy.com
Telephone No. 432-685-5717

For State Use Only

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 6/24/05
Conditions of Approval, if any:

BDCDGU 2333-252

10/25/04

MI & RUSU R 2.375 Tbg to 2554'

Swab Well Dry Rec 60 BBL P & LD Tbg

Dump 6 BBL 15% HCL Acid + 8 BBL KCL

11/11/04

RU WL R Gamma Ray, CCL

R 3.125 Gun Perforate x 6 DPJSPF @ .52" Hole

2366' to 2386' , 2410' to 2430' 60 deg Phase = 240 Holes

11/12/04

Put Well on Production – 1st Day of Production

12/02/04

RU WL R 3.125" Gun, Perforate x 6 DPJSPF @ .52 hole

2430' to 2450' 60 deg phase= 120 holes

12/15/04

RU WL R 20' of Gas Gun

Shoot from 2430' to 2450'

Left gun in the hole, could not fish.

Swab and return well to prod.