

**Permit Conditions Of Approval**  
**C-101, Permit 11242**

Operator: RANGE OPERATING NEW MEXICO INC , 227588

Well: SOUTH CULEBRA BLUFF 23 #016

OCD Reviewer	Condition
VBARTON	If any type of earthen pit is used in association with the drilling of this well, the requirements of Rule 50 must be met.
BARRANT	Please report on Form C103 any unusual occurances while driling the Salado formation. Such as water flows, sand flows sauturated with brine, encounters with h2s, etc. Thankyou. Bryan Arrant
BARRANT	Surface casing depth is too deep. Operator to set surface casing above the Salado. Preferably 50 into the Rustler formation. Please refer to offset geological data such as e logs for more information.