District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(505) 393-6161 Fax:(505) 393-0720

District II

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Form C-140 Permit 27478 Revised June 10, 2003

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 (505) 476-3440

APPLICATION FOR WELL WORKOVER PROJECT

I.	Operato	r and Well:							2000-2000-000-000-00-00-00-00-00-00-00-0		
Operator name & address									OGRID Number		
OCCIDENTAL PERMIAN LTD									157984		
PO Bo		•									
		77210									
Contact Party Karen Ellis									Phone 713-366-5161		
							Well Num	NOT.	API Number	.01	
Property Name Well Number NORTH HOBBS G/SA UNIT 221								, 4	30-025-07430		
UL - I	Lot	Section	Tow	mship	Range	Feet From The	North/South Lir	e Feet From The	East/West L:	ine County	
F		29	1	8S	38E	2310	И	1650	W	Lea	
п	Workov	PT.	NY.			ž.	ai.	***	iller	100	
Date Wo	rikover	Commenced:	-	Previous	Producing P	ool(s) (Prior to W	orkover):				
12/9/2	12/9/2005 HOBBS;GRAYBURG-SAN ANDRES										
Date Wo 12/13/		Completed:									
12/13/	2002		2								
ш	Attach a	description o	f the W	orkover 1	Procedures per	formed to increase	production.				
							nths of production	prior to the workov	ver and at least t	three months of production	
		ig the workove description o				ion increase. formed to increase	production.				
	Signatu	10)-i						
			ation al	howe is tr	ne and comple	ete to the hest of n	ny knowledge and	helief			
Signature Electronically Signed					, , , , , , , , , , , , , , , , , , ,					4/13/2006	
Туре	or pri	nt nameEl	izabet	h Bush-	-Ivie E	-mail addres:	Elizabeth_Bus	h@oxy.com Te	elephone No	o. 713-366-5303	
										_	
	CONS	ERVATION I	DIVISI	ON USE	ONLY:						
VI. CERTIFICATION OF APPROVAL: This Application is hereby approved and the above-referenced well is designated a Well Workover Project and									1 - 1		
										i nereby vermes the data artment of this Approval and	
						leted on: 12/13/2					
Signature District Supervisor: Paul Kautz District 1 Date 4/13/2006								/2006			
0		1		35	1900 of 1900 of the				3		

DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT: 4/13/2006

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-200s

12/18/2005

505/397-8206

TELEPHONE NO.

DATE

Revised 5-27-2004 FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO. DISTRICT I 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 30-025-07430 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease 1301 W. Grand Ave, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd, Aztec, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A NORTH HOBBS (G/SA) UNIT DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 29 1. Type of Well: 8. Well No. 221 Oil Well X Gas Well Other 2. Name of Operator 9. OGRID No. 157984 Occidental Permian Ltd. 3. Address of Operator 10. Pool name or Wildcat HOBBS (G/SA) 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 4. Well Location Feet From The NORTH Feet From The Unit Letter F : 2310 1650 WEST Line NMPM Section 29 Township 18-S County LEA 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3642' GR Pit or Below-grade Tank Application or Closure Pit Type _____ Depth of Ground Water _ Distance from nearest fresh water well Distance from nearest surface water Below-Grade Tank: Volume bbls; Construction Material Pit Liner Thickness _____ mil 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Х ALTERING CASING CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON Multiple Completion CASING TEST AND CEMENT JOB PULL OR ALTER CASING OTHER: OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU. Pull ESP production equipment. Clean out to PBTD @4237'. Run CNL/SNG/CCL from 4237' to 3250'. 2. Perforate the following intervals; 4138-58 and 4183-89, using 2 spf, 180 deg sp ph. (56 holes). Stimulate perfs 4138-4189 and open hole 4213-37 w/3000 g 15% NEFE HCL acid. RIH w/Reda ESP equipment on 121 jts 2-7/8" tbg. Intake set @3856'. 5 Install OCI wellhead connection. RDPU. Clean Location. 12/09/2005 Rig Up Date: Rig Down Date: 12/13/2005 Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines or an (attached) alternative OCD-approved , a general permit plan

TITLE Workover Completion Specialist

robert_gilbert@oxy.com

TITLE

E-mail address:

CONDITIONS OF APPROVAL IF ANY:

Robert Gilbert

SIGNATURE

For State Use Only

APPROVED BY

TYPE OR PRINT NAME

C140 Comments

OGRID: [157984] OCCIDENTAL PERMIAN LTD

Permit Number: 27478
Permit Type: C140

Created By	Comment	Comment Date	
pkautz	Feb & Mar production shows increase	4/13/2006	