UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an				Lease Serial No. N00C14203598 If Indian, Allottee or Tribe Name		
abandoned well. Use form 3160-3 (APD) for such proposals.				EASTÉRN NAVAJO		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM87152	
Type of Well	ner: COAL BED METHANE				8. Well Name and No. BUENA SUERTE	3 G COM 1
Name of Operator DJR OPERATING LLC	Contact: E-Mail: sford@djrlld	SHAW-MARII c.com	FORD		9. API Well No. 30-045-28646-00	D-S1
3a. Address 1 ROAD 3263 AZTEC, NM 87410 3b. Phone N Ph: 505-6			(include area code) 2-3476			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)				11. County or Parish, S	tate
Sec 3 T25N R11W SWNE 240 36.430618 N Lat, 107.988037					SAN JUAN COU	INTY, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICAT	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION			TYPE OI	F ACTION		
Notice of Intent	☐ Acidize	☐ Deep	en	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
☑ Notice of Intent	☐ Alter Casing	☐ Hydi	aulic Fracturing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	olete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug	and Abandon	□ Tempor	arily Abandon	
	☐ Convert to Injection	□ Plug	Back	☐ Water I	Disposal	
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final At determined that the site is ready for final DJR Operating, LLC requests Procedure, Current & Propose	operations. If the operation respondonment Notices must be file inal inspection. permission to Plug & Abaed Wellbore Diagram and	ults in a multiple od only after all r ndon the sub	e completion or reco equirements, include ect well accord	ompletion in a r ling reclamation	new interval, a Form 3160 n, have been completed an	0-4 must be filed once
Com	Electronic Submission #5 For DJR OP mitted to AFMSS for proce	ERATING LL¢	, sent to the Far	mington	•	
	ARIE FORD	- Jg ~ J . I = A		ATORY SPI	•	
Signature (Electronic S	Submission)		Date 10/23/2	020		
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE	
_Approved By_JOE KILLINS			TitlePETROLE	UM ENGINI	======================================	Date 01/12/2021
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the		Office Farming	ton		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					ake to any department or a	agency of the United

Revisions to Operator-Submitted EC Data for Sundry Notice #535275

Operator Submitted BLM Revised (AFMSS)

Sundry Type: ABD NOI NOI

Lease: N00C14203598 N00C14203598

Agreement: NMNM87152 NMNM87152 (NMNM87152)

Operator: DJR OPERATING LLC DJR OPERATING LLC 1 ROAD 3263 AZTEC, NM 87410 Ph: 505-632-3476 1 ROAD 3263

AZTEC, NM 87410 Ph: 505-632-3476

SHAW-MARIE FORD SHAW-MARIE FORD Admin Contact:

REGULATORY SPECIALIST REGULATORY SPECIALIST E-Mail: sford@djrllc.com E-Mail: sford@djrllc.com

Ph: 505-632-3476 Ph: 505-632-3476

SHAW-MARIE FORD REGULATORY SPECIALIST SHAW-MARIE FORD REGULATORY SPECIALIST Tech Contact:

E-Mail: sford@djrllc.com E-Mail: sford@djrllc.com

Ph: 505-632-3476 Ph: 505-632-3476

Location:

State: NM SAN JUAN County: SAN JUAN

Field/Pool: BASIN FRUITLAND COAL BASIN FRUITLAND COAL

BUENA SUERTE 3 G COM 1 Sec 3 T25N R11W SWNE 2400FNL 1820FEL Well/Facility:

BUENA SUERTE 3 G COM 1 Sec 3 T25N R11W SWNE 2400FNL 1820FEL

36.430675 N Lat, 107.988670 W Lon 36.430618 N Lat, 107.988037 W Lon

Plug and Abandonment Procedure

for

DJR Operating, LLC
Buena Suerte 3G Com 1
API # 30-045-28646

SW/NE, Unit G, Sec. 3, T25N, R11W

San Juan County, NM

I.

- 1. Hold pre-job meeting, comply with all NMOCD, BLM and environmental regulations.
- 2. Check and record tubing, casing and bradenhead pressures.
- 3. Remove existing piping from casing valve, RU blow lines from casing valves and blow down casing pressure. Kill well as necessary. Ensure that well is dead or on a vacuum.
- 4. Trip out of hole with rods and pump. Lay down to be sent in for storage/salvage.
- 5. ND WH, NU BOP, function test BOP.
- 6. Trip out of hole with 2 3/8" tubing. LD tubing to be sent in for storage/salvage.

II.

- 7. PU workstring, TIH with bit and scraper, make sure that the bit and scraper will go below 1180'. TOOH.
- 8. PU and RIH with a 4 ½" cement retainer. Set the CR at +/- 1180'. Pressure test tubing to 1000 psi, sting out of CR, test casing to 600 psi. If casing does not test, contact engineering.

Provided that casing test was good, proceed to step 9.

- 9. RU cement equipment. Pump water to assure that tubing is clear.
- 10. Plug 1. Mix and attempt to pump 10 sx class G cement through cement retainer and displace with 5.1 bbl water. If zone pressures up, sting back out of retainer and continue with Plug 2.

- 11. Plug 2. Fruitland, Kirtland, Ojo Alamo, and surface casing shoe. From 1180' to surface, mix and pump cement until cement circulation is achieved at surface.
- 12. RD cementing equipment. Cut off wellhead, fill annuli with cement as necessary. Install P&A marker as per regulatory requirements. Record GPS coordinates for P&A marker and the final P&A report. Photograph the P&A marker and attach to the report.
- 13. RD and MO all rig and cement equipment. Assure that location is free of trash and contamination before moving off.
- 14. Send all reports and attachments to DJR Aztec office for regulatory filings.

Note: All cement is to be class G mixed at 15.8 ppg, yield 1.15 cu ft / sx. Cement volumes are based on inside capacities + 50' excess and outside capacities + 100 % excess.

BLM FLUID MINERALS Geologic Report

Date Completed: 01/04/2021

Well No. Buena Suerte 3G Com #001 (API# 30-045-28646)			Location	2400	FNL	&	1820	FEL
Lease No. N00-C-1420-3598		Sec. 03	T25N		R11W			
Operator	DJR Operating, LLC		County	San Juan Stat		State	New Mexico	
Total Depth	1510'	PBTD 1455'	Formation	on Fruitland Coal (producing), Pictured Cliffs (TD)			s (TD)	
Elevation (GL)	L) 6245'		Elevation (KB)					

Geologic Formations	Est. Top	Est. Bottom	Log Top	Log Bottom	Remarks
San Jose Fm					Surface/Fresh water sands
Nacimiento Fm	Surface	370			Fresh water sands
Ojo Alamo Ss	370	481			Aquifer (fresh water)
Kirtland Shale	481	1071			
Fruitland Fm	1071	1355			Coal/Gas/Possible water
Pictured Cliffs Ss	1355	PBTD			Gas
Lewis Shale					
Chacra					
Cliff House Ss					Water/Possible gas
Menefee Fm					Coal/Ss/Water/Possible O&G
Point Lookout Ss					Probable water/Possible O&G
Mancos Shale					
Gallup					O&G/Water
Graneros Shale					
Dakota Ss					O&G/Water

Remarks:

P & A

- BLM estimate for the top of the Fruitland formation varies from operator pick, as the operator reported the top of the basal coal in the Fruitland, and BLM estimated the top of the Fruitland formation itself.
- Log analysis of reference well #3 indicates the Nacimiento and Ojo Alamo sands investigated likely contain fresh water (≤5,000 ppm TDS). Plugging plan has cement from the cement retainer @ 1180' to Surface which will protect freshwater sands in this well bore.
- Fruitland coal perforations @ 1220'-1238'.
- Low concentrations of H₂S (10 ppm GSV) have been reported in the SESE of Section 2, T25N, R11W.

Reference Well:

- 1) **Formation Tops** Same
- 2) Formation Tops
 DJR Operating, LLC
 Buena Suerte 3L Com #1T
 1740' FNL, 1420' FWL
 Sec. 3, T25N, R11W
 GL 6274'
- 3) Water Analysis Giant E & P Co. Carson Unit #23 1980' FSL, 1980' FEL Sec. 19, T25N, R11W GL 6438' KB 6447'


Prepared by: Chris Wenman

DJR Operating, LLC Current Wellbore Diagram

Buena Suerte 3G Com 1

API # 30-045-28646 SW/NE, Unit G, Sec 3, T25N, R11W San Juan County, NM

GL 6245' KB N/A Spud Date 1/23/1992



Production Tubing/Rod Detail

1 jt. 2.375", SN, 39 jts. 2.375" tbg.


2"x1.5"x12' RWAC pump, .75"x4' guided rod sub, 8x.75" guided rods, 1x.75" rod, 1x.75" guided rod, 36x.75" plain rods, .75x2'x2' rod subs, 1.25"x16' polished rod with 8' liner.

DJR Operating, LLC Proposed Wellbore Diagram

Buena Suerte 3G Com 1

API # 30-045-28646 SW/NE, Unit G, Sec 3, T25N, R11W San Juan County, NM

GL 6245' KB N/A Spud Date 1/23/1992



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon

Well: Buena Suerte 3G Com 1

API: 3004528646

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. If casing fails to test contact BLM Engineering. No changes are to be made to this approved Sundry without prior approval from the BLM.
- 4. A Subsequent Report Sundry Notice (Form 3160-5) must be submitted within 30 days after plugging operations are complete.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
 - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
 - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
 - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
 - 4.1 The cement shall be as specified in the approved plugging plan.
 - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.3 Surface plugs may be no less than 50' in length.
 - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
 - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

2

- 5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.
 - 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
 - 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
 - 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
 - 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
 - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
 - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain H_2S .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), five copies, with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

(October 2012 Revision)

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 14523

COMMENTS

Operator:			OGRID:	Action Number:	Action Type:
DJR OPERATING, LLC	1 Road 3263	Aztec, NM87410	371838	14523	C-103F

Created By	Comment	Comment Date
kpickford	KP GEO Review 1/14/2020	01/14/2021

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 14523

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
DJR OPERATING, LLC	1 Road 3263	Aztec, NM87410	371838	14523	C-103F

OCD Reviewer	Condition
kpickford	Notify NMOCD 24 Hours Prior to beginning operations