
Received by OCD: 8/8/2021 12:20:03	State of New Mex	xico	Form C-103 ¹ of			
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION		WELL API NO. 30-021-20505			
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178			5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. France		STATE FEE			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	303	6. State Oil & Gas Lease No.			
87505 SLINDRY NOT	PICES AND DEPORTS ON WELLS		7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPO	CICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH		WEST BRAVO DOME UNIT			
1. Type of Well: Oil Well	Gas Well ☐ Other ✔		8. Well Number 181			
2. Name of Operator OXY USA INC. (16696)			9. OGRID Number 16696			
3. Address of Operator			10. Pool name or Wildcat			
PO BOX 4294, HOUSTON	, TX 77210-4294		WEST BRAVO DOME CO2 GAS			
4. Well Location	2040 a a NODTH		O A A WEST II			
	2210 feet from the NORTH	line and 165				
Section 18	Township 19N Rar 11. Elevation (Show whether DR,	ige 30E RKR RT GR etc.)	NMPM County			
	11. Elevation (blow whether BR,	nnb, ni, on, cic.)				
12. Check	Appropriate Box to Indicate Na	ture of Notice,	Report or Other Data			
NOTICE OF IN	NTENTION TO:	SUB	SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	ΓJOB ∐			
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM						
OTHER:	TA EXTENSION - MIT	OTHER:				
			d give pertinent dates, including estimated date			
of starting any proposed we proposed completion or rec		. For Multiple Con	mpletions: Attach wellbore diagram of			
	•	wile a Alexandra of	Otation Francisco francisto a communit			
TA expiration date of 09/23/2		•	Status Exemption from the current			
TA expiration date of 09/23/2	2020. Flatt forward is as folio	JW5.				
1. Set retrievable bridge plug (RBP) ~50' above top perf to perform MIT.						
2. Notify NMOCD of casing i		•	•			
3. PU pump truck, circulate v	<u> </u>		g to 500psi for 30 minutes.			
4. Remove RBP.						
*THIS IS A MONITOR WELL	*					
Spud Date:	Rig Release Dat	0:				
Spud Date.	Kig Kelease Dat	е.				
I hereby certify that the information	above is true and complete to the best	st of my knowledge	e and belief.			
SIGNATURE Gray Melfel	TITLE_REGUL	ATORY LEAD	DATE 09/08/21			
	ER F-mail address:	EMILY MESSE	R@OXY.COM PHONE: 713-497-2076			
For State Use Only	L-man address.		110ML 101 Z010			
	Kushling TITLE Depu	ty Oil and Gas Ir	achaetar DATE 0/0/21			
APPROVED BY:		ty Oil ailu Gas II	nspector DATE 9/9/21			

OXY USA Inc. - Current/Proposed WEST BRAVO DOME UNIT #181 API No. 30-021-20505



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 46839

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	46839
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created	Condition	Condition
Ву		Date
mkuehling	NMOCD witness required on all testing. Northwest bradenhead test required prior to MIT - performed day of MIT - all valves need to be dug out and plumbed to surface - do not bury till after	9/9/2021
	testing - chart recorder with 1000 lb spring - 1 hour clock - chart should match spring and clock.	