

Submit 1 Copy To Appropriate District Office
 District I – (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II – (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III – (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV – (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-31781
1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator RAYBAW Operating, LLC		6. State Oil & Gas Lease No. 330200
3. Address of Operator 2626 Cole Ave, Ste 300, Dallas, TX 75204		7. Lease Name or Unit Agreement Name Chimayo 16 State
4. Well Location Unit Letter C : 660 feet from the N line and 1980 feet from the W line Section 16 Township 25S Range 29E NMPM County Eddy		8. Well Number #001
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 2988' GL		9. OGRID Number 330220
10. Pool name or Wildcat (96100) SWD; Delaware		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
DOWNHOLE COMMINGLE ☐			
CLOSED-LOOP SYSTEM ☐			
OTHER: ☐		OTHER: ☐	

Notify OCD 24 hrs. prior to any work done

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Tag CIBP @ 4700' w/ 35' cmt on top.
2. Set 5 1/2" CIBP @ 3210'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 3210-3010'.
3. Spot 25 sx cmt @ 2840-2640'. WOC & Tag (B/Salt)
4. Perf & Sqz 50 sx cmt @ 1050-850'. WOC & Tag (8 5/8" Shoe)
5. Perf & Sqz 140 sx cmt @ 650' to surface.
6. Cut off well head, verify cmt @ surface, weld on Dry Hole Marker.

Spud Date:

Rig Release Date:

****SEE ATTACHED COA's****

Must be plugged by 2/3/2023

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nancy J. Winn TITLE Regulatory Analyst DATE 2/2/2022
 Type or print name Nancy J. Winn E-mail address: nwinns@sbcbglobal.net PHONE: 281-793-5452
For State Use Only

APPROVED BY: [Signature] TITLE Staff Manager DATE 2/3/2022
 Conditions of Approval (if any):

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, **Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water **will not** be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3. API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)-----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S – R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S – R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A- F. Sec 27 Unit A,B,C,F,G,H.

T 19S – R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S – R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S – R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S – R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 20 – 29. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S – R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S – R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S – R 30E

Sec 1 – Sec 36

T 21S – R 31E

Sec 1 – Sec 36

T 22S – R 28E

Sec 36 Unit A,H,I,P.

T 22S – R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S – R 30E

Sec 1 – Sec 36

T 22S – R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S – R 28E

Sec 1 Unit A

T 23S – R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S – R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S – R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S – R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S – R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S – R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.



CHIMAYO 16 ST 1 SWD

devon

Data Cleanup Schematic


API/UWI 3001531781		Surface Legal Location 16-25-S 29-E-6		Field Name CARLSBAD SOUTH - PB		Permit No.		State/Province NM		Well Configuration Type VERTICAL					
Ground Elevation (ft) 2,988.00		Casing Flange Elevation (ft) 0.00		KB - Ground Level (ft) 12.00		KB - Casing Flange (ft) 3,000.00		Original Drlg Spud Date 5/27/2001 00:00		Original Drlg Rig Release Date 6/20/2001 00:00					
VERTICAL, OH, 1/18/2021 9:32:56 AM				Production Failures											
MD (ftKB)		Vertical schematic (actual)		Failure Date		Failure Des		Fail Type		Cause		Total Est. Cost (Cost)			
11.8				4/28/2005		ROD REPAIR						17,100.00			
600.1				9/1/2005								9,350.00			
2,980.0		13 3/8; 600.0		7/20/2006		ROD REPAIR						28,320.00			
3,173.6		8 5/8; 2,980.0		10/9/2006		ROD REPAIR						8,525.00			
3,181.1				6/7/2007		ROD REPAIR						25,050.00			
3,188.0				Jobs											
3,259.8				Job Cat		Job Subtype		Job Start		Job End		Total Fld Est (Cost)			
3,410.1		3,260.0-3,300.0		RECOMPLETION				10/1/2001		10/8/2002		\$180,053			
3,520.0		3,410.0-3,430.0		PROD MAINT				11/11/2002		11/14/2002		\$12,100			
3,684.1		3,520.0-3,546.0		PROD MAINT		ROD REPAIR		10/6/2003		10/7/2003		\$106,575			
3,950.1		3,684.0-3,710.0		PROD MAINT		ROD REPAIR		10/25/2004		10/27/2004		\$9,500			
4,009.8		3,950.0-3,970.0		PROD MAINT		ROD REPAIR		4/28/2005		5/2/2005		\$17,100			
4,086.0		4,010.0-4,030.0		PROD MAINT		ROD REPAIR		9/1/2005		9/2/2005		\$9,350			
4,204.1		4,086.0-4,100.0		PROD MAINT		ROD REPAIR		7/20/2006		7/22/2006		\$28,320			
4,339.9		4,204.0-4,220.0		PROD MAINT		ROD REPAIR		10/9/2006		10/10/2006		\$8,525			
4,419.9		4,340.0-4,370.0		PROD MAINT		ROD REPAIR		6/7/2007		6/7/2007		\$25,050			
4,665.0		4,420.0-4,450.0		RECOMPLETION		ADD PAY		10/4/2010		10/19/2010		\$136,541			
4,702.1		4,700.0; Other in Hole		RECOMPLETION		ADD PAY		3/15/2011		3/24/2011		\$98,012			
4,959.0		4,953.0-4,959.0		RECOMPLETION		CONVERSION		9/26/2011		11/29/2011		\$373,071			
5,055.1		5,049.0-5,055.0		PROD MAINT		ACID STIMULATION		11/27/2013		11/28/2013		\$27,500			
5,095.1		5,081.0-5,095.0		PROD MAINT		BATCH/MILD ACID		5/2/2016		5/3/2016		\$23,862			
5,137.1		5,133.0-5,137.0		PROD MAINT		REPAIR/REPLACE		5/10/2016		5/11/2016		\$4,832			
5,145.0		5,142.0-5,145.0		PROD MAINT		BATCH/CORROSION/S CALE		11/1/2017		11/2/2017		\$23,275			
5,174.9		5,170.0-5,175.0		PROD MAINT		BATCH/CORROSION/S CALE		5/15/2018		5/16/2018		\$14,228			
5,182.1		5,178.0-5,182.0		WORKOVER		TUBING REPAIR		6/26/2018		7/4/2018		\$99,409			
5,225.1		5,220.0-5,225.0		PROD MAINT		BATCH/CORROSION/S CALE		8/27/2020		8/29/2020		\$18,168			
5,233.9		5,229.0-5,234.0		Production Tests & Emissions											
5,275.9		5,260.0-5,276.0		Date		Q Oil (bbl/day)		Rate Gas (MCF/day)		Q Water (bbl/day)		Tub Pres (psi)		Cas Pres (psi)	
5,342.8		5,335.0-5,343.0													
5,356.0		5,352.0-5,356.0		Production Settings											
5,387.1		5,369.0-5,387.0		Method		Method Detail		Start Date		End Date					
5,649.9		5,650.0; Other in Hole		Rod Pump Detail				1/1/2004		12/1/2011					
8,575.1		8,610.0; Other in Hole		Other		IN		12/1/2011							
8,612.9		CROSSLINKED FRAC; 8,702.0-8,734.0		Perforation Intervals											
8,733.9		8,990.0; Other in Hole		Date		Top (ftKB)		Btm (ftKB)		Shot Dens (shots/ft)		Phasing (°)		Linked Zone	
8,990.2		9,118.0-9,134.0		10/17/2011		3,260.0		3,300.0		3.0		60		DELAWARE, OH	
9,118.1		5 1/2; 9,300.0		10/17/2011		3,410.0		3,430.0		3.0		120		DELAWARE, OH	
9,299.9				10/17/2011		3,520.0		3,546.0		3.0		120		DELAWARE, OH	
				10/17/2011		3,684.0		3,710.0		3.0		60		DELAWARE, OH	
				10/17/2011		3,950.0		3,970.0		3.0		60		DELAWARE, OH	
				10/4/2011		4,010.0		4,030.0		2.0		60		DELAWARE, OH	
				10/4/2011		4,086.0		4,100.0		2.0		60		DELAWARE, OH	
				10/4/2011		4,204.0		4,220.0		2.0		60		DELAWARE, OH	
				10/4/2011		4,340.0		4,370.0		2.0		120		DELAWARE, OH	
				10/4/2011		4,420.0		4,450.0		3.0		120		DELAWARE, OH	
				3/16/2011		4,953.0		4,959.0		3.0				DELAWARE, OH	
				3/16/2011		5,049.0		5,055.0		3.0				DELAWARE, OH	
				3/16/2011		5,081.0		5,095.0		3.0				DELAWARE, OH	
				3/16/2011		5,133.0		5,137.0		3.0				DELAWARE, OH	
				3/16/2011		5,142.0		5,145.0		3.0				DELAWARE, OH	
				3/16/2011		5,170.0		5,175.0		3.0				DELAWARE, OH	
				3/16/2011		5,178.0		5,182.0		3.0				DELAWARE, OH	
				3/16/2011		5,220.0		5,225.0		3.0				DELAWARE, OH	
				3/16/2011		5,229.0		5,234.0		3.0				DELAWARE, OH	
				3/16/2011		5,260.0		5,276.0		3.0				DELAWARE, OH	

CHIMAYO 16 ST 1 SWD

devon

Data Cleanup Schematic


API/UWI 3001531781	Surface Legal Location 16-25-S 29-E-6	Field Name CARLSBAD SOUTH - PB	Permit No.	State/Province NM	Well Configuration Type VERTICAL
Ground Elevation (ft) 2,988.00	Casing Flange Elevation (ft) 0.00	KB - Ground Level (ft) 12.00	KB - Casing Flange (ft) 3,000.00	Original Drig Spud Date 5/27/2001 00:00	Original Drig Rig Release Date 6/20/2001 00:00



RayBaw (Devon)		CURRENT	
Author:	Abby @ BCM	Well No.	#1
Well Name	Chimayo 16 State	API #:	30-015-31781
Field/Pool	Willow Lake Southeast	Location:	Sec 16, T25S, R29E
County	Eddy		660 FNL & 1980 FWL
State	NM	GL:	2988'
Spud Date	5/27/2001		

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	13 3/8	H40	48#	600	17 1/2	460	0
Inter Csg	8 5/8	J55	32#	1,000	12 1/4	1,000	0
Prod Csg	5 1/2	N80	17#	9,300	7 7/8	1,205	1850 CBL

Formation	Top
B/Salt	2790
Delaware	2980
Bone Springs	6790




32.1355171
-103.9916763

RayBaw (Devon)		PROPOSED	
Author:	Abby @ BCM	Well No.	#1
Well Name	Chimayo 16 State	API #:	30-015-31781
Field/Pool	Willow Lake Southeast	Location:	Sec 16, T25S, R29E
County	Eddy		660 FNL & 1980 FWL
State	NM	GL:	2988'
Spud Date	5/27/2001		

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	13 3/8	H40	48#	600	17 1/2	460	0
Inter Csg	8 5/8	J55	32#	1,000	12 1/4	1,000	0
Prod Csg	5 1/2	N80	17#	9,300	7 7/8	1,205	1850 CBL

Formation	Top
B/Salt	2790
Delaware	2980
Bone Springs	6790



13 3/8 48# CSG @ 600
5. Perf & Sqz 140 sx cmt @ 650' to surface.

8 5/8 32# CSG @ 1,000
4. Perf & Sqz 50 sx cmt @ 1050-850'. WOC & Tag (8 5/8" Shoe)

3. Spot 25 sx cmt @ 2840-2640'. WOC & Tag (B/Salt)

2. Set 5 1/2" CIBP @ 3210'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 3210-3010'.

Perfs @ 3260-4450'

1. Tag CIBP @ 4700' w/ 35' cmt on top
10/04/2011 CIBP @ 4700' w/ 35' cmt on top

Perfs @ 4953-5387'

03/16/2011 CIBP @ 5650'

10/14/2010 CIBP @ 8610 w/ 35' cmt on top

Perfs @ 8702-8734'

10/07/2010 CIBP @ 8990' w/ 35' cmt on top

Perfs @ 9118-9134

5 1/2 17# CSG @ 9,300

TDPB @ 4665'
TD @ 9300'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 77710

CONDITIONS

Operator: RAYBAW Operating, LLC 2626 Cole Avenue Dallas, TX 75204	OGRID: 330220
	Action Number: 77710
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	2/3/2022