

District 1
1625 N. French Dr., Hobbs NM 88240
Phone(575)393-6161 Fax: (575)939-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name	API Number
MAVERICK NATURAL RESOURCES	30-025-26394

Property Name	Well No
EVGSAU 0524	001

UL - Lot	SEC	Tnsp	Range	Surface Location Feet From	N/S Line	Feet From	E/W Line	County
C	05	18S	35E	10	NORTH	1443	WEST	LEA

Well Status				PRODUCER		DATE
TA'D WELL	SHUT-IN	INJECTOR	SWD	OIL	GAS	
YES	NO YES	NO INJ				5-13-24

OBSERVED DATA					
	(A)Surface	(B)Interm (1)	(C)Interm (2)	(D) Prod Csg	(E)Tubing
Pressure	0			157	1102
Flow Characteristics					CO2
Puff	Y / N	Y / N	Y / N	Y / N	WTR
Steady Flow	Y / N	Y / N	Y / N	Y / N	GAS
Surges	Y / N	Y / N	Y / N	Y / N	
Down to Nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks- Please state for each string (A,B,C,D) pertinent information regarding bleed down or continuous build up if applies.
Maverick contested 8-2023 failure- wanted a retest -
Want to retest + Prod. csg blew to zero + would not stop
flowing fluid. Failed - leave Shut in.

Signature:		OIL CONSERVATION DIVISION
Print name:		Entered in RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness: Gary Robinson		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 347218

CONDITIONS

Operator: Maverick Permian LLC 1000 Main Street, Suite 2900 Houston, TX 77002	OGRID: 331199
	Action Number: 347218
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Retest well and repair as needed	6/4/2024