Office	OPM State of New Mexico	Page 1 of Form C-103
District I (675) 202 (161	Energy, Minerals and Natural Resources	Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Diorgy, Willions and Natural Resources	WELL API NO.
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION	30-005-29217
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
And the state of t	ΓICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	LICATION FOR PERMIT" (FORM C-101) FOR SUCH	WISHBONE STATE
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other: SWD	8. Well Number
1. Type of wen. On wen	das well Oulel. SwD	001
2. Name of Operator		9. OGRID Number
COBRA OIL & GAS CORPORA	ATION	147404
3. Address of Operator		10. Pool name or Wildcat
P O BOX 8206, WICHITA FALL	LS, TX 76307	TOWERS SAN ANDRES (Code 59770)
4. Well Location		
	: 1672 feet from the SOUTH line an	nd 476 feet from the WEST line
Section 1 Tov	wnship 11S Range 31E NMPM	County: CHAVES
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 4503 GR	c.)
NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	PLUG AND ABANDON REMEDIAL WORD CHANGE PLANS COMMENCE DR MULTIPLE COMPL CASING/CEMEN	RILLING OPNS. P AND A NT JOB lugback
13. Describe proposed or composed of starting any proposed we proposed completion or re	vork). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re Cobra Oil & Gas Corporation composed.	work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion.	ompletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re Cobra Oil & Gas Corporation complugback reports.	work). SEE RULE 19.15.7.14 NMAC. For Multiple Conception. menced plugback operations on 05/03/2021, and complete the conception of the co	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re Cobra Oil & Gas Corporation composed com	work). SEE RULE 19.15.7.14 NMAC. For Multiple Concompletion.	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re Cobra Oil & Gas Corporation complugback reports.	work). SEE RULE 19.15.7.14 NMAC. For Multiple Conception. menced plugback operations on 05/03/2021, and complete the conception of the co	ompletions: Attach wellbore diagram of
of starting any proposed w proposed completion or re Cobra Oil & Gas Corporation complugback reports.	work). SEE RULE 19.15.7.14 NMAC. For Multiple Conception. menced plugback operations on 05/03/2021, and complete the conception of the co	ompletions: Attach wellbore diagram of
13. Describe proposed or composed of starting any proposed we proposed completion or re Cobra Oil & Gas Corporation complugback reports. Spud Date:	work). SEE RULE 19.15.7.14 NMAC. For Multiple Conception. menced plugback operations on 05/03/2021, and complete conceptions. Rig Release Date:	ompletions: Attach wellbore diagram of leted operations on 06/06/2021. Attached are the
13. Describe proposed or composed of starting any proposed we proposed completion or re Cobra Oil & Gas Corporation complugback reports. Spud Date:	work). SEE RULE 19.15.7.14 NMAC. For Multiple Conception. menced plugback operations on 05/03/2021, and complete the conception of the co	leted operations on 06/06/2021. Attached are the ge and belief.
13. Describe proposed or composed of starting any proposed we proposed completion or re Cobra Oil & Gas Corporation complugback reports. Spud Date:	Rig Release Date: TITLE Prod & Reg Compl Support Supp	ompletions: Attach wellbore diagram of leted operations on 06/06/2021. Attached are the ge and belief.
13. Describe proposed or composed of starting any proposed we proposed completion or recomplugate reports. Spud Date: I hereby certify that the information SIGNATURE	Rig Release Date: TITLE Prod & Reg Compl Support Supp	ompletions: Attach wellbore diagram of leted operations on 06/06/2021. Attached are the ge and belief.
13. Describe proposed or composed of starting any proposed we proposed completion or recompleted and the proposed completion completed and the proposed completed completed and the proposed completed and the proposed completed completed completed completed complete	Rig Release Date: TITLE Prod & Reg Compl Support Supp	ompletions: Attach wellbore diagram of leted operations on 06/06/2021. Attached are the ge and belief.

COBRA OIL & GAS CORPORATION WISHBONE STATE 001 PLUGBACK REPORTS

MI HT Services PU, set rig mat & RU. MI approx. 11,500' of 2 7/8" L-80 tubing (work-string) & 05/03/21:

tally top row. SICP = vacuum, ND wellhead & NU 7 1/16" 3K BOP. PU 2 7/8" SN & TIH with 130

- joints of WS (4,237'). Had to SDFD due to rain, hail & lightning.
- 05/04/21: SICP = blow, SITP = blow. Continue in the hole with WS to 11,507', POOH Standing pipe back

noticing the last 3 rows (2,268') of pipe were covered in good oil. Had The Wireline Group rigged up but decided to run a packer & swab well. RD The Wireline Group, called for 7" Arrow set PKR.

- PU compression PKR, SN, TIH with 50 stands (3256'), SWI & SDFN.
- 05/05/21: SICP = blow, SITP = blow, Continue in the hole with WS, PKR to 11,540' & set PKR with 16K in compression. Loaded backside with 29 bbls (FL = 1,000') & tested good to 500 PSIG. RU swab,

made a total of 16 swab runs with IFL = 1,300' & EFL = 1,700'. Each run had a TRC of oil on them but not recordable. Recovered 98 BW & 0 BO. RD swab, un-set PKR & POOH. LD PKR, SWI & SDFN.

05/06/21: SICP = 0 PSIG, RU The Wireline Group, RIH with 7" gauge ring to 11,555' with no issues. POOH, PU

7" CIBP, correlate to radial bond GR/CCL log dated 04-Jun-2018 & RIH to 11,550' (found FL @ 1,300') & set. Tagged CIBP & POOH. RIH with dump bailer & dumped 35' of class "H" cement on top of CIBP. POOH & LD bailer. TIH with WS to 11,452' & circulate hole with 350 bbls of 9.5# brine water. POOH, PU 7" CIBP, RIH to 8,989' (found FL @ 700') & set CIBP. tagged plug, POOH & PU dump bailer. RIH & dump 35' of class "H" cement on top of CIBP. POOH, RD WLU, SWI & SDFN.

05/07/21: SICP = 0 PSIG, RIH with 200 joints of WS then LD WS (15 were already layed down) & RIH with 75 stands placing EOT @ 4906.00'. RU J & B Well Service, LLC, load hole with 18 bbls of 9.5# brine water. Batched up 25 sacks of class "C" cement mixed @ 14.8# with 1.32 yield with 3.75 water requirement. Pumped cement followed by 18.3 bbls of 9.5# brine water. Checked to see if plug

was balanced & it was. LD 22 joints of WS then TOOH with WS. SWI & SDFN.

SICP = 0 PSIG, RU Kill Truck & loaded casing with 15 bbls of 9.5# brine water. Tested casing to 05/08/21:

500 PSIG & held good for 15 minutes, RU The Wireline Group, PU gamma & CCL with 25' of perf guns. RIH & corrolate to Radial Bond, Gamma Ray/CCL dated 04-Jun-2018. Perforte from 4,250' 4,275' with 60° phasing with 4 SPF, POOH finding all shots fired & RD WL truck. PU S/N 2 joints of tail pipe, PKR & TIH with WS placing S/N @ 4,187'. Set PKR, loaded casing with 1 bbl of 9.5# brine water & tested good to 500 PSIG. RU Swab, 1st run = surface, 2 nd run 1300', 3rd = 2500', 4th = 2900' pulling from SN recovering grey mud on that run (looked like drilling mud). Waited 1 hr, 5th =1500', 6th 2500', 7th 2800' & 8th 3700' pulling from SN. Recovered 56 BW, SWI & SDFN.

SICP = 10#, Unseat PKR, TIH placing tailpipe @ 4270', RU Crane acidizing Services & spot 500 05/10/21:

gallons of 15% HCl NEFE on bottom. Pulled tail pipe to 4,187, revered acid into tubing & set PKR. Tested backside good to 500 PSIG, RU on tubing & acidize as follows: Pumped 9,500 gallons of 15% HCl NEFE acid, broke well down with matrix rates of .3 bpm @ 500 PSIG, .5 bpm @ 700 PSIG, 1 bpm @ 1220 PSIG when well broke & started to take fluid. Increased rate to 2 bpm @ 2110 PSIG, pumped 26.4 bbls then started dropping 10 ball sealers @ a time for a total of 200 balls but never saw ball action. Went to flush still with 2 BPM @ 1220 PSIG. Flushed with 27.3 bbls of fresh water. ISIP =1190 PSIG, 5 min = 670 PSIG, 10 min = 470 PSIG & 15 min = 380 PSIG. Max pressure = 2110 PSIG, Avg PSI = 1232, Max rate = 2.5 BPM, Avg rate = 1.5625 BPM. SWI & SDFD. LWTR = 252

- bbls, We did ND BOP & flang well up.
- 05/11/21: SICP = 500#, SITP = Vac. RU Swab, IFL = 700' & EFL =2100', made a total of 39 runs, last 24 runs the FL = 2100'. Recovered 235 BW & 0 BO. SWI & SDFD.
- 05/12/21: SICP = 500#, SITP = 40#. IFL = 1400' & EFL = 2100', made 35 runs, last 23 runs the FL = 2100'. Recovered 216 BW & 0 BO. SWI & SDFD.
- 05/13/21: SICP = 500#, SITP = 20#. IFL = 1400' & EFL =2300', made 35 runs, last 12 runs the FL = 2300'. Recovered 207 BW & 0 BO. SWI & SDFD. Had swab water checked as follows: MW = 9.7 ppg & chlorides = 140,000.

05/14/21: SICP = 500#, SITP = 20#. IFL = 1400' & EFL =2400', made 33 runs, last 10 runs the FL = 2400'.

Recovered 203 BW & 0 BO. SWI & SDFD. Water I jusgt black iron sulfide water.

05/15/21: SICP = 500#, SITP = 10#. IFL = 1500' & EFL =2400', made 29 runs, last 10 runs the FL = 2400'.

Recovered 186 BW & 0 BO. SWI & SDFD. Water I just black iron sulfide water.

05/17/21: SICP = 500#, SITP = 10#. IFL = 1200' & EFL =2400', made 30 runs, last 14 runs the FL = 2400'.

Recovered 196 BW & 0 BO. SWI & SDFD. Water I just black iron sulfide water. Note: 2nd run had

2% oil on top of run. After 1st run, RD PU & MO. MI & RU Mesa Swabbing unit & RU.

05/18/21: SICP = 500#, SITP = 0 PSIG. IFL = 1600' & EFL =1800', made 34 runs, last 2 runs the FL = 1800'.

Recovered 210 BW & 0 BO. SWI & SDFD. Water is just black iron sulfide water. Note: 1st run had

2% oil on top of run, runs 2 -32 the FL = 1700' & last 2 runs FL = 1800'.

05/26/21: MI HT Energy Services & RU. SDFN.

05/27/21: SITP = 0 PSIG, Bled casing off to 0 PSIG. ND wellhead & NU 5K BOP. Un-set PKR, POOH with

tubing & LD PKR (rubbers looked good). SWI & SDFD. Had to flush the radiator on the WSU this

afternoon.

05/28/21: SICP = 0 PSIG. MIRU WLU, MU gauge ring, RIH & tagged cement plug @ 4,800'. POOH, PU 7" CIBP,

RIH, correlated with gamma & set @ 4,505'. PU RIH finding plug had moved down hole very slowly (must have broken a slip on the way in the hole. POOH PU another CIBP (wrapped bailing wire around slips), RIH & set it @ 4,505'. PU & tagged it solid. POOH, LD setting tool, PU 7" X 1' csg gun w/6 spf, 60° phasing, RIH & shoot squeeze perfs @ 4,500'. POOH finding all shots fired. SWI &

SDFN.

06/01/21: SICP = 0 PSIG. RU WLU, PU 7" CICR, RIH, correlate with gamma, set @ 4,495', PU, RIH & tagged in same place. POOH, LD tools, PU cmt stinger, TIH with tubing to top of CICR & pumped 2 tubing

volumes 52 bbls to clear tubing. Sting into retainer & established a injection rate of 1 bpm @ 50 PSIG with no blow on backside. Sting out of retainer batch up 30 sx of Class "C" + 5% salt + 0.5% C-47B + 0.005 GPS NoFoam V1A, mixed @ 14.8 ppg, 1.37 cf/sx yield with 6.52 pgs mix water. Pumped cement followed by 17 bbls of fresh water (note: checked backside & it was blowing by this time) & SI BS. Sting back into retainer when well went on a vacuum, pumped 2 bpm & caught cement in 2 bbls. Slowed rate to 0.5 bpm, displaced cmt to retainer with 130 PSIG of lift

pressure & 7" had very small returns back to tank. Stung out of retainer (casing U-tubed for 10 seconds), RD floor, pulled tubing slow for 5 stands pulling a dry string & TOOH. LD stinger, SWI &

SDFN.

06/02/21: SICP = 0 PSIG. MU 7" CIBP, RIH, correlate with gamma to 4,055' & set. PU, RIH, tagged plug & POOH.RU cement pump truck, loaded hole with 25 bbls & tested CIBP to 2500 PSIG & held good.

MU 7" X 1' csg gun w/6 spf, 60° phasing & RIH to 4,050'. Shot 6 holes, POOH & confirmed all shots fired. MU 7" CICR, RIH, correlate with gamma & set plug @ 4,045', PU, RIH & tagged retainer. POOH, RDMO WLU. PU stinger, TIH with tubing to top of retainer & pumped tubing capacity. Sting into retainer, got a 1 bpm injection rate @ 25 PSIG. Sting out of retainer, batched up 36 sx of Class "C" + 2% CaCl + 0.005 GPS NoFoam V1A, mixed @ 14.8 ppg with 1.35 cf/sx yield & 6.35 gps water requirement. Displaced cement to 1 bbl from EOT, stung into retainer with well on a

vacuum @ a 2.5 bpm rate. Let well suck to see if it would stop but it sucked it 2 bbls past retainer. SD sting out, reversed out 24 bbls with tubing clean the entire time. Pulled 20 stands,

SWI & SDFN.

06/03/21: SICP = 0 PSIG, SITP = 0 PSIG, TIH, Sting into retainer, got an injection rate of 0.5 bpm @ 280

PSIG, pumped 5 bbls @ that rate then went to 1 bpm @ 900 PSIG but broke back to 8 psig after 3 bbls. Stung out of retainer broke circulation to insure there was no air bubbles in casing with 28 bbls. Batched up 50 sx (12 bbls) of Class "C" + 2% CaCl + 0.005 GPS NoFoam V1A, mixed @ 14.8 ppg, 1.35 cf/sx yield & 6.38 pps water requirement. Spot cement 2 bbls from EOT, sting into retainer, pressured backside up to 500 PSIG & held on squeeze manifold (monitored during job) & pumped 7 bbls of cement into perfs @ .5 bpm. Pressure up to 1000 PSIG then SD with tubing press dropping to 600 PSIG. Waitied 30 minutes got back onto tubing @ .5 bpm with 500 PSIG on

tubing, pumped 3 bbls into perfs & SD for 20 minutes. Got back on to tubing @ 0.25 bpm with 250

PSIG pumping into perfs, pumped cement away 4 bbls past retainer to insure perfs were clear &

SD. Went to sting out of retainer but found we were stuck, tried to work it free eith the tongs (put 40 rounds into it only getting 4 back). Worked pipe up to 70K string weight several times but never could got stung out. Called Rotary wireline free point truck, Waited 3.5 hrs, pumped 0.25 bpm down tubing with 130 PSIG on tubing, when it got to 170 PSIG we were pumping into it. SD & RD Cementers. RU free point truck, RIH & tag @ 4,050'. Found we were 100% stuck @ 4,050' but 100% free @ 3,400'. POOH, PU chemical cutter, RIH, cut tubing 15' above a free collar @ 3,385'. POOH, RD wireline & TOOH with tubing. SWI & SDFN.

06/04/21:

SICP = 0 PSIG, LD 14 joints out of derrick, TIH with tubing & set on slips. RD HT Energy Services & MO. MI & RU Mico Services 24 hr PU & RU. TOOH, PU 6 1/8" hard band shoe, 10 joints of 5 1/2" body wash pipe, TIH to 3,385' & tagged tubing. Worked over tubing then tagged cement @ 3400'. RU power swivel, milled from 3,400' - 3,410' @ report time.

06/05/21:

Continue to wash over tubing to 3420' when shoe seemed to be worn out. Circulated hole clean, TOOH finding it was worn out (while TOOH, called rotary wireline to free point again), PU 6 1/2" overshot, TIH & latched onto tubing. PU on tubing when it jumped, tried to go down & latch back on with no success. TOOH finding we had a 20' piece of sliced tubing in overshot. Decided to RU 6 1/2" Piranha mill. PU mill, 1 -6 1/8" stabilizer, 1 3-1/2" DC, 1 - 6 1/8" stabilizer & 5-31/2" DC's. TIH to 3400', tagged up, RU power swivel & milled what was left of the tubing down to 3420'. Continue to mill down to 3427' when rig blew a hydraulic hose. Called for mechanic @ report time

06/06/21:


Continue to mill down to 3435' when mill started to slow down, Called Baker Hughes for the version of a good mill, they sent out 2 lills that had a much harder cutting surface with opticut inserts & Superloy buttons for cement. TOOH finding mill was worn, LD mill & PU Baker mill. TIH with same set up, Wash down to bottom, Pumped 4 BPM & milled from 3435' to 3452' @ report time.



Downhole Well Profile Well Name: WISHBONE STATE SWD #1 Prospect: TOWER

	Surface Legal Location	Field Name	State/Province	Well Type
Original KB Elevation (ft) 4,520,00	UL Lot L, Section 1, T11S, R31E Ground Elevation (ft) 4,503,00	PBTD (All) (ftKB)	New Mexico Total De	Disposal oth All (TVD) (ftKB)

<i>г</i> ре						
Des	Make	Model	WP (psi)	Service	WP Top (psi)	Bore Min (in)



Csq Des		OD	(in)	Wt/Len (lb/ft)	_	Grade	T 7	op Thread	Cot Do	pth (ftKB	
Surface	_						op mieau				
			13 3/8		54.50 J-55			1,599			
Intermediate			9 5/8	40,00	40,00 J-55 4,				1,000,0		
Production			7	7 26,00 L-80				11,70			
Perforations							- 100				
Date	Тор	(ftKB)		Btm (ftKB)	(ftKB)			Linked Zone			
12/13/2023		25	55.0	25	6,0				177		
12/12/2023		1,6	50.0	1,65	1.0						
12/12/2023		2,3	10.0	2,31	1.0	100	17				
6/2/2021		4,0	50.0	4,05	1.0						
5/8/2021		4,2	50.0	4,27	5,0						
Tubing Strings											
Tubing Description	Run	Date		String	eng	th (ft)	200	Set Depth (ftKB)			
Item Des		Jts	Ma	ke	Mod	lel	OD (in)	Wt (lb/ft)	Grade	Len (ft)	
Rod Strings		_					<u> </u>	l.	-		
Rod Description	Run	Date		String	eng	ith (ft)		Set Depth (ftKB)			
Item Des		Jts	Ma	ke	Mod	lel	OD (in)	Wt (lb/ft)	Grade	Len (ft)	

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 408667

CONDITIONS

Operator:	OGRID:
COBRA OIL & GAS CORPORATION	147404
P O BOX 8206	Action Number:
WICHITA FALLS, TX 76307	408667
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

С	reated By	Condition	Condition Date
	oren.diede	This plugback report had been missing, this late submission now completes the Plugback and P&A subsequent reports.	12/4/2024