

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

MAR 17 2015

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

SUBMIT IN TRIPLICATE - Other Instructions on page 2.		5. Lease Serial No.
1. Type of Well ☐ Oil Well ☐ Gas Well ☒ Other		6. If Indian, Allottee or Tribe Name
2. Name of Operator Hess Corporation		7. If Unit of CA/Agreement, Name and/or No.
3a. Address 1501 McKinney Street Houston, TX 77010		8. Well Name and No. NMNM-78449X
3b. Phone No. (include area code) 713-496-4000		9. API Well No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) see attached		10. Field and Pool or Exploratory Area
		11. Country or Parish, State Harding County, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other Transfer
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hess Corporation is transferring operatorship of the wells and associated permits, as identified on the attached spreadsheet, to its affiliate Hess CO2 Resources LLC, effective upon approval of the Secretary of the Interior and New Mexico Oil Conservation Division. A \$25,000 Statewide Surety Bond covering all operations on Federal leases in the State of New Mexico was accepted effective February 10, 2015, for Hess CO2 Resources LLC. The BLM Bond Number is NMB001236 and the Surety Bond Number is 015042501.

OIL CONS. DIV DIST. 3

APR 01 2015

* wells highlighted in yellow were updated.

14. I hereby certify that the foregoing is true and correct.
Name (Printed/Typed)

Title

Signature

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOC

Attachment to Form 3160-5

Hess Corporation

Well	Lease Type	ULSTR	API	Well	Pool Name
WEST BRAVO DOME UNIT #291	P	M-29-19N-30E	30-021-05047	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #081	P	M-8 -19N-30E	30-021-05071	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #111	S	N-11-19N-29E	30-021-20032	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #051	P	J-5 -18N-30E	30-021-20033	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #081	P	C-8 -18N-30E	30-021-20043	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #041	P	E-4 -18N-30E	30-021-20044	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #052	P	K-5 -18N-30E	30-021-20045	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #301	S	F-30-19N-30E	30-021-20059	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #061	S	G-6 -18N-30E	30-021-20118	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #071	S	F-7 -18N-30E	30-021-20119	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #201	S	F-20-18N-30E	30-021-20121	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #032	S	F-3 -19N-29E	30-021-20123	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #161	S	H-16-19N-29E	30-021-20124	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #251	S	K-25-19N-29E	30-021-20125	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #361	S	F-36-19N-29E	30-021-20126	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #311	S	K-31-19N-30E	30-021-20127	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #321	S	K-32-20N-29E	30-021-20128	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #331	S	G-33-20N-29E	30-021-20129	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #291	S	G-29-18N-30E	30-021-20140	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #211	PP	F-21-18N-29E	30-021-20142	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #291	PP	F-29-19N-29E	30-021-20143	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #331	F	G-33-19N-29E	30-021-20191	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #181	S	F-18-19N-29E	30-021-20229	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #321	S	F-32-19N-30E	30-021-20231	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #131	S	A-13-18N-29E	30-021-20233	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #031	F	O-3 -18N-29E	30-021-20412	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #111	F	F-11-18N-29E	30-021-20413	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #341	F	G-34-19N-29E	30-021-20414	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #171	P	G-17-18N-30E	30-021-20427	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #011	S	G-1 -18N-29E	30-021-20428	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #121	P	F-12-18N-29E	30-021-20429	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #221	P	G-22-18N-30E	30-021-20430	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #151	P	F-15-18N-30E	30-021-20434	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #051	P	G-5 -18N-29E	30-021-20435	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #321	P	G-32-19N-29E	30-021-20436	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #161	S	G-16-18N-29E	30-021-20437	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #211	P	G-21-18N-30E	30-021-20438	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #101	P	J-10-18N-29E	30-021-20439	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #082	P	J-8 -18N-30E	30-021-20441	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #091	P	F-9 -18N-30E	30-021-20443	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #091	P	G-9 -18N-29E	30-021-20444	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #101	P	K-10-18N-30E	30-021-20445	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #031	P	K-3 -18N-30E	30-021-20446	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #351	P	G-35-19N-29E	30-021-20447	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #041X	P	G-4 -18N-29E	30-021-20448	C	WEST BRAVO DOME CO2 GAS
MITCHELL #092F	P	F-9 -18N-30E	30-021-20494	S	SWD,YESO
WEST BRAVO DOME UNIT #191	P	J-19 19N-30E	30-021-20504	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #181	P	F-18-19N-30E	30-021-20505	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #221	S	J-22-19N-29E	30-021-20506	C	WEST BRAVO DOME CO2 GAS

NMMN
19714NMMN
19714
NMMN
63272
NMMN-
19714

Attachment to Form 3160-5

Hess Corporation

Well	Lease Type	ULSTR	API	Well	Pool Name
WEST BRAVO DOME UNIT #171	P	K-17-19N-29E	30-021-20507	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #181	P	B-18-18N-30E	30-021-20508	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #162	S	G-16-18N-30E	30-021-20509	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #231 <i>G</i>	P	G-23-18N-29E	30-021-20510	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #111L	P	L-11-18N-30E	30-021-20511	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #201	P	J-20-19N-29E	30-021-20512	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #191	P	G-19-18N-30E	30-021-20513	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #141	P	F-14-18N-29E	30-021-20514	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #281	P	F-28-19N-29E	30-021-20515	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #141J	P	J-14-19N-29E	30-021-20534	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #081	P	K-8 -19N-29E	30-021-20535	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #162	S	K-16-18N-29E	30-021-20537	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #042	P	O-4 -18N-29E	30-021-20538	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #221	P	F-22-18N-29E	30-021-20539	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #271	P	F-27-18N-30E	30-021-20540	S	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #292	P	J-29-19N-29E	30-021-20541	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #322	S	J-32-19N-30E	30-021-20542	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #312	S	G-31-19N-30E	30-021-20543	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #302	S	J-30-19N-30E	30-021-20544	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #231	P	J-23-19N-29E	30-021-20546	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #322	P	K-32-19N-29E	30-021-20547	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #152	P	K-15-18N-29E	30-021-20548	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #191	P	J-19-19N-29E	30-021-20549	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #261	P	B-26-18N-29E	30-021-20550	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #332	P	N-33-19N-29E	30-021-20551	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #012	P	N-1 -18N-29E	30-021-20552	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #142	P	N-14-18N-29E	30-021-20553	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #211	P	D-21-19N-29E	30-021-20554	C	WEST BRAVO DOME CO2 GAS
WEST BRAVO DOME UNIT #022	S	J-2 -18N-29E	30-021-20555	C	WEST BRAVO DOME CO2 GAS

FEE