1625 N. French Dr., Hobbs, NM 88240 Phone:(505) 393-6161 Fax:(505) 393-0720

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK [ PLUG AND ABANDON [

☐ CHANGE OF PLANS

☐ MULTIPLE COMPL

TEMPORARILY ABANDON

APPROVED BY: Ed Martin

PULL OR ALTER CASING

Other:

## State of New Mexico

Energy, Minerals and Natural Resources

**Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

Form	C-10
Permit I	1629

WELL API NUMBER

5. Indicate Type of Lease

SUBSEQUENT REPORT OF:

COMMENCE DRILLING OPNS. 
PLUG AND ABANDON

ALTER CASING

DATE 6/25/2010 1:52:20 PM

X

30-021-20413

F

JISHICLI V					
1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462	6. State Oil & Gas Lease No.				
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name WEST BRAVO DOME UNIT				
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFRENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number				
PROPOSALS.)	111 F				
I. Type of Well:C	<del> </del>				
2. Name of Operator	9. OGRID Number				
HESS CORPORATION	495				
3. Address of Operator	10. Pool name or Wildcat				
P.O. BOX 840, SEMINOLE, TX 79360	1				
1. Well Location					
Unit Letter F: 1720 feet from N line and 1950 feet from the	W line				
Section 11 Township 18N Range 29E NMPN	1 Harding County				
11. Elevation (Show whether DR, KB, BT, GR, etc.)	<del> </del>				
5328 GR					
Pit or Below-grade Tank Application or Closure					
Pit Type Depth to Groundwater Distance from nearest fresh water well Distance from r	earest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Materia	1				
12. Check Appropriate Box to Indicate Nature of Notice, Repor					

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

REMEDIAL WORK

CASING/CEMENT JOB

Other: Drilling/Cement

RU, safety meeting rig inspection, spud well, drill, circulate and condition, run surf csg, cement surf csg, test lines, wait on cement, drill plug and cement, circ and condition TOOH, run log,

Run production csg, circ and condition cement production csg, circ cement to surface. Wait on cement, Clean pit, ND BOP, RD 5/22/2010 Spudded well.

Casing and	Cement P	rogram													
Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1" Dpth	Pres Held	Pres O Drop F	Open Hole
05/24/10	Surf		12.25	8.625	24	J55	9	1875	600	1.74	PP2% CC				
05/24/10	Surf		12.25	8.625	24	J55	9	1875	200	1.35	tail prem				
05/24/10	Surf		12.25	8.625	24	J55	9	1875	200	1.35	2nd tail				
05/24/10	Surf		12.25	8.625	24	J55	0	1875	156	1.35	top out				
05/27/10	Prod		7.875	4.5	12.75	J55	0	3015	355	1.85	midcon2plu				
05/27/10	Prod		7.875	4.5	4.4	IJ	0	2796	135	2.94	midcon2plu				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . SIGNATURE Electronically Signed TITLE Engineering Tech DATE 6/22/2010  Type or print name Rita Smith E-mail address rsmith@hess.com Telephone No. 432-758-6726															
For State Use Only:															

TITLE District Supervisor