Submit 3 Copies To Appropriate District Office District I Energy, Minerals and Natural Resources	Form C-103 March 4, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II	30-045-22716 & 30-045-30937
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Hughes B
1. Type of Well:	8. Well Number
Oil Well Gas Well X Other	2A & 2B
2. Name of Operator	9. OGRID Number
BP America Production Company	000778
3. Address of Operator	10. Pool name or Wildcat
P O Box 3092 Houston, TX 77253 Attn: Mary Corley Rm 19.171	Blanco Mesaverde & Pictured Cliffs
4. Well Location	
Unit Letter O: 875 feet from the South line and	1610 feet from the Foot line
Omit Letter <u>O : 875</u> leet from the <u>South</u> line and	ieet nom the <u>East</u> me
Section 19 Township 29N Range 08W	NMPM San Juan County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
6480'GL	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL_Sect_Twp_Rng_Pit typeDepth to GroundwaterDistant	ce from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp	Rng;
feet from theline andfeet from theline	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUE	SSEQUENT REPORT OF:
	SSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	SSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORD TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling X OTHER:	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A COMPLETION CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A COMPLETION CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DREMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DREMEDIAL WORK PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle productions from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesaverence.	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle productions from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will be from the Homes B No. 2A; and Blanco Mesaverde production will	BSEQUENT REPORT OF: RK ALTERING CASING ALTERI
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the Howell will be metered prior to commingling (please note: production from well no. 2A	ALTERING CASING ABANDONMENT Ad give pertinent dates, including estimated date ttach wellbore diagram of proposed completion on the Blanco Mesaverde and Pictured Cliffs arde & Pictured Cliffs production will lughes B No. 2B. The production from each currently is being commingled downhole
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the H well will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming	SSEQUENT REPORT OF: RK ALTERING CASING ALTERING CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the H well will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the	SSEQUENT REPORT OF: RK ALTERING CASING ALTERING CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the H well will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming	SSEQUENT REPORT OF: RK ALTERING CASING ALTERING CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle productive Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the Hewell will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the sales meter. (Continued on reverse side of form)	SSEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the H well will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A COMPLETION CEMENT JOB OTHER: Surface Commingling Total Completions: A of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the H well will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the sales meter. (Continued on reverse side of form) I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit Thereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit The completion of the plants	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the H well will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the sales meter. (Continued on reverse side of form) I hereby certify that the information above is true and complete to the best of my knowledge.	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A COMPLETION CEMENT JOB OTHER: Surface Commingling Total Completions: A of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle production Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the H well will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the sales meter. (Continued on reverse side of form) I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit Thereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit The completion of the plants	SEQUENT REPORT OF: RK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle productive Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the Hewell will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the sales meter. (Continued on reverse side of form) I hereby certify that the information above is true and complete to the best of my knowledgerade tank has been/will be constructed for closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Regulatory	Analyst ALTERING CASING ALTER
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle productive Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the Hewell will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the sales meter. (Continued on reverse side of form) I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Regulatory Type or print name Mary Corley E-mail address: corleyml@bp.com	Analyst ALTERING CASING ALTER
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB OTHER: Surface Commingling OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. BP America Production Company request permission to surface commingle productive Pools from our Hughes B Wells No. 2A & 2B. Surface commingling Blanco Mesave consist of the Hughes B No. 2A; and Blanco Mesaverde production will be from the Hewell will be metered prior to commingling (please note: production from well no. 2A with production allocated to each Pool based on a fixed percentage) then the comming separator where the liquids will be removed. The commingled gas will then be sent the sales meter. (Continued on reverse side of form) I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit SIGNATURE TITLE Sr. Regulatory Type or print name Mary Corley E-mail address: corleyml@bp.com	SEQUENT REPORT OF: RK

Please reference the attached schematics reflecting the Current Facilities Layout and the Proposed Surface Commingling Layout provided for your reference.

The working interest, royalty and overriding royalty interest owners in the subject wells are identical.

The proposed commingling of production is to reduce operating expenses between the wells and will result in increased economic life of the wells.

BLM has also been notified of this proposal by copy of BLM Form 3160-5.