

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy  
Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Revised April 14, 2022  
Email to [ocdadmincomp@state.nm.us](mailto:ocdadmincomp@state.nm.us)

|               |                                 |
|---------------|---------------------------------|
| Company:      | Riley Permian Operating Co, LLC |
| OGRID:        | 372290                          |
| ACOI #:       | 201968                          |
| MO/YR report: | 06/2024                         |

## ACOI Well Report

Do not report on all wells. Only report the wells that have had full action taken on them in this reporting month.

| API#         | Well Name               | Action taken (Plugged or RTP?)                              | Action ID # of action taken   |
|--------------|-------------------------|-------------------------------------------------------------|-------------------------------|
| 30-015-40494 | Waldrop 13 O 2          | RTP                                                         |                               |
| 30-015-30127 | Kaiser B 1              | RTP                                                         |                               |
| 30-015-35829 | Condor 8 Fed 1H         | RTP                                                         |                               |
| 30-015-44495 | Terry 14 G 7            | RTP                                                         |                               |
| 30-015-40805 | Vandagriff 8 D Fed 4    | RTP                                                         |                               |
| 30-015-42550 | Windfohr 4 J Fed 9      | RTP                                                         |                               |
| 30-015-35271 | Sterling 7 F 6          | RTP                                                         |                               |
| 30-015-41119 | Logan 2 C State 5       | RTP                                                         |                               |
| 30-015-43951 | Hawk 8 K Fed 51         | RTP                                                         |                               |
| 30-015-30132 | Kaiser B 6              | Plugged (P&A by Redwood/last operator)                      |                               |
| 30-015-30749 | Logan 35 Fed 11         | Plugged (P&A by Redwood/last operator)                      |                               |
| 30-015-33427 | Eagle 35 A Fed 19       | Plugged (P&A by Redwood/last operator)                      |                               |
| 30-015-40488 | Everest 14 N 8          | Plugged                                                     |                               |
| 30-015-40796 | Kaiser 18 A 15          | Plugged                                                     |                               |
| 30-015-36970 | Condor 7 Federal Com 3H | Plugged (P&A by Redwood/last operator)                      |                               |
| 30-015-39459 | Eagle 33 O Federal 19   | Plugged (P&A by Redwood/last operator)                      |                               |
| 30-015-35238 | Kaiser B18 B11          | RTP                                                         |                               |
| 30-015-29726 | Hawk 17 C Fed 2         | RTP                                                         |                               |
| 30-015-39541 | Kaiser B 18 G 12        | RTP                                                         |                               |
| 30-015-34176 | Kaiser B 18 F 7         | RTP                                                         |                               |
| 30-015-43180 | Eagle 35 A Fed 30       | RTP                                                         |                               |
| 30-015-43278 | Hawk 9 B Fed 18         | RTP                                                         |                               |
| 30-015-39807 | Hawk 8 L Fed 15         | RTP                                                         |                               |
| 30-015-41069 | Stirling 6 M 4          | RTP                                                         |                               |
| 30-015-43216 | Hawk 9 G Fed 19         | RTP                                                         |                               |
| 30-015-43765 | Hawk 9 A Fed 22         | RTP                                                         |                               |
| 30-015-34964 | Hawk 9 N Fed 21         | RTP                                                         |                               |
| 30-015-42052 | Windfohr 4 Fed 10       | RTP                                                         |                               |
| 30-015-41721 | Matthews 25 Fed 2       | RTP                                                         |                               |
| 30-015-34838 | Stirling 7 C 4          | Plugged (C103 has been submitted)                           |                               |
| 30-015-41751 | Eagle 35 F Fed 24       | RTP 3/29/24                                                 |                               |
| 30-015-41015 | Everest 14 O 7          | RTP 3/27/24                                                 |                               |
| 30-015-02272 | State H 2               | RTP 5/8/24                                                  |                               |
| 30-015-41255 | Falcon 3 C Fed 31       | RTP 5/9/24                                                  |                               |
| 30-015-29483 | Hawk 9 J Fed 16         | RTP 4/15/24                                                 |                               |
| 30-015-21707 | Higgins Trust Inc Com 1 | Repaired 5/2/24, but waiting on DCP line leak repair to RTP | Still waiting as of 6/12/2024 |
| 30-015-30442 | Mann 3 Fed 3            | Duplicate on original ACOI list (listed twice)              |                               |
| 30-015-34103 | Eagle 33 P Fed 16       | RTP 4/17/24                                                 |                               |
| 30-015-30475 | Logan 35 Fed 5          | RTP 4/14/24                                                 |                               |
| 30-015-40808 | Logan 35 P Fed 19       | RTP 4/16/24                                                 |                               |
| 30-015-41697 | Eagle 35 H Fed 25       | RTP 5/31/24                                                 |                               |
| 30-015-30735 | Logan 35 Fed 13         | RTP 5/29/24                                                 |                               |
| 30-015-34008 | Eagle 33 H Fed 23       | RTP 6/4/24                                                  |                               |
| 30-015-41640 | Simon A 5 M Fed 2       | Repaired 6/5/24, but waiting for electrical hookup to RTP   |                               |
| 30-015-41435 | Logan 35 O Fed 10       | RTP 6/7/24                                                  |                               |
| 30-015-29110 | Eagle 34 H Fed 15       | RTP 6/7/24                                                  |                               |
| 30-015-33355 | Falcon 3 C Fed 24       | Repaired 6/12/24, but not TIL yet                           |                               |
| 30-015-41446 | Eagle 34 J Fed 63       | RTP 6/11/24                                                 |                               |
|              |                         |                                                             |                               |

Signature: Spence Laird Date: 6/12/2024  
Printed Name: Spence Laird Title: EHS&R Manager