

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Thursday, October 27, 2011 2:16 PM
To: 'Michael Stubblefield'
Cc: gnewton@pvtnetworks.net
Subject: RE: REVISED CONOCO 7 STATE NO 12

Mike,

Your request to install liner and backfill at this site is approved. It is OCD's understanding that the site was excavated up to the closed (legacy/historic) drilling pit.

Mike Bratcher

NMOCD District 2
811 S. First Street
Artesia, NM 88210
575-748-1283 Ext. 108
575-626-0857
mike.bratcher@state.nm.us

From: Michael Stubblefield [<mailto:mstubblefield@talonlpe.com>]
Sent: Thursday, October 27, 2011 10:14 AM
To: Bratcher, Mike, EMNRD
Cc: gnewton@pvtnetworks.net
Subject: FW: REVISED CONOCO 7 STATE NO 12

Dear Mr. Mike Bratcher,

Talon/LPE is sending you the analytical results for the soil samples collected on 9/20/2011 from the excavated area located at the Conoco 7 State No. 12. Based on the analytical results Quantum Resources Management, LLC is requesting permission to place the 20 Mil. liner into the bottom of the excavated area and to start backfilling with new soil transported to the location.

Sincerely,

Mike Stubblefield
Talon/LPE Project Manager

From: Celey Keene [<mailto:celey.keene@cardinallabsnm.com>]
Sent: Thursday, October 13, 2011 11:50 AM
To: Michael Stubblefield
Cc: David Adkins
Subject: REVISED CONOCO 7 STATE NO 12

This is the revised report for the above referenced project. This report will replace the previously sent on one 09/26/11

Thank you,

Celey Keene

Lab Director
Cardinal Laboratories
101 East Marland
Hobbs, NM 88240
T: (575) 393-2326
F: (575) 393-2476
e-mail: celey.keene@cardinallabsnm.com

The information contained in this message is confidential and is only intended for the use of the individual/firm named above. If the reader of this message is not the intended recipient or the employee/agent responsible to deliver it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by e-mail or telephone in order to return the message.