Distric <u>t I</u>				54	ata af		ina		ECEIV			
District I 1625 N. French Dr., Hobbs, NM 88240 District II				State of New Mexico Energy Minerals and Natural Resource				S JUL 03 2012 Form C-141 Revised October 10,2003				
1301 W. Grand District III									NMOCD ARTESIA optes to appropriate			
1000 Rio Brazos District IV				1220 South St. Francis Dr.			is Dr.			District Off	Rule 116 on back	
1220 S. St. Francis DL, Santa Fe, NM 87505					Santa Fe, NM 87505				Oncean of the second		side of form	
Release Notification and Corrective Action												
Name of Co	N12	<u>\9 441(</u>		GUC 779	127	OPERA Contact	FOR	Pat E		al Report	_ Final Report	
Address 550 W. Texas, Suite 100, Midland, TX 79701						Telephone No. 432-230-0077						
Facility Name Jenkins Water Flood						Facility Type Tank Battery					·	
Surface Owner Federal Mineral Owner Lease No. (API#) 30-015-2097 Closest well location Closest well location Closest well location Closest well location												
				LOCA	ATIO	N OF REI	LEASE	Y	Mc Enture	DK Fed #	6	
Unit Letter N	Section 17	Township 17S	Range 30E	Feet from the	North	South Line	Feet from the	e E	ast/West Line	County Edd	ly	
Latitude 32 49.817 Longitude 103 59.765												
				NAT	URE	OF REL						
Type of Release Oil Source of Release Gun barrel						Volume of Release 75bbls Volume Recovered 70bbls Date and Hour of Occurrence Date and Hour of Discovery 06/26/2012 06/26/2012 9:30 a.m.						
Was Immediate Notice Given?							If YES, To Whom? Mike Bratcher-OCD					
							Date and Hour 06/27/2012 9:27 a.m.					
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.					
If a Watercou	irse was Im	pacted, Descr	ibe Fully.'	- 		<u> </u>	ţ					
Describe Cause of Problem and Remedial Action Taken.*												
The gun barrel at the Jenkins Water Flood & Tank Battery overflowed due to motor valves that did not open. Electricians have been called out to ensure that the problem with the motor valves has been resolved.												
Describe Are	a Affected	and Cleanup A	Action Tal	(en.*								
Initially 75bbls of oil were released from the gun barrel at the facility and we were able to recover 70bbls with a vacuum truck. The entire release was contained inside the diked walls of the facility. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.												
regulations al public health should their o or the environ	II operators or the envir operations h ament. In a	are required to ronment. The nave failed to a	o report ar acceptanc idequately ICD accept	t is true and comp nd/or file certain r the of a C-141 report v investigate and r otance of a C-141	release n ort by the remediat	otifications and e NMOCD m e contamination	nd perform con arked as "Fina ion that pose a ve the operator	Tective I Repo threat of resp	e actions for re- ort" does not rel to ground wate ponsibility for c	leases which ma lieve the operato r, surface water compliance with	ay endanger or of liability r, human health a any other	
Signature:	/.	2 1/	25				<u>OIL CO</u>	NSE	RVATION	DIVISION	<u> </u> ./	
Printed Name	. /	Josh	Russo			Approved by	District Super	visor:	Signed By	M1/4 K	Semance-	
Title:			ordinator			.l Approval Da		012	Expiration	Date:		
E-mail Addro	255:	jrusso@conc	horesourc	es.com		Conditions of	f Approval:			Attached [
Date: 0 Attach Addi	6/26/2012	Phone ets. If Necess		-212-2399						<u> </u>		
			<i>y</i>		Guid	elines. SUI	on per OCD BMIT REME T LATER TH	DIAT	ION	9 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	2-1217	
						-						

Bratcher, Mike, EMNRD


From:	Joshua Russo [jrusso@concho.com]
Sent:	Tuesday, July 03, 2012 1:21 PM
То:	Bratcher, Mike, EMNRD; Jim Amos office (jamos@blm.gov); Gregston, Terry G
Cc:	Tavarez, Ike; Dorey, Kim; Franklin, Tom K.
Subject:	C-141 Initial Report - Jenkins Water Flood
Attachments:	JENKINS FEDERAL WATER FLOOD & TANK BATTERY DATE OF RELEASE 06-26-2012.pdf

Please see attached a C-141 Initial Report for a release that occurred at our Jenkins Water Flood and Tank Battery.

Thank you,

Joshua Russo

HSE Coordinator 550 W. Texas Ave, Suite 100 Midland, Texas 79701 Phone: (432) 683-7443 Cell: (432) 212-2399 jrusso@conchoresources.com



Bratcher, Mike, EMNRD

From:	Michelle Mullins [MMullins@concho.com]
Sent:	Tuesday, June 26, 2012 9:02 AM
То:	Bratcher, Mike, EMNRD; Amos, James A; Gregston, Terry G
Cc: .	Joshua Russo
Subject:	Northwest Central overflow tank-Immediate Notification

Mr. Bratcher, Mr. Amos, Ms. Gregston:

On 06/25/2012 at approximately 10:15 am, a 10,000 bbl overflow tank was found to be running over. An estimated 100 bbls of produced water and an estimated 700 bbls of oil was released. The tank is inside an unlined dike. Water has been diverted from the overflow tank and rerouted. We will get more details and follow up with a C-141 Report.

GPS coordinates, legal description, and driving directions below.

N32* 49.817 W103* 59.765

McIntyre DK Fed #6 (closest well location) 990' FSL & 2310' FWL Sec. 17 T175 R30E Eddy County, NM-86025 API 30-015-20972

From Loco Hills drive west on Highway 82 to CR 217 Turn north, go .7 miles, turn west and travel .6 miles. Battery is on the left.

Thank you.

Michelle Mullins HSE Field Tech 2407 Pecos Avenue P.O. Box 1630 Artesia, NM 88211-1630 Phone: (575)746-2010 Cell: (432) 934-1052 mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.