<u>District I</u> 1625 N French Dr , Hobbs, NM 88240 District II
1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr. Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUL 2-6 2012

RECEIVED

Form C-141 evised October 10, 2003

NMOGD ARY Survivale District Office in 19.15.29 NMAC

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

			Rele	ease Notifica	ioiti	n and Co	rrective A	ction				
nJAW 1221463896						OPERATOR						
Name of Company: Linn Operating 261324						Contact: Joe Hernandez						
		der Hobbs		Telephone No.: 575-738-1739								
Facility Nar				Facility Type: Oil								
Surface Ow	ner: Feder	al	: Federal API No.: 3001529573									
				LOCAT	ΓΙΟΙ	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North/South Line F		Feet from the	East/W	est Line	County		
N	30	17S	31E	1120		South	2230	l w	est		′	
	<u> </u>		Latitu	ude: 32.80137246	50168	6 Longitud	e: -103.909588	456907				
				NATU	JRE	OF RELI	EASE					
Type of Rele	ase: Produc	ed Water	Volume of Release: 8 Volume Recovered: 4									
Source of Re	lease Poly	pipeline	Date and Hour of Occurrence: Date and Hour of Discovery: 07/13/2012 4pm 07/13/2012 4:30pm									
Was Immedia	ate Notice C	iiven?	If YES, To			0,,,15,20	12. 1.50					
		\boxtimes	Yes	No 🗌 Not Req								
By Whom? J	oe Hernand	ez	Date and Hour 07/16/2012 4:50pm									
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
If a Watercou	irse was Imi	pacted Descri	be Fully *	*·								
Describe Cau	ise of Proble	em and Reme	dial Action	n Taken,*: Poly line	deve	loped pin hole						
				•							•	
				ken.* : About 50 ya	rds we	est from Turno	er B 56 Injection v	well and	covered a	n area 30x2:	5 Bas	ic trk picked
up fluid. Fu	rther remed	ial action pend	ııng									
_												
				is true and comple								
				nd/or file certain rel								
				ce of a C-141 report								
				vinvestigate and renotance of a C-141 re								
		vs and/or regu		runce or a C 11111e	port a	ioes not renev	e the operator or	сэроны	iiity ioi c	omphanee v	with this	other
			11.13				OIL CON	SERV	ATION	DIVISIO)N	
	1.	OIL CONSERVATION DIVISION										
Signature.	met flet in the s	Silver Colored	<i>p^</i>								1,	
. D. C. 4 . 1 . 1 . 1	/ - I !!	en d			Approved by District Supervisor:							
Printed Name	e: Joe Herna	ındez		<u> </u>	ALIC D 1 2012 Signed By M1/4 Demonstrate							
Title: Produc	tion Forems	nn	Approval Dat	AUG 01	2012	xpiration	Date:					
THE TOUCK	HOLL I OLCHIC					Approvai Da			дриацоп	Date.	-	
E-mail Addre	ess: ihernan	dez@linnener	gy.com			Conditions of	Approval:			Attached	i 🖂	
Date. 07/26/2				-942-9492			t t				٠ ـــ	
Attach Addi						Domodist	ion per OCD F	Rules &		18	P-	1241
,			,			Remediat	ion her oco i	raics or		~1	U -	[[نسب

Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

Bratcher, Mike, EMNRD

From: Theresa McCracken < TMcCracken@linnenergy.com>

Sent: Thursday, July 26, 2012 8:04 AM

To: Bratcher, Mike, EMNRD; Terry Gregston (tgregsto@blm.gov)

Cc: Daniel Frick; Nancy Fitzwater; Terry Callahan; Ron Ragland; Gary Wink; Joe Hernandez

Subject: Linn- Turner B #113 Initial C-141
Attachments: Turner B # 113 7-13-12.pdf

Please find attached Initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

2130 W Bender Hobbs NM 88240 1 575-738-1739 / F: 575-738-1740 tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.