

2RP-1246

Bratcher, Mike, EMNRD

From: Michelle Mullins [MMullins@concho.com]
Sent: Thursday, July 19, 2012 1:55 PM
To: Bratcher, Mike, EMNRD; Amos, James A; Gregston, Terry G
Cc: Joshua Russo; Pat Ellis
Subject: Dry Land Shiner Federal #1-Immediate Notification

Mr. Bratcher, Mr. Amos, Ms. Gregston:

On 7-18-12 at approximately 2:30 pm, a produced water release was discovered at the above-referenced battery. The dump on the free water knockout failed, sending fluid to the oil tanks. An estimated 500bbls of produced water was released with approximately 480 bbls being recovered. This facility is not lined. The free water knockout has been removed from service while the dump is being replaced. We will get more details and follow up with a C-141 Report.

GPS coordinates, legal description, and driving directions below.

N 32.51975 W 104.37667

Dry Land Shiner Federal #1
Section 3
T21 S, R 25E
430' FNL, 2435' FEL
Eddy Co. NM
API 30-015-32815

From Artesia, head south on 285. Turn left onto Capitan Reef Road. Turn right at first caliche road. Follow road into location on the left.

Michelle Mullins
HSE Field Tech
2407 Pecos Avenue
P.O. Box 1630
Artesia, NM 88211-1630
Phone: (575)746-2010
Cell: (432) 934-1052
mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Amos, James A [jamos@blm.gov]
Sent: Thursday, July 19, 2012 3:12 PM
To: Michelle Mullins; Bratcher, Mike, EMNRD; Gregston, Terry G
Cc: Joshua Russo; Pat Ellis
Subject: RE: Dry Land Shiner Federal #1-Immediate Notification

In case Terry has not responded, we did get your report. thanks

From: Michelle Mullins [<mailto:MMullins@concho.com>]
Sent: Thursday, July 19, 2012 1:55 PM
To: mike.bratcher@state.nm.us; Amos, James A; Gregston, Terry G
Cc: Joshua Russo; Pat Ellis
Subject: Dry Land Shiner Federal #1-Immediate Notification

Mr. Bratcher, Mr. Amos, Ms. Gregston:

On 7-18-12 at approximately 2:30 pm, a produced water release was discovered at the above-referenced battery. The dump on the free water knockout failed, sending fluid to the oil tanks. An estimated 500bbls of produced water was released with approximately 480 bbls being recovered. This facility is not lined. The free water knockout has been removed from service while the dump is being replaced. We will get more details and follow up with a C-141 Report.

GPS coordinates, legal description, and driving directions below.

N 32.51975 W 104.37667

Dry Land Shiner-Federal #1
Section 3
T21 S, R 25E
430' FNL, 2435' FEL
Eddy Co. NM
API 30-015-32815

From Artesia, head south on 285. Turn left onto Capitan Reef Road. Turn right at first caliche road. Follow road into location on the left.

Michelle Mullins
HSE Field Tech
2407 Pecos Avenue
P.O. Box 1630
Artesia, NM 88211-1630
Phone: (575)746-2010
Cell: (432) 934-1052
mmullins@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you

have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.