District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

Form C-141

SEP 12 2012 Revised October 10, 2003

Submit 2 Copies to appropriate

NMOCD ARTESTA, Office in accordance

NMOCD ARTESTA, the Rule 116 on back side of form

Release Notification and Corrective Action

nJMW1225	440827				OPERA	ГOR			X Revise	d Report	Final Rep	
Name of Co						Contact: 5	teve Collins	s, V.P.	- Operatio i	18-		
Address: 110 Cypress Station Drive, Suite 220 – Houston, TX 77090-1629						Telephone No.: 281.537-9920						
Facility Nan	ne: <i>Near</i>	est Well - Be	eson "F	" Federal,	Well 29	Facility Ty	pe: <i>Active O</i>	il Proa	lucing Leas	se		
Surface Owner: Bureau of Land Management Mineral Ov Revenue						ner Office of Natural Resources Jo-0/5-3//64 Well location: A-3)-17s-30e						
				LO	CATION	N OF REI	en LEASE 32	l location 1993	in! A-3)- 19N 104	175-30E		
Unit Letter	Section	Township	Range	Feet from the	he North/	South Line	Feet from the	Eas	t/West Line	County:	EDDY	
Latitude: <u>32.80151 N</u> Longitude: <u>-103.96690 W</u>												
NATURE OF RELEASE												
Type of Release: PRODUCED WATER						Volume of Release: 488 bbl Volume Recovered. ZERO bbl						
Source of Release: Buried hi-pressure fiberglass pipeline						Date and Hour of Occurrence: 08/22/2012 – Unknown hour			08/22/	Date and Hour of Discovery: 08/22/2012 – 1000 hrs		
Was Immediate Notice Given? X Yes No Not Required						If YES, To Whom? E-mail transmission – NMOCD, Artesia office						
By Whom? <i>Mark Weatherly, Consultant for Southern Bay</i> Was a Watercourse Reached?						Date and Hour 08/23/20112 – 1020 hrs CDT If YES, Volume Impacting the Watercourse.						
If a Watercou			Yes X !			I II YES, Vo	lume Impacting	g the W	atercourse.			
ii a watereou	isc was iiii	pacieu, Descri	be runy.									
Describe Caus	sa of Proble	am and Damac	lial Action	Tokon *								
Describe Cau.	sc of Froom	om and Remee	nai Actioi	i rakcii,								
Produced V	Vater Inje	ection Syste	m with b	ouried hi-pr	essure 3-i	nch nomin	al fiberglass	pipelin	e At abov	ve coordinat	es, line had a	
							nd produced					
							e crew with t		oe was bro	ought to site	and	
					of leak L	ine was re	paired and te	ested				
Describe Area	Affected :	and Cleanup A	ction Tak	ten.*								
		stimated to l disposal fac		200 sq/ft C	Contamina	ted soil are	ea to be delin	neated	by samplir	ng/lab analy:	sis, excavatec	
regulations al public health should their o or the environ	l operators or the envir perations h ment. In a	are required to ronment. The ave failed to a	report an acceptanc dequately CD accep	nd/or file certa ce of a C-141 investigate a	in release no report by the nd remediate	otifications and NMOCD me contaminati	knowledge and nd perform corr arked as "Final on that pose a t e the operator o	ective a Report' hreat to	ctions for rel does not rel ground wate	eases which m ieve the operat r, surface wate	ay endanger or of liability r, human health	
Signature:						OIL CONSERVATION DIVISION						
		nukhus	thenh	•							_	
			1	-			D1 - 1 - 0	J. 1	9. j			
Printed Name MARK WEATHERLY						REVISE	District Suberv	1901/	4 BRAG	ede se	•	
Title: Environmental / Regulatory Coordinator						Approval Date: Expiration Date:						
E-mail Address: Mark@SBEnergy.com						Conditions of		<u>د 8</u>	*	Attached		
Date: 09/12/	2012	Pho	ne: 281	537-9920, X	(-120	ا ممند	Approval: Der OCD Rule HIT REMEDIA LATER THAN	TION		- macrica		
Attach Addit					Ret	nediation	IIT REMEDIA			01		
	2		J		cuidel	ines. Subi	LATER THAN	· ·	α	KP-1,	176	
					DROP	OSALNO	INT REMIED. WATER THAN 12012				•	