

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Monday, October 25, 2010 1:12 PM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis
Subject: Schley Fed. Battery Spill Immediate Notification

Mr. Bratcher,

30-015-30031
2RP-471

Please see below the details to a release that occurred over the weekend. We will follow up with a C-141 Initial Report.

Thank you,

Joshua Russo
HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
[Jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rick Wright
To: Joshua Russo
Sent: Mon Oct 25 14:04:05 2010
Subject: FW: Schled Fed. Battery Spill

Thanks,

Rick Wright
Production Foreman
COG Operating, LLC
2407 Pecos Ave.
Artesia, NM 88210
575.746.2010 office
432.528.5363 cell
575.746.2096 fax
rwright@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited.

If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rick Wright
Sent: Monday, October 25, 2010 9:19 AM
To: Pat Ellis; Josh Shannon
Cc: Ron Beasley; Kent Greenway; Gail Lamb
Subject: Schled Fed. Battery Spill

On 8-23-10 at 8:00am the produced water tank ran-over at the Schley Fed. Battery. This was caused by an electrical problem with the water transfer pump. 40bbls of produced water was released and 35bbls were recovered and disposed. This battery has a dike, but the water ran under the dike into the old pit area. The contaminated area is 15' X 300'. The electrical problem was fixed and the pump returned to service. We will await instructions from HSE before performing any cleanup of the area. GPS, legal description, and driving directions below.

Schley Fed. Tank Battery
Sec29-T17S-R29E
Eddy Co., NM29281

N 32* 48.162'
W 104* 05.895'

East of Artesia on Hwy 82 to CR 210, T/S .5 mi, T/W .25 mi, .15 mi to Schley Fed. Battery.

Thanks,

Rick Wright
Production Foreman
COG Operating, LLC
2407 Pecos Ave.
Artesia, NM 88210
575.746.2010 office
432.528.5363 cell
575.746.2096 fax
rwright@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.