


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

nJMW 1312328817

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Cypress 28 Federal #3H	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-38287

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	28	23S	29E	435	North	60	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Oil	Volume of Release	140 bbls	Volume Recovered	130 bbls
Source of Release	Power failure on a transfer pump caused tank to overflow	Date and Hour of Occurrence	04/11/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen, James Amos -BLM		
By Whom?	Chancey Summers	Date and Hour	04/12/2013 @ 8:18 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Power failure on a transfer pump caused a tank to overflow and leak 140 bbls of oil on the ground. 130 bbls of oil were recovered via vacuum truck and power was restored to the pump.

Describe Area Affected and Cleanup Action Taken.\*

Power failure on a transfer pump caused a tank to overflow and leak 140 bbls of oil on the ground. 130 bbls of oil were recovered via vacuum truck and power was restored to the pump. Remediation will be performed in accordance with a plan approved by NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Chancey Summers	Approved by District Supervisor:	Signed By: <i>Mike Bratcher</i>
Title: HES Specialist	Approval Date: MAY 03 2013	Expiration Date:
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-29-12 Phone: (575) 397-8216	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: June 3, 2013	

\* Attach Additional Sheets If Necessary

2RP-1639

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Monday, April 29, 2013 9:36 AM  
**To:** Bratcher, Mike, EMNRD; jvancure@blm.gov; jamos@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141 Cypress 28 Federal #3H  
**Attachments:** Initial C-141, signed 4-29-13.pdf

Attached is the initial C-141 for a leak located at the Cypress 28 Federal #3H that occurred on 04/11/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. Please contact me if you have any questions.

*Kathy Purvis*

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

**Bratcher, Mike, EMNRD**

---

**From:** Van Curen, Jennifer <jvancure@blm.gov>  
**Sent:** Monday, April 29, 2013 9:50 AM  
**To:** Kathy Purvis  
**Cc:** Bratcher, Mike, EMNRD; Jim Amos; C J Summers; Brunson; kswinney@bbcinternational.com; Jennifer Gilkey  
**Subject:** Re: Initial C-141 Cypress 28 Federal #3H

Received

JENNIFER E VAN CUREN  
ENVIRONMENTAL PROTECTION SPECIALIST  
DOI-BLM-CARLSBAD FIELD OFFICE  
320 E GREENE ST. CARLSBAD, NM 88220  
OFFICE- 575-234-5905  
CELL - 575-361-0042  
FAX - 575-234-5927

On Mon, Apr 29, 2013 at 9:35 AM, Kathy Purvis <[kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)> wrote:

Attached is the initial C-141 for a leak located at the Cypress 28 Federal #3H that occurred on 04/11/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. Please contact me if you have any questions.

*Kathy Purvis*

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

## Bratcher, Mike, EMNRD

---

**From:** Chancey\_Summers@oxy.com  
**Sent:** Friday, April 12, 2013 8:18 AM  
**To:** jamos@blm.gov; jvancure@blm.gov; Bratcher, Mike, EMNRD;  
cbrunson@bbcinternational.com; jgilkey@bbcinternational.com;  
kathy@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** FW: SPILL CDR CREATED (OP55556398) DELAWARE CYPRESS 28 3 SINGLE WELL  
BATTERY

All this is to inform you Oxy Permian Primary South had a leak at the Cypress 28 3 on April 11, 2013. Oxy released 140 bbls of oil, and recovered 130 bbls. The leak was due to power failure on transfer pump causing tank to overfill. The leak is located in Sect 28, T23S, R29E, of Eddy county. Oxy will do some initial remediation, BBC will delineate at a later date. C-141 to follow. If you have any questions let me know. Driving directions: Off CR 128 turn south at mile marker 4, go down Rawhide rd 3 miles, turn west go 4 miles location is on the right.

Thank You

C.J. Summers

HES Advisor

Cell # 575-631-9436

Office # 575-397-8216

[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)

"When the blind lead the blind, get out of the way!"