District I 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED

Form C-141 Revised October 10, 2003 JUL 29 2013

Submit 2 Copies to appropriate

NMOCD ARTESIA th Rule 116 on back
side of form

Release Notification and Corrective Action												
n/Mh	11321	11308	65			OPERATOR						
Name of Company Chevron Delaware Basin 4323						Contact Bradley Blevins						
Address PO Box 190, Hobbs, NM 88241						Telephone No. (575) 391-1462						
Facility Na	ne Bens	on Shugart '	WFU #2	СТВ		Facility Type Battery						
Surface Owner BLM Mineral Owner						API # 30-015-20572						
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North/	/South Line Feet from the East/W			st Line County			
G	26	18S	30E_	1650	1	North	1800	East	East Eddy County, NM		M	
Latitude Longitude												
NATURE OF RELEASE												
Type of Rele	ase Produ	iced Water	···	11288	UILL				me Recovere	tecovered 51 bbls		
Source of Release Tank overflow						Date and Hour of Occurrence D			ate and Hour of Discovery			
Was Immediate Notice Given?						07/29/2013 @ 10:00 am						
Was Immedi	ate Notice C		Ves [No. T Not Re	ouired	If YES, To Whom?						
Yes No Not Required Mike Bratcher- NMOCD; James Amos- BLM												
By Whom? Bradley Blevins Was a Watercourse Reached?						Date and Hour 07/29/2013 @ 3:22 pm If YES, Volume Impacting the Watercourse.						
was a water	course Reac		Yes 🛭	No		If YES, Vo	lume Impacting to	ne Watercours	se.			
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.* Failure to get a load from the tank caused an overflow and 59 bbls of produced water leaked onto the ground. 51 bbls of produced water were recovered via vacuum truck.												
Describe Area Affected and Cleanup Action Taken.* Failure to get a load from the tank caused an overflow and 59 bbls of produced water leaked onto the ground. 51 bbls of produced water were recovered via vacuum truck. Further remediation will be performed in accordance with a NMOCD and BLM approved remediation plan.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: Tradler Jenny						OIL CONSERVATION DIVISION						
						11						
Printed Name: Bradley Blevins						Approved by District Supervisor Signed By Mile Beauce						
						JUL 3 0 2013						
Title: HES	pecialist					Approval Date	e:	Expira	tion Date:			
E-mail Addre	ss: Bradle	ey.blevins@c	hk.com)		Conditions of Approval;			Attached			
Date: Ho	19/13			391-1462			1					
Attach Addit	ional Shee	ts If Necess	arv						A 7	Ω	100	

Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION 2KP-171/L

PROPOSAL NO LATER THAN:

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Monday, July 29, 2013 4:24 PM

To:

Bratcher, Mike, EMNRD; jamos@blm.gov

Cc:

'Bradley Blevins'; cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com

Subject:

Initial C-141, BS WFU #2 CTB

Attachments:

Initial C-141, BS WFU #2 CTB.pdf

Attached is the initial C-141 for a leak occurring at the Benson Shugart WFU #2 CTB on 07/29/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. If you have any questions, please contact me.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388

Phone: (575) 397-6388 Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Blevins, Bradley G < Bradley.Blevins@chevron.com>

Sent: Monday, July 29, 2013 3:23 PM

To: Bratcher, Mike, EMNRD; 'Amos, James' **Cc:** Blevins, Bradley G; 'Cliff P. Brunson'

Subject: BSWFU 2 CTB- Release

Mike/Jim

Chevron had a release on the BSWFU 2 Battery today at 10:00am. 58.5 barrels of fluid was released. Water hauled failed to get a load from the tank causing the tank to run over. 51 barrels was recovered by vac truck. If you need further info please let me know. We will follow up with a Initial C-141.

Thanks,



Bradley Blevins Chevron Delaware Basin HE Specialist Hobbs FMT Direct 575-391-1462 86424 Cell- 575-441-0341