


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised January 1, 2008
Submit 1 Copy to appropriate
Office

Release Notification and Corrective Action

njmw 1326741225 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company: DCP Midstream, LP 36785	Contact: Patricia A. Grajeda	
Address: 10 Desta Drive, Suite 400 W, Midland, TX., 79705	Telephone# & E-mail: 432.620.4166 / pgrajedadebabb@dcpmidstream.com	
Facility Name: ZZ-1-6- Ext Rat Camp	Facility Type: Pipeline	
Surface Owner: BLM	Mineral Owner:	Well API No.:

LOCATION OF RELEASE

Unit Letter	Section 12	Township 16	Range 27	Feet from the	North/South Line S	Feet from the	East/West Line E	County
Latitude		N32.941231		Longitude		W104.234294		

NATURE OF RELEASE

Type of Release: Gas	Volume of Release: 1086 Mscf	Volume Recovered: No liquids
Source of Release: Pipeline	Date & Hour of Occurrence: 03/17/2012 14:30	Date & Hour of Discovery: Same
Was Immediate Notice Given OCD? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom @ OCD? Mike Bratcher and Geoffrey Leking via email	
By Whom? Patricia Grajeda	Date and Hour: 03/17/2011 via email at 20:10	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken. (If water spilled, give Chloride content)* On March 17, 2012, at approximately 14:30 M.T. DCP Midstream discovered a pipeline leak on the ZZ1-6 -Ext Rat Camp Discharge line at Lat: 32.941231 Long: 104.234294. The estimated volume of the blow down was 1086 Mscf. There were no liquids associated with this event. DCP Midstream shutdown booster stations and gas was shut in. DCP Midstream repaired the leak on March 18, 2012.		
Describe Area Affected, Dimensions, and Cleanup Action Taken.* No cleanup actions were taken.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Patricia Grajeda</i>	Approved by District Supervisor:	
Printed Name: Patricia A. Grajeda	Accepted for record NMOCD	
Title: Environmental Specialist II	Approval Date: SEP 24 2013	Expiration Date:
E-mail Address: pgrajedadebabb@dcpmidstream.com	Conditions of Approval:	
Date: 03/21/2012 Phone: 432.620.5403		

* Attach Additional Sheets If Necessary

njmw 1326740521

2RP-1930

njmw 1326741624

Grajeda De Babb, Patricia

From: Grajeda De Babb, Patricia
Sent: Saturday, March 17, 2012 9:10 PM
To: Bratcher, Mike, EMNRD; Leking, Geoffrey R, EMNRD (GeoffreyR.Leking@state.nm.us) (GeoffreyR.Leking@state.nm.us)
Cc: Bebbington, Jon D; Cook, John W; Lamb, Johnny F; Hill, Lewis J; Betz, Michael R
Subject: Pipeline Leak (Immediate Notification)

Mr. Bratcher,

Today, at approximately 14:30 M.T. DCP Midstream discovered a pipeline leak on the ZZ1-6-6-Ext Rat Camp Discharge line at Lat: 32.941231 Long: 104.234294. The estimated volume of the blow down was 1086 Mscf. There were no liquids associated with this event. DCP Midstream shutdown booster stations and gas was shut in.

DCPM will follow up with a C-141 as soon as all the pertinent information is gathered.

I tried calling your number 575.626.0857 and no answer.

Patricia A. Grajeda de Babb
Environmental Specialist II
DCP Midstream, LP

Bratcher, Mike, EMNRD

From: Grajeda De Babb, Patricia [PGrajedaDeBabb@dcpmidstream.com]
Sent: Wednesday, March 21, 2012 10:55 AM
To: Bratcher, Mike, EMNRD
Cc: Bebbington, Jon D; Hill, Lewis J; Case, Nicholas L
Subject: C-141- Pipeline Vent, DCP Midstream, LP
Attachments: C-141 ZZ-1-6 Ext Rat Camp.pdf

Mr. Bratcher,

Please find file attached that contains a C-141 form for the venting on the ZZ-1-6 Ext Rat Camp line which occurred on March 17, 2012, due a pipeline leak. If you should have any comments or concerns, please do not hesitate to email me or give me a call.

Patricia A. Grajeda
Environmental Specialist II
DCP Midstream, LP