


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMW 1326836453

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company DCP Midstream, LP 36785	Contact Dan Landenberger
Address 10 Desta Drive, Suite 400 W, Midland, TX., 79705	Telephone# & E-mail: 432.620.4085/ drlandenberger@depdmidstream.com
Facility Name Line Name: 20106B	Facility Type Pipeline

Surface Owner State	Mineral Owner	API No.
---------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section 2	Township 24S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N32.251146 Longitude W103.756658

NATURE OF RELEASE

Type of Release Gas	Volume of Release 130 Mscf	Volume Recovered
Source of Release Pipeline (Line Name: 20106B)	Date and Hour of Occurrence 4/23/2013	Date and Hour of Discovery 4/23/2013 10:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Line leak occurred on 8 inch steel line. Very little liquids (less than 1 barrel condensate) associated with gas release.

Describe Area Affected and Cleanup Action Taken.*

8' X 10' affected area. Smith and Sons repaired line. Contaminated soil was excavated and samples were collected to verify clean up. Waiting on sample analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist:	
Printed Name: Dan Landenberger	Signed By	
Title: Sr. Environmental Specialist	SEP 25 2013 Approval Date:	Expiration Date:
E-mail Address: drlandenberger@depdmidstream.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/6/2013 Phone: 432-620-4085		

FJMW 1326836316
iJMW 1326836901

2RP-1932

Bratcher, Mike, EMNRD

From: Leking, Geoffrey R, EMNRD
Sent: Monday, May 06, 2013 2:06 PM
To: Bratcher, Mike, EMNRD
Cc: Landenberger, Dan R
Subject: FW: C-141 Report for Line Leak 20106B
Attachments: C-141Line20106B.pdf

Mike

This one's Eddy Co.

Geoff

From: Landenberger, Dan R [<mailto:DRLandenberger@dcpmidstream.com>]
Sent: Monday, May 06, 2013 9:17 AM
To: Leking, Geoffrey R, EMNRD
Cc: Maggard, Roger L
Subject: C-141 Report for Line Leak 20106B

Mr. Leking,

Please find the attached file containing the C-141 form for the release from the 20106B Line which occurred on April 23, 2013. If you should have any comments or concerns, please do not hesitate to email me or give me a call.

Dan Landenberger
Senior Environmental Specialist
Permian Region

DCP Midstream, LP
10 Desta Drive, Suite 400 West
Midland, TX 79705
Ofc: 432-620-4085
Cell: 432-557-4824
e-mail: drlandenberger@dcpmidstream.com