

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Wednesday, March 12, 2014 10:15 AM
To: Bratcher, Mike, EMNRD
Subject: RE: Final C-141, 2RP-283 (Walt Canyon AMA Federal #4)

Mike,

Yates would also request permission to backfill the two (2) open excavation sites on the well pad.

Thank you.

Robert Asher
Yates Petroleum Corporation
NM Environmental Regulatory Supervisor
boba@yatespetroleum.com

From: Bob Asher
Sent: Wednesday, March 12, 2014 10:06 AM
To: (mike.bratcher@state.nm.us)
Subject: Final C-141, 2RP-283 (Walt Canyon AMA Federal #4)

Mike,

I have attached the Form C-141 Final Report and supporting documentation for the captioned well. Yates is in process of plugging and abandoning the well/location. I have checked OCD Online for the status of 2RP-283, and it is still open. As I have highlighted on the cover page that the impacted soils that were stockpiled have been removed and was taken to an NMOCD approved facility for disposal. Remaining chlorides left in-place (899 ppm and 23.5 ppm) should not pose a threat to ground water, (DTGW was documented on the C-141 at 493' per the NMOSE), the ChevronTexaco Trend Map shows DTGW at 75'.

Yates would like to request verbal permission to proceed with the P & A process and reclamation of the well pad area. Please contact me if there are any questions.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed,

arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
