

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n HMP 1407731743

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>260737</i>		Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: PLU-59 Tank Battery. The tank is located on the PLU-49 well pad 2960 ft. S.W. of the gas well		Facility Type: Exploration and Production	

Surface Owner: USA	Mineral Owner: USA	API No. 30-015-24196
--------------------	--------------------	----------------------

PLU-49 API 30-015-23430 **LOCATION OF RELEASE**

Unit Letter F	Section 17	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.219106 Longitude W 103.908567

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls	Volume Recovered: 5 bbls
Source of Release: Leaking production tank	Date and Hour of Occurrence: 3/14/14 time unknown	Date and Hour of Discovery: 3/14/14 at 9:50 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The tank was leaking due to internal corrosion. The tank was emptied and isolated.


Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 900 sq. ft. of an area inside the earthen containment around the tank.

All of the free standing fluid was removed with a vacuum truck.

The spill will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



OIL CONSERVATION DIVISION	
Signature: <i>Tony Savoie</i>	Approved by Environmental Specialist: <i>[Signature]</i>
Printed Name: Tony Savoie	Approval Date: <i>3-18-14</i> Expiration Date:
Title: Waste Management and Remediation Specialist	Conditions of Approval:
E-mail Address: <i>tasavoie@basspet.com</i>	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION
Date: 3/17/14	Attached <input type="checkbox"/>
Phone: 432-556-8730	PROPOSAL NO LATER THAN:

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

4-18-14

2RP-2217

PLU-59 WELL

Gavain Rd

PLU-49


PLU-59 Battery

© 2013 Google

GOO

1996

Imagery Date: 3/2/2012 lat 32.221041° lon -103.908400° elev 3240 ft



Data use subject to license.

© DeLorme. Topo North America™ 9.

www.delorme.com

