## **NM OIL CONSERVATION**

ARTESIA DISTRICT

Revised August 8, 2011

Form C-141 JAN **26** 2015

## State of New Mexico **Energy Minerals and Natural Resources**

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240

1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

811 S. First St., Artesia, NM 88210 District III

District II

District IV

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

**Release Notification and Corrective Action** 

Submit 1 Copy to appropriate District Office in RECEIVED with 19.15.29 NMAC.

NAB 15	02726	5789		OPERATOR OPERATOR									
Name of Company: BOPCO, L.P. 260 3						Contact: To							
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329							
Facility Name: Legg Federal Tank Battery						Facility Type: Production Facility							
Surface Own	ner: Feder	al	Mineral O	wner: I	Federal			API No. 30-015-04734					
				LOCA	TION	N OF REI	LEASE						
								West Line   County:					
В	27 22S 30E 660		North		2004	East		Eddy					
Latitude N 32.369047 Longitude W 103.867870													
NATURE OF RELEASE													
Type of Relea	ase: Crude	oil and produc	ed water			Volume of Release: 18 bbls crude   Volume Recovered: 3 bbls crude oil and							
C CD . 1		oil and 5 bbls PW  Date and Hour of Occurrence:			3 bbls PW								
Source of Rel	ease: Heate	er-treater			iour of Occurrenc ne unknown	Date and Hour of Discovery: 1/24/15 at 4:00 a.m. approximately 11:00 a.m.							
Was Immedia	ite Notice C			If YES, To Whom? M. Bratcher, H. Patterson, and Jim Amos									
			Yes _	No Not Red	quired								
By Whom? T				Date and Hour 1/24/14 at 11:42 a.m.									
Was a Watero	course Reac	inea?		If YES, Volume Impacting the Watercourse.									
If a Watercourse was Impacted, Describe Fully.*													
n a watercou	n a watercourse was impacted, Describe runy."												
Describe Cause of Problem and Remedial Action Taken.* A gasket failed on the hearter-treater fire tube. The production was diverted and the gasket was replaced.													
Describe Area Affected and Cleanup Action Taken.*													
The release p	ooled up in	an area meas	uring abοι	ıt 1640 sq. ft inside									
				ng fluid was picked				area wi	ll be left as	is pending r	emedia	ation.	
The impacted	area wiii o	be cleaned up	in accorda	nce to the NMOCI	J and B	slivi remedia	tion guidelines.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
				nd/or file certain re									
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.							OIL CONSERVATION DIVISION						
Q o						OIL CONSERVATION DIVISION							
Signature: \ One \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						Approved by Environmental Specialist:							
Printed Name: Tony Savoie						Approved by	Environmental S	o <del>ecialist</del>	177 20	PERRENCE SE	=		
Title: Waste Management and Remediation Specialist						Approval Date: 1/27/15 Expiration Date: NA							
E-mail Addre	ss: tasavoie	abasspet.com	n			Conditions of Approval:							
E-mail Address: tasavoie@basspet.com  Conditions of Approval  Remediation per O.C.D. Rules & Guldelinesttached													
Date: 1/26/15 Phone: 432-556-8730 SUBMIT REMEDIATION PROPOSAL NO													
Attach Additional Sheets If Necessary  LATER THAN: 27211												2761	

