

Bratcher, Mike, EMNRD

From: Tavaréz, Ike [Ike.Tavaréz@tetratech.com]
Sent: Tuesday, August 31, 2010 2:38 PM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; Joshua Russo
Subject: COG - Spill Notifications, Eddy County, NM

COG Operating

Harper State #5
Section 5, T17S, R30E
Eddy County, New Mexico

Antelope SWD 8" Lateral Line
Section 36, T17S, R31E
Eddy County, New Mexico

Red Lake Sand #45
Section 20, T17S, R28E
Eddy County, New Mexico

Mike ,

Tetra Tech will be onsite tomorrow (September 1, 2010) to collect soil samples (hand augers) to assess the spills listed above. Please call me if you have any questions, thanks

Ike Tavaréz, PG | Senior Project Manager

Main: 432.682.4559 | Fax: 432.682.3946 | Cell: 432.425.3878

Ike.Tavaréz@tetratech.com

Tetra Tech | Complex World. Clear Solutions™

1910 North Big Spring | Midland, TX 79705 | www.tetratech.com

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Tuesday, August 17, 2010 9:06 PM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis; 'ike.tavarez@tetrattech.com'
Subject: Antelope SWD lateral line release immediate notification

Mr. Bratcher,

*30-015-32151
2RP-477*

Please see below the detailed description of a release that occurred earlier today (08-17-2010). We will follow up with a C-141 Initial Report.

Thank you,

Josh Russo

HSE Coordinator

550 W. Texas Ave, Suite 100

Midland, Texas 79701

Phone: 432-683-7443

Cell: 432-212-2399

jrusso@conchoresources.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Rick Wright
To: Pat Ellis; Joshua Russo
Cc: Ron Beasley; Kent Greenway; Ryan Faulkenberry; Keenan Kern
Sent: Tue Aug 17 20:09:29 2010
Subject: Antelope SWD lateral line release

On 8-17-10 at 3:00pm a leak occurred on the Antelope 8" SWD lateral line. A portion of the line became uncovered and weathered, weakening the pipe and causing it to rupture. 80 bbls of produced water was released. We were unable to recover any fluids due to the spill location and absorption rate. Line has been repaired but was left out of service pending integrity evaluation. The contaminated area is 12ft X 90ft. We will await instruction before performing any cleanup of the area. The airplane reported "no leaks" at 9:00am of the same day. GPS coordinates, legal description, and driving directions below.

GPS:
N 32° 47.503 W 103° 49.432

Closest well is 100 yds South of spill site:
Antelope St. #3
2310' FSL & 2310' FWL
Sec.36-T17S-R31E

Eddy Co. B-3627
API #30-01532151

Drive-to directions:

East of Loco Hills to SR529, at mm4 turn right, 1/10 mile to Tee, turn right 500ft to Tee, turn left 2/10mi, turn right 1/10 mi to Tee, turn right to Antelope #3. Spill site is 100 yards North of well pad in pasture.

Thanks,

Rick Wright
Production Foreman
COG Operating, LLC
2407 Pecos Ave.
Artesia, NM 88210
575.746.2010 office
432.528.5363 cell
575.746.2096 fax
rwright@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.