

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Big Walt CTB	Facility Type	Gathering

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East-West Line	County
H	2	22S	24E					Eddy County, NM

Latitude N 32.42289° Longitude W 104.46129°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	10 bbls of water and 4 bbls of oil	Volume Recovered	0 bbls
Source of Release	Failure in fire tube on west heater treater	Date and Hour of Occurrence	11/12/2012	Date and Hour of Discovery	11/12/2012
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD and Terry Gregston-BLM		
By Whom?	Christopher Jones	Date and Hour	11/14/2012 @ 8:50 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

RECEIVED

APR 29 2013

NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The failure of a fire tube on the west heater treater caused 10 bbls of produced water and 4 bbls of oil to leak inside the firewall. 0 bbls were recovered. The tube was repaired to prevent further leaking.

Describe Area Affected and Cleanup Action Taken.*

The area affected was approximately 35' x 45'. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 01/15/2013 and approved by Terry Gregston of BLM via email on 01/30/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Chris Jones

Title: HES Specialist

E-mail Address: Christopher.Jones@oxy.com

Date: 1/25/13

Phone: (575) 628-4121

Approved by District Supervisor:

Approval Date: 4/21/15

Expiration Date: N/A

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

2PP-1425

2 RP 1320 to 1325 VIA 1/10 1321
Propose 1' ex Across release area
Thomas Disc
Conf sample graham

Op4 Fed C 35 #3
2RP-1320 DOR 9/21/12
Exc 1 1/2' across release area
No conf sample - debris to clean

Op4 Smokey Bites St Can # 5H
2RP-1285 DOR 8/14/12
Exc Tank bottom 1' rif
Exc 1' Across Klumpth - no conf req.

Meeting w/
Cliff Brunson
12/17/12
→ Op4 Big WMT CTB
2RP-? 1425 015-33315
Exc 2' across spill area

Op4 McCall #2 Btry
2RP-822 015-29447 DOR 2/1/11
Surg SCAPE 1-2-3 & 4 - 3 @ 5 & 6
No hyd. taken - will take (comp) for hyd.
Comp 1-4 Comp 5 & 6

Bratcher, Mike, EMNRD

Did not

Get scanned

2RP-1425

From: Christop
Sent: Wednesday, November 14, 2012 8:50 AM
To: Bratcher, Mike, EMNRD; Terry_Gregston@blm.gov
Cc: kswinney@bbcinternational.com; cbrunson@bbcinternational.com; kathy@bbcinternational.com
Subject: Big Walt CTB

This is to inform you that Oxy Permian Primary had a spill of produced water & oil at the Big Walt CTB on November 12, 2012. Oxy released 10 bbls of produced water and 4 bbls of oil, 0 bbls was recovered. Leak was due to failure in the fire tube on the west heater treater. Oxy will do some initial remediation, a C-141 to follow. BBC International will delineate at a later date. SECT 2 T22S R24E EDDY COUNTY NEW MEXICO Driving directions: ON 285 NORTH OUT OF CARLSBAD TURN LEFT ON WATER HOLE RD GO 16 MILES, TURN RIGHT AT BIG WALT CTB SIGN GO 1/4 MILE TO BATTERY

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from
our ancestors; we borrow it from
our children." Chief Seattle