

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

SEP 16 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1526537304

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Hackberry 18 Fed 1	Facility Type	Oil

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-29780
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	18	19S	31E	660	South	1980	East	Eddy

Latitude: N 32°65'49.53"

Longitude: W 103°90'65.32"

NATURE OF RELEASE

Type of Release Spill	Volume of Release	Volume Recovered
Oil and Produced water	400 oil and 70 produced water	397 oil and 68 produced water
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
2 phase separator on the Sirius 17 Fed 3 overflowed into the tank	9/14/2015 @ 9:30 am	9/14/2015 @ 9:30 am
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	BLM Jim Amos OCD Mike Bratcher	
By Whom?	Date and Hour	
Lynn Smith	9/14/2015 4:03 pm 9/15/2015 7:40 am	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> Yes <input type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On September 14, 2015 lease operator went to the Hackberry 18 Fed 1 and noticed the tanks were overflowing. The 2 phase separator at the Sirius 17 Fed 8 was swamped and was sending the fluid to the Hackberry 18 Fed 1 compressor. 400 bbls of oil and 70 bbls of produced water spilled into unlined containment. Standard Trucking was called to recover 397 bbls of oil and 68 bbls of produced water.

Describe Area Affected and Cleanup Action Taken.*

The spill affected a 44'x80' area. Talon will do the cleanup for the remained of the 5 bbls.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <u>Mike Bratcher</u>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: corina.moya@dvn.com	Approval Date: 9/22/15	Expiration Date: N/A
Date: 9/16/2015 Phone: 575.746.5559	Conditions of Approval:	
	Remediation per O.C.D. Rules & Guidelines	
	SUBMIT REMEDIATION PROPOSAL NO	
	LATER THAN: 10/22/15	

* Attach Additional Sheets If Necessary

2RP-3272

Bratcher, Mike, EMNRD

From: Moya, Corina <Corina.Moya@dev.com>
Sent: Wednesday, September 16, 2015 2:57 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Jim Amos (jamos@blm.gov); stucker@blm.gov
Subject: Hackberry 18 fed 1_400 bbl oil and 70 bbl pw spill 9.14.2015
Attachments: Hackberry 18 Fed 1_ 400 bbl oil and 70 bbl pw spill 9.14.2015 pic 1 of 3.jpg; Hackberry 18 Fed 1_ 400 bbl oil and 70 bbl pw spill 9.14.2015 Initial C-141.doc; Hackberry 18 Fed 1_ 400 bbl oil and 70 bbl pw spill 9.14.2015 GIS Mapping.pdf; Hackberry 18 Fed 1_ 400 bbl oil and 70 bbl pw spill 9.14.2015 pic 3 of 3.jpg; Hackberry 18 Fed 1_ 400 bbl oil and 70 bbl pw spill 9.14.2015 pic 2 of 3.jpg

Good afternoon,

Please see attached incident for the Hackberry 18 Fed 1 that occurred on 9.14.2015. Red dot on GIS Mapping indicate where the spill occurred.

Have a great day!!!

Thank you,

Corina Moya
Field Admin Support
Production
B Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.