

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526538998

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Cypress 33 Federal #1H Battery	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-015-36321
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	23S	29E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	28 bbls	Volume Recovered	27 bbls
Source of Release	Corrosion of a tank	Date and Hour of Occurrence	08/30/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	09/01/2015 @ 4:56 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NM OIL CONSERVATION ARTESIA DISTRICT		

If a Watercourse was Impacted, Describe Fully.\*

SEP 16 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.\*

Corrosion of a tank caused 28 bbls of oil to leak inside the lined battery. A vacuum truck recovered 27 bbls of oil and the tank was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 45' x 15' with all of the leak staying inside the lined battery on location. Remediation was completed by removing the impacted gravel from the lined battery and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: CJ Summers

Title: HES Lead

E-mail Address: chancey\_summers@oxy.com

Date: 9-11-15 Phone: (432) 685-5824

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 9/22/15

Expiration Date: N/A

Conditions of Approval:

FINAL

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-3273

## **Patterson, Heather, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Wednesday, September 16, 2015 4:22 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov  
**Cc:** C J Summers; 'Dusty Wilson'; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial and Final C-141, Cypress 33 Federal #1H Battery  
**Attachments:** Initial and Final C-141, Cypress 33 Federal #1H Battery.pdf

Attached is the initial and final C-141 for a leak that occurred at the Cypress 33 Federal #1H Battery on 08/30/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Tuesday, September 01, 2015 4:56 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; Kathy Purvis  
**Subject:** Cypress 33 Federal #1H battery

This is to inform you that Oxy Permian had a leak at the Cypress 33 Federal #1H battery on August 30, 2015. Oxy spilled 28 bbls of oil due to corrosion of a tank. The preliminary report shows the leak measuring approximately 45' x 15' inside the lined battery. A vacuum truck recovered approximately 27 bbls of oil. The release is located in the southern half of Section 33, T23S, R29E of Eddy County, NM. The contaminated gravel will be replaced with new material and an initial C-141 will follow. Driving directions: From NM128 at mile marker 5, turn south on Rawhide Rd and go to the end of the pavement, turn right and go 3.4 miles, turn left and go 2 miles, turn right at sign to battery. API# 30-015-36321 GPS coordinates are not available at this time.

### *Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)