District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Provised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABI	-700A	OPERATOR			X	Initia	l Report		Final Report				
Name of Company Burnett Oil Co., Inc.						Contact 817-583-8730							
			1500, For	t Worth, TX 761	02 7	Telephone No. 817-583-8730							
Facility Nan	ne Jackson	1B5			1	Facility Type Tank Battery							
Surface Own	ner BLM		Mineral O	wner	BLM API No. 30-015-41191								
LOCATION OF RELEASE													
Unit Letter						/South Line Feet from the East/West				ne County			
P	ł	17S	30E	1145'	South	n	1283'	East	East Eddy				
Latitude, ,'Longitude_													
NATURE OF RELEASE													
Type of Release Oil/Water Source of Release Poly Line Rupture							Volume of Release Sheen/5 BBLS Volume Recovered 0 BBLS						
Was Immedia				Date and Hour of Occurrence/25/16 0730 If YES, To Whom?									
was immedia	ne mine C		No 🗌 Not Re	quired									
By Whom?						Date and Hour							
Was a Watero	ourse Reac	hed?			If YES, Volume Impacting the Watercourse.								
Yes X No									<u>;</u>				
If a Watercourse was Impacted, Describe Fully.*													
N/A													
i e e e e e e e e e e e e e e e e e e e													
Describe Cause of Problem and Remedial Action Taken.*													
Poly line ruptured at weld. Line will be repaired and return to service.													
Tory this replaced at well. Line will be repaired and return to service.											s		
Describe Are										,			
Impacted	a 5'x 25' a	nd 20'x15' a	rea in pas	ture to the west	of Jack	son B 5 Tan	k Battery. Area	will be re	emediat	ed to regula	nory s	tandards.	
			•						1				
									r H		<u> </u>		
				is true and compl									
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
federal, state,	or local lav	ws and/or regi	ulations.				OIL CON	ciin V A	THAN	DIVICIO	79-4 		
6		,	•		OIL CONSERVATION DIVISION								
Signature: Julie Salvo											_		
Printed Name: Leslie Garvis						Approved by Environmental Specialist:							
	4						برامراجع		1	11/	<u> </u>		
Title: Regu	latory Cod	ordinator				Approval Da	1e: 0112116) <u>E</u>	piration	Date: Y	7_		
E-mail Addre	_{ess:} Igarvis	@burnettoil	.com			Conditions o	f Approval:			مالدالات م	,		
				Remediation per O.C.D. Rules & Guidelinesed Submit REMEDIATION PROPOSAL NO									
Date: 7/25/	···		SUBMIT F	EMEDIATION	PROF	USAL	ηU						
Attach Addi	tional She	ets If Necess	ary		į	LATER TH	AN: <i>/ </i>	11169			212	P 3803	

Patterson, Heather, EMNRD

From:

Leslie Garvis < lgarvis@burnettoil.com>

Sent:

Tuesday, August 09, 2016 9:26 AM

To:

Patterson, Heather, EMNRD; stucker@blm.gov

Cc:

Johnny Titsworth

Subject:

RE: Initial C141 for Release at the Jackson B 5 Tank Battery | API # 30-015-36146

Attachments:

2016.08.09JB 5 C141 Revised.pdf

Heather,

Attached is the revised C141 with the correct API number.

Johnny - can you please provide the Lat/Long of the spill location?

Thank you,

LESLIE GARVIS

REGULATORY COORDINATOR
NMOGA SE NM PUBLIC LANDS COMMITTEE CHAIR

BURNETT OIL CO., INC.

BURNETT PLAZA - SUITE 1500 801 CHERRY STREET - UNIT 9 FORT WORTH, TEXAS 76102 DIRECT LINE: 817.583.8730 MOBILE: 713.819.4371

FAX: 817.332.2438

EMAIL: LGARVIS@BURNETTOIL.COM

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]

Sent: Friday, August 05, 2016 12:46 PM

To: Leslie Garvis < lgarvis@burnettoil.com>; Johnny Titsworth < jtitsworth@burnettoil.com>
Subject: RE: Initial C141 for Release at the Jackson B 5 Tank Battery | API # 30-015-36146

Leslie and Johnny,

Can you double check the API on this? It doesn't seem to match the location. Also, can you provide the lat/long for the actual spill location. That helps us in mapping our spills.

Thanks,

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Leslie Garvis [mailto:lgarvis@burnettoil.com]

Sent: Monday, July 25, 2016 4:23 PM

To: stucker@blm.gov; Patterson, Heather, EMNRD Cc: Johnny Titsworth; Kyle Adams; Walter Glasgow

Subject: Initial C141 for Release at the Jackson B 5 Tank Battery | API # 30-015-36146

Shelly/Heather,

Attached you will find the initial C-141 for the release on 7/25/16 at the Jackson B 5 Tank Battery.

Please let me know if you have any questions or need any additional information.

Thank you

LESLIE GARVIS

REGULATORY COORDINATOR
NMOGA SE NM PUBLIC LANDS COMMITTEE CHAIR

BURNETT OIL CO., INC.

BURNETT PLAZA - SUITE 1500 801 CHERRY STREET - UNIT 9 FORT WORTH, TEXAS 76102 DIRECT LINE: 817.583.8730

MOBILE: 713.819.4371 FAX: 817.332.2438

EMAIL: LGARVIS@BURNETTOIL.COM

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited. This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.