

# **NM OIL CONSERVATION**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

ARTESIA DISTRICT

DEC 06 2016

RECEIVED

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

# **NM OIL CONSERVATION**

ARTESIA DISTRICT

DEC 09 2016

RECEIVED

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

NAB1634429601

**OPERATOR**

X Initial Report

Final Report



Name of Company: Burnett Oil Co., Inc. 308D	Contact: Johnny Titsworth
Address: Burnett Plaza-Ste 1500, 801 Cherry St-Unit 9, Fort Worth, TX 76102	Telephone No. (432) 425-2891
Facility Name: Nosler Federal TB	Facility Type: Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-38633	

## **LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	12	17S	31E	799	FSL	564	FEL	Eddy

Latitude: 32.84420 Longitude: -103.81650

## **NATURE OF RELEASE**

Type of Release: oil	Volume of Release: 3bbls	Volume Recovered: 0
Source of Release: Fire at Heater Treater	Date and Hour of Occurrence: 11:00 pm 12/5/16	Date and Hour of Discovery: 11:20 pm 12/5/16
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD - H. Patterson BLM - S. Tucker	
By Whom? Johnny Titsworth	Date and Hour: 12/6/16	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Fire at Heater Treater caused the release of oil. The majority of the oil was consumed by the fire, with small amounts left inside the lined facility as well as the location pad.		
Describe Area Affected and Cleanup Action Taken.* The impacted area is approx. 20'x50' inside the lined facility and a 40'x70' area on the pad. The area will be scrapped, with the impacted material being hauled to disposal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 12/8/16	Expiration Date: N/A
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 12/6/16 Phone: (432) 425-2891		

\* Attach Additional Sheets If Necessary

2RP-4028

## **Patterson, Heather, EMNRD**

---

**From:** Johnny Titsworth <jtitsworth@burnettoil.com>  
**Sent:** Tuesday, December 6, 2016 1:24 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Weaver, Crystal, EMNRD; Tucker, Shelly  
**Cc:** Kyle Adams; Leslie Garvis  
**Subject:** Nosler Fed TB C-141  
**Attachments:** Nosler Fed TB initial C-141.pdf

All,

Last night we had a small fire at the Nosler Fed TB. The release stayed inside the lined facility as well as on the pad. The pasture was not impacted. The majority of the oil that was released was consumed by the fire, but the remaining impact will be scrapped up and hauled to disposal. If there are any questions or concerns, feel free to contact us. Thank you.

**Johnny Titsworth**  
HSE COORDINATOR

**BURNETT OIL CO., INC.**  
P.O. Box 188  
CR 220 North  
Loco Hills, NM 88255  
MOBILE: (432)-425-2891  
EMAIL: [jtitsworth@burnettoil.com](mailto:jtitsworth@burnettoil.com)

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.