

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

DEC 21 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1636346190 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company <i>Oxy Permian Ltd.</i>	Contact <i>Casey Summers</i>
Address <i>PO Box 4294; Houston, TX 77210</i>	Telephone No. <i>(575) 513-8289</i>
Facility Name <i>Cedar Canyon 16 SWD #003</i>	Facility Type <i>SWD Facility</i>
Surface Owner <i>Draper/McDonald</i>	Mineral Owner <i></i> API No. <i>30-015-41324</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	24S	29E					Eddy County, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>Oil and Produced water</i>	Volume of Release <i>2 bbls oil, 4 bbls produced water</i>	Volume Recovered <i>6 bbls</i>
Source of Release <i>Tank spill due to frozen valve</i>	Date and Hour of Occurrence <i>12/18/16</i>	Date and Hour of Discovery <i></i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher, Crystal Weaver- NMOCD</i>	
By Whom? <i>Kathy Purvis, BBC International</i>	Date and Hour <i>12/20/16 @ 9:42 am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A frozen valve caused a skim tank to spill over into the lined containment. A vacuum truck recovered all the fluids.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 40' x 40' on location inside the lined containment. Remediation was completed by recovering all the leaked fluids inside the lined containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Casey Summers</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>NM Environmental Advisor</i>	Approval Date: <i>12/29/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Casey.Summers@oxy.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>12-21-16</i> Phone: <i>(575) 513-8289</i>		

* Attach Additional Sheets If Necessary

2RP-4050

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, December 21, 2016 9:49 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc: Casey_Summers@oxy.com; Jennifer_Hudgens@oxy.com; 'Cliff Brunson'; 'Ken Swinney'; 'Jennifer Gilkey'
Subject: Initial and Final C-141, Cedar Canyon 16 SWD #003
Attachments: Initial and Final C-141, Cedar Canyon 16 SWD #003.pdf

Attached is the initial and final C-141 for a leak that occurred at the Cedar Canyon 16 SWD #003 inside a lined containment on 12/18/16. Receipt notification and closure via email are greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, December 20, 2016 9:42 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc: Casey_Summers@oxy.com; Frank_Barnett@oxy.com; Jennifer_Hudgens@oxy.com; 'Cliff Brunson'; 'Ken Swinney'; 'Jennifer Gilkey'; kathy@bbcinternational.com
Subject: Cedar Canyon 16 SWD #003

This is to inform you that Oxy Permian had a release at the Cedar Canyon 16 SWD #003 on December 18, 2016. Oxy released 2 bbls of oil and 4 bbls of produced water due to a frozen valve causing a skim tank spill. The preliminary report indicates that the leak measures 40' x 40' on location inside the lined containment. A vacuum truck recovered all the fluid. The release is located in U/L D, Section 16, T24S, R29E in Eddy County, NM. Driving directions: From Carlsbad, go South on US285 to Malaga, turn left on Duarte Rd, turn right on McDonald Rd, turn left on Dogtown Rd, cross the river, turn left and follow road to the first right, stay on road to the next first right to location. GPS coordinates are not available at this time. API# 30-015-41324

Kathy Purvis

BBC International, Inc.
1324 W. Marland Blvd.
Hobbs, NM 88240
Business: (575) 397-6388
Cell: (575) 441-8619
kathy@bbcinternational.com