

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 23 2016

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

DAB1701043105

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Abby BLF State #1	Facility Type Battery	
Surface Owner State	Mineral Owner State	API No. 30-025-38951

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	19	9S	33E	660	South	2310	West	Lea

Latitude 33.54260 Longitude 103.55593

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 30 B/PW
Source of Release Fiberglass Tank	Date and Hour of Occurrence 12/18/2016; AM	Date and Hour of Discovery 12/18/2016; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding & Kristen Lynch/NMOCD I	
By Whom? Robert Asher/EOG Y Resources, Inc.	Date and Hour 12/19/2016; PM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Ball valve on the fiberglass produced water tank froze and broke. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 30' X 70' within the lined and bermed battery. Vacuum truck recovered all the produced water, with the liner in very good condition. The valve was repaired and the well put back into service. Depth to Ground Water: 50-99' (approximately 65', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on the battery being lined/bermed, EOG Y Resources, Inc. requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: Sr. Environmental Supervisor	Approval Date: 1/10/17	Expiration Date: N/A
E-mail Address: Robert_Asher@eogresources.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: December 23, 2016	Phone: 575-748-4217	1RP-

* Attach Additional Sheets If Necessary

1RP-4552

Weaver, Crystal, EMNRD

From: Weaver, Crystal, EMNRD
Sent: Tuesday, December 27, 2016 8:08 AM
To: 'Bob Asher'
Cc: Bratcher, Mike, EMNRD
Subject: RE: RE - Corrections requested for Patsy BPI State #7 & Abby BLF State #1 Initial C-141s

Hello Bob,

Thank you very much for the corrections and for helping me out with some of my own too. Hope you had a happy holiday. ☺

Yes for now please include us, Tomas and Kristen in your sends to District I.

Thanks,

Crystal

From: Bob Asher [mailto:Bob_Asher@eogresources.com]
Sent: Friday, December 23, 2016 9:20 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: RE: RE - Corrections requested for Patsy BPI State #7 & Abby BLF State #1 Initial C-141s

Crystal, Yes, it was a typo in the Latitude being 33.xxxxx, not 32.xxxxx also the same with Kristen (the 'y' and 'u' next to each letter, and auto correct didn't change the miss spelling on my part), but we all do typo's (Aretesia).

As far as the Patsy BPI State #7, we had generally used Range 30 and up (numerically) and or, the last five digits of the API number beginning with '2' (30-005-2xxxx), the well is likely to be District 1, In most cases with Range 29 and down being District 2 (but again, not all) the last five digits of the API number for Chaves wells in District 2, begin with '6' (30-005-6xxxx).

We had received notification from Mr. Oberding/Santa Fe that he is responding to All environmental issues from D1, though he also stated he would be out from December 19 – December 28, and to plan accordingly. For any District 1 notifications and or C-141/Workplans, should they be forwarded to you and Mike also?

Thank you.

Robert C. "Bob" Asher
Environmental Department
EOG Resources, Inc.
Artesia Division Office
EOG Safety Begins With YOUR Safety



From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]
Sent: Thursday, December 22, 2016 12:25 PM
To: Bob Asher

Cc: Bratcher, Mike, EMNRD

Subject: RE - Corrections requested for Patsy BPI State #7 & Abby BLF State #1 Initial C-141s

** External email. Use caution.**

Hello Bob,

Sorry for more than one email about the same two Initial C-141's but I am having a hard time correctly locating your coordinates. You wrote a different legal (PLSS) then what the coordinates end up in. I figured out that you had a typo it seems in the Latitude numbers, you wrote 32.xxxx when it was supposed to be 33.xxxx. Also some of your section information is incorrect. Also your API for Patsy BPI State #7 is correct but you submitted your C-141 to District 1 for this and this location is in District 2. The only reason we ended up with it in District 2 is because we are currently covering for the Environmental team of District 1. I made some written suggestions on the C-141 and I attached a scanned copy with my suggestions on it. Please correct your C-141's and return them to us.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283

Fax: 575-748-9720

From: Weaver, Crystal, EMNRD

Sent: Thursday, December 22, 2016 9:35 AM

To: 'Bob_Asher@eogresources.com' <Bob_Asher@eogresources.com>

Subject: RE: Form C-141 Initial/Final Report (Patsy BPI State #7)

Hey Bob,

We got your initial C-141's for this one and Abby BLF State #1. Mike Bratcher and I are covering for District II for a while. Just wanted to let you know.

Also FYI Kristen's last name (District I) is Lynch not Lunch.

Merry Christmas! ☺

Thanks,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283

Fax: 575-748-9720

Cc: Bratcher, Mike, EMNRD

Subject: RE - Corrections requested for Patsy BPI State #7 & Abby BLF State #1 Initial C-141s

** External email. Use caution.**

Hello Bob,

Sorry for more than one email about the same two Initial C-141's but I am having a hard time correctly locating your coordinates. You wrote a different legal (PLSS) then what the coordinates end up in. I figured out that you had a typo it seems in the Latitude numbers, you wrote 32.xxxx when it was supposed to be 33.xxxx. Also some of your section information is incorrect. Also your API for Patsy BPI State #7 is correct but you submitted your C-141 to District 1 for this and this location is in District 2. The only reason we ended up with it in District 2 is because we are currently covering for the Environmental team of District 1. I made some written suggestions on the C-141 and I attached a scanned copy with my suggestions on it. Please correct your C-141's and return them to us.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283

Fax: 575-748-9720

From: Weaver, Crystal, EMNRD

Sent: Thursday, December 22, 2016 9:35 AM

To: 'Bob_Asher@eogresources.com' <Bob_Asher@eogresources.com>

Subject: RE: Form C-141 Initial/Final Report (Patsy BPI State #7)

Hey Bob,

We got your initial C-141's for this one and Abby BLF State #1. Mike Bratcher and I are covering for District II for a while. Just wanted to let you know.

Also FYI Kristen's last name (District I) is Lynch not Lunch.

Merry Christmas! ☺

Thanks,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283

Fax: 575-748-9720

Weaver, Crystal, EMNRD

From: Weaver, Crystal, EMNRD
Sent: Tuesday, December 27, 2016 8:08 AM
To: 'Bob Asher'
Cc: Bratcher, Mike, EMNRD
Subject: RE: RE - Corrections requested for Patsy BPI State #7 & Abby BLF State #1 Initial C-141s

Hello Bob,

Thank you very much for the corrections and for helping me out with some of my own too. Hope you had a happy holiday. ☺

Yes for now please include us, Tomas and Kristen in your sends to District I.

Thanks,

Crystal

From: Bob Asher [mailto:Bob_Asher@eogresources.com]
Sent: Friday, December 23, 2016 9:20 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: RE: RE - Corrections requested for Patsy BPI State #7 & Abby BLF State #1 Initial C-141s

Crystal, Yes, it was a typo in the Latitude being 33.xxxxx, not 32.xxxxx also the same with Kristen (the 'y' and 'u' next to each letter, and auto correct didn't change the miss spelling on my part), but we all do typo's (Aretesia).

As far as the Patsy BPI State #7, we had generally used Range 30 and up (numerically) and or, the last five digits of the API number beginning with '2' (30-005-2xxxx), the well is likely to be District 1, In most cases with Range 29 and down being District 2 (but again, not all) the last five digits of the API number for Chaves wells in District 2, begin with '6' (30-005-6xxxx).

We had received notification from Mr. Oberding/Santa Fe that he is responding to All environmental issues from D1, though he also stated he would be out from December 19 – December 28, and to plan accordingly. For any District 1 notifications and or C-141/Workplans, should they be forwarded to you and Mike also?

Thank you.

Robert C. "Bob" Asher
Environmental Department
EOG Resources, Inc.
Artesia Division Office
EOG Safety Begins With YOUR Safety



From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]
Sent: Thursday, December 22, 2016 12:25 PM
To: Bob Asher

From: Lynch, Kristen, EMNRD
Sent: Wednesday, December 21, 2016 4:12 PM
To: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: Fw: Form C-141 Initial/Final Report (Patsy BPI State #7)

From: Bob Asher <Bob_Asher@eogresources.com>
Sent: Tuesday, December 20, 2016 3:10 PM
To: Lynch, Kristen, EMNRD; Oberding, Tomas, EMNRD
Cc: Amber Griffin; Veronica Alvarado
Subject: Form C-141 Initial/Final Report (Patsy BPI State #7)

Thank you.

Robert C. "Bob" Asher
Sr. Environmental Supervisor
Environmental Department
EOG Resources, Inc.
Artesia Division Office
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)
EOG Safety Begins With YOUR Safety

