

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

AUG 03 2017

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1722634368 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company: XTO Energy BORED 240737	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU Pierce Canyon 20-24-30 USA Battery (@ API Poker Lake CVX JV PC #010H)	Facility Type: Exploration and Production



Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-39692
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	17	24S	30E	60	South	1670	East	Eddy

Latitude 32.210609° Longitude -103.900262°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	120 BPW	Volume Recovered	120 BPW
Source of Release	Victaulic blind/nipple on pump suction line	Date and Hour of Occurrence	7/17/2017 time unknown	Date and Hour of Discovery	7/17/2017 11:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Crystal Weaver (NMOCD), Jim Amos/Shelly Tucker (BLM)		
By Whom?	Jacob Foust	Date and Hour	7/18/2017 10:41 am by email		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* A Victaulic blind with a threaded regular coated nipple, placed along suction line prior to water pump suction entry point, became corroded and released fluid to secondary containment. The blind and nipple were replaced.					
Describe Area Affected and Cleanup Action Taken.* The leak affected the area within the secondary impermeable tank containment (metal walled, bottom lined with felt, spray coated with PVC based material). All fluids were removed and recovered via vacuum truck. The containment and affected equipment were cleaned. The liner was visually inspected and XTO attests to its integrity at the time of the event and recovery.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Amy C. Ruth		Approved by Environmental Specialist: 			
Title: Environmental Supervisor		Approval Date: 8/10/17		Expiration Date: N/A	
E-mail Address: Amy.Ruth@xtoenergy.com		Conditions of Approval: FINAL		Attached <input type="checkbox"/> 22P-4338	
Date: 8/3/2017 Phone: 432-661-0571					

* Attach Additional Sheets If Necessary

7/10/17 NAB

Bratcher, Mike, EMNRD

From: Ruth, Amy <Amy_Ruth@xtoenergy.com>
Sent: Thursday, August 3, 2017 3:43 PM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; jamos@blm.gov; stucker@blm.gov
Cc: Sanders, Toady; Foust, Bryan
Subject: RE: Initial notification for release at XTO Pierce Canyon 20-25-30 battery
Attachments: Initial C-141 PLU PC 20-25-30 Battery.pdf

Hi Crystal,

Please find the revised initial form C-141 for the referenced leak event. Thank you for your help, as always. Photos are available if needed, and sorry for the delay in replying. If you have any questions, please don't hesitate to call. Have a good evening...

Amy
432-661-0571

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]
Sent: Monday, July 31, 2017 10:36 AM
To: Ruth, Amy; Bratcher, Mike, EMNRD; jamos@blm.gov; stucker@blm.gov
Cc: Sanders, Toady; Foust, Bryan
Subject: RE: Initial notification for release at XTO Pierce Canyon 20-25-30 battery

Good morning all,

Hope you are doing well.

I have one small adjustment I needed to request from XTO regarding initial/final containment captured spills. OCD has had many internal discussions on this matter and we are all under agreement that when receiving an initial/final that involves the statement more or less of "all production fluids were kept in lined secondary containment" we need you all to include the following additional statements on the C-141:

- What type of containment it is.
- That the fluids were completely removed and that if fill material was in place within the containment that it was taken out and replaced.
- We need a statement that includes the mentioning that the liner/containment was completely checked and that you all "attest to the integrity of the liner/containment."
- **In certain cases OCD may also request photo documentation of the liner/containment.**

So for this one we need you all to send a revised copy of the initial/final C-141 that includes statements in your own words addressing all the above requested information (FYI no photos are being requested at this time for this release). Please continue to make all these requested statements on any initial/final C-141's of this nature that are submitted to OCD in the future as well.

If you have any questions or concerns please contact myself or Mike Bratcher here at the OCD District II Office.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

-----Original Message-----

From: Ruth, Amy [mailto:Amy_Ruth@xtoenergy.com]
Sent: Thursday, July 27, 2017 1:48 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; jamos@blm.gov; stucker@blm.gov
Cc: Sanders, Toady <Toady_Sanders@xtoenergy.com>; Foust, Bryan <Bryan_Foust@xtoenergy.com>
Subject: RE: Initial notification for release at XTO Pierce Canyon 20-25-30 battery

Hello All,

Please find attached, the initial/final C-141 for the PLU Pierce Canyon 20-24-30 USA Battery leak event, referenced below in the initial release notification. Please let us know if we can provide any additional assistance and, as always, thank you for yours.

-----Original Message-----

From: Foust, Bryan
Sent: Tuesday, July 18, 2017 10:41 AM
To: Mike EMNRD Bratcher; Crystal EMNRD Weaver; jamos@blm.gov; stucker@blm.gov
Cc: Ruth, Amy; Sanders, Toady
Subject: Initial notification for release at XTO Pierce Canyon 20-25-30 battery

Good morning. Yesterday we had a release of produced water at our pierce canyon 20-25-30 battery. It will be over 25 barrels. All fluid was within the plastic containment and recovered. There was no impact to the soil or any plant or animal life. We will submit an initial and final c141 since the cleanup is already complete.

Thank you, please let me know if you have any questions

Weaver, Crystal, EMNRD

From: Foust, Bryan <Bryan_Foust@xtoenergy.com>
Sent: Tuesday, July 18, 2017 10:41 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; jamos@blm.gov; stucker@blm.gov
Cc: Ruth, Amy; Sanders, Toady
Subject: Initial notification for release at XTO Pierce Canyon 20-25-30 battery

Good morning. Yesterday we had a release of produced water at our pierce canyon 20-25-30 battery. It will be over 25 barrels. All fluid was within the plastic containment and recovered. There was no impact to the soil or any plant or animal life. We will submit an initial and final c141 since the cleanup is already complete.

Thank you, please let me know if you have any questions

20-24-30
location
AB