

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

FEB 19 2018

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

HAB1717248605
NAB1805129860

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services, LLC	Contact	Alena Miro
Address	PO Box 4324, Houston, TX 77210	Telephone No.	575-628-6802
Facility Name	Pipeline ROW, Poker Lake Discharge	Facility Type	Natural Gas Pipeline
Surface Owner	BLM	Mineral Owner	N/A
API No.	N/A		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Unit Line	Feet from the	East/West Line	County
I	19	24S	30E	569	South	456	West	Eddy

Latitude N32.200969

Longitude W103.914914

NAD83

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	210 MCF and 4 bbl of pipeline liquid	Volume Recovered	N/A
Source of Release	Pipeline Release	Date and Hour of Occurrence	2/13/2018 @ 9:00 MDT	Date and Hour of Discovery	2/13/2018 @ 9:00 MDT
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
Date and Hour					
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Natural gas was released due to a pipeline leak. Pipeline segment was isolated, blown down, and will be repaired following a standard one-call.

Describe Area Affected and Cleanup Action Taken.*

Remediation actions will follow the Enterprise Products, General Release Notification, Response and Remediation Plan (March 9, 2015).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Jon E. Fields

Approved by Environmental Specialist:

Title: Director, Field Environmental

Approval Date: 2/19/18

Expiration Date: N/A

E-mail Address: jefields@eprod.com

Conditions of Approval:

Date: 2/15/2018

Phone: 713-381-6684

FINAL

Attached

220-4628

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Monday, February 19, 2018 1:09 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Yolanda Jordan (yjordan@BLM.gov)
Cc: Miro, Alena; Reinermann, Paul
Subject: Poker Lake Pipeline ROW
Attachments: Eddy County Poker Lake Pipeline ROW (2-13) February 2018.pdf

Attached for your review and handling is the Poker Lake Pipeline ROW initial report for a release that occurred on 2/13. Should you need additional information, please contact Ms. Alena Miro, our area environmental representative at 575-628-6802.

Shiver Nolan
Sr. Compliance Administrator

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.