
County Rio Arriba Pool South Blanco - Pictured Cliffs



	CT 2324252				FORM	APPROVED		
Form 3160-3 August 1999)	DEPVETMENT OF THE	ES HINTEROR	04 JUL 011: ALBU	-8 III 8:30 OUERDUE. N.M	OMB N Expires No 5. Lease Serial No.	o. 1004-0136 vember 30, 20		
APPLIC	BUREAU OF LAND MAN	AGEMENT DRIEL OR R	EENTER	USERGUE. N.M.	6. If Indian, Allottee	101990 e or Tribe Nar	ne	
a. Type of Work: 🔀 DRILL		ENTER			7. If Unit or CA Ag	reement, Narr	ne and No.	
b. Type of Well: 🚺 Oil Well	Gas Well 🚺 Other	X Sing	le Zone	Multiple Zone	8. Lease Name and Regina Ran		al 32 #1	
2. Name of Operator	Texas Crude,	Inc.			9. API Well No. 30-04	3-20	989	7
 3A. Address c/o Walsh Engineering,7415 E. 4. Location of Well (Report location) 	Main, Farmington, NM 87402		(505) 327-4	,	10. Field and Pool WC 23 N.1 11. Sec., T., R., M.,	W32;	Ent	rea
At surface 435' FSL and At proposed prod. Zone 44 . Distance in miles and direction	and 990' FWL	•	<u></u>	97399	N Sec. 32 12. County or Paris	h 1	3. State	
 Distance from proposed • location to nearest 	1 mile southwest of I 435'	Regina, NM 16. No. of Acre	s in lease	17. Spacing Unit de	Sandova dicated to this well		NM	_
property or lease line, ft. (Also to nearest drig, unit line, i	if any}	40	+		SW/SW 40 ac	res		
 Distance from proposed locatio to nearest well, drilling, compl applied for, on this lease, ft 	leted, NA	19. Proposed D 8750	•	20. BLM/BIA Bond	No. on file			
21. Elevations (Show whether DF, 7423	, KDB, RT, GL, etc.) 3' GR	22. Approxima	te date work w October 1,		23. Estimated dura	tion month		
			achments					-
 Well plat certified by a register A Drilling Plan. A Surface Use Plan (if the local 	rdance with the requirements of Or red surveyor. ation is on National Forest System ppropriate Forest Service Office.	Lands, the	 Bond to control to control term 20 ab Operator control term 	over the operations un pove). ertification. site specific informati	iless covered by an ex	-	·	
2 5. Sign ature <u>Hand</u> C. The Title	/	Name	(Printed/Typed Pau	i) Il C. Thompson,	P.E.	Date 7/6	5/2004	
			gent	·····				
A		Name	(Printed/Typed	1)		Date DOT	212	004
Approved by (Signature)	David R. Sitzler							


Title 18 U.S.C. Section 1001and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. *(Instructions on reverse)

ς.

1

District I PO Box 1980, H District II PO Drawer DD. District III 1000 Rio Brazo District IV PO Box 2088, S	Artesia M os Rd., Az	NM 88211-0 tec, NM 874	719 110	Energy. OIL (CONSERVATI PO Box	1 Resources Departmè	Submit to	Appropr Sta	Instruc Viate Di Ste Leas Vee Leas	Form C-102 Wary 21. 1994 tions on back strict Office se - 4 Copies se - 3 Copies ED REPORT
FU DUX 2000, S			_000							
			WELL			REAGE DEDI				
30.00	PI Number	0989	3 9	Pool Code		VC23NIN		en tra	da	
Property	Code	010			Property	Name	Je je je	70,000		ell Number
3431	66			REG		FEDERAL 32			9G	1 levation
UZS	68				[•] Operator TEXAS (7423
L					¹⁰ Surface 1				L	
UL or lot no. M	Section 32	Township 23N	Range 1W	Lot Idn	Feet from the 435	North/South line	Feet from the		est line IST	SANDOVAL
		1	Bottom	l Hole L	ocation I		From Sur	1		
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the		lest line	County
¹² Dedicated Acre	s	L	I		¹³ Joint or Infill	¹⁴ Consolidation Code	¹⁵ Onder No.			
SW/SI	N AD	ACRES			N			· <u>· </u>		
NO ALLO	WABLE W	VILL BE	ASSIGNE	D TO TH	IS COMPLETIO	ON UNTIL ALL	INTERESTS	HAVE B	EEN CC	NSOLIDATED
15			5	290.56'	OCT OCT	2004 2004 DN. 73	I here contai	by certify red herein best of m line line J Name	that the is true a	IFICATION information and complete lige and belief
LONG	35 10.4 106 58 ATUM: NAU	.2508 W		32 - 			O. I hereb notes o and cor U. <u>SUrvi</u> Signatu	y certify n this pla f actual s rvision ar rect to tr ey Date re and Sea N N History A History History A History History A History A History Hist	that the at was plo surveys man of that th be best of e: MARC al of Prof	HUL SS
	435			5280.00	, 	1	Cer	tificate	Number	DWARDS 15269





TEXAS CRUDE, INC. OPERATIONS PLAN Regina Ranch Federal 32 #1

I. Location: 435' FSL & 990' FWL Sec 32, T23N, R1W Sandoval County, NM Date: April 29, 2004

Elev: GL 7423'

Field: Wildcat Entrada Surface: Regina Ranch, LLC Minerals: NM 1019**90**

II. Geology: Surface formation _ San Jose

A.	Formation Tops	Depths
	Ojo Alamo	2600'
	Kirtland	2790'
	Pictured Cliffs	2920'
	Cliff House	4690'
	Menefee	4740'
	Point Lookout	5170 '
	Gallup	6260'
	Dakota	7460′
	Morrison	7800'
	Todilto	8475'
	Entrada	8550 '
	Total Depth	8750 ′

Estimated depths of anticipated water, oil, gas, and other mineral bearing formations which are expected to be encountered: Water and gas - 2920', 4690', 5170', 7460'

- B. Logging Program: Induction/GR and density logs at TD.
- C. No over pressured zones are expected in this well. No H_2S zones will be penetrated in this well. Max. BHP = 3750 psig.

III. Drilling

A. Contractor:

Oil - 8550'.

B. Mud Program:

The surface hole will be drilled with a fresh water mud.

The production hole will be drilled with a fresh water polymer mud. The weighting material will be drill solids or if conditions dictate, barite. The maximum mud weight expected is 9.0 ppg.

Regina Ranch 32 #1 Operations Plan Pg #2

C. Minimum Blowout Control Specifications:

Double ram type 2000 psi working pressure BOP with a rotating head. See the attached Exhibit #1 for details on the BOP equipment. All ram type preventers and related equipment will be hydraulically tested at nippleup and after any use under pressure to 1000 psi.

The blind rams will be hydraulically activated and checked for operational readiness each time pipe is pulled out of the hole. All checks of the BOP stack and equipment will be noted on the daily drilling report. The BOP equipment will include a kelly cock, floor safety valve, and choke manifold all rated to 2000 psi.

IV. Materials

A. Casing Program:

Hole Size	Depth	Casing Size	Wt. & Grade
12-1/4"	5001	9-5/8"	36# J-55
8-3/4"	8750'-6200'	5-1/2"	17.0# N-80 LT&C
	6200' - 0'	5-1/2"	17.0# J-55 LT&C

B. Float Equipment:

a) Surface Casing: Notched collar on bottom and insert float on top of the bottom joint. 5 centralizers on the bottom 5 joints.

b) Production Casing: 5-1/2" cement float shoe and self fill insert float collar. Place float one joint above shoe. Place stage tools at approximately 4000' and 6260' KB. Ten centralizers spaced every other joint above shoe and turbolizers above and below the stage tools and every fifth joint from 2600' to the surface casing.

Regina Ranch 32 #1 Operations Plan Pg #3

V. Cementing:

Surface casing: 9-5/8'' - Use 285 sx (336 cu. ft.) of Cl "B" with 2% CaCl₂ (Yield = 1.18 cu. ft./sk; slurry weight = 15.6 PPG). 100% excess to circulate cement to surface. WOC 12 hours. Pressure test surface casing to 1000 psi for 30 min.


Production Casing: 7" - Before cementing circulate hole with at least 1-1/2 hole volumes of mud. Precede cement with 20 bbls of fresh water and 30 sx of flyash - gel spacer. 1^{st} Stage: Cement with 730 sx (1066 cu.ft) of Cl "H" 50:50 poz with 0.9% Halad®-9 Fluid loss control, 0.1% HR-5 (retarder), 0.2% CFR-3 (dispersant), 5 #/sk gilsonite and ¼ #/sk flocele. (Yield = 1.46 cu.ft./sk; slurry weight = 13.0 PPG). Displace cement and bump the plug to 1500 psi. Open the stage tool at 6260' and circulate for four hours. Total cement volume is 1066 cu.ft. (65% excess to circulate the stage tool at 6260').

 2^{nd} Stage: Precede cement with 20 bbls of fresh water and 30 sx of flyash - gel spacer. Lead with 445 sx (801 cu.ft) of TXI Lightweight cement with 0.6% Halad®-9 (fluid loss control), 2% CaCl2, 5 #/sk gilsonite and 4 #/sk flocele. (Yield = 1.80 cu.ft./sk; slurry weight = 12.0 PPG). Tail with 100 sx (142 cu.ft.) of TXI Lightweight cement with 0.6% Halad®-9 (fluid loss control), 2% CaCl2, 5 #/sk gilsonite and 4 #/sk flocele. (Yield = 1.42 cu.ft.) of TXI Lightweight cement with 0.6% Halad®-9 (fluid loss control), 2% CaCl2, 5 #/sk gilsonite and 4 #/sk flocele. (Yield = 1.42 cu.ft./sk; slurry weight = 13.0 PPG). Displace cement and bump the plug to 1500 psi. Open the stage tool at 4000' and circulate for four hours. Total cement volume is 943 cu.ft. (65% excess to the stage tool at 4000').

3rd Stage: Precede cement with 10 bbls of fresh water, 20 bbls of mud flush, and 10 bbls of fresh water. Lead with 850 sx (1530 cu.ft) of TXI Lightweight cement with 0.4% Halad®-9 (fluid loss control), 2% CaCl2, 5 #/sk gilsonite and ¼ #/sk flocele. (Yield = 1.80 cu.ft./sk; slurry weight = 12.0 PPG). Tail with 100 sx (142 cu.ft.) of TXI Lightweight cement with 0.4% Halad®-9 (fluid loss control), 2% CaCl2, 5 #/sk gilsonite and ¼ #/sk flocele. (Yield = 1.42 cu.ft./sk; slurry weight = 13.0 PPG). Displace cement and bump the plug to 1500 psi. Total cement volume is 1672 cu.ft. (65% excess to circulate cement to surface).

Taul C. Tho

Paul C. Thompson, P.E.



Form C-104B

Permit 15463

C104BForm

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Change of Operator Name

 OGRID:
 22568

 Effective Date:
 12/13/2004

Previous Ope	erator Name and Information	New Operate	or Name and Information
Name:	TEXAS CRUDE INC	Name:	WESTERLY EXPLORATION, INC.
Address:	PO Box 56586	Address:	···
Address:		Address:	
City, State. Zip:	Houston, TX 77256	City, State, Zip:	

I hereby certify that the rules of the Oil Conservation Division have been complied with and that the information given on this form and the certified list of wells is true to the best of my knowledge and belief.

Signature:	Jay Lomans
Printed Name	Gray Komans
Title:	SR. Landman
Date:	<u>9/8/05</u> Phone: <u>713-599-9900</u>

NI	MOCD Approval
Electronic Signature:	David Brooks
District:	District IV
Date:	September 08, 2005


http://www.emnrd.state.nm.us/ocdpermitting/C104BForm.aspx?PermitID=15463

9/8/2005

	Form 3160-5 (August 1999)	UNITED STA DEPARTMENT OF TH BUREAU OF LAND MA	E INTERIOR		Budget Bure	M APPROVED au No. 1004-01 /ember 30, 2000 No.	35	
	Do not use the	NOTICES AND REPORT is form for proposals to dril I. Use Form 3160-3 (APD)	ll or to re-enter an		NM-1019 6. If Indian, All 7. If Unit or CA	lottee or Tribe 1		
		(1911: 11: 4) I - Other attricts	at paracreze side		8. Well Name a	- 4 No		
	I. Type of Well Oil Well Gas V	Well Other					DERAL 32 #1	
	2. Name of Operator	······			9. API Well No			
	Westerly Exploration, In 3a. Address c/o Walsh Engingeeirng	المتحص بالمستقد أعذوصا كالبربات مستبنا فالتكريب الناويها بقاطا البستا	ne No. (include area code)		30-043-20 10. Field and Po			
	3a. Address c/o Walsh Engingeeirng 7415 East Main St. Farmingto	· · ·	(5) 327-4892		1	T ENTRAD	-	
	4. Location of Well (Footage, Sec., T., 435' FSL & 990' FWL Sec. 32, 7				11. County or Pa Sandoval	rish, State County, Nev	w Mexico	
	12. CHECK A	PPROPRIATE BOX(ES) TO	DINDICATE NATURE	E OF NOTICE, F	EPORT, OR	OTHER DA	ГА	
	TYPE OF SUBMISSION		TYPE OF A	CTION	······································			
	Notice of Intent Subsequent Report	Aoidize Aiter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (S Reclamation Recomplete	tart/Resume)	Water Sh Well Inte		
Å		Change Plans	Piug and Abandon	Temporarily /	Ubandon		T REPORT	_
)	Final Abandonment Notice	Convert to Injection	Phug Back	🗍 Water Dispos	a)			
	11/20/05: Spud 12-1/4" sur to 498' KB. Cemented w/ 2 11/21/05: Nippled up the B0	70 sx (318.60 cu.ft) of Clas	s "B" w/ 2% CaCl2 and	1 1/4 #/sk flocele	Circulated 2	5 bbls of goo		
	14. I hereby certify that the foregoing is (rue and correct	······································		and the second secon			جانط
	Name (Printed/Typed) John C. Thompson	\sim	Title	Engineer /	Agent			
	- (1) =							
I	Signature	· 1 ~~~	Date	April 5, 20				
		THISISPACEDING	DR REDERAL OR SI	Fair Off Car	USE	10. A M		
	Approved by		Title			Date	\wedge 3	A.
	Conditions of approval, if any, are attached. App certify that the applicant holds legal or equitable	noval of this notice does not warrant or title to those rights in the subject lesse	r			A A	PR 2008	
1	which would entitle the applicant to conduct ope Title 18 U.C.S. Section 1001 and Title 43 U.S.C	erstion thereon. 2. Section 1212, makes it a crime for an	TV PETSON knowingly and willful	ly to make any departm	cut or agency of the	No. V	ON: 3	
:	States any false, fictitious or fraudulent statemer	nts or representations as to any matter w	vithin its jurisdiction.			R- WIL	1985.8 C	<u>Ş</u>
			NMOCI	D Do		Star Contraction	1292 St. 19	

orm 3160-5	UNITED	STATES	1	FORM APPROVED	
August 1999)	DEPARTMENT OF	F THE INTERIOR		udget Bureau No. 1004-0135	
	BUREAU OF LANE	D MANAGEMENT		xpires: Novepater 30, 2000	
CINDE	Y NOTICES AND REPO	ADTS ON WELLS		ease Serial No. IM-101990	
	this form for proposals to			Indian, Allottee or Tribe Name	
	well. Use Form 3160-3 (A)		P		
			7. 1	Unit or CA/Agreement, Name and	/or No.
SUBMIT	IN TRIPLICATE Other mitr	ncioni en avers: ade			
1. Type of Well			8. V	Vell Name and No.	
	as Well Other			EGINA RANCH FEDERAL	L 32 #1
2. Name of Operator	 T			PI Well No.	
Westerly Exploration,				0-043-20989	
		Phone No. (include area code) (505) 327 4807		ield and Pool, or Exploratory Area WILDCAT ENTRADA	
7415 East Main St. Farmin 4. Location of Well (Footage, Sec.,		(505) 327-4892		ounty or Parish, State	
435' FSL & 990' FWL Sec. 32		9	1	Sandoval County, New Mexi	ico
455 I 55 @ 576 I WE 600. 52	., 12514, 101 10				
2. CHECK	APPROPRIATE BOX(ES) TO INDICATE NATU	RE OF NOTICE, REPO	ORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION		
D Notice of Intent	Acidize	Deepen	Production (Start/Re	sume) 🔲 Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		ING &
	Change Plans	Plug and Abandon	Temporarily Abando	CEMENT REPO	ORT
Final Abandonment Notice	Convert to Injection	Piug Back	Water Disposal		
12/17/05: TD 7/78" hole at		stuck. Unable to free pipe		acked of pipe, leaving bit, bit su ate and condition hole to run ca	
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin) sx (1717 cu. ft.) CL "B" con	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at <u>7244</u> ' l ttaining 1/4# Flocele, 5# Gils	after multiple attempts. Bacop of fish at 7251'. Circul KB, with float collar at 72 conite, 1% Halad 9-2, 10%	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite.	
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 1 Cemented 1 stage with 1100 Bumped plug at 1500 psi.	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin) sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' l taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no	after multiple attempts. B op of fish at 7251 ¹ . Circul KB, with float collar at 72 conite, 1% Halad 9-2, 10% t circulate any cement to s	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. urface. Bond log	
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 1 Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin) sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 350'. Cemented 2nd stage with	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at <u>7244</u> ' l taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72 sonite, 1% Halad 9-2, 10% t circulate any cement to s i III lead cmnt containing	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite,	
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at <u>7244</u> " I taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. surface. Bond log 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite,	sing.
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, neld OK. Circulated 150 bbls of	sing.
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. aurface. Bond log 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, neld OK. Circulated 150 bbls of	sing.
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. aurface. Bond log 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, neld OK. Circulated 150 bbls of	sing.
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, held OK. Circulated 150 bbls of	sing.
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, held OK. Circulated 150 bbls of	sing.
12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 350. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug 9, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, 5# Gilsonite, teld OK. Circulated 150 bbls of B	sing.
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. (indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing Name (PrintedTyped) 	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 350. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug 9, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, 555# Gilsonite, held OK. Circulated 150 bbls of B	sing.
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 350. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug 9, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' h taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72' sonite, 1% Halad 9-2, 10% <u>t circulate any cement to s</u> ill lead cmnt containing tail cement containing 1/4	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, 5# Gilsonite, teld OK. Circulated 150 bbls of B	sing.
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. (indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing Name (PrintedTyped) 	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 350. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug 9, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' 1 taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05.	after multiple attempts. Bap of fish at 7251'. Circul KB, with float collar at 72 conite, 1% Halad 9-2, 10% t circulate any cement to s a III lead cmnt containing tail cement containing 1/4 e up casing to 1500 psi - h	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. aurface. Bond log 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, neld OK. Circulated 150 bbls of BOR DEFINITION	sing.
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. (indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing Name (PrintedTyped) 	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casin 9 sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 350. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug 9, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' 1 taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05.	after multiple attempts. Bap of fish at 7251'. Circul KB, with float collar at 72 conite, 1% Halad 9-2, 10% t circulate any cement to s a III lead cmnt containing tail cement containing 1/4 e up casing to 1500 psi - h	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, 5# Gilsonite, the ld OK. Circulated 150 bbls of BCC BCC BCC BCC BCC BCC BCC BCC BCC BC	sing. <u>f</u>
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing Name (Printed Typed) John C. Thompson	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casim) sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 50'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug o , set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' 1 taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. <u>Did no</u> h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05.	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72: conite, 1% Halad 9-2, 10% t circulate any cement to s i III lead cmnt containing 1/4 e up casing to 1500 psi - h Engineer / Agen	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 6 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, 5# Gilsonite, the ld OK. Circulated 150 bbls of BCC BCC BCC BCC BCC BCC BCC BCC BCC BC	sing. <u>f</u>
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at cement to surface. ND BOP 14. I hereby certify that the foregoing Name (PrintedTyped) John C. Thompson Signature	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casim) sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 50'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug o , set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' 1 taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05. Title Date FOR 14 DERAL OR	after multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72: conite, 1% Halad 9-2, 10% t circulate any cement to s i III lead cmnt containing 1/4 e up casing to 1500 psi - h Engineer / Agen	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, held OK. Circulated 150 bbls of R	sing. £
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 6 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I bereby certify that the foregoing Name (PrintedTyped) John C. Thompson Signature Signature pproved by onditions of approvel, if any, are attached.	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casim) sx (1717 cu. ft.) CL "B" con Open DV tool and circulate fo 350. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug . o, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' l taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. <u>Did no</u> h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05. Title Title	After multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72: sonite, 1% Halad 9-2, 10% t circulate any cement to s i III lead cmnt containing tail cement containing 1/4 e up casing to 1500 psi - 1 Engineer / Agen April 5, 2005	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. aurface. Bond log 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, reld OK. Circulated 150 bbls of B B B B B B B B B B B B B B B B B B B	sing. f f Son Hiscrof 7 2006
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 6 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 as 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing Name (Printed/Typed) John C. Thompson Signature Signature signature signature	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casim 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 50'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug of set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' l taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. <u>Did no</u> h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05. Title Title	After multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72 ionite, 1% Halad 9-2, 10% t circulate any cement to s i III lead crnnt containing tail cement containing 1/4 e up casing to 1500 psi - f Engineer / Agen April 5, 2005	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, teld OK. Circulated 150 bbls of Date APR 0 FARMINGTO	sing. £
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 as 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing Name (Printed/Typed) John C. Thompson Signature Signature signature signature signature	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casim 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 50'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug of r, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' 1 taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05. Title Date Tor resperse Title Construction of the second second second Title	After multiple attempts. B. op of fish at 7251'. Circul KB, with float collar at 72 conite, 1% Halad 9-2, 10% t circulate any cement to s ill lead cmnt containing tail cement containing 1/4 e up casing to 1500 psi - 1 Engineer / Agen April 5, 2005	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, reld OK. Circulated 150 bbls of Dete APR 0 FARMinkgTOI BY	sing. f 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5.
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 6 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 as 1% Halad 9-2, 10% HR-5 ar cement to surface. ND BOP 14. I hereby certify that the foregoing Name (Printed/Typed) John C. Thompson Signature Signature signature signature	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casim 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug of b, set slips and cut off casing. c, set slips and cut off casing.	stuck. Unable to free pipe a t 4-1/2" drill pipe in well. To ng. Landed casing at 7244' 1 taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 100 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05. Title Date FOR FEDERAL OR Title Title Title Title Title Title Title	After multiple attempts. B. po of fish at 7251'. Circul KB, with float collar at 72: sonite, 1% Halad 9-2, 10% t circulate any cement to s ill lead crmt containing tail cement containing 1/4 e up casing to 1500 psi - 1 Engineer / Agen April 5, 2005 FATE OFFICE USE Magnetic any department or	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, reld OK. Circulated 150 bbls of Dete APR 0 FARMinkgTOI BY	sing. f 5 5 5 5 7 2006
 12/17/05: TD 7/78" hole at shock sub, 20 ea. 6-1/4" dril 12/23/05: Ran 190 jts of 5 J Cemented 1 stage with 1100 Bumped plug at 1500 psi. 0 indicates top of cement at 43 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at 1% Halad 9-2, 10% HR-5 at cement to surface. ND BOP 14. I hereby certify that the foregoing Name (Printed/Typed) John C. Thompson Signature Sign	8693'. Drilling string became I collars, 4-1/2" weight pipe & 1/2", 17.0#, J-55 & N-80 casim 9 sx (1717 cu. ft.) CL "B" com Open DV tool and circulate fo 350'. Cemented 2nd stage with nd 8# silicalite. Followed by 4 nd 8# silicalite. Dropped plug of b, set slips and cut off casing. c, set slips and cut off casing.	stuck. Unable to free pipe a 4-1/2" drill pipe in well. To ng. Landed casing at 7244' 1 taining 1/4# Flocele, 5# Gils or 4 hrs while WOC. Did no h 700 sx (1092 cu. ft.) Type 400 sx (624 cu. ft.) Type III and closed DV tool, pressur Rig released 12/24/05. Title Date FOR SEE DERAL OR Coffice for any person providely and with	After multiple attempts. B. po of fish at 7251'. Circul KB, with float collar at 72: sonite, 1% Halad 9-2, 10% t circulate any cement to s ill lead crmt containing tail cement containing 1/4 e up casing to 1500 psi - 1 Engineer / Agen April 5, 2005 FATE OFFICE USE Magnetic any department or	acked of pipe, leaving bit, bit su ate and condition hole to run ca 03' KB, DV tool at 3518'. 5 HR-5 and 8# silicalite. 1/4# Flocele, 5# Gilsonite, # Flocele, C555# Gilsonite, reld OK. Circulated 150 bbls of Dete APR 0 FARMinkgTOI BY	sing. f 5 5 5 5 7 2006

,....



PBTD @ 7203' KB