## **BLACKWOOD & NICHOLS COMPANY**

Box 1237

DURANGO, COLORADO

261

June 20, 1961

761 MM

Mr. A. L. Porter Secretary-Director Oil Conservation Commission P. O. Box 871 Santa Fe, New Mexico

Dear Mr. Porter:

As operator of the Northeast Blanco Unit, we request permission to drill an unorthodox well to be located 1470' F/SL - 1250' F/WL, Section 30, T 31N, R6W, Rio Arriba County, New Mexico.

The normal location of this well is situated in such difficult topography, it is necessary to select a more suitable location for a drilling site.

Section 30, T 31N, R6W is a part of the Northeast Blanco Unit and the new location, as requested, will present no drainage problem to offset operators.

We enclose a location plat for the new location.

Very truly yours,

BLACKWOOD & NICHOLS COMPANY

DeLasso Loos

Field Superintendent

DL:lw Enclosure adm

Certificate No. 1941.

## NEW MEXICO OIL CONSERVATION COMMISSION Well Location and Acreage Dedication Plat

990 1320 1650 1980 2310 2640

Date: May 11, 1961 Section A. Operator BLACKWOOD & NICHOLS CO. Lease NORTHEAST BLANCO UNIT Well No. 62-30 Unit Letter L Section 30 Located 1470 Feet From southline, 1250 Township 31 N. Range Feet From west Line County Rio Arriba G. L. Elevetion 6365 UG Dedicated Acreage\_ Pool Blanco Mesa Verde Name of Producing Formation Mesa Verde 1. Is the Operator the only owner\* in the dedicated acreage outlined on the plat below? 2. If the anguer to question one is "no", have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes X No . If answer is "yes", Type of Consolidation Unitization 3. If the answer to question two is "no", list all the owners and their respective interests below: Land Description Cwner Section B This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief. Blackwood & Nichols Company (Operator) DeLasso Loos (Representative) Federal Land P.O. Box 1237, Durango, Colorado Address This is to certify that the well location shown on the plat in Section B was plotted from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief. Data Surveyed May 10, 1961 John A. Kroeger Registered Land Surveyor Durango, Colorado

1000

500°