MARTIN YATES, III

FRANK W. YATES 1936-1986



105 SOUTH FOURTH STREET ARTESIA, NEW MEXICO 88210-2118 TELEPHONE (505) 748-1471 S.P. YATES

JOHN A. YATES CHAIRMAN OF THE BOARD

PEYTON YATES

FRANK YATES, JR. EXECUTIVE VICE PRESIDENT

JOHN A. YATES, JR. SENIOR VICE PRESIDENT

October 10, 2006

Mr. Larry Johnson NMOCD District I 1625 French Drive Hobbs, NM 88240

RE: Amanda AMN Federal #1 1-RP#933 Section 11, T23S-R32E Lea County, New Mexico

Dear Mr Johnson,

Enclosed are requested pictures of the excavation area and the release area.


Thank you for your assistance in this matter.


YATES PETROLEUM CORPORATION


Robert Asher Environmental Regulatory Agent


/rca



















est '	•							
Hobbs NM 88240	State of New Mexico				Form C-141			
Avenue, Artesia, NM 88210	Energy Minerals and Natural Resources				Revised October 10, 2003			
vazos Road Aztec NM 87410	Oil Conservation Division 1220 South St. Francis Dr.				Submit 2 Copies to appropriate District Office in accordance			
	St. Francis Dr. with Rule 116 on back side of form							
Release Notification and Corrective Action								
OPERATOR Initial Report Final Report								
Name of Company OGRID Nun	Contact							
YATES PETROLEUM CORPORATION 25575 Address				ROBERT ASHER Telephone No.				
104 S. 4 TH STREET	505-748-1471							
Facility Name API Number	Facility Type WATER LINE							
Surface OwnerMineral OFEE - STACY MILLSFEDERA	Lease NM-77							
LOCATION OF RELEASE								
		/South Line	Feet from the	East/West Li	West Line County			
F 11 23S 32E 2310	1	NORTH	1650	EAST	LEA	i		
Latitude 32.32016 Longitude 103.64814								
NATURE OF RELEASE								
Type of Release				e Recovered	Recovered			
PRODUCED WATER & OIL	180 B/PW & 4 B/O0 B/PW & 0 B/ODate and Hour of OccurrenceDate and Hour of Discovery							
Source of Release WATER LINE	4/27/2006 PM 4/27/2006 AM							
Was Immediate Notice Given?	equired	If YES, To Whom? LARRY JOHNSON						
By Whom?	Date and Hour							
ROBERT ASHER Was a Watercourse Reached?	4/28/2006 (V/M APPROXIMATELY 9:00 AM; E-MAIL @ 11:23 AM) If YES, Volume Impacting the Watercourse.							
🗌 Yes 🛛 No	N/A							
If a Watercourse was Impacted, Describe Fully.* N/A								
Describe Cause of Problem and Remedial Action Taken.* WATER LINE SPLIT DUE TO COLD WELD. WATER LINE REPAIRED.								
Describe Area Affected and Cleanup Action Taken.* AN APPROXIMATE AREA OF 15' X 650', (LEAK IS APPROX. 300' NW FROM THE TANK BATTERY). REPAIRS MADE, CONTAMINATED SOILS WERE EXCAVATED, PLACED ON PLASTIC AND FENCED OFF. AREA TO BE EVALUATED. SITE RANKING IS 0.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.								
Signature: SALA,	OIL CONSERVATION DIVISION							
Printed Name: Robert Asher	Approved by District Supervisor:							
Title: Environmental Regulatory Agent	Approval Date: Expir		Expirat	ration Date:				
E-mail Address: boba@ypcnm.com	Conditions of Approval:		Attached 🔲					
Date: Thursday, May 04, 2006 Phone: 505-748-147								

* Attach Additional Sheets If Necessary