
NORTHWEST PIPELINE CORPORATION

PRODUCTION & DRILLING POBOX 90 FARMINGTON. NEW MEXICO 87499 5112-4-84




SANTA ET

NSP-1412 Rule 104DI S/2 Section 25

January 13, 1984

Mr. R. L. Stamets NMOCD P.O. Box 2088 Santa Fe, N.M. 87501



Dear Mr. Stamets:

Northwest Pipeline Corporation requests permission to complete the Gallup formation in the above captioned well in an unorthodox location due to topography. This location was previously approved for the Dakota formation by Administrative Order NSL-1652 dated February 14, 1983.

The South half of Section 25 has been dedicated to the Gallup well. The South half consists of 270.04 acres and is Non-Standard due to a variation in the legal subdivision of the U.S. Public Land Survey. Northwest requests permission to produce the Gallup as a Non-Standard Gas Unit. A Non-Standard Gas Proration Unit was approved for the Dakota formation on September 28, 1983.

An application to commingle the Gallup and Dakota formations has previously been submitted for your consideration.

Sincerely,

and C. Thompson

Paul C. Thompson Sr. Drilling Engineer

PCT:djb Enclosure NORTHWEST PIPELINE CORPORATION

PRODUCTION & DRILLING P 0 BOX 90 FARMINGTON, NEW MEXICO 87499 5112-2-84

CONSERVATIO OH: ULC: NOR SANTA PE

January 13, 1984

Mr. David Poage EPNG P.O. Box 289 Farmington, N.M. 87499

Re: Non-Standard Location San Juan 30-5 Unit #91 835 FWL & 1950 FSL Section 25, T30N, R5W

Dear Mr. Poage:

Northwest Pipeline has requested permission from the NMOCD to complete the Gallup formation in the above referenced well in a Non-Standard Location due to topographical reasons. Our records show you to be the owners of some offset acreage. Notify Joe Ramey, with the NMOCD in Santa Fe, New Mexico, within 20 days if you have any objections to this location. This letter is being sent by certified mail in accordance with NMOCD regulations.

Sincerely,

aul C. Thompson

Paul C. Thompson Sr. Drilling Engineer

PCT:djb

NORTHWEST PIPELINE CORPORATION

PRODUCTION & DRILLING P.O. BOX 90 FARMINGTON, NEW MEXICO 87499

5112-3-84



January 13, 1984

Mr. A.M. Roney Amoco Production Company 1670 Broadway, Suite 750 Amoco Building Denver, Colo 80202

Re: Non-Standard Location San Juan 30-5 Unit #91 835 FWL & 1950 FSL Section 25, T30N, R5W

Dear Mr. Roney:


Northwest Pipeline has requested permission from the NMOCD to complete the Gallup formation in the above referenced well in a Non-Standard Location due to topographical reasons. Our records show you to be the owners of some offset acreage. Notify Joe Ramey, with the NMOCD in Santa Fe, New Mexico, within 20 days if you have any objections to this location. This letter is being sent by certified mail in accordance with NMOCD regulations.

Sincerely,

and C. Thompson

Paul C. Thompson Sr. Drilling Engineer

PCT:djb



Ć

R5W

.

R4W

Ţ

7 30 N

.....

P.O. Box 289


CENT TO


STREET AND

ા ગયુ ને સ્પ્રેલ્લક)

'5

EPNG - David Poage





PSI