




PHILLIPS OIL COMPANY

A SUBSIDIARY OF PHILLIPS PETROLEUM COMPANY

EXPLORATION AND PRODUCTION GROUP
Permian Basin Region

ODESSA, TEXAS 79762
4001 PENBROOK

January 11, 1984



NSL-1788
Rule 104 F (I, III)

Verbal given 1/18/84

Re: Unorthodox Location -

Burch B #36, 530' FW & 1300' FS Lines,
Unit M, Sec. 23, T-17-S, R-29-E, Eddy
County
Grayburg-Jackson Pool

Federal lease

New Mexico Department of Energy & Minerals - 3
Oil Conservation Division
P. O. Box 2088,
Santa Fe, New Mexico 87501

Attention: Mr. Gilbert Quintana

Gentlemen:

Enclosed are copies of subject filing originally mailed November 9, 1983, which have apparently been lost in the mail. This request is re-submitted in this manner per our conversation earlier today.

Please note that copies were originally mailed to pertinent offset operators and that receipt cards indicate they were received by all parties on November 10, 1983. Marybob Energy Corporation responded by waiver of objections (copy also attached) with no response received from other parties.

I trust you will be able to process this application on receipt. Please feel free to call me collect if you have a question -- telephone (915) 367-1257. Your consideration is appreciated.

Yours very truly,

T. Harold McLemore
Regulation and Proration Supervisor


THM:se
Enclosures



marbob

energy corporation

November 11, 1983



OIL CONSERVATION DIVISION
SANTA FE

Mr. Joe D. Ramey
Division Director
Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87501

RE: Phillips Oil Company
Unorthodox Location-
Burch B No. 36, 530'
FWL & 1300' FSL,
Section 23, T-17S, R-29E,
Eddy County, New Mexico

Dear Sir:

Marbob Energy Corporation has no objection to the proposed unorthodox location. If there are any changes in Phillips Oil Company's request we would like to be advised of them.

Thanks for your help in this matter.

Sincerely,

Ray Miller

Ray Miller
Secretary-Treasurer

RM:kmh

cc: T. Harold McLemore
Regulation and Proration Supervisor
Phillips Oil Company
4001. Penbrook
Odessa, Texas 79762

CC: JAM
11/18/83



PHILLIPS OIL COMPANY

A SUBSIDIARY OF PHILLIPS PETROLEUM COMPANY

EXPLORATION AND PRODUCTION GROUP
Permian Basin Region


ODESSA, TEXAS 79762
4001 PENBROOK

November 9, 1983

Re: Unorthodox Location -
Burch B No. 36, 530' FW & 1300' FS
Lines, Unit M, Sec. 23, T-17-S,
R-29-E, Grayburg-Jackson Pool,
Eddy County, New Mexico

New Mexico Department of Energy & Minerals - 3
Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87501

Attention: Mr. Joe D. Ramey
Division Director



Gentlemen:

We respectfully request an exception to Statewide Rule No. 104 (C)(1) for, and administrative approval under Statewide Rule 104 (F)(I,III) of the unorthodox location of the Burch B Well No. 36 - 530 feet from west and 1300 feet from south lines, Unit M, Section 23, T-17-S, R-29-E, Eddy County. This well is a proposed Grayburg-Jackson Pool oil completion with a projected total depth of 3500 feet. Further, it is in the same proration unit as the Grayburg-Keely Unit Tract BB No. 2 as well as the Burch B No. 35 (a proposed well). The above location for Well No. 36 exceeds the required 330 feet minimum distance from any other well in its proration unit. Form C-102 is attached.

The Burch B lease is a Federal lease. The proposed unorthodox location is necessary to secure archeological clearance for drillsite construction in this segment of the proration unit.

Offset operators are notified of this request by certified mail copy hereof. Attention is called to the 20 day time limit for lodging objections to the proposed location with the Oil Conservation Division and Phillips.

Your consideration and advice will be appreciated.

Very truly yours,

T. Harold McLemore
Regulation and Proration Supervisor

THM:ss

Attachments

cc: Oil Conservation Division, Artesia, New Mexico
Bureau of Land Management, U. S. Dept. Of Interior, Roswell, New Mexico
Offset Operators - Addressee List Attached

Attachments

Unorthodox Location

Burch-B No. 36

530' FW & 1300' FS Lines, Unit M, Sec. 23, T-17-S, R-29-E
Grayburg Jackson Pool, Eddy County, New Mexico

Burch B 36
West Offset
Marbob Energy Corp.
Box 304
Artesia, New Mexico 88210

Moran Exploration, Inc.
400 Wilco Bldg.
Midland, TX 79701

Southwest Offset
Southland Royalty Company
21 Desta Drive
Midland, TX 79701

NEW MEXICO OIL CONSERVATION COMMISSION
WELL LOCATION AND ACREAGE DEDICATION PLAT

Form C-102
Supersedes C-128
Effective 1-1-83

All distances must be from the outer boundaries of the Section


Operator PHILLIPS OIL CO.			Lease BURCH B			Well No. 36		
Grid Letter M	Section 23	Township 17S	Range 29E	County EDDY				
Actual Footage Location of Well: 1300 feet from the SOUTH line and 530 feet from the WEST line								
Ground Level Elev. 3579.0 (Unprepared)		Producing Formation SR-Q-Gb-SA		Pool Grayburg-Jackson			Dedicated Acreage: 40 Acres	

1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☐ Yes ☐ No If answer is "yes" type of consolidation _____


If answer is "no" list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) _____

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission.

D	C			A
E	F			G
L	K	J	I	
M	N	P		

330' 343.5' 665' 100'

Grayburg-Keely Unit Tract BB #2



CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

T. Harold McLemore

Name

T. Harold McLemore

Position

Regulation & Proration Super

Company

Phillips Oil Company

Date

November 8, 1983


I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed

11/2/83

Registered Professional Engineer and/or Land Surveyor

John W. West



PHILLIPS OIL COMPANY
Burch B # 36 - Unorthodox Location
M, 23, 17, 29, Eddy County, N. Mexico
Grayburg Jackson Pool

AYBURG JACKSON
EST CO-OP UNIT

INNECO (OPER.)

SO ROY (OPER.)
ROBINSON JACKSON
CO-OP UNIT

U-16154 297723.00

Tr 10-A Tr 10-B

Tr 34 Tr 36

Tr 16 Tr 15

Tr 24 Tr 25


Tr 30 Tr 31

Tr 32 Tr 33

Tr 34 Tr 35


Tr 36

PHILLIPS OIL COMPANY
SUBSIDIARY OF PHILLIPS PETROLEUM COMPANY
EXPLORATION AND PRODUCTION GROUP
OIL BASIN REGION
PENBROOK
ARLINGTON, TEXAS 79762



Marbob Energy Corp.
Box 304
Artesia, New Mexico 88210

PHILLIPS OIL COMPANY
SUBSIDIARY OF PHILLIPS PETROLEUM COMPANY
EXPLORATION AND PRODUCTION GROUP
OIL BASIN REGION
PENBROOK
ARLINGTON, TEXAS 79762





Southland Royalty Company
21 Desta Drive
Midland, Texas 79701

PHILLIPS OIL COMPANY

SUBSIDIARY OF PHILLIPS PETROLEUM COMPANY

EXPLORATION AND PRODUCTION GROUP
OILIAN BASIN REGION
PENBROOK
MIDLAND, TEXAS 79762




CERTIFIED

P 273 888-620

MAIL

Moran Exploration, Inc.
400 Wilco Building
Midland, Texas 79701



PS Form 3811, Dec. 1980

SENDER: Complete items 1, 2, 3, and 4.
Add your address in the "RETURN TO" space on reverse.

(CONSULT POSTMASTER FOR FEES)

1. The following service is requested (check one).
☒ Show to whom and date delivered
☐ Show to whom, date, and address of delivery
2. ☐ RESTRICTED DELIVERY
(The restricted delivery fee is charged in addition to the return receipt fee.)

TOTAL \$

3. ARTICLE ADDRESSED TO:
Moran Exploration, Inc.
400 Miles Bldg.
Midland, Texas 79701

4. TYPE OF SERVICE: ARTICLE NUMBER
☐ REGISTERED ☐ INSURED
☒ CERTIFIED ☐ COD
☐ EXPRESS MAIL

(Always obtain signature of addressee or agent)

I have received the article described above.
SIGNATURE ☐ Addressee ☐ Authorized agent

5. DATE OF DELIVERY
11/10/83

6. ADDRESSEE'S ADDRESS (Only if requested)

7. UNABLE TO DELIVER BECAUSE:

7a. EMPLOYEE'S INITIALS

POSTMARK
NOV 10 1983

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

PS Form 3811, Dec. 1980

SENDER: Complete items 1, 2, 3, and 4.
Add your address in the "RETURN TO" space on reverse.

(CONSULT POSTMASTER FOR FEES)

1. The following service is requested (check one).
☒ Show to whom and date delivered
☐ Show to whom, date, and address of delivery
2. ☐ RESTRICTED DELIVERY
(The restricted delivery fee is charged in addition to the return receipt fee.)

TOTAL \$

3. ARTICLE ADDRESSED TO:
Market Energy Corp.
Box 304
Artesia, New Mexico 88210

4. TYPE OF SERVICE: ARTICLE NUMBER
☐ REGISTERED ☐ INSURED
☒ CERTIFIED ☐ COD
☐ EXPRESS MAIL

(Always obtain signature of addressee or agent)

I have received the article described above.
SIGNATURE ☐ Addressee ☐ Authorized agent

5. DATE OF DELIVERY
11/10/83

6. ADDRESSEE'S ADDRESS (Only if requested)

7. UNABLE TO DELIVER BECAUSE:

7a. EMPLOYEE'S INITIALS

POSTMARK
NOV 10 1983

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

PS Form 3811, Dec. 1980

SENDER: Complete items 1, 2, 3, and 4.
Add your address in the "RETURN TO" space on reverse.

(CONSULT POSTMASTER FOR FEES)

1. The following service is requested (check one).
☒ Show to whom and date delivered
☐ Show to whom, date, and address of delivery
2. ☐ RESTRICTED DELIVERY
(The restricted delivery fee is charged in addition to the return receipt fee.)

TOTAL \$

3. ARTICLE ADDRESSED TO:
Royalty Company
21 Santa Drive
Midland, Texas 79701

4. TYPE OF SERVICE: ARTICLE NUMBER
☐ REGISTERED ☐ INSURED
☒ CERTIFIED ☐ COD
☐ EXPRESS MAIL

(Always obtain signature of addressee or agent)

I have received the article described above.
SIGNATURE ☐ Addressee ☐ Authorized agent

5. DATE OF DELIVERY
11/10/83

6. ADDRESSEE'S ADDRESS (Only if requested)

7. UNABLE TO DELIVER BECAUSE:

7a. EMPLOYEE'S INITIALS

POSTMARK
NOV 10 1983

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

Wildlife Refuge

