LOGGED IN 9/7/07

TYPE NSL

APP NO. O TDS 0725055365

ABOVE THIS LINE FOR DIVISION USE ONLY

# NEW MEXICO OIL CONSERVATION DIVISION

- Engineering Bureau -

1220 South St. Francis Drive, Santa Fe, NM 87505



### ADMINISTRATIVE APPLICATION CHECKLIST

HECKLIST 56

THIS CHECKLIST IS MANDATORY FOR ALL ADMINISTRATIVE APPLICATIONS FOR EXCEPTIONS TO DIVISION RULES AND REGULATIONS WHICH REQUIRE PROCESSING AT THE DIVISION LEVEL IN SANTA FE **Application Acronyms:** [NSL-Non-Standard Location] [NSP-Non-Standard Proration Unit] [SD-Simultaneous Dedication] [DHC-Downhole Commingling] [CTB-Lease Commingling] [PLC-Pool/Lease Commingling] [PC-Pool Commingling] [OLS - Off-Lease Storage] [OLM-Off-Lease Measurement] [WFX-Waterflood Expansion] [PMX-Pressure Maintenance Expansion] [SWD-Salt Water Disposal] [IPI-Injection Pressure Increase] [EOR-Qualified Enhanced Oil Recovery Certification] [PPR-Positive Production Response] [1] **TYPE OF APPLICATION** - Check Those Which Apply for [A] Location - Spacing Unit - Simultaneous Dedication NSL NSP SD Check One Only for [B] or [C] [B]Commingling - Storage - Measurement ☐ DHC ☐ CTB ☐ PLC ☐ PC ☐ OLS ☐ OLM [C] Injection - Disposal - Pressure Increase - Enhanced Oil Recovery ☐ WFX ☐ PMX ☐ SWD ☐ IPI ☐ EOR ☐ PPR [D]Other: Specify [2] **NOTIFICATION REQUIRED TO: -** Check Those Which Apply, or Does Not Apply Working, Royalty or Overriding Royalty Interest Owners [B] Offset Operators, Leaseholders or Surface Owner Application is One Which Requires Published Legal Notice [C] [D]Notification and/or Concurrent Approval by BLM or SLO U.S. Bureau of Land Management - Commissioner of Public Lands, State Land Office [E]For all of the above, Proof of Notification or Publication is Attached, and/or, [F] Waivers are Attached [3] SUBMIT ACCURATE AND COMPLETE INFORMATION REQUIRED TO PROCESS THE TYPE OF APPLICATION INDICATED ABOVE. [4] **CERTIFICATION:** I hereby certify that the information submitted with this application for administrative approval is accurate and complete to the best of my knowledge. I also understand that no action will be taken on this application until the required information and notifications are submitted to the Division. Note: Statement must be completed by∕an individual with managerial and/or supervisory capacity. Print or Type Name Signature



P. O. Box 640 Aztec, NM 87410 (505) 634-4222 (505) 634-4205 (fax) Heather.riley@williams.com

September 4, 2007

Mark E. Fesmire NEW MEXICO OIL CONSERVATION DIVISION 1220 South Saint Francis Drive Santa Fe, NM 87505

Request for Administrative approval for non-standard Dakota Location

Rosa Unit #85C API # 30-039-30220 Sec. 20, T31N, R5W 2,310' FNL & 330' FEL

### Dear Mr. Fesmire:

Re:

Williams Production Co., LLC, is requesting administrative approval to construct the Rosa Unit #85C as a dual Mesaverde/Dakota with the Dakota being non-standard. Pursuant to Order No. R-10987-B(2), spacing requirements allow for up to 4 Dakota wells in a standard GPU and they shall be located not closer than 660 feet to the outer boundary of the GPU and not closer than 10 feet to any interior quarter or quarter-quarter section line or subdivision inner boundary. Given these requirements, this location is non-standard to the east by 330 feet and to the south by 330 feet.

Williams intends to make the well a dual well thereby capturing the reserves from the Dakota with a single well bore. By itself the Dakota in this area is at best very marginal economically and a dual completion helps capture additional reserves from the Dakota that otherwise would not be able to be economically developed. Utilizing a single well bore for a dual completion would also negate the need for additional disturbance of another wellpad, road, and pipeline.

The surface location was picked by considering drainage patterns from the offset Mesaverde wells. In particular, the drainage patterns we are trying to avoid are from the Rosa Unit #153 in the southeast of 17, the Rosa Unit #85 in the northeast of 20, the Rosa Unit #85A in the northeast of 20, and the Rosa Unit #17A in the southeast of 20. See drainage map.

Mark E. Fesmire September 4, 2007 Page 2 of 2

As the Unit Operator of the Rosa Unit, Williams Production is the only offset operator, thereby this proposed non-standard location would not affect any other operators.

The offset unit's working interest and mineral owners are not common with the subject unit; however, there are no unleased mineral owners so notice is not required.

Enclosed for your reference are copies of the Participating Area maps for the Mesaverde and Dakota Formations. All of section 20 and the west half of section 21 are in the PA in the Mesaverde Formation. Neither section 20 nor 21 are in the PA in the Dakota formation.

The spacing unit for the Mesaverde is the north half of the section and the other Mesaverde wells in the spacing unit are the Rosa Unit #85, #85A and #85B.

The spacing unit for the Dakota is the north half of the section and the Rosa Unit #85 is the only other Dakota well in the spacing unit.

Should you have any questions or concerns, please don't hesitate to contact me at the phone numbers listed above. You can also contact Vern Hansen at our Tulsa office at (918) 573-6169.

Regulatory Specialist

Enc.: 1<sup>st</sup> page of APD

Plat

Topographic map Drainage Map

PA Maps (MV & DK)

(September 2001)

# **UNITED STATES** DEPARTMENT OF THE INTERIOR

APPLICATION FOR PERMIT TO DRILL OR REENTER

**BUREAU OF LAND MANAGEMENT** 

	_			
5.	1	ease	Serial	No.

NMSF-0078764
6. If Indian, Allottee or Tribe Name

OMB No. 1004-0136 Expires January 31, 2004

		ח <u>ל</u>	77 1110	_ O _ AM	7. 110	
la. Type of Work: DRILL REE	ENTER	L	or Henn	O RIT		eement, Name and No.
			REI	CEIVED		<u> </u>
lb. Type of Well:		☑ Single Zone	☐ Multi	iple Zone	8. Lease Name and W 85C	/eii No.
2. Name of Operator		2	10 FAR	EMETO	9. API Well No.	
Williams Production Company, LLC					30-039-	30220
3a. Address	3b. Pl	none No. (include a	rea code)		10. Field and Pool, or	Exploratory
P.O. Box 640 Aztec, NM 87410		(505) 634-4208			Blanco Mesave	erde
4. Location of Well (Report location clearly and in accordance wit	th any State re	equirements. *)			11. Sec., T., R., M., o	r Blk. and Survey or Area
At surface 685' FNL & 835' FEL						
At proposed prod. zone 2310' FNL 330' FEL					Section 20, 31	N R.5W
14. Distance in miles and direction from nearest town or post office	ce*				12. County or Parish	13. State
approximately 32 miles northeast of Blanco, New Mex	ico ·				Rio Arriba	l _ NM_
15. Distance from proposed* location to nearest property or lease line, ft.	16. 1	No. of Acres in leas	se .	17. Spacing	g Unit dedicated to this	well
(Also to nearest drig. unit line, if any)330'		2,507.30			.0 (N/2)	
18. Distance from proposed location* to nearest well, drilling, completed, applied for, on this lease, ft.	. 19. I	Proposed Depth 6,741'		20. BLM/E	IA Bond No. on file  347	9
21. Elevations (Show whether DF, KDB, RT, GL, etc.)	22. /	Approximate date	work will s		23. Estimated duration	on
6,429' GR		April 1, 2007			1 month	
	24	. Attachments				
The following, completed in accordance with the requirements of O	Onshore Oil a	nd Gas Order No.1,	shall be att	ached to this	form:	
<ol> <li>Well plat certified by a registered surveyor.</li> <li>A Drilling Plan.</li> <li>A Surface Use Plan (if the location is on National Forest Sys SUPO shall be filed with the appropriate Forest Service Off</li> </ol>		the 5. Opera 6. Such	20 above). itor certific	ation.	·	existing bond on file (see
25. Signature		Name (Printed/Typ	ned)			Date
Larry Mices		Larry Higgi	ns			3-7-01
Title						
Drilling COM						
Approved by Signature) Man Carlota	$\bigcirc$	Name (Printed/Typ	oed)			Date 4/9/05
Title AM		Office T	<b>-</b>			
Application approval does not warrant or certify that the applicant h	holds legal or	equitable title to th	ose rights ir	the subject 1	ease which would entitl	e the applicant to conduct
operations thereon. Conditions of approval, if any, are attached.						

\*(Instructions on reverse)

Williams Exploration and Production Company, LLC, proposes to drill a well to develop the Blanco Mesaverde formation at the above described location in accordance with the attached drilling and surface use plans.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

The well pad surface is under jurisdiction of the Bureau of Land Management, Farmington Field Office (BLM/FFO).

This location has been archaeologically surveyed La Plata Archaeological Consultants. Copies of their report have been submitted directly to the BLM.

An approximately 250.00-foot access road is needed to access this location. A pipeline tie of 292.50 feet would be required for this location, Williams Field Services has filed a pipeline route plan for the associated pipeline. The pipeline would be owned and operated by Williams Field Services.

**OPERATOR** 

District I 1625 N. French Dr., Hobbs, NM 88240

District III

State of New Mexico
Energy, Minerals & Natural Resources Department

Form C-102 Revised October 12, 2005 Instructions on back Submit to Appropriate District Office

District II 1301 W. Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe. NM 87505 State Lease - 4 Copies Fee Lease - 3 Copies

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505


AMENDED REPORT

### WELL LOCATION AND ACREAGE DEDICATION PLAT


'API Number 30-039-30		'Pool Code 'Pool Name 72319 / 71599 BLANCO MESAVERDE / BASIN DAKOTA				
Property Code			operty Name OSA UNIT	*Well Number 85C		
'OGRID No 120782		-,-	erator Name RODUCTION COMPANY	*Elevation 6429		
10 Surface Location						

DOLLARE FORGETON Lot Idn Feet from the UL or lot no. Section Township North/South line Feet from the East/West line RIO 685 Δ 50 31N 5W NORTH 835 EAST ARRIBA <sup>11</sup>Bottom Hole Location If Different From Surface UL or lot no. Lot Idn North/South line Feet from the Sect ion Township Range Feet from the East/West line RIO H 20 31N 5W 2310 NORTH 330 EAST ARRIBA 12 Dedicated Acres <sup>13</sup> Joint or Infill 14 Consolidation Code <sup>55</sup> Order No. 320.0 Acres - (N/2)

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



# WILLIAMS RODUCTION COMPANY ROS, JNIT #850 685' FNL & 835' FEL, SECTION 20, T3IN, R5W, N.M.P.M. RIO ARRIBA COUNTY, NEW MEXICO £ Brak 6288 309A



Name Disease NM V	Projection: NAD 1983 State Plane NM West	2 2 2 200															Contraction of the last of the	A. A
lew Mexico	Rosa Unit Dakota Formation San Juan and Rio Arriba Counties, New Mexico	San Juan and															Fee Partially Committed State	Fee Partially State
Williams	Exporation & Production	William's E														18th Expansion	Dakota Pancipating Area-18th Expansion	Dakota Paris
	5		55		*		12	3	10		D.	3	12	4	36		* 1	7
			T-30-N R-4-W	7-30-					T-30-N R-5-W	T-30		1			T-30-N R-6-W	T-30-N		
						3				Б	AN .	光			ы	ŭ.	v	b
	¥	<b>3</b>		8	12	\$1.00 SF-07774	36. SF-077748	35 96-019773	3.4 96-078773	8491113	5307	50 34 50 50 50 50 50 50 50 50 50 50 50 50 50	35	3	E		15	
	SF-078887	7000		SF-078894	35-078884	55-079777 11-4 11-4 11-4 11-4 11-4 11-4 11-4 1	SF-071788	SF-078768	SF-078770	SF-078769	Security of	24-018188	SF-078788	SF-078771				
	25		State of the state	28	29	SF-018774	25)	7	27	20	कु-ताका क कु-ताका क	S   #S   #S	28	26	27	28	3	30
	55-074887	SF-078893	SF-072893	SF-078893	55-478889	TAN DE-OTHERS	SF-076768	5F-078768	SF-078770	SF-078789	SPOTSTAL SE	PLEIDE SEGIETA	SE-OTRIPE	as-orariu	\$5-078768	Section	7	~
	2		7-31-N R-4-W	7-37-1	20	19 19 miles	22.44	\$5-078770 16	PR .	24 L. C. L.	SF-078764	1	E CONTRACTOR OF THE PARTY OF TH	1-37-N K-6-W	1-37-N	E-189	la la	19
	95-071887	SF-078892	SF-078892	SF-078892	55-072449	SF-071889	SF-078762	SF-078762	SF-GT87TO	SF-GT8789	SEGINTES	SF-078764	S-Didnet	SF-078771	SF-078765	) mes	Spores	
	7	7	#	16	17	18 175 176 176 176 176 176 176 176 176 176 176	7	14	d d	16		1 # E E	25 2100 CHAT	74	ange of the state	25 ES		3
	SF-0718877	55-078888	5F-078488	SF-078888	55-078888	2 St-011890	SF-078762	SF-078762	\$F-078770	SF-078763	SECTIONS	N. S. OTE781	SE-OTHERS.	SE-OTITY	\$ 2 B	SF-078765	SF-078765	
	12	=	10	10	1	A SE SE	7		SFOIRTAZ		SF-078767	N   M	Name (1. part)			10	SF-078765	4
	SEC078881 0.54 0.54	57-072891	SF-078891	SF-07#890	SF-078890	12.00 10.00 10.00	1		SF-078783	SF-078763	SEATURE STATES	114 SF-011167	SF-078172	2 Same	SF-078TT2	SF-078772	SF-074765	Ø)
	8- 8- 8- 8- 8- 8- 8- 8- 8- 8- 8- 8- 8- 8	25 25 25	is a second	44 A4 A	100 mg		38	15	1	23	25	5-346	E-14	35 72 8F-078772	34 34 SECTION 34	55.00 SE-011172	1	31
	3		R		13										~	T-32-N R-6-W	-7-	
	7		T-32-N R-4-W	T-32-			25	26	R-5-W	T-32-N R-5-W	Ç.	30	25	28		County	29	30
30 29					90		-						County	and the same of th	1			

Map Document: (G:Project/San\_Juan/Rosa\_Unit/Participating\_Areas/rosa-unit\_dk\_pa.n 3/7/2007 -- 11:03:28 AM

## Brooks, David K., EMNRD

From: Brooks, David K., EMNRD

Sent: Wednesday, October 03, 2007 1:46 PM

To: 'Riley, Heather (E&P)'

Subject: Rosa Unit #85C

### Heather

I am looking at you NSL application for the referenced well.

This is an application for an NSL in the Dakota. You state that the unit is not in the Dakota PA, and that the working interest ownership is not common between the subject unit and the offsetting units. If that is correct, notice is required to all working interest owners in offsetting Dakota units to the east, south, and, if applicable, to the southeast. You have correctly concluded that notice to mineral owners is not required, but notice to WI owners is required. See Section 19.15.14.1210.A(2)(b) NMAC.

Please advise us who these owners are and furnish proof of notice.

Please call if you have questions.

David K. Brooks Legal Examiner 505-476-3450

## Brooks, David K., EMNRD

From: Riley, Heather (E&P) [Heather.Riley@Williams.com]

Sent: Tuesday, October 09, 2007 2:13 PM

To: Brooks, David K., EMNRD

Cc: Hansen, Vern (E&P); Higgins, Larry (E&P); Winters, Lacey (E&P)

Subject: RE: Rosa Unit #85C

### David.

It looks like my letter was incorrect concerning the working interest ownership. I forwarded your email on to our land department and received this clarification:

The Rosa Unit #85C Dakota well has a dedication of the N/2 of Sec. 20, T31N, R5W. The working interest ownership is common with the S/2 of Sec. 20, and all of Sec. 21 to the East. BP is the working interest owner of all of Sections. 20 and 21, T31N, R5W which covers the acreage being encroached upon.

Will this email suffice to correct the application?

Heather Riley Regulatory Specialist Williams Production Co., LLC (505) 634-4222 (office) (970) 749-8747 (cell)

From: Brooks, David K., EMNRD [mailto:david.brooks@state.nm.us]

Sent: Wednesday, October 03, 2007 2:46 PM

**To:** Riley, Heather (E&P) **Subject:** Rosa Unit #85C

Heather

I am looking at you NSL application for the referenced well.

This is an application for an NSL in the Dakota. You state that the unit is not in the Dakota PA, and that the working interest ownership is not common between the subject unit and the offsetting units. If that is correct, notice is required to all working interest owners in offsetting Dakota units to the east, south, and, if applicable, to the southeast. You have correctly concluded that notice to mineral owners is not required, but notice to WI owners is required. See Section 19.15.14.1210.A(2)(b) NMAC.

Please advise us who these owners are and furnish proof of notice.

Please call if you have questions.

David K. Brooks Legal Examiner 505-476-3450

Confidentiality Notice: This e-mail, including all attachments is for the sole use of the intended recipient

### Well File Search - Select API Number to View

Please select the API Number you wish to view from the list below by clicking the radio button next to the API Number. Then click the "Continue" button to see the thumbnails for the API you selected. The search results are broken out by groups of 25 on each page. Switching pages can be done by clicking the "Next 25" or "Previous 25" links.

15 Records Found

Displaying Screen 1 of 1

	API Number	ULSTR	Footages		
$\bigcirc$	3003907952	M -20-31N-5W	990 FSL & 990 FWL		
	Well Name & Number: ROS				
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	.C N = M		
$\bigcirc$	3003922778	A -20-31N-5W	800 FNL & 990 FEL DIC / M (		
	Well Name & Number: ROS		•		
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	.C		
$\bigcirc$	3003923750	L -20-31N-5W	1470 FSL & 960 FWL		
	Well Name & Number: PRE	E-ONGARD WELL No. 121			
	Operator: PRE-ONGARD	WELL OPERATOR			
$\bigcirc$	3003924357	M -20-31N-5W	1300 FSL & 955 FWL		
	Well Name & Number: PRE	E-ONGARD WELL No. 232	2		
	Operator: PRE-ONGARD	WELL OPERATOR			
$\bigcirc$	3003924643	M -20-31N-5W	1310 FSL & 985 FWL		
	Well Name & Number: ROSA UNIT No. 232				
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL			
$\bigcirc$	3003924962	B -20-31N-5W	1205 FNL & 1765 FEL FC		
	Well Name & Number: ROS	SA UNIT No. 321			
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	.C		
$\bigcirc$	3003925576	O -20-31N-5W	790 FSL & 1450 FEL		
	Well Name & Number: ROS	SA UNIT No. 017A			
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	.C		
$\bigcirc$	3003926272	O -20-31N-5W	790 FSL & 1450 FEL		
	Well Name & Number: ROS	SA UNIT No. 017A			
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	.C		
$\bigcirc$	3003926314	B -20-31N-5W	1185 FNL & 1845 FEL $\mathcal{H} V$		
	Well Name & Number: ROS		·		
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	_C		
$\bigcirc$	3003926947	D -20-31N-5W	10 FNL & 10 FWL M		
	Well Name & Number: ROS		-		
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	-C		
$\bigcirc$	3003926971	J -20-31N-5W	1480 FSL & 2360 FEL		
	Well Name & Number: ROS				
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	_C		
$\bigcirc$	3003929507	J -20-31N-5W	1385 FSL & 2020 FEL		
	Well Name & Number: ROS	SA UNIT No. 232A			
	Operator: WILLIAMS PRO	DUCTION COMPANY, LL	_C		
$\bigcirc$	3003929881	L -20-31N-5W	1935 FSL & 480 FWL		
	Well Name & Number: ROS	SA UNIT No. 321A			

Operator: WILLIAMS PRODUCTION COMPANY, LLC

O 3003930130

D -20-31N-5W

10 FNL & 10 FWL

11/

Well Name & Number: ROSA UNIT No. 085B

Operator: WILLIAMS PRODUCTION COMPANY, LLC

O 3003930220

A -20-31N-5W

685 FNL & 835 FEL

HU

Well Name & Number: ROSA UNIT No. 085C

Operator: WILLIAMS PRODUCTION COMPANY, LLC

15 Records Found

Displaying Screen 1 of 1

Continue Go Back