District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

PP#1666

X Initial Report

Form C-141

X Final Report

Revised October 10, 2003

## **Release Notification and Corrective Action**

**OPERATOR** 

	Name of Company Range Operating New Mexico, Inc.   Contact Linda C. Stiles				
Address 777 Main Street Suite 800 Fort Worth TX 76102	Telephone No. (817) 869-4208				
Facility Name Elliott B Federal # 2 Facility Type Well site					
Surface Owner Mineral Owner	See Attached	Lease N	0.		
LOCATION OF RELEASE					
Unit Letter Section Township Range Feet from the Nort	h/South Line Feet from the	East/West Line	County		
A J Q 22S 37E			Lea		
30025 10077 LatitudeLongitude					
NATURE OF RELEASE					
Type of Release Vapor(Gas) Mist	Volume of Release ?	Volume R	ecovered 0		
Source of			Hour of Discovery		
Casing Flowline leak	11-6-07 11:30 am		-		
Was Immediate Notice Given?	If YES, To Whom?				
Yes ☐ No ☐ Not Required Linda Stiles(Range) Gary Wink NMOCD					
By Whom? Chris Garcia	Date and Hour 11-7-07				
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.				
☐ Yes ☒ No	Date and Hour 11-7-07  If YES, Volume Impacting the Watercourse. NA  NOV 2007				
If a Watercourse was Impacted, Describe Fully.*					
NA	,		Received 8		
Hobbs 2					
If a Watercourse was Impacted, Describe Fully.*  NA  NA  NA  NO  NO  NO  NO  NO  NO  NO					
Ø 60/					
Was a Watercourse Reached?  Yes No  If a Watercourse was Impacted, Describe Fully.*  NA  Describe Cause of Problem and Remedial Action Taken.*  Poly-line weld opened up causing misty gas to blow into pasture. Refused poly-line and checked for line blockage.					
Describe Area Affected and Cleanup Action Taken.*					
250' SE of Elliott B Federal #2 Area affected was 250'L x 75' W. Spray affected area with microblaze and recheck area in a couple of weeks.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and					
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger					
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws and/or regulations.					
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	OIL CONSERVATION DIVISION				
Signature: Cond ( Av. ( )	Daluson				
- Comment of the comm	Approved by District Supervisor:				
Printed Name: Linda C. Stiles	Approved by District Supervisor: ENVIRONMENTAL ENGINEER				
Title: Sr. Engineering Tech	Approval Date: 11.27.07 Expiration Date:				
E-mail Address: lstiles@rangeresources com	Conditions of Approval:		Attached		
Date. 11-06-07 Phone: (817) 869-4208					

## SPILL REPORT FORM – RANGE PRODUCTION COMPANY USEPA REGULATION 40 CFR 112 / RRC SWR 8, 20 & 91

DATE SPILL DISCOVERED:	TIME:	i	NAME OF RESPONDER:		
11-06-07	1130am	Kenny Angel			
LEASE WHERE SPILL OCCUR	RED:	SOURCE OF SPILL (PIPELINE, TANK, ETC.)			
Elliott B Federal #2 flowline		Flowline			
COUNTY WHERE SPILL OCCURRED:		WEATHER CONDITIONS:			
Lea County		Warm			
(IF KNOWN) SIZE OF SPILL:	DID SPILL REACH A DITCH	DID SPILL REACH NAVIGABLE WATERS,			
250x75	OR STORM DRAIN?	STREAM OR	POND:		
	NO	NO			
CAUSE OF SPILL AND REMEDIAL ACTION TAKEN: Poly-line weld opened up causing misty gas to blow into					
pasture. Refused poly-line and checked for line blockage.					
TYPE OF DISCHARGE	QUANTITY SPILLED	DURATION OF SPILL:			
(OIL , WATER, FUEL, ETC):	(BBLS): ?	?	?		
Water					
TIME SPILL CONTAINED:	DATE SPILL CONTAINED:	BBLS RECOVERED:			
11:30 am	11-6-07	0			
DEATHS/INJURIES/ACCIDENTS: N/A					
DESCRIBE AREA AFFECTED AND CLEANUP ACTION TAKEN: 250' SE of Elliott Federal #2 well. Area affected was 250'x75'. Spray affected area w/ microblaze and recheck area after a couple of weeks.					
WITHIN COMPANY					
REPORTED BY:	то:	TIME	DATE:		
Kenny Angel	Chris Garcia	11:30	11-6-07		
REPORTED BY:	TO:	TIME:	DATE:		
Chris Garcia	Linda Stiles	133pm	11-06-07		
AGENCIES NOTIFIED					
AGENCY:	REPORTED TO:	TIME	DATE:		
MODITO I	REI GRADE TO:				
NMOCD	Gary Wink	12:00pm	11-06-07		
USFS					
BLM					
RRC OF TEXAS					
	•	1			

Fill out this form the same day the spill event is discovered and FAX to: SPCC Coordinator 100 Throckmorton Street, Suite 1200, Fort Worth TX 76102 (817) 869-9108