

**GW - 020**

**GENERAL  
CORRESPONDENCE**

**YEAR(S): 2007 - 2010**

# Frontier Field Services, LLC

Southern Ute Indian Tribe

Randy McCollum  
Manager of Compliance

RECEIVED

2007 JUL 2

Phone: 505-676-3505

Cell: 505-361-0128

Fax: 505-676-2401

rmccollum@frontierfieldservices.com

**CERTIFIED MAIL:**

**7006 0100 0004 2382 0928**

**RETURN RECEIPT REQUESTED**

June 28, 2007

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**Re: GW-020 Discharge Plan  
Maljamar Gas Plant  
Annual Sump Inspection  
Frontier Field Services**

Dear Mr. Price:

On June 13, 2007 notice was given to Chris Williams of the local NMOCD office in Hobbs, NM that a planned inspection of sumps as required in our Discharge Plan would be performed beginning April 21, 2007.

During the time period from June 21 through June 22, 2007 the plant sumps and #8 Clark cellar were inspected. Results of the inspections are attached.

If you have any questions or require more information please contact me at 505-676-3505.

Sincerely,



Randy L. McCollum

Chris Williams, OCD-Hobbs (Certified 7006 0100 0004 2382 0935)

---

**From:** Lizardo, Rudolfo  
**Sent:** Thursday, June 28, 2007 9:59 AM  
**To:** McCollum, Randy  
**Cc:** Prentiss, John  
**Subject:** Plant sump inspection

Randy;

The sump around #8 Clark was cleaned out; I looked it over and did not find any indication that we might have any leaks.

The sump on the west end of the eclectic building was also cleaned out, no indication of any leaks. Filled with water, starting level was 8'8" on 6/21/07 @ 8:45 AM. On 6/22/07 @ 8:45 AM the level was 8'8"

The sump on expander #2 was cleaned out; I visually looked in it no indication of any leaks. The starting level was 3'1" @ 9:30 AM on 6/21/07 AM, on 6/22/07 9:30 AM the level was 3'1"

The sump on expander #1 was cleaned out; I visually looked in it, no indication of any leaks. Starting level was 3'2" @ 9:45 AM on 6/21/07 AM, on 6/22/07 AM the level was 3'2".

The sump for the amine skid was cleaned out, no indication of any leaks. Starting level was 3'8" on 6/21/07 @ 10:30 AM, on 6/22/07 AM @ 10:30 AM the level was 3'8"

The refrigeration building sump was filled with water, starting level was 6'3" on 6/21/07 @ 11:00AM, on 6/22/07 @ 11:00 AM the level was 6'3"

Rudy Lizardo  
Maintenance Foreman  
Frontier Field Services  
P.O. Box 7  
Maljamar, New Mexico  
Office: (505) 676-3504  
Cell: (505) 361-0135  
Email: [rlizardo@frontierfieldservices.com](mailto:rlizardo@frontierfieldservices.com)

**McCollum, Randy**

---

**From:** Lizardo, Rudolfo  
**Sent:** Friday, June 15, 2007 10:06 AM  
**To:** McCollum, Randy  
**Subject:** Annual sump inspection

Randy;

I called Chris Williams on June 13<sup>th</sup> at 3:00 PM to notify the state on our up coming annual sump inspection scheduled for the 21<sup>st</sup> of this month.

Rudy Lizardo  
Maintenance Foreman  
Frontier Field Services  
P.O. Box 7  
Maljamar, New Mexico  
Office: (505) 676-3504  
Cell: (505) 361-0135  
Email: [rlizardo@frontierfieldservices.com](mailto:rlizardo@frontierfieldservices.com)

6/28/2007