## GW - \_\_\_\_28\_

## NPDES



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 6 1445 ROSS AVENUE, SUITE 1200 DALLAS, TX 75202-2733 December 6, 2000

REPLY TO: 6WQ-CA

Mr. Darrell Moore Navajo Refining Company 501 East Main Street P.O. Box 159 Artesia, New Mexico 86211-0159

Re: NPDES Application No. NM0030074-Navajo Refining Company

Dear Mr. Moore:

In accordance with your request of September 7, 2000, you are hereby notified that your National Pollutant Discharge Elimination System (NPDES) application for the above referenced facility has been discontinued and void.

Any resumption of the discharge or any new discharge from your facility without a permit will be unlawful. Should you again propose to discharge any pollutants from this facility to waters of the United States, it will be necessary to file a new NPDES application at least 180 days in advance of the proposed discharge.

If you have any questions, please do not hesitate to contact La Gayla Bradley at the above address or telephone (214) 665-7517.

Sincerely yours,

enoie Franke

Jayne Fontenot Chief **Customer Service Branch** 

cc: New Mexico Environmental Department

The second product of the second second second second

· "你们,我们我们就是我们的,我们就是你们的,你们们不会。"

Internet Address (URL) • http://www.epa.gov Recycled/Recyclable • Printed with Vegetable Oil Based Inks on Recycled Paper (Minimum 25% Postconsumer)



## REFINING COMPANY

FAX (505) 746-5283 DIV. ORDERS (505) 746-5481 TRUCKING (505) 746-5458 PERSONNEL

501 EAST MAIN STREET • P. O. BOX 159 ARTESIA, NEW MEXICO 88211-0159 TELEPHONE (505) 748-3311 FAX (505) 746-5419 ACCOUNTING (505) 746-5451 EXECUTIVE (505) 746-5421 ENGINEERING (505) 746-5480 P / L

October 10, 2000

Storm Water Notice Of Termination 401 M Street, S.W. Washington, DC 20460

To whom it may concern:

Enclosed is a form 3510-7 detailing Navajo Refining Company's intention to terminate our storm water permit. This plant has constructed retention basins and drainage to the point where we haven't had a stormwater discharge in several years. We will continue the best management practices as a matter of good housekeeping.

If there are any questions, please call me at 505-746-5281. Thank you for your attention to this matter.

NAVAJO REFINING COMPANY

MARA

Darrell Moore Environmental Mgr. for Water and Waste

encl.

THIS FORM REPLACES PREVIOUS FORM 3510-7 (8-92) Form Approved. ONB N	
United States Environmental Protection Agency	al oxpires: 9-31-98
NPDES   Washington, DC 20460     FORM   Visit Control of Coverage Under a NPDES ( Storm Water Discharges Associated with Industria)	Seneral Permit for Activity
Submission of this Notice of Termination constitutes notice that the party identified in Section II of this form is no longer authorized to discharge storm water associated with industrial activity under the NPDES program. ALL NECESSARY INFORMATION MUST BE PROVIDED ON THIS FORM.	
J. Permit Information	
NPDES Storm Water   N   M   R   O   O   A   1   5   9   Check Here if You are No Longer   Check Here if the S   Check Here if the S   Discharge is Being   Di	torm Water Terminated: XXX
II. Facility Operator Information	
Name: [N_A, V, A, J, O, R, E, F, I, N, I, N, G, C, O, M, P, A, N, Y, I, I, I, Phone: 5101	5 74 8 3 3 1 1 1
Address: P.O., B. O. X. 1.5.9.	
City: AIRITIESIIA ZIP Code: 81812	211.01-111
III. Facility/Site Location Information	
Name: NIAIVIAIJ, OL REFIINII, NG COMPANN, Y	
Address: $[5,0,1,E,A,S,T, M,A,I,N, H,I,N, H, H,$	
City: A RITIESIIA Code: 8.8.2	2 1 1 0 1 1 1 1
Latitude:   3   12   5   10   5   11   10   14   2   3   4   2   Quarter:    Section:    Township:	Range:
IV. Certification: I certify under penalty of law that all storm water discharges associated with industrial activity from the identified facility that are authorized by a NPDES general permit have been eliminated or that I am no longer the operator of the facility or construction site. I understand that by submitting this Notice of Termination, I am no longer authorized to discharge storm water associated with industrial activity under this general permit, and that discharging pollutants in storm water associated with industrial activity to waters of the United States is unlawful under the Clean Water Act where the discharge is not authorized by a NPDES permit. I also understand that the submittal of this Notice of Termination does not release an operator from liability for any violations of this permit or the Clean Water Act.	
Print Name: P, h, i, 1, 1, i, p, L, YOUN, g, b, 1, 0, 0, d, Date:	00600
Signature: AMulty J. Jourgolos	
Instructions for Completing Notice of Termination (NOT) Form	
Who May File a Notice of Termination (NOT) Form Where to File NOT Form	
Permittees who are presently covered under an EPA-issued National Pollutant Send this form to the the following address: Discharge Elimination System (NPDES) General Permit (including the 1995	
Multi-Sector Permit) for Storm Water Dicharges Associated with Industrial Activity Storm Water Notice of Termination (4203)   may submit a Notice of Termination (NOT) form when their facilities no longer 401 M Street, S.W.   have any storm water discharges associated with industrial activity as defined in Washington, DC 20460   the storm water regulations at 40 CFR 122.26(b)(14), or when they are no longer Washington, DC 20460	
the operator of the facilities. Completing the Form	
For construction activities, elimination of all storm water discharges associated with industrial activity occurs when disturbed soils at the construction site have been finally stabilized and temporary erosion and sediment control measures have been removed or will be removed at an appropriate time, or that all storm water discharges associated with industrial activity from the construction site that are authorized by a NPDES general permit have otherwise been eliminated. Final stabilization means that all soil-disturbing activities at the site have been completed, and that a uniform perennial vegetative cover with a density of 70% of the cover for unpaved areas and areas not covered by permanent structures has been established, or equivalent permanent stabilization measures (such as the use of riprap, gabions, or geotextiles) have been employed.	necessary to stay within hiy one space for breaks hey are needed to clarify

EPA Form 3510-7 (8-98)

4 . 4  $(-, \gamma) = (-, \gamma)$ 

.,

-4