MARTIN YATES, III 1912 - 1985 FRANK W. YATES 1936 - 1986



The second se

105 SOUTH FOURTH STREET ARTESIA, NEW MEXICO 88210-2118 TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

November 21, 2003

Mr. Bryan Arrant Oil Conservation Division, District II Office 1301 W. Grand Ave. Artesia, NM 88210

RECEIVED

NOV 2 1 2003

OCD-ARTESIA

Re: Mangas BDM State #1 Re-entry

330' FSL and 330' FEL Section 28, T8S-R32E

Chaves County, New Mexico

H2S Contingency Plan

Sources at Yates Petroleum Corporation have relayed information to me that they believe there will not be enough H2S found from the surface to the Cisco/Canyon Formation to meet the OCD's minimum requirements for the submission of a contingency plan per Rule 118.

Thank you,

YATES PETROLEUM CORPORATION

Robert Asher Regulatory Agent

