

DHC No. Assigned 1-7-2003

	Order Number Нов-0067	API Number Operator 30- 025-36422 Amerada Hess	County Lea			
	Order Date	Well Name B, M. Marcus	n Number	Location B 20 205 38E UL Sec T (+Dir) R (+Dir)		
Pool 1	06660	Blinebry OildGas (Oil)	<mark>0i1 %</mark> 31 <i>1</i> 2	Gas % 4478		
Pool 2	\$7080	Warren Tubb (Gas) (inges port.)	<u>467</u>	367.		
Pool 3	\$7000	Skaggs Drinkard	32,	20%		
Pool 4						
		ork completed effective ork cancelled effective upplement	·			
,	1-8-2 Postal RBDM			, , , , , , , , , , , , , , , , , , ,		

	DOWNHOLE COMMINGLE CALCULATIONS:	30-025	- 36422	
	OPERATOR: Amerada Hess Corp.	++(	0B-0067	
	PROPERTY NAME: B. M. Marcus			
	WNULSTR: 3-B, 20-20-38			
06660	SECTION I: POOL NO. 1_ Blinebry Oil+Gg. (Oil)	<b>ALLOWAB</b> <u>107</u>	BLE AMOUNT 4 <u>28</u> MCF	4000
87080	POOL NO. 2 Warren Tubbi (Gas)	999	<u>9999</u> MCF	
57000	POOL NO. 3 Skaggs Drinkard	142	<u> 421)</u> mcf	10000
	POOL NO. 4POOL TOTA	ALS <u>249</u>	MCF	
	SECTION II.	Oil		Gas
ABLIY000C	pool NO. 1 Blinebry Oila Gas (Dil)	31%		44%
	OPOOL NO. 2 (Darren Tubb (Gas)	6670 X:	249=164,34	36%
A= A5000	POOL NO. 3 <u>Skacas</u> Drinkard	3%		20%
ASKA	) POOL NO. 4			
	SECTION III: $107 \pm 667 = 162.13(163)$	GAS		
			·	-
	SECTION IV: $\frac{163 \times 317_{0} = 50.53 (51)}{163 \times 662 = 107.58 (107)}$ $\frac{163 \times 32}{163 \times 32} = 4.89 (5)$		· · · · · · · · · · · · · · · · · · ·	_

- .

Office	trict		New Me				۲۰ Revised	orm C May 08	
District I 1625 N. French Dr., Hobbs, NM 8824 District II					API NO. 25-36422	ice vised		, 2005	
1301 W. Grand Ave., Artesia, NM 88 District III	3210 OII	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indic	ate Type of I			
1000 Rio Brazos Rd., Aztec, NM 874	10		e, NM 87			TATE	FEE	X	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	1	Santa 1	c, 14141 07	505	6. State	Oil & Gas L	ease No.		
SUNDRY 1 (DO NOT USE THIS FORM FOR PF DIFFERENT RESERVOIR. USE "A		ILL OR TO DEE	PEN OR PLI	JG BACK TO A		e Name or Ur Marcus	it Agreen	nent Na	ame
PROPOSALS.)						Number			
1. Type of Well: Oil Well X Gas Well	l 🔲 Other				3	Number			
2. Name of Operator		1 1				ID Number			
Amerada Hess Corporation 3. Address of Operator	n			·····		00495 I name or Wi	Ideat Ska	aas Dr	inkard
-	, Texas 79360					nebry Oil & Ga			
4. Well Location			<u>.</u>			·······	·		
Unit Letter B	: 660	_feet from the	North	line and	1980	feet from th	ne Eas	t	line
Section 20		Township 2	0S Ra	inge 38E	NMPM	C	ounty	_ea	
	11. Elev			RKB, RT, GR, et					
		3553							19. T
			ndicate N	ature of Notice	· •				
NOTICE O		N TO: ND ABANDON	1	SU REMEDIAL WO					G 🗌
TEMPORARILY ABANDON		E PLANS		COMMENCE D	RILLING OF			IFNT	
PULL OR ALTER CASING				CASING TEST	AND				
OTHER: Downhole Comming		٠	X	OTHER:		· · · · · · · · · · · ·			
OTHER: Downhole Comming 13. Describe proposed or of of starting any propose or recompletion.	completed opera	ttions. (Clearl RULE 1103. 1 1363	y state all j For Multip	pertinent details, a	and give per Attach well	tinent dates, i pore diagram	ncluding of propos	estimat ed com	ed dat
13. Describe proposed or of starting any proposed	completed opera ed work). SEE PC C R - unit. NU BOP. L log from PBTD of 715'-6940', W	RULE 1103. 1 - 113 63 TIH w/gauge ri to 3000'. RIH arren; Tubb (8	y state all p For Multip ng on 2 7/8 I w/4" csg o 7080 or 63	bertinent details, a le Completions: 2 3" tbg to top of floa guns loaded w/3 s 280 based on gra	Attach wellt at collar @ + of and perf avity) from 6	oore diagram -/-7044'. TOF csg in followin 520'-6686.3',	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n.
<ul> <li>13. Describe proposed or of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH</li> <li>Working, royalty and of the start of the s</li></ul>	completed opera ed work). SEE PC r R unit. NU BOP. L log from PBTD 6715'-6940', W I w/prod eqpt an	RULE 1103. I IIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ	y state all p For Multip I g on 2 7/6 W/4" csg g 7080 or 63 cing well a	bertinent details, a le Completions: 2 3" tbg to top of floa guns loaded w/3 s 280 based on gra	Attach wellt at collar @ + of and perf avity) from 6	oore diagram -/-7044'. TOF csg in followin 520'-6686.3',	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n.
<ul> <li>13. Describe proposed or of of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH Working, royalty and of Commingling will not recommingling will not recommend to the recommend of the recommend will not recommend to the recommend of the r</li></ul>	completed opera ed work). SEE C C R unit. NU BOP. L log from PBTD 6715'-6940', W I w/prod eqpt an overriding royalty reduce the value	RULE 1103. I IIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ	y state all p For Multip I g on 2 7/6 W/4" csg g 7080 or 63 cing well a	bertinent details, a le Completions: 2 3" tbg to top of floa guns loaded w/3 s 280 based on gra	Attach wellt at collar @ + of and perf avity) from 6	oore diagram -/-7044'. TOF csg in followin 520'-6686.3',	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n.
<ul> <li>13. Describe proposed or of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling under RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIHE Working, royalty and commingling will not refuse to commingling will not</li></ul>	completed opera ed work). SEE C C R unit. NU BOP. L log from PBTD 6715'-6940', W I w/prod eqpt an overriding royalty reduce the value rate land.	RULE 1103. I IIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ y interests are of production	y state all p For Multip I g on 2 7/6 W/4" csg g 7080 or 63 cing well a	bertinent details, a le Completions: 2 3" tbg to top of floa guns loaded w/3 s 280 based on gra	Attach wellt at collar @ + of and perf avity) from 6	oore diagram -/-7044'. TOF csg in followin 520'-6686.3',	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n.
<ul> <li>13. Describe proposed or of of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH Working, royalty and of Commingling will not recommingling will not recommend to the recommend of the recommend will not recommend to the recommend of the r</li></ul>	completed opera ed work). SEE C C R unit. NU BOP. L log from PBTD 6715'-6940', W I w/prod eqpt an overriding royalty reduce the value rate land.	RULE 1103. I IIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ y interests are of production	y state all p For Multip I g on 2 7/6 W/4" csg g 7080 or 63 cing well a	bertinent details, a le Completions: 2 3" tbg to top of floa guns loaded w/3 s 280 based on gra	Attach wellt at collar @ + of and perf avity) from 6	oore diagram -/-7044'. TOF csg in followin 520'-6686.3',	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n.
<ul> <li>13. Describe proposed or of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling under RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIHE Working, royalty and commingling will not refuse to commingling will not</li></ul>	completed opera ed work). SEE PC r R - unit. NU BOP. L log from PBTD 6715'-6940', W I w/prod eqpt an overriding royalty reduce the value vate land. vell tests and fixe	RULE 1103. I IIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ y interests are of production ed percents.	y state all p For Multip ng on 2 7/4 l w/4" csg y 7080 or 63 cing well a identical in	bertinent details, a le Completions: 2 3" tbg to top of floa guns loaded w/3 s 280 based on gra	Attach wellt at collar @ + of and perf avity) from 6	oore diagram -/-7044'. TOF csg in followin 520'-6686.3',	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n.
<ul> <li>13. Describe proposed or of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH</li> <li>Working, royalty and c Commingling will not r Well is located on priv Allocation based on w Attachment: reservoir</li> </ul>	completed opera ed work). SEE PC r R unit. NU BOP. Log from PBTD 6715'-6940', W d w/prod eqpt an overriding royalty reduce the value vate land. vell tests and fixe	RULE 1103. 1 TIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ- y interests are of production ed percents. commingling	y state all j For Multip ng on 2 7/8 I w/4" csg g 7080 or 63 cing well a identical in	pertinent details, a le Completions: A 3" tbg to top of floa guns loaded w/3 s 280 based on gra s downhole comm a all commingled z	Attach wellt at collar @ + spf and perf avity) from 6 ningled. cones.	pore diagram -/-7044'. TOF csg in followin 520'-6686.3', 1392027	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n. ggs
<ul> <li>13. Describe proposed or of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH</li> <li>Working, royalty and c Commingling will not r Well is located on priv Allocation based on w Attachment: reservoir</li> </ul>	completed opera ed work). SEE PC r R unit. NU BOP. Log from PBTD 6715'-6940', W d w/prod eqpt an overriding royalty reduce the value vate land. vell tests and fixe	RULE 1103. 1 TIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ- y interests are of production ed percents. commingling	y state all j For Multip ng on 2 7/8 I w/4" csg g 7080 or 63 cing well a identical in	pertinent details, a le Completions: A 3" tbg to top of floa guns loaded w/3 s 280 based on gra s downhole comm a all commingled z	Attach wellt at collar @ + spf and perf avity) from 6 ningled. cones.	pore diagram -/-7044'. TOF csg in followin 520'-6686.3', 1392027	of propos I. Circula ng interval and Bline	ed com te clear s: Skaç	ed dat pletio n. ggs
<ul> <li>13. Describe proposed or of starting any proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH</li> <li>Working, royalty and c Commingling will not r Well is located on priv Allocation based on w Attachment: reservoir</li> <li>DHC Order</li> <li>I hereby certify that the information of the proposed of the p</li></ul>	completed opera ed work). SEE PC r R unit. NU BOP. Log from PBTD 6715'-6940', W d w/prod eqpt an overriding royalty reduce the value vate land. vell tests and fixe	RULE 1103. 1 TIH w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ- y interests are of production ed percents. commingling	y state all p For Multip I on 2 7/6 W/4" csg g 7080 or 63 cing well a identical in percentage <u>6 7</u> ete to the b	pertinent details, a le Completions: A 3" tbg to top of floa guns loaded w/3 s 280 based on gra s downhole comm a all commingled z	Attach wellt at collar @ + spf and perf avity) from 6 ningled. cones.	pore diagram -/-7044'. TOF csg in followin 520'-6686.3', 1392027	of propos	ed com te clear s: Skaç	ed dat pletio n. ggs 660)
<ul> <li>13. Describe proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH</li> <li>Working, royalty and c Commingling will not r Well is located on priv Allocation based on w Attachment: reservoir DHC Oreler</li> <li>I hereby certify that the information SIGNATURE</li> <li>Type or print name Carol</li> </ul>	completed opera ed work). SEE PC r R unit. NU BOP. Log from PBTD 6715'-6940', W d w/prod eqpt an overriding royalty reduce the value vate land. vell tests and fixe	RULE 1103. I III w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ- y interests are of production ed percents. commingling B - 00 ue and comple	y state all p For Multip I on 2 7/6 W/4" csg g 7080 or 63 cing well a identical in percentage <u>6 7</u> ete to the b	ertinent details, a pertinent details, a le Completions: A guns loaded w/3 s 280 based on gra s downhole comm all commingled z es. est of my knowled Senior Advisor	Attach wellt at collar @ + spf and perf avity) from 6 ningled. cones.	pore diagram -/-7044'. TOF csg in followin 520'-6686.3', 1392027	of propos I. Circula ing interval and Bline	te clear s: Skag ory (06	ed dat pletio n. ggs 660)
<ul> <li>13. Describe proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling L RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH Working, royalty and c Commingling will not r Well is located on priv Allocation based on w Attachment: reservoir DHC Order</li> <li>DHC Order</li> <li>SIGNATURE</li> </ul>	completed opera ed work). SEE PCT R- unit. NU BOP. L log from PBTD of 715'-6940', W d w/prod eqpt an overriding royalty reduce the value vate land. rell tests and fixe r data to support No. HO ation above is tr	RULE 1103. I III w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ- y interests are of production ed percents. commingling B - 00 ue and comple	y state all j For Multip I on 2 7/4 w/4" csg g 7080 or 63 cing well a identical in percentage <u>6 7</u> tet to the b	ertinent details, a pertinent details, a le Completions: A guns loaded w/3 s 280 based on gra s downhole comm all commingled z es. est of my knowled Senior Advisor	Attach wellt at collar @ + spf and perf avity) from 6 ningled. cones.	pore diagram -/-7044'. TOF csg in followin 520'-6686.3', 18192021 18192021 18192021	of propos I. Circula ing interval and Bline	te clear s: Skag ory (06	ed dat pletio n. ggs 660)
<ul> <li>13. Describe proposed or of starting any proposed or recompletion.</li> <li>Plan to MIRU pulling u RU wireline. Run CBL Drinkard (57000) from from 5904'-6092'. TIH</li> <li>Working, royalty and c Commingling will not r Well is located on priv Allocation based on w Attachment: reservoir DHC Oreler</li> <li>I hereby certify that the information SIGNATURE</li> <li>Type or print name Carol</li> </ul>	completed opera ed work). SEE PCT R- unit. NU BOP. L log from PBTD of 715'-6940', W d w/prod eqpt an overriding royalty reduce the value vate land. rell tests and fixe r data to support No. HO ation above is tr	RULE 1103. I III w/gauge ri to 3000'. RIH arren; Tubb (8 d begin produ- y interests are of production ed percents. commingling B - 00 ue and comple	y state all j For Multip I on 2 7/4 w/4" csg g 7080 or 63 cing well a identical in percentage <u>6 7</u> tet to the b	ertinent details, a pertinent details, a le Completions: A guns loaded w/3 s 280 based on gra s downhole comm all commingled z es. est of my knowled Senior Advisor	Attach wellt at collar @ + spf and perf avity) from 6 ningled. cones.	pore diagram -/-7044'. TOF csg in followin 520'-6686.3', 18192021 18192021 ef. ef. 99 $tezt$ Telephone	of propos I. Circula ing interval and Bline	ed com te clear s: Skag ory (060 2)758-6	ed dat pletio n. 3gs 660) 3 3 5738

## ALLOCATION OF PRODUCTION FOR MARCUS #3 WELL (Allocation by zone for Drinkard, Tubb, and Blinebry zones based on offset reserves)

SKAGGS DRINKARD (57000)			
WELL NAME	RESERVES		
	MBO	MMCF	
B.M. MARCUS #2	9	138	
F. TURNER JR B #2	2	60	
M.J. RALEY #2	9	58	
F. TURNER A #7	2	36	
TOTAL FOR ZONE	22	292	
AVERAGE	6	73	
ALLOCATION PERCENTAGE	3%	20%	

(GAS)

1

۰.

WARREN TUBB (87080 /-63290) 7 m	Γ	
WELL NAME	RESERVES	
	MBO	MMCF
B.M. MARCUS #2	118	157
CONOCO BURGER B-20 #1 (SW OFFSET)	60	66
CONOCO BURGER B-20 #2 (S OFFSET)	255	242
CONOCO BURGER B-20 #3 (SE OFFSET)	14	57
TOTAL FOR ZONE	447	522
AVERAGE	112	131
ALLOCATION PERCENTAGE	66%	36%

BLINEBRY OIL AND GAS (6660)	7		
WELL NAME	RESERVES		
	MBO	MMCF	
B.M. MARCUS #2	47	189	
CONOCO BURGER B-20 #1 (SW OFFSET)	43	108	
CONOCO BURGER B-20 #2 (S OFFSET)	98	233	
CONOCO BURGER B-20 #3 (SE OFFSET)	23	112	
TOTAL FOR ZONE	211	642	
AVERAGE	53	161	
ALLOCATION PERCENTAGE	31%	44%	

TOTAL FOR ALL ZONES	680	1456
AVERAGE FOR ALL ZONES	170	364

Allocation of Production for Marcus 3\_3 ZONE.xls 12/11/2003

