



493

Burlington Resources Oil & Gas Co LP
"A subsidiary of ConocoPhillips Company"

February 28, 2013

Bureau of Land Management
Farmington Resource Area
6251 College Blvd., Suite A
Farmington, NM 87402

Commissioner of Public Lands
State of New Mexico
P. O. Box 1148
Santa Fe, NM 87501-1148

Oil Conservation Division
State of New Mexico
1220 S. Saint Francis Drive
Santa Fe, NM 87505

**RE: 2013 Plan of Development
SAN JUAN 30-6 UNIT 14-06-001-538
RIO ARRIBA COUNTY, NEW MEXICO**

Ladies and Gentlemen:

The following Participating Areas currently exist in the SAN JUAN 30-6 UNIT:

FORMATION	EXPANSION	EFFECTIVE DATE
DAKOTA	018	01-JUL-03
FRUITLAND COAL	030	01-JUL-91
MESAVERDE	030	01-FEB-01
PICTURED CLIFFS	007	01-APR-11

The 2012 Plan of Development (or amendments thereto) provided for the following activity:

WELL NAME	FORMATION	TYPE	DEDICATION	STATUS
SAN JUAN 30-6 UNIT 1N	MESAVERDE/DAKOTA	New Drill – Commingle	E2 09-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 13N	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 32-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 29B	MESAVERDE/DAKOTA & MANCOS	New Drill – Trimingle	E2 12-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 29M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	NSP 12-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 35M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	NSP 24-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 36M	MESAVERDE/DAKOTA	New Drill – Commingle	E2 08-030N-006W	CANCELLED
SAN JUAN 30-6 UNIT 37M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E/2 10-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 41N	MESAVERDE/DAKOTA & MANCOS	New Drill – Trimingle	W2 13-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 46M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 11-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 51B	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 30-030N-006W	COMPLETED
SAN JUAN 30-6 UNIT 57B	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	W2 30-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 57M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	W2 30-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 101B	MESAVERDE/DAKOTA	New Drill – Commingle	E2 35-030N-007W	CARRYOVER
SAN JUAN 30-6 UNIT 114N	MESAVERDE/DAKOTA & MANCOS	New Drill – Trimingle	W2 11-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 114P	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	W2 11-030N-006W	CARRYOVER

SAN JUAN 30-6 UNIT
2013 PLAN OF DEVELOPMENT

SAN JUAN 30-6 UNIT 126M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 15-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 146	BARKER CREEK PARADOX	New Drill – Single	ALL 26-030N-006W	CARRYOVER
SAN JUAN 30-6 UNIT 148	PICTURED CLIFFS	New Drill – Single	SE4 32-030N-007W	CARRYOVER

Pursuant to Section 10 of the SAN JUAN 30-6 UNIT Agreement, Burlington Resources Oil & Gas Company LP, as Unit Operator, hereby submits the **2013 Plan of Development** as follows:

WELL NAME	FORMATION	TYPE	DEDICATION
SAN JUAN 30-6 UNIT 1N	MESAVERDE/DAKOTA	New Drill – Commingle	E2 09-030N-006W
SAN JUAN 30-6 UNIT 13N	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 32-030N-006W
SAN JUAN 30-6 UNIT 29B	MESAVERDE/DAKOTA & MANCOS	New Drill – Trimingle	E2 12-030N-006W
SAN JUAN 30-6 UNIT 29M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	NSP 12-030N-006W
SAN JUAN 30-6 UNIT 35M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	NSP 24-030N-006W
SAN JUAN 30-6 UNIT 37M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 10-030N-006W
SAN JUAN 30-6 UNIT 41N	MESAVERDE/DAKOTA & MANCOS	New Drill – Trimingle	W2 13-030N-006W
SAN JUAN 30-6 UNIT 46M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 11-030N-006W
SAN JUAN 30-6 UNIT 57B	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	W2 30-030N-006W
SAN JUAN 30-6 UNIT 57M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	W2 30-030N-006W
SAN JUAN 30-6 UNIT 101B	MESAVERDE/DAKOTA	New Drill – Commingle	E2 35-030N-007W
SAN JUAN 30-6 UNIT 114N	MESAVERDE/DAKOTA & MANCOS	New Drill – Trimingle	W2 11-030N-006W
SAN JUAN 30-6 UNIT 114P	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	W2 11-030N-006W
SAN JUAN 30-6 UNIT 126M	MESAVERDE, DAKOTA & MANCOS	New Drill – Trimingle	E2 15-030N-006W
SAN JUAN 30-6 UNIT 146	BARKER CREEK PARADOX	New Drill – Single	ALL 26-030N-006W
SAN JUAN 30-6 UNIT 148	PICTURED CLIFFS	New Drill – Single	SE4 32-030N-007W

The working interest owners are being furnished a copy of this letter, well status listing and enclosed map. Burlington, as Unit Operator, will drill any offset wells required to prevent drainage of unitized substances and any other wells deemed necessary by the working interest owners or Unit Operator.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of the attached approval page to the undersigned.

Please contact me at (505) 326-9749 if there are any questions regarding this letter.

Sincerely,

Vanessa Thompson

Vanessa Thompson, RPL
Land Supervisor, SJBU SE

VT/vw


xc: San Juan 30-6, 3.0 (2013)
San Juan 30-6 Working Interest Owners

SAN JUAN 30-6 UNIT
2013 PLAN OF DEVELOPMENT

SAN JUAN 30-6 UNIT
2013 PLAN OF DEVELOPMENT APPROVALS

Bureau of Land Management

Date



New Mexico Oil Conservation Division

2/15/2013

Date

New Mexico Commissioner of Public Lands

Date

SAN JUAN 30-6 UNIT
2013 PLAN OF DEVELOPMENT

SAN JUAN 30-6 UNIT WORKING INTEREST OWNERS


ACTON ENERGY LP	T H MCELVAIN OIL AND GAS PROP
BP AMERICA PRODUCTION COMPANY	TAMACAM LLC
BURLINGTON RESOURCES O&G CO LP	WPC OIL & GAS LP
BURLINGTON RESOURCES O&G SJBT	WPX ENERGY INC
CHARLES W GAY	XTO ENERGY INC
CONOCOPHILLIPS COMPANY	
EMIL MOSBACHER III	
HENRY G ROBELDO	
J&M RAYMOND LTD	
JANE P MOSBACHER ESTATE TRUST	
LORRAYN GAY HACKER	
MESA ROYALTY TRUST	
MOSBACHER USA INC.	
OMIMEX PETROLEUM INC	
PHILLIPS NEW MEXICO PARTNERS LP	
PHILLIPS SAN JUAN LTD PARTNERSHIP	
PIONEER NATURAL RESOURCES USA INC	
ROBERT E GALL	
ROBERT MORRISON ESTATE	
ROBERT UMBACH CANCER FOUNDATION	
SAN JUAN BASIN TRUST	
SILVERADO OIL & GAS LLP	
ST JOHN INSTITUTIONAL INVESTOR	

SAN JUAN 30-6 UNIT

R7W

R6W

R
30
N



SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392580400S01	SAN JUAN 30-6 10 102A DK	RIO ARRIBA	NM	30	N	6	W 22	O	G	A707388	30274	11	7/18/98		1/1/94	8/3/98
300392636800	SAN JUAN 30-6 10B MV	RIO ARRIBA	NM	30	N	7	W 31	I	G	A705599	30274	11			1/26/01	1/26/01
300392663500	SAN JUAN 30-6 114M	RIO ARRIBA	NM	30	N	6	W 11	R	G	A705599	30274	11			11/10/01	11/10/01
300392598500S01	SAN JUAN 30-6 12 124 DK	RIO ARRIBA	NM	30	N	6	W 28	G	G	A707388	30274	11			1/1/94	1/29/99
300392607600S01	SAN JUAN 30-6 12 128 DK	RIO ARRIBA	NM	30	N	6	W 29	I	G	A707388	30274	11			1/1/94	8/30/99
300392598300	SAN JUAN 30-6 125 DK	RIO ARRIBA	NM	30	N	6	W 7	O	G	A707388	165581	11				
300392600300	SAN JUAN 30-6 126 DK	RIO ARRIBA	NM	30	N	6	W 15	P	G	A707388	165581	11				
300392621600S01	SAN JUAN 30-6 130 PC	RIO ARRIBA	NM	30	N	6	W 28	G	G	A707362	30274	PS			1/1/94	1/1/94
300392644800	SAN JUAN 30-6 135 DK	RIO ARRIBA	NM	30	N	8	W 27	O	G	A707404	30274	61				
300392650900	SAN JUAN 30-6 139 DK	RIO ARRIBA	NM	30	N	6	W 19	F	G	A707388	30274	11				
300392677200	SAN JUAN 30-6 145 DK	RIO ARRIBA	NM	30	N	6	W 22	E	G	A707388	30274	11			11/29/01	11/29/01
300392681600	SAN JUAN 30-6 15B MV	RIO ARRIBA	NM	30	N	7	W 29	N	G	A705599	30274	11				
300392567000	SAN JUAN 30-6 17A DK	RIO ARRIBA	NM	30	N	6	W 18	E	G	A707388	1542298000	11				
300392567000	SAN JUAN 30-6 17A MV	RIO ARRIBA	NM	30	N	6	W 18	E	G	A705599	30274	11	11/21/97		1/1/94	12/15/97
300392699900	SAN JUAN 30-6 1A MV	RIO ARRIBA	NM	30	N	6	W 9	O	G	A705599	30274	11				
300392687000	SAN JUAN 30-6 24B MV	RIO ARRIBA	NM	30	N	6	W 16	I	G	A705599	30274	11	7/1/03			
300392637500	SAN JUAN 30-6 31Y DK	RIO ARRIBA	NM	30	N	6	W 33	D	G	A707388	30274	11				
300392642900	SAN JUAN 30-6 33B DK	RIO ARRIBA	NM	30	N	6	W 8	D	G	A707388	165581	11				
300392642900	SAN JUAN 30-6 33B MV	RIO ARRIBA	NM	30	N	6	W 8	D	G	A705599	165581	11				
300392581200	SAN JUAN 30-6 34A DK	RIO ARRIBA	NM	30	N	6	W 10	C	G	A707388	1542298000	11				
300392581200S01	SAN JUAN 30-6 34A MV	RIO ARRIBA	NM	30	N	6	W 10	C	G	A705599	30274	11			1/1/94	1/1/94
300392641000	SAN JUAN 30-6 34B MV	RIO ARRIBA	NM	30	N	6	W 10	K	G	A705599	30274	11			11/16/01	11/16/01
300392651300	SAN JUAN 30-6 35A MV	RIO ARRIBA	NM	30	N	6	W 24	J	G	A705599	30274	11	6/1/04			
300392568300	SAN JUAN 30-6 36A DK	RIO ARRIBA	NM	30	N	6	W 8	P	G	A707388	1542298000	11				
300392568300S01	SAN JUAN 30-6 36A MV	RIO ARRIBA	NM	30	N	6	W 8	P	G	A705599	30274	11	9/21/97		1/1/94	10/21/97
300392577700	SAN JUAN 30-6 37A DK	RIO ARRIBA	NM	30	N	6	W 10	I	G	A707388	1542298000	11				
300392577700S01	SAN JUAN 30-6 37A MV	RIO ARRIBA	NM	30	N	6	W 10	I	G	A705599	30274	11			1/1/94	8/10/98
300392678000	SAN JUAN 30-6 38B MV	RIO ARRIBA	NM	30	N	7	W 27	F	G	A705599	30274	11				
300392689900	SAN JUAN 30-6 38C MV	RIO ARRIBA	NM	30	N	7	W 27	K	G	A705599	30274	11				
300392581100	SAN JUAN 30-6 39A DK	RIO ARRIBA	NM	30	N	6	W 13	J	G	A707388	1542298000	11				
300392580500	SAN JUAN 30-6 3A DK	RIO ARRIBA	NM	30	N	6	W 24	D	G	A707388	1542298000	11				
300392580500	SAN JUAN 30-6 3A MV	RIO ARRIBA	NM	30	N	6	W 24	D	G	A705599	30274	11			1/1/94	7/21/98
300392940300	SAN JUAN 30-6 400S FC	RIO ARRIBA	NM	30	N	7	W 14	F	G	A705781	30274	11				
300392940200	SAN JUAN 30-6 401S FC	RIO ARRIBA	NM	30	N	7	W 13	C	G	A705781	30274	11				
3004579675200S	SAN JUAN 30-6 406S FC	RIO ARRIBA	NM	30	N	7	W 15		G	A705781	30274	99				
300392583500	SAN JUAN 30-6 40A DK	RIO ARRIBA	NM	30	N	6	W 12	E	G	A707388	1542298000	11				
300392583500	SAN JUAN 30-6 40A MV	RIO ARRIBA	NM	30	N	6	W 12	E	G	A705599	30274	11			1/1/94	1/3/99
300392941700	SAN JUAN 30-6 410S FC	RIO ARRIBA	NM	30	N	6	W 26		G	A705781	30274	11				
300392960500S01	SAN JUAN 30-6 416S FC DUP	RIO ARRIBA	NM	30	N	7	W 24		G	A705781	30274	99				
	SAN JUAN 30-6 418S FC DUP	RIO ARRIBA	NM	28	N	6	W 28	C	G	A655268	30274	99				
300392943800	SAN JUAN 30-6 419S FC	RIO ARRIBA	NM	30	N	7	W 11	J	G	A705781	30274	11				
300392583600	SAN JUAN 30-6 41A DK	RIO ARRIBA	NM	30	N	6	W 13	F	G	A707388	1542298000	11				
300392944900	SAN JUAN 30-6 420S FC	RIO ARRIBA	NM	30	N	7	W 12	I	G	A705781	30274	11				
300392940700S01	SAN JUAN 30-6 423S (hCO)	RIO ARRIBA	NM	30	N	7	W 28	P	G	A705781	216600	99				
300392940700S01	SAN JUAN 30-6 423S (hPH)	RIO ARRIBA	NM	30	N	7	W 28	P	G	A655268	216600	99				
300392940600	SAN JUAN 30-6 424S FC	RIO ARRIBA	NM	30	N	7	W 33	E	G	A705781	30274	11	8/1/05			
300392954100	SAN JUAN 30-6 429S FC	RIO ARRIBA	NM	30	N	7	W 32		G	A705781	30274	11	8/1/05			
300392580300	SAN JUAN 30-6 42A DK	RIO ARRIBA	NM	30	N	6	W 14	F	G	A707388	1542298000	11				
300392580300	SAN JUAN 30-6 42A MV	RIO ARRIBA	NM	30	N	6	W 14	F	G	A705599	30274	11			1/1/94	7/13/98
300392677000	SAN JUAN 30-6 42M DK	RIO ARRIBA	NM	30	N	6	W 14	L	G	A707388	1542298000	11	3/1/04			

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392677000	SAN JUAN 30-6 42M MV	RIO ARRIBA	NM	30	N 6	W 14	L	G	A705599	30274	BLANCO::MESAVERDE	11				
30039294480000	SAN JUAN 30-6 433S FC	RIO ARRIBA	NM	30	N 7	W 11	D	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	4/1/05			
300392949400	SAN JUAN 30-6 436S FC	RIO ARRIBA	NM	30	N 6	W 15	I	G	A705781	30274	BASIN CB::FRUITLAND COAL	11				
300392583700S01	SAN JUAN 30-6 43A DK	RIO ARRIBA	NM	30	N 6	W 14	M	G	A707388	1542298000	BASIN::DAKOTA	11	10/3/07			10/3/07
300392583700	SAN JUAN 30-6 43A MV	RIO ARRIBA	NM	30	N 6	W 14	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392764300S01	SAN JUAN 30-6 441S FCDUP	RIO ARRIBA	NM	30	N 6	W 31	I	G	A705781	30274	BASIN CB::FRUITLAND COAL	99				
300392728400S01	SAN JUAN 30-6 443S FC PA	RIO ARRIBA	NM	30	N 6	W 36	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	4/30/03	12/12/12	5/14/03	5/14/03
300392728400S01	SAN JUAN 30-6 443S FC PA	RIO ARRIBA	NM	30	N 6	W 36	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	4/30/03	12/12/12	5/14/03	5/14/03
300393092300C02	SAN JUAN 30-6 447S FC	RIO ARRIBA	NM					G	A705781	30274	BASIN CB::FRUITLAND COAL	11				5/27/11
300392563700	SAN JUAN 30-6 454S DK	RIO ARRIBA	NM	30	N 6	W 15	C	G	A707388	1542298000	BASIN::DAKOTA	11				
300392563700	SAN JUAN 30-6 44A MV	RIO ARRIBA	NM	30	N 6	W 15	C	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	10/15/97
300392766600S01	SAN JUAN 30-6 452S FC Pad	RIO ARRIBA	NM	30	N 6	W 8	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	11/2/04	11/30/12	11/18/04	11/18/04
300392766600S01	SAN JUAN 30-6 452S FC Pad	RIO ARRIBA	NM	30	N 6	W 8	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	11/2/04	11/30/12	11/18/04	11/18/04
300392940500	SAN JUAN 30-6 454S FC	RIO ARRIBA	NM	30	N 6	W 17	J	G	A705781	30274	BASIN CB::FRUITLAND COAL	11				
300392943900	SAN JUAN 30-6 455S FC	RIO ARRIBA	NM	30	N 6	W 18	D	G	A705781	30274	BASIN CB::FRUITLAND COAL	11				
300392447500S01	SAN JUAN 30-6 46 467 JCV	RIO ARRIBA	NM	30	N 7	W 22	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			1/1/94	9/20/90
300392447500S01	SAN JUAN 30-6 46 467 JCV	RIO ARRIBA	NM	30	N 7	W 22	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			1/1/94	9/20/90
300392940400	SAN JUAN 30-6 462S FC	RIO ARRIBA	NM	30	N 7	W 12	E	G	A705781	30274	BASIN CB::FRUITLAND COAL	11				
30039294110000	SAN JUAN 30-6 466S FC	RIO ARRIBA	NM	30	N 7	W 22		G	A705781	30274	BASIN CB::FRUITLAND COAL	11	4/1/05			
300392447500N01	SAN JUAN 30-6 467 FC NU.	RIO ARRIBA	NM					G	A712260	216600	BASIN CB::FRUITLAND COAL	11				
300392447500N01	SAN JUAN 30-6 467 FC NU.	RIO ARRIBA	NM					G	A721122	216600	BASIN CB::FRUITLAND COAL	11				
300392447500N01	SAN JUAN 30-6 467 FC UT	RIO ARRIBA	NM					G	A728855	216600	BASIN CB::FRUITLAND COAL	11				
300392447500N01	SAN JUAN 30-6 467 FC UT	RIO ARRIBA	NM					G	A728855	216600	BASIN CB::FRUITLAND COAL	11				
300392940800	SAN JUAN 30-6 467S FC	RIO ARRIBA	NM	30	N 7	W 22	F	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	8/1/05			
300392940800N01	SAN JUAN 30-6 467S FC NU	RIO ARRIBA	NM					G	A712260	216600	BASIN CB::FRUITLAND COAL	11				
300392940800N01	SAN JUAN 30-6 467S FC NU.	RIO ARRIBA	NM					G	A721122	216600	BASIN CB::FRUITLAND COAL	11				
300392940800N01	SAN JUAN 30-6 467S FC UT	RIO ARRIBA	NM					G	A728855	216600	BASIN CB::FRUITLAND COAL	11				
300392940800N01	SAN JUAN 30-6 467S FC UT	RIO ARRIBA	NM					G	A728855	216600	BASIN CB::FRUITLAND COAL	11				
300392687600	SAN JUAN 30-6 46B MV	RIO ARRIBA	NM	30	N 6	W 11	B	G	A705599	30274	BLANCO::MESAVERDE	11				
300392943600	SAN JUAN 30-6 473S FC	RIO ARRIBA	NM	30	B 6	W 22	E	G	A705781	30274	BASIN CB::FRUITLAND COAL	11				
300392941200	SAN JUAN 30-6 479S FC	RIO ARRIBA	NM	30	N 6	W 29	F	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	8/1/05			
300392625900	SAN JUAN 30-6 47B DK	RIO ARRIBA	NM	30	N 7	W 32	B	G	A707388	1542298000	BASIN::DAKOTA	11				
300392625900	SAN JUAN 30-6 47B MV	RIO ARRIBA	NM	30	N 7	W 32	B	G	A705599	30274	BLANCO::MESAVERDE	11				
	SAN JUAN 30-6 482S FC	RIO ARRIBA	NM	30	N 6	W 31		G	A705781	30274	BASIN CB::FRUITLAND COAL	99				
300392957800S01	SAN JUAN 30-6 494S FC	RIO ARRIBA	NM	30	N 6	W 33	J	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	10/27/05		1/21/06	1/21/06
300392940100	SAN JUAN 30-6 497S FC	RIO ARRIBA	NM	30	N 7	W 29	O	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	8/1/05			
300392940100	SAN JUAN 30-6 497S PC	RIO ARRIBA	NM	30	N 7	W 29	O	G	A655409	30274	BLANCO::PICTURED CLIFFS	11	5/1/06			
300392940100	SAN JUAN 30-6 497S PC	RIO ARRIBA	NM	30	N 7	W 29	O	G	A655409	30274	BLANCO::PICTURED CLIFFS	11	5/1/06			
300390780500S01	SAN JUAN 30-6 54 MV	RIO ARRIBA	NM	30	N 6	W 21	H	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300390780500	SAN JUAN 30-6 54 PC	RIO ARRIBA	NM	30	N 6	W 21	H	G	A707439	30274	BLANCO S::PICTURED CLIFFS	11				
300392567200S01	SAN JUAN 30-6 6 62A DK	RIO ARRIBA	NM	30	N 6	W 28	C	G	A707388	30274	BASIN::DAKOTA	11			1/1/94	11/3/97
300392689800	SAN JUAN 30-6 60B DK	RIO ARRIBA	NM	30	N 6	W 31	B	G	A709155	1292493000	BASIN::DAKOTA	11				
300392689800	SAN JUAN 30-6 60B DK	RIO ARRIBA	NM	30	N 6	W 31	B	G	A709155	1292493000	BASIN::DAKOTA	11				
300392689800	SAN JUAN 30-6 60B MV	RIO ARRIBA	NM	30	N 6	W 31	B	G	A705599	1292493000	BLANCO S::MESAVERDE	11				
300392265200S01	SAN JUAN 30-6 7 73ARON	RIO ARRIBA	NM	30	N 7	W 22	F	G	A705602	30274	BLANCO::MESAVERDE	11			1/1/94	1/4/82
300390778800S01	SAN JUAN 30-6 7 73RON	RIO ARRIBA	NM	30	N 7	W 22	M	G	A705602	30274	BLANCO::MESAVERDE	11	8/23/55		8/23/55	8/23/55
300392542400	SAN JUAN 30-6 71A DK	RIO ARRIBA	NM	30	N 7	W 13	J	G	A707388	1542298000	BASIN::DAKOTA	11				
300392542400S01	SAN JUAN 30-6 71A MV	RIO ARRIBA	NM	30	N 7	W 13	J	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/24/95
300390778800N01	SAN JUAN 30-6 73 MV NU	RIO ARRIBA	NM					G	A712261	216600	BLANCO::MESAVERDE	11				
300390778800N01	SAN JUAN 30-6 73 MV NU	RIO ARRIBA	NM					G	A720699	216600	BLANCO::MESAVERDE	11				

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TFMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300390778800N01	SAN JUAN 30-6 73 MV NU	RIO ARRIBA	NM					G	A712261	216600	BLANCO::MESAVERDE	11				
300390778800N01	SAN JUAN 30-6 73 MV NU	RIO ARRIBA	NM					G	A720699	216600	BLANCO::MESAVERDE	11				
300390778800N01	SAN JUAN 30-6 73 MV UT	RIO ARRIBA	NM					G	A728853	216600	BLANCO::MESAVERDE	11				
300392265200N01	SAN JUAN 30-6 73A MV NU	RIO ARRIBA	NM					G	A720700	216600	BLANCO::MESAVERDE	11				
300392265200N01	SAN JUAN 30-6 73A MV NU	RIO ARRIBA	NM					G	A712261	216600	BLANCO::MESAVERDE	11				
300392265200N01	SAN JUAN 30-6 73A MV NU	RIO ARRIBA	NM					G	A720700	216600	BLANCO::MESAVERDE	11				
300392265200N01	SAN JUAN 30-6 73A MV NU	RIO ARRIBA	NM					G	A712261	216600	BLANCO::MESAVERDE	11				
300392265200N01	SAN JUAN 30-6 73A MV UT	RIO ARRIBA	NM					G	A728853	216600	BLANCO::MESAVERDE	11				
300392676200	SAN JUAN 30-6 74B MV	RIO ARRIBA	NM	30	N	7	W 23	P	G	A705599	30274	BLANCO::MESAVERDE	11			
300392567500	SAN JUAN 30-6 76A DK	RIO ARRIBA	NM	30	N	7	W 24	O	G	A707388	1542298000	BASIN::DAKOTA	11			
300392567500S01	SAN JUAN 30-6 76A MV	RIO ARRIBA	NM	30	N	7	W 24	O	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 10/30/97
300392600400	SAN JUAN 30-6 76E DK	RIO ARRIBA	NM	30	N	7	W 24	H	G	A707388	165581	BASIN::DAKOTA	11			
300392573800	SAN JUAN 30-6 77A DK	RIO ARRIBA	NM	30	N	7	W 24	E	G	A707388	1542298000	BASIN::DAKOTA	11			
300392573800S01	SAN JUAN 30-6 77A MV	RIO ARRIBA	NM	30	N	7	W 24	E	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 11/15/97
300392565700	SAN JUAN 30-6 82A DK	RIO ARRIBA	NM	30	N	6	W 20	E	G	A707388	1542298000	BASIN::DAKOTA	11			
300392565700S01	SAN JUAN 30-6 82A MV	RIO ARRIBA	NM	30	N	6	W 20	E	G	A705599	30274	BLANCO::MESAVERDE	11	9/11/97		1/1/94 10/15/97
300392167300	SAN JUAN 30-6 89A PC	RIO ARRIBA	NM	30	N	6	W 4		G	A655409	30274	GOBERNADOR:PICTURED CLIFF	11	1/4/84		
300392636900	SAN JUAN 30-6 88 MV	RIO ARRIBA	NM	30	N	7	W 31	E	G	A705599	30274	BLANCO::MESAVERDE	11			5/4/01 5/4/01
300392626500	SAN JUAN 30-6 91R MV	RIO ARRIBA	NM	30	N	7	W 28	O	G	A705599	30274	BLANCO::MESAVERDE	11			6/18/01 6/18/01
300392687400	SAN JUAN 30-6 92B DK	RIO ARRIBA	NM	30	N	7	W 33	O	G	A707388	165581	BASIN::DAKOTA	11			
300392687400	SAN JUAN 30-6 92B MV	RIO ARRIBA	NM	30	N	7	W 33	O	G	A705599	165581	BLANCO::MESAVERDE	11			
300392689300	SAN JUAN 30-6 93B MV	RIO ARRIBA	NM	30	N	7	W 33	F	G	A705599	30274	BLANCO::MESAVERDE	11			
300392689400	SAN JUAN 30-6 93M DK	RIO ARRIBA	NM	30	N	7	W 33	M	G	A707388	30274	BASIN::DAKOTA	11			
300392689400	SAN JUAN 30-6 93M MV	RIO ARRIBA	NM	30	N	7	W 33	M	G	A705599	30274	BLANCO::MESAVERDE	11			
300392626600	SAN JUAN 30-6 94B DK	RIO ARRIBA	NM	30	N	7	W 28	L	G	A707388	1542298000	BASIN::DAKOTA	11			
300392626600	SAN JUAN 30-6 94B MV	RIO ARRIBA	NM	30	N	7	W 28	L	G	A705599	30274	BLANCO::MESAVERDE	11			
300392689500	SAN JUAN 30-6 94M MV	RIO ARRIBA	NM	30	N	7	W 28	E	G	A705599	30274	BLANCO::MESAVERDE	11			
300392980700	SAN JUAN 30-6 95B DK	RIO ARRIBA	NM	30	N	7	W 23		G	A710356	30274	BASIN::DAKOTA	99			
300392980700	SAN JUAN 30-6 95B MV	RIO ARRIBA	NM	30	N	7	W 23		G	A705599	30274	BLANCO::MESAVERDE	99			
300392701100	SAN JUAN 30-6 96B MV	RIO ARRIBA	NM	30	N	7	W 26	H	G	A705599	30274	BLANCO::MESAVERDE	11			
300392769500	SAN JUAN 30-6 99B DK	RIO ARRIBA	NM	30	N	7	W 34	E	G	A728852	30274	BASIN::DAKOTA	11			
300392769500	SAN JUAN 30-6 99B MV	RIO ARRIBA	NM	30	N	7	W 34	E	G	A705599	30274	BLANCO::MESAVERDE	11	5/1/05		
300392687500	SAN JUAN 30-6 99C DK	RIO ARRIBA	NM	30	N	7	W 34	N	G	A707388	30274	BASIN::DAKOTA	11			
300392687500	SAN JUAN 30-6 99C MV	RIO ARRIBA	NM	30	N	7	W 34	N	G	A705599	30274	BLANCO::MESAVERDE	11	2/1/06		
300392683500	SAN JUAN 30-6 MV 000087B	RIO ARRIBA	NM	30	N	7	W 36	N	G	A705599	30274	BLANCO::MESAVERDE	11			
300390774100	SAN JUAN 30-6 MV 10 RON	RIO ARRIBA	NM	30	N	7	W 31	B	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 1/1/94
300390771800S01	SAN JUAN 30-6 MV 100 RON	RIO ARRIBA	NM	30	N	7	W 35	N	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 1/1/94
300392190600S01	SAN JUAN 30-6 MV 100ARON	RIO ARRIBA	NM	30	N	7	W 35	E	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 8/22/79
300390773100S01	SAN JUAN 30-6 MV 101 RON	RIO ARRIBA	NM	30	N	7	W 35	H	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 1/1/94
300392227000S01	SAN JUAN 30-6 MV 101ARON	RIO ARRIBA	NM	30	N	7	W 35	O	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 12/3/80
300392580400S01	SAN JUAN 30-6 MV 102ARON	RIO ARRIBA	NM	30	N	6	W 22	O	G	A705599	30274	BLANCO::MESAVERDE	11	7/18/98		1/1/94 8/3/98
300392051900S01	SAN JUAN 30-6 MV 102RRON	RIO ARRIBA	NM	30	N	6	W 22	G	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 10/11/72
300392052500S01	SAN JUAN 30-6 MV 103 RON	RIO ARRIBA	NM	30	N	6	W 25	G	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 9/7/72
300392559400S01	SAN JUAN 30-6 MV 103ARON	RIO ARRIBA	NM	30	N	6	W 25	J	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 12/13/96
300392560100	SAN JUAN 30-6 MV 10ARON	RIO ARRIBA	NM	30	N	7	W 31	O	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 1/8/97
300390779300	SAN JUAN 30-6 MV 11 RON	RIO ARRIBA	NM	30	N	6	W 23	L	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 4/17/57
300392588800	SAN JUAN 30-6 MV 114RON	RIO ARRIBA	NM	30	N	6	W 11	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 1/1/94
300392589800	SAN JUAN 30-6 MV 11ARON	RIO ARRIBA	NM	30	N	6	W 24	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 1/1/94
300390775200	SAN JUAN 30-6 MV 12 RON	RIO ARRIBA	NM	30	N	6	W 26	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94 1/1/94
300392570000	SAN JUAN 30-6 MV 12ARON	RIO ARRIBA	NM	30	N	6	W 26	D	G	A705599	30274	BLANCO::MESAVERDE	11	8/27/97		1/1/94 9/16/97

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN		RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300390773700	SAN JUAN 30-6 MV 13 RON	RIO ARRIBA	NM	30	N	6	W	32	G	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	12/23/55
300392167000	SAN JUAN 30-6 MV 13ARON	RIO ARRIBA	NM	30	N	6	W	32	J	G	A705599	30274	BLANCO::MESAVERDE	11	1/16/79		1/1/94	1/16/79
300390771500	SAN JUAN 30-6 MV 14 RON	RIO ARRIBA	NM	30	N	6	W	32	N	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392231300	SAN JUAN 30-6 MV 14ARON	RIO ARRIBA	NM	30	N	6	W	32	D	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	9/15/80
300390775700	SAN JUAN 30-6 MV 15 RON	RIO ARRIBA	NM	30	N	7	W	29	L	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392190200	SAN JUAN 30-6 MV 15ARON	RIO ARRIBA	NM	30	N	7	W	29	O	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/7/79
300390776400	SAN JUAN 30-6 MV 16 RON	RIO ARRIBA	NM	30	N	6	W	26	H	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392567100	SAN JUAN 30-6 MV 16ARON	RIO ARRIBA	NM	30	N	6	W	26	C	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/27/97
300390783300	SAN JUAN 30-6 MV 17 RON	RIO ARRIBA	NM	30	N	6	W	18	N	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300390785600	SAN JUAN 30-6 MV 18 RON	RIO ARRIBA	NM	30	N	6	W	18	A	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	9/12/57
300392197700	SAN JUAN 30-6 MV 18ARON	RIO ARRIBA	NM	30	N	6	W	18	I	G	A705599	30274	BLANCO::MESAVERDE	11	9/20/79		1/1/94	9/20/79
300390785700	SAN JUAN 30-6 MV 24 RON	RIO ARRIBA	NM	30	N	6	W	16	B	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	4/17/57
300392206600	SAN JUAN 30-6 MV 24ARON	RIO ARRIBA	NM	30	N	6	W	16	O	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	5/19/80
300390780400	SAN JUAN 30-6 MV 25 RON	RIO ARRIBA	NM	30	N	6	W	19	H	G	A705599	30274	BLANCO::MESAVERDE	11	6/16/58		1/1/94	1/1/94
300392561800	SAN JUAN 30-6 MV 25ARON	RIO ARRIBA	NM	30	N	6	W	19	P	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300390779000	SAN JUAN 30-6 MV 26 RON	RIO ARRIBA	NM	30	N	6	W	19	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392193900	SAN JUAN 30-6 MV 26ARON	RIO ARRIBA	NM	30	N	6	W	19	F	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/30/79
300390780600	SAN JUAN 30-6 MV 27 RON	RIO ARRIBA	NM	30	N	6	W	23	H	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	5/28/58
300392585000	SAN JUAN 30-6 MV 27ARON	RIO ARRIBA	NM	30	N	6	W	23	O	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	2/17/99
300390774200	SAN JUAN 30-6 MV 28 RON	RIO ARRIBA	NM	30	N	6	W	33	B	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392169200	SAN JUAN 30-6 MV 28ARON	RIO ARRIBA	NM	30	N	6	W	33	J	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/15/79
300390789900S01	SAN JUAN 30-6 MV 29 RON	RIO ARRIBA	NM	30	N	6	W	12	B	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392560700S01	SAN JUAN 30-6 MV 29ARON	RIO ARRIBA	NM	30	N	6	W	12	J	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/28/97
300396009800	SAN JUAN 30-6 MV 3 RON	RIO ARRIBA	NM	30	N	6	W	24	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/11/53
300392567900S01	SAN JUAN 30-6 MV 30ARON	RIO ARRIBA	NM	30	N	6	W	20	J	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	10/15/97
300392526100S01	SAN JUAN 30-6 MV 30RRON	RIO ARRIBA	NM	30	N	6	W	20	A	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	3/18/94
300390771200S01	SAN JUAN 30-6 MV 31 RON	RIO ARRIBA	NM	30	N	6	W	33	N	G	A705599	30274	BLANCO::MESAVERDE	11	7/22/59		1/1/94	1/1/94
300392562000S01	SAN JUAN 30-6 MV 31ARON	RIO ARRIBA	NM	30	N	6	W	33	F	G	A705599	30274	BLANCO::MESAVERDE	11	4/26/97		1/1/94	5/9/97
300390788700S01	SAN JUAN 30-6 MV 32 RON	RIO ARRIBA	NM	30	N	6	W	7	H	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300392197600S01	SAN JUAN 30-6 MV 32ARON	RIO ARRIBA	NM	30	N	6	W	7	J	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	10/2/79
300390786900S01	SAN JUAN 30-6 MV 33 RON	RIO ARRIBA	NM	30	N	6	W	8	N	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	10/29/60
300392565600S01	SAN JUAN 30-6 MV 33ARON	RIO ARRIBA	NM	30	N	6	W	8	E	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	11/21/97
300390786600S01	SAN JUAN 30-6 MV 34 RON	RIO ARRIBA	NM	30	N	6	W	10	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/13/60
300390788600S01	SAN JUAN 30-6 MV 36 RON	RIO ARRIBA	NM	30	N	6	W	8	G	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/16/61
300390789500S01	SAN JUAN 30-6 MV 37 RON	RIO ARRIBA	NM	30	N	6	W	10	B	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	9/1/61
300390911000	SAN JUAN 30-6 MV 38 RON	RIO ARRIBA	NM	30	N	7	W	27	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	10/25/52
300392567300S01	SAN JUAN 30-6 MV 38ARON	RIO ARRIBA	NM	30	N	7	W	27	C	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	9/24/97
300390785800S01	SAN JUAN 30-6 MV 39 RON	RIO ARRIBA	NM	30	N	6	W	13	B	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	6/16/55
300392581100S01	SAN JUAN 30-6 MV 39A MV	RIO ARRIBA	NM	30	N	6	W	13	J	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300390787600	SAN JUAN 30-6 MV 40XRON	RIO ARRIBA	NM	30	N	6	W	12	M	G	A705599	30274	BLANCO::MESAVERDE	11	8/20/57		1/1/94	8/20/57
300391820100	SAN JUAN 30-6 MV 41 RON	RIO ARRIBA	NM	30	N	6	W	13	M	G	A705599	30274	BLANCO::MESAVERDE	11	8/20/57		1/1/94	8/20/57
300392583600	SAN JUAN 30-6 MV 41ARON	RIO ARRIBA	NM	30	N	6	W	13	F	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	9/3/98
300390783100	SAN JUAN 30-6 MV 42 RON	RIO ARRIBA	NM	30	N	6	W	14	M	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300390786000	SAN JUAN 30-6 MV 43 RON	RIO ARRIBA	NM	30	N	6	W	14	A	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300390783700	SAN JUAN 30-6 MV 44 RON	RIO ARRIBA	NM	30	N	6	W	15	N	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94
300390785200	SAN JUAN 30-6 MV 45 RON	RIO ARRIBA	NM	30	N	6	W	15	G	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/20/57
300392193700	SAN JUAN 30-6 MV 45ARON	RIO ARRIBA	NM	30	N	6	W	15	I	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	6/17/80
300390788900S01	SAN JUAN 30-6 MV 46 RON	RIO ARRIBA	NM	30	N	6	W	11	H	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	8/14/58
300392581000S01	SAN JUAN 30-6 MV 46ARON	RIO ARRIBA	NM	30	N	6	W	11	I	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	9/14/98
300390772900S01	SAN JUAN 30-6 MV 47 RON	RIO ARRIBA	NM	30	N	7	W	32	H	G	A705599	30274	BLANCO::MESAVERDE	11			1/1/94	1/1/94

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392559300S01	SAN JUAN 30-6 MV 47ARON	RIO ARRIBA	NM	30	N	7	W	32	J	G	A705599	30274			1/1/94	1/1/94
300390776000S01	SAN JUAN 30-6 MV 48 RON	RIO ARRIBA	NM	30	N	6	W	27	L	G	A705599	30274			1/1/94	5/14/52
300392563600S01	SAN JUAN 30-6 MV 48ARON	RIO ARRIBA	NM	30	N	6	W	27	L	G	A705599	30274		10/8/97	1/1/94	11/18/97
300392527300S01	SAN JUAN 30-6 MV 48RRON	RIO ARRIBA	NM	30	N	6	W	27	L	G	A705599	30274			1/1/94	3/21/94
300392194100S01	SAN JUAN 30-6 MV 49ARON	RIO ARRIBA	NM	30	N	6	W	27	O	G	A705599	30274		8/5/80	1/1/94	8/5/80
300392033000S01	SAN JUAN 30-6 MV 49RRON	RIO ARRIBA	NM	30	N	6	W	27	B	G	A705599	30274			1/1/94	1/1/94
300392169300	SAN JUAN 30-6 MV 4ARON	RIO ARRIBA	NM	30	N	6	W	35	J	G	A705599	30274			1/1/94	1/2/79
300392032300	SAN JUAN 30-6 MV 4RRON	RIO ARRIBA	NM	30	N	6	W	35	G	G	A705599	30274			1/1/94	1/1/94
300390771600	SAN JUAN 30-6 MV 5 RON	RIO ARRIBA	NM	30	N	6	W	35	N	G	A705599	30274			1/1/94	1/1/94
300390778900S01	SAN JUAN 30-6 MV 50 RON	RIO ARRIBA	NM	30	N	6	W	22	M	G	A705599	30274			1/1/94	1/1/94
300392560500S01	SAN JUAN 30-6 MV 50ARON	RIO ARRIBA	NM	30	N	6	W	22	E	G	A705599	30274		12/4/96	1/1/94	1/1/94
300390777300S01	SAN JUAN 30-6 MV 51 RON	RIO ARRIBA	NM	30	N	6	W	30	B	G	A705599	30274			1/1/94	1/1/94
300392221300S01	SAN JUAN 30-6 MV 51ARON	RIO ARRIBA	NM	30	N	6	W	30	P	G	A705599	30274			1/1/94	9/15/80
300390779600S01	SAN JUAN 30-6 MV 52 RON	RIO ARRIBA	NM	30	N	6	W	21	K	G	A705599	30274		9/15/53	1/1/94	1/1/94
300392562500S01	SAN JUAN 30-6 MV 52ARON	RIO ARRIBA	NM	30	N	6	W	21	D	G	A705599	30274		6/1/01	1/1/94	1/1/94
300390774700S01	SAN JUAN 30-6 MV 53 RON	RIO ARRIBA	NM	30	N	6	W	29	M	G	A705599	30274			1/1/94	1/1/94
300392221200S01	SAN JUAN 30-6 MV 53ARON	RIO ARRIBA	NM	30	N	6	W	29	F	G	A705599	30274			1/1/94	12/22/80
300392194000S01	SAN JUAN 30-6 MV 54ARON	RIO ARRIBA	NM	30	N	6	W	21	J	G	A705599	30274			1/1/94	5/14/80
300390776600S01	SAN JUAN 30-6 MV 55 RON	RIO ARRIBA	NM	30	N	6	W	29	H	G	A705599	30274		6/16/58	1/1/94	1/1/94
300392561900S01	SAN JUAN 30-6 MV 55ARON	RIO ARRIBA	NM	30	N	6	W	29	I	G	A705599	30274		4/22/97	1/1/94	4/30/97
300390773600S01	SAN JUAN 30-6 MV 56 RON	RIO ARRIBA	NM	30	N	6	W	34	H	G	A705599	30274			1/1/94	1/1/94
300392167100S01	SAN JUAN 30-6 MV 56ARON	RIO ARRIBA	NM	30	N	6	W	34	P	G	A705599	30274			1/1/94	1/9/79
300390775800S01	SAN JUAN 30-6 MV 57 RON	RIO ARRIBA	NM	30	N	6	W	30	K	G	A705599	30274			1/1/94	9/14/53
300392224100S01	SAN JUAN 30-6 MV 57ARON	RIO ARRIBA	NM	30	N	6	W	30	C	G	A705599	30274			1/1/94	12/18/80
300390771900S01	SAN JUAN 30-6 MV 58 RON	RIO ARRIBA	NM	30	N	6	W	31	N	G	A705599	30274			1/1/94	9/14/53
300392224200S01	SAN JUAN 30-6 MV 58ARON	RIO ARRIBA	NM	30	N	6	W	31	C	G	A705599	30274		11/6/80	1/1/94	11/6/80
300392527400S01	SAN JUAN 30-6 MV 58BRON	RIO ARRIBA	NM	30	N	6	W	31	C	G	A705599	30274			1/1/94	3/14/94
300390777100S01	SAN JUAN 30-6 MV 59 RON	RIO ARRIBA	NM	30	N	6	W	28	A	G	A705599	30274			1/1/94	1/1/94
300392194200S01	SAN JUAN 30-6 MV 59ARON	RIO ARRIBA	NM	30	N	6	W	28	J	G	A705599	30274			1/1/94	5/14/80
300392559500	SAN JUAN 30-6 MV 5ARON	RIO ARRIBA	NM	30	N	6	W	35	F	G	A705599	30274		11/21/96	1/1/94	12/5/96
300390773800S01	SAN JUAN 30-6 MV 60 RON	RIO ARRIBA	NM	30	N	6	W	31	A	G	A705599	30274		12/29/55	1/1/94	1/1/94
300392195100S01	SAN JUAN 30-6 MV 60ARON	RIO ARRIBA	NM	30	N	6	W	31	I	G	A705599	30274		8/14/79	1/1/94	8/14/79
300390771400S01	SAN JUAN 30-6 MV 61 RON	RIO ARRIBA	NM	30	N	6	W	34	N	G	A705599	30274			1/1/94	1/1/94
300392571100S01	SAN JUAN 30-6 MV 61ARON	RIO ARRIBA	NM	30	N	6	W	34	E	G	A705599	30274			1/1/94	1/1/94
300392567200S01	SAN JUAN 30-6 MV 62ARON	RIO ARRIBA	NM	30	N	6	W	28	E	G	A705599	30274			1/1/94	11/3/97
300390775000S01	SAN JUAN 30-6 MV 62XRON	RIO ARRIBA	NM	30	N	6	W	28	M	G	A705599	30274			1/1/94	1/1/94
300390784100S01	SAN JUAN 30-6 MV 63 RON	RIO ARRIBA	NM	30	N	7	W	15	L	G	A705599	30274			1/1/94	8/4/52
300392192400S01	SAN JUAN 30-6 MV 63ARON	RIO ARRIBA	NM	30	N	7	W	15	C	G	A705599	30274			1/1/94	8/28/79
300390789600S01	SAN JUAN 30-6 MV 64 RON	RIO ARRIBA	NM	30	N	7	W	11	A	G	A705599	30274			1/1/94	1/1/94
300392573400S01	SAN JUAN 30-6 MV 64ARON	RIO ARRIBA	NM	30	N	7	W	11	O	G	A705599	30274			1/1/94	12/3/97
300392192200S01	SAN JUAN 30-6 MV 65ARON	RIO ARRIBA	NM	30	N	7	W	13	C	G	A705599	30274			1/1/94	8/30/79
300392032000S01	SAN JUAN 30-6 MV 65RRON	RIO ARRIBA	NM	30	N	7	W	13	L	G	A705599	30274			1/1/94	1/1/94
300390784400S01	SAN JUAN 30-6 MV 66 RON	RIO ARRIBA	NM	30	N	7	W	14	K	G	A705599	30274			1/1/94	9/15/52
300392192300S01	SAN JUAN 30-6 MV 66ARON	RIO ARRIBA	NM	30	N	7	W	14	F	G	A705599	30274			1/1/94	9/24/79
300392540000S01	SAN JUAN 30-6 MV 66RRON	RIO ARRIBA	NM	30	N	7	W	14	M	G	A705599	30274			1/1/94	1/17/95
300390789000S01	SAN JUAN 30-6 MV 67 RON	RIO ARRIBA	NM	30	N	7	W	12	H	G	A705599	30274			1/1/94	1/1/94
300392571200S01	SAN JUAN 30-6 MV 67ARON	RIO ARRIBA	NM	30	N	7	W	12	I	G	A705599	30274			1/1/94	11/14/97
300390775300S01	SAN JUAN 30-6 MV 68 RON	RIO ARRIBA	NM	30	N	6	W	25	M	G	A705599	30274			1/1/94	1/1/94
300392567400S01	SAN JUAN 30-6 MV 68ARON	RIO ARRIBA	NM	30	N	6	W	25	F	G	A705599	30274		9/28/97	1/1/94	10/8/97
300390785300S01	SAN JUAN 30-6 MV 69 RON	RIO ARRIBA	NM	30	N	7	W	14	H	G	A705599	30274			1/1/94	1/1/94

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392561100S01	SAN JUAN 30-6 MV 69ARON	RIO ARRIBA	NM	30	N	7	W	14	E	G	A705599	30274			1/1/94	6/9/97
300390775500	SAN JUAN 30-6 MV 7 RON	RIO ARRIBA	NM	30	N	7	W	30	K	G	A705599	30274			1/1/94	1/1/94
300390787200S01	SAN JUAN 30-6 MV 70 RON	RIO ARRIBA	NM	30	N	7	W	12	M	G	A705599	30274			1/1/94	1/1/94
300392192100S01	SAN JUAN 30-6 MV 70ARON	RIO ARRIBA	NM	30	N	7	W	12	E	G	A705599	30274			1/1/94	9/27/79
300390786200S01	SAN JUAN 30-6 MV 71 RON	RIO ARRIBA	NM	30	N	7	W	13	H	G	A705599	30274			1/1/94	1/1/94
300390781800S01	SAN JUAN 30-6 MV 72 RON	RIO ARRIBA	NM	30	N	7	W	22	B	G	A705599	30274		2/25/53	1/1/94	2/25/53
300392192600S01	SAN JUAN 30-6 MV 72ARON	RIO ARRIBA	NM	30	N	7	W	22	P	G	A705599	30274			1/1/94	8/22/79
300390781000S01	SAN JUAN 30-6 MV 74 RON	RIO ARRIBA	NM	30	N	7	W	23	A	G	A705599	30274			1/1/94	1/1/94
300392544700S01	SAN JUAN 30-6 MV 74ARON	RIO ARRIBA	NM	30	N	7	W	23	J	G	A705599	30274			1/1/94	1/18/95
300390779700S01	SAN JUAN 30-6 MV 75 RON	RIO ARRIBA	NM	30	N	7	W	23	K	G	A705599	30274			1/1/94	1/1/94
300392544600S01	SAN JUAN 30-6 MV 75ARON	RIO ARRIBA	NM	30	N	7	W	23	D	G	A705599	30274			1/1/94	1/18/95
300390781100S01	SAN JUAN 30-6 MV 76 RON	RIO ARRIBA	NM	30	N	7	W	24	H	G	A705599	30274			1/1/94	1/1/94
300390779800S01	SAN JUAN 30-6 MV 77 RON	RIO ARRIBA	NM	30	N	7	W	24	K	G	A705599	30274			1/1/94	1/1/94
300390777700S01	SAN JUAN 30-6 MV 78 RON	RIO ARRIBA	NM	30	N	7	W	25	A	G	A705599	30274			1/1/94	1/1/94
300392192700S01	SAN JUAN 30-6 MV 78ARON	RIO ARRIBA	NM	30	N	7	W	25	J	G	A705599	30274			1/1/94	9/20/79
300390775900S01	SAN JUAN 30-6 MV 79 RON	RIO ARRIBA	NM	30	N	7	W	25	L	G	A705599	30274			1/1/94	1/1/94
300392546900S01	SAN JUAN 30-6 MV 79ARON	RIO ARRIBA	NM	30	N	7	W	25	C	G	A705599	30274			1/1/94	1/1/94
300392170000	SAN JUAN 30-6 MV 7ARON	RIO ARRIBA	NM	30	N	7	W	30	F	G	A705599	30274			1/1/94	10/3/78
300390772600	SAN JUAN 30-6 MV 8 RON	RIO ARRIBA	NM	30	N	7	W	31	K	G	A705599	30274			1/1/94	1/1/94
300390784300S01	SAN JUAN 30-6 MV 80 RON	RIO ARRIBA	NM	30	N	6	W	17	L	G	A705599	30274			1/1/94	3/31/53
300392563400S01	SAN JUAN 30-6 MV 80ARON	RIO ARRIBA	NM	30	N	6	W	17	C	G	A705599	30274			1/1/94	10/28/97
300390785500S01	SAN JUAN 30-6 MV 81 RON	RIO ARRIBA	NM	30	N	6	W	17	A	G	A705599	30274			1/1/94	1/1/94
300392193800S01	SAN JUAN 30-6 MV 81ARON	RIO ARRIBA	NM	30	N	6	W	17	J	G	A705599	30274			1/1/94	10/4/79
300390779400S01	SAN JUAN 30-6 MV 82 RON	RIO ARRIBA	NM	30	N	6	W	20	L	G	A705599	30274			1/1/94	1/1/94
300390786100S01	SAN JUAN 30-6 MV 83 RON	RIO ARRIBA	NM	30	N	7	W	15	A	G	A705599	30274			1/1/94	1/1/94
300392560600S01	SAN JUAN 30-6 MV 83ARON	RIO ARRIBA	NM	30	N	7	W	15	J	G	A705599	30274			1/1/94	11/22/96
300390787300S01	SAN JUAN 30-6 MV 84 RON	RIO ARRIBA	NM	30	N	7	W	11	M	G	A705599	30274			1/1/94	1/1/94
300392265100S01	SAN JUAN 30-6 MV 84ARON	RIO ARRIBA	NM	30	N	7	W	11	E	G	A705599	30274			1/1/94	1/4/82
300390784200S01	SAN JUAN 30-6 MV 85 RON	RIO ARRIBA	NM	30	N	6	W	16	L	G	A705599	30274			1/1/94	1/1/94
300392559900S01	SAN JUAN 30-6 MV 85ARON	RIO ARRIBA	NM	30	N	6	W	16	E	G	A705599	30274			1/1/94	3/7/97
300390773200S01	SAN JUAN 30-6 MV 86 RON	RIO ARRIBA	NM	30	N	7	W	36	G	G	A705599	30274			1/1/94	1/1/94
300392230300S01	SAN JUAN 30-6 MV 86ARON	RIO ARRIBA	NM	30	N	7	W	36	J	G	A705599	30274		11/13/80	1/1/94	11/13/80
300390772400S01	SAN JUAN 30-6 MV 87 RON	RIO ARRIBA	NM	30	N	7	W	36	L	G	A705599	30274			1/1/94	1/1/94
300392230400S01	SAN JUAN 30-6 MV 87ARON	RIO ARRIBA	NM	30	N	7	W	36	D	G	A705599	30274			1/1/94	12/1/80
300390787900S01	SAN JUAN 30-6 MV 88 RON	RIO ARRIBA	NM	30	N	6	W	7	K	G	A705599	30274			1/1/94	1/1/94
300392221100S01	SAN JUAN 30-6 MV 88ARON	RIO ARRIBA	NM	30	N	6	W	7	F	G	A705599	30274		12/23/80	1/1/94	12/23/80
300390773000S01	SAN JUAN 30-6 MV 89 RON	RIO ARRIBA	NM	30	N	6	W	36	H	G	A705599	30274			1/1/94	1/1/94
300392167300S01	SAN JUAN 30-6 MV 89ARON	RIO ARRIBA	NM	30	N	6	W	36	O	G	A705599	30274		1/25/79	1/1/94	1/25/79
300392170100	SAN JUAN 30-6 MV 8ARON	RIO ARRIBA	NM	30	N	7	W	31	C	G	A705599	30274			1/1/94	7/29/78
300390776500	SAN JUAN 30-6 MV 9 RON	RIO ARRIBA	NM	30	N	7	W	30	G	G	A705599	30274			1/1/94	11/14/55
300390772300S01	SAN JUAN 30-6 MV 90 RON	RIO ARRIBA	NM	30	N	6	W	36	L	G	A705599	30274			1/1/94	1/1/94
300392560000S01	SAN JUAN 30-6 MV 90ARON	RIO ARRIBA	NM	30	N	6	W	36	E	G	A705599	30274		2/20/97	1/1/94	3/4/97
300391824200S01	SAN JUAN 30-6 MV 91 RON	RIO ARRIBA	NM	30	N	7	W	28	A	G	A705599	30274		10/19/52	1/1/94	1/1/94
300392219300S01	SAN JUAN 30-6 MV 91ARON	RIO ARRIBA	NM	30	N	7	W	28	P	G	A705599	30274		12/17/99	1/1/94	12/8/80
300390773500S01	SAN JUAN 30-6 MV 92 RON	RIO ARRIBA	NM	30	N	7	W	33	H	G	A705599	30274			1/1/94	1/1/94
300392540900S01	SAN JUAN 30-6 MV 92ARON	RIO ARRIBA	NM	30	N	7	W	33	I	G	A705599	30274			1/1/94	1/19/95
300390772500S01	SAN JUAN 30-6 MV 93 RON	RIO ARRIBA	NM	30	N	7	W	33	K	G	A705599	30274			1/1/94	1/1/94
300392580600S01	SAN JUAN 30-6 MV 93ARON	RIO ARRIBA	NM	30	N	7	W	33	E	G	A705599	30274			1/1/94	7/29/98
300391824100S01	SAN JUAN 30-6 MV 94 RON	RIO ARRIBA	NM	30	N	7	W	28	N	G	A705599	30274			1/1/94	10/25/52
300392265400S01	SAN JUAN 30-6 MV 94ARON	RIO ARRIBA	NM	30	N	7	W	28	F	G	A705599	30274			1/1/94	1/4/82

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392169900S01	SAN JUAN 30-6 MV 95ARON	RIO ARRIBA	NM	30	N	7	W	26	D	G	A705599	30274			1/1/94	1/24/79
300392052000S01	SAN JUAN 30-6 MV 95RRON	RIO ARRIBA	NM	30	N	7	W	26	M	G	A705599	30274			1/1/94	9/22/72
300392527500S01	SAN JUAN 30-6 MV 95XRON	RIO ARRIBA	NM	30	N	7	W	26	N	G	A705599	30274			1/1/94	3/3/94
300390777200S01	SAN JUAN 30-6 MV 96 RON	RIO ARRIBA	NM	30	N	7	W	26	B	G	A705599	30274			1/1/94	1/1/94
300392568000S01	SAN JUAN 30-6 MV 96ARON	RIO ARRIBA	NM	30	N	7	W	26	I	G	A705599	30274			1/1/94	9/16/97
300390776700S01	SAN JUAN 30-6 MV 97 RON	RIO ARRIBA	NM	30	N	7	W	27	G	G	A705599	30274			1/1/94	1/1/94
300392544800S01	SAN JUAN 30-6 MV 97ARON	RIO ARRIBA	NM	30	N	7	W	27	J	G	A705599	30274			1/1/94	5/3/95
300390773300S01	SAN JUAN 30-6 MV 98 RON	RIO ARRIBA	NM	30	N	7	W	34	G	G	A705599	30274			1/1/94	1/1/94
300392190500S01	SAN JUAN 30-6 MV 98ARON	RIO ARRIBA	NM	30	N	7	W	34	J	G	A705599	30274			1/1/94	8/3/79
300390772000S01	SAN JUAN 30-6 MV 99 RON	RIO ARRIBA	NM	30	N	7	W	34	M	G	A705599	30274			1/1/94	5/19/55
300392190400S01	SAN JUAN 30-6 MV 99ARON	RIO ARRIBA	NM	30	N	7	W	34	F	G	A705599	30274			1/1/94	7/30/79
300392190300	SAN JUAN 30-6 MV 9ARON	RIO ARRIBA	NM	30	N	7	W	30	P	G	A705599	30274			1/1/94	8/14/79
300392190400	SAN JUAN 30-6 PC 99A	RIO ARRIBA	NM						F	G	A655409	30274		10/4/01		
300392190400	SAN JUAN 30-6 PC 99A	RIO ARRIBA	NM						F	G	A655409	30274		10/4/01		
300392451800S01	SAN JUAN 30-6 SWD 2 ME	RIO ARRIBA	NM	30	N	7	W	23	D	S	A068947	216600			2/9/90	2/9/90
300392612000S01	SAN JUAN 30-6 UNI 71E DK	RIO ARRIBA	NM	30	N	7	W	13	L	G	A707388	30274			1/1/94	10/19/99
300393076700C01	SAN JUAN 30-6 UNIT 40M DK	RIO ARRIBA	NM	30	N	6	W	12	N	G	A728852	216600		11/3/09	12/2/09	12/2/09
300393076700C02	SAN JUAN 30-6 UNIT 40M MV	RIO ARRIBA	NM	30	N	6	W	12	N	G	A728853	216600		11/3/09	12/2/09	12/2/09
300392563600C01	SAN JUAN 30-6 UNIT 48A DK	RIO ARRIBA	NM	30	N	6	W	27	C	G	A728852	216600		10/8/97	11/18/97	11/18/97
300392563600C02	SAN JUAN 30-6 UNIT 48A MV	RIO ARRIBA	NM	30	N	6	W	27	C	G	A728853	216600		10/8/97	11/18/97	11/18/97
300390780600S01	SAN JUAN 30-6 UT 27 MV	RIO ARRIBA	NM	30	N	6	W	23	H	G	A728853	216600		4/23/58	5/29/58	
300390774101S01	SAN JUAN 30-6 UT 10 MV	RIO ARRIBA	NM	30	N	7	W	31	B	G	A728853	216600		8/23/55	8/23/55	8/23/55
300390771800S01	SAN JUAN 30-6 UT 100 MV	RIO ARRIBA	NM	30	N	7	W	35	N	G	A728853	216600		12/2/55	12/19/55	12/19/55
300392190600S01	SAN JUAN 30-6 UT 100A MV	RIO ARRIBA	NM	30	N	7	W	35	E	G	A728853	216600		8/22/79	11/1/79	11/1/79
300393083500C01	SAN JUAN 30-6 UT 100B DK	RIO ARRIBA	NM	30	N	7	W	35	E	G	A713487	216600		2/3/11	4/4/11	4/4/11
300393083500C02	SAN JUAN 30-6 UT 100B MV	RIO ARRIBA	NM	30	N	7	W	35	E	G	A728853	216600		2/3/11	4/4/11	4/4/11
300393077700C01	SAN JUAN 30-6 UT 100M DK	RIO ARRIBA	NM	30	N	7	W	35	N	G	A714017	216600		2/18/11	2/18/11	3/24/11
300393077700C02	SAN JUAN 30-6 UT 100M MV	RIO ARRIBA	NM	30	N	7	W	35	N	G	A728853	216600		2/18/11	2/18/11	3/24/11
300390773100S01	SAN JUAN 30-6 UT 101 MV	RIO ARRIBA	NM	30	N	7	W	35	H	G	A728853	216600		5/16/56	5/29/56	5/29/56
300392227000S01	SAN JUAN 30-6 UT 101A MV	RIO ARRIBA	NM	30	N	7	W	35	O	G	A728853	216600		12/3/80	2/1/81	2/1/81
300393075600C01	SAN JUAN 30-6 UT 101M DK	RIO ARRIBA	NM	30	N	7	W	35	H	G	A713482	216600		7/17/10	7/17/10	7/7/10
300393075600C02	SAN JUAN 30-6 UT 101M MV	RIO ARRIBA	NM	30	N	7	W	35	H	G	A728853	216600		7/17/10	7/17/10	7/7/10
300392580400C01	SAN JUAN 30-6 UT 102A DK	RIO ARRIBA	NM	30	N	6	W	22	O	G	A728852	216600		7/17/98	9/14/98	9/14/98
300392580400C02	SAN JUAN 30-6 UT 102A MV	RIO ARRIBA	NM	30	N	6	W	22	O	G	A728853	216600		7/17/98	8/3/98	8/3/98
300393095600C01	SAN JUAN 30-6 UT 102M DK	RIO ARRIBA	NM	30	N	6	W	22	B	G	A728852	216600		9/3/11	9/6/11	9/6/11
300393095600C02	SAN JUAN 30-6 UT 102M MV	RIO ARRIBA	NM	30	N	6	W	22	B	G	A728853	216600		9/6/11	9/6/11	9/6/11
300393082800C01	SAN JUAN 30-6 UT 102N DK	RIO ARRIBA	NM	30	N	6	W	22	O	G	A728852	216600		10/28/10	10/28/10	1/5/11
300393082800C02	SAN JUAN 30-6 UT 102N MV	RIO ARRIBA	NM	30	N	6	W	22	O	G	A728853	216600		10/28/10	10/28/10	5/1/11
300392051900S01	SAN JUAN 30-6 UT 102R MV	RIO ARRIBA	NM	30	N	6	W	22	G	G	A728853	216600		10/11/72	12/1/82	12/1/82
300392052500S01	SAN JUAN 30-6 UT 103 MV	RIO ARRIBA	NM	30	N	6	W	25	G	G	A728853	216600		9/7/72	1/1/73	1/1/73
300392559400S01	SAN JUAN 30-6 UT 103A MV	RIO ARRIBA	NM	30	N	6	W	25	J	G	A728853	216600		12/2/96	12/13/96	12/13/96
300393081700C01	SAN JUAN 30-6 UT 104M DK	RIO ARRIBA	NM	30	N	7	W	28	A	G	A714868	216600		3/21/11	3/25/11	3/25/11
300393081700C02	SAN JUAN 30-6 UT 104M MV	RIO ARRIBA	NM	30	N	7	W	28	A	G	A728853	216600		3/21/11	3/25/11	3/25/11
300393095700C01	SAN JUAN 30-6 UT 104N DK	RIO ARRIBA	NM	30	N	7	W	28	P	G	A716078	216600		3/15/11	5/11/11	5/11/11
300393095700C02	SAN JUAN 30-6 UT 104N MV	RIO ARRIBA	NM	30	N	7	W	28	P	G	A728853	216600		3/15/11	5/11/11	5/11/11
300392560100S01	SAN JUAN 30-6 UT 104A MV	RIO ARRIBA	NM	30	N	7	W	31	O	G	A728853	216600		12/17/96	8/97	8/97
300392636800S01	SAN JUAN 30-6 UT 10B MV	RIO ARRIBA	NM	30	N	7	W	31	I	G	A728853	216600		11/9/00	1/26/01	1/26/01
300390779300S01	SAN JUAN 30-6 UT 11 MV	RIO ARRIBA	NM	30	N	6	W	23	L	G	A728853	216600		1/29/57	4/18/57	4/18/57
300392588800D01	SAN JUAN 30-6 UT 114 DK	RIO ARRIBA	NM	30	N	6	W	11	C	G	A724981	216600		1/18/99	2/2/99	2/2/99
300392588800D01	SAN JUAN 30-6 UT 114 DK	RIO ARRIBA	NM	30	N	6	W	11	C	G	A724981	216600		1/18/99	2/2/99	2/2/99

PRODUCTION STATUS

11 - FLOWING WELL
41 - SHUT IN
59 - SOLD
61 - TEMP ABANDON

71 - PERM ABANDON ZONE
72 - PERM ABANDON WELL
PA - PLUG ABANDON
PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN		RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392588800D02	SAN JUAN 30-6 UT 114 MV	RIO ARRIBA	NM	30	N	6	W	11	C	G	A728853	216600	BLANCO::MESAVERDE	11	1/18/99		2/2/99	2/2/99
300392663500C01	SAN JUAN 30-6 UT 114M DK	RIO ARRIBA	NM	30	N	6	W	11	K	G	A724981	216600	BASIN::DAKOTA	11	11/10/01		11/14/01	11/14/01
300392663500C01	SAN JUAN 30-6 UT 114M DK	RIO ARRIBA	NM	30	N	6	W	11	K	G	A724981	216600	BASIN::DAKOTA	11	11/10/01		11/14/01	11/14/01
300392663500C02	SAN JUAN 30-6 UT 114M MV	RIO ARRIBA	NM	30	N	6	W	11	K	G	A728853	216600	BLANCO::MESAVERDE	11	11/10/01		11/14/01	11/14/01
300392589800D01	SAN JUAN 30-6 UT 11A DK	RIO ARRIBA	NM	30	N	6	W	23	D	G	A724972	216600	BASIN::DAKOTA	11	12/14/98		1/6/99	1/6/99
300392589800D01	SAN JUAN 30-6 UT 11A DK	RIO ARRIBA	NM	30	N	6	W	23	D	G	A724972	216600	BASIN::DAKOTA	11	12/14/98		1/6/99	1/6/99
300392589800D02	SAN JUAN 30-6 UT 11A MV	RIO ARRIBA	NM	30	N	6	W	23	D	G	A728853	216600	BLANCO::MESAVERDE	11	12/14/98		1/6/99	1/6/99
300393099000C01	SAN JUAN 30-6 UT 11M DK	RIO ARRIBA	NM	30	N	6	W	23	D	G	A715388	216600	BASIN::DAKOTA	11	8/12/11		8/24/11	8/24/11
300393099000C02	SAN JUAN 30-6 UT 11M MV	RIO ARRIBA	NM	30	N	6	W	23	D	G	A728853	216600	BLANCO::MESAVERDE	11	8/12/11		8/24/11	8/24/11
300390775200S01	SAN JUAN 30-6 UT 12 MV	RIO ARRIBA	NM	30	N	6	W	26	M	G	A728853	216600	BLANCO::MESAVERDE	11	10/10/55		10/17/55	10/17/55
300392586800S01	SAN JUAN 30-6 UT 122 PC	RIO ARRIBA	NM	30	N	7	W	28	D	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	8/11/98		9/16/98	9/16/98
300392600200S01	SAN JUAN 30-6 UT 123 DK	RIO ARRIBA	NM	30	N	6	W	7	F	G	A724984	216600	BASIN::DAKOTA	11	12/1/98		12/10/98	12/10/98
300392600200S01	SAN JUAN 30-6 UT 123 DK	RIO ARRIBA	NM	30	N	6	W	7	F	G	A724984	216600	BASIN::DAKOTA	11	12/1/98		12/10/98	12/10/98
300392598500S01	SAN JUAN 30-6 UT 124 DK	RIO ARRIBA	NM	30	N	6	W	28	G	G	A728852	216600	BASIN::DAKOTA	11	1/29/99		2/12/99	2/12/99
300392598300S01	SAN JUAN 30-6 UT 125 DK	RIO ARRIBA	NM	30	N	6	W	7	O	G	A728852	216600	BASIN::DAKOTA	11	11/27/98		12/7/98	12/7/98
300392600300S01	SAN JUAN 30-6 UT 126 DK	RIO ARRIBA	NM	30	N	6	W	15	P	G	A728852	216600	BASIN::DAKOTA	72	6/21/99	12/7/12	7/1/99	7/1/99
300392598700S01	SAN JUAN 30-6 UT 127 DK	RIO ARRIBA	NM	30	N	6	W	21	A	G	A728852	216600	BASIN::DAKOTA	11	6/12/99		6/25/99	6/25/99
300392607600S01	SAN JUAN 30-6 UT 128 DK	RIO ARRIBA	NM	30	N	6	W	29	I	G	A728852	216600	BASIN::DAKOTA	11	8/30/99		9/23/99	9/23/99
300392612400S01	SAN JUAN 30-6 UT 129 DK	RIO ARRIBA	NM	30	N	7	W	25	P	G	A724988	216600	BASIN::DAKOTA	11	10/14/99		10/25/99	10/25/99
300392612400S01	SAN JUAN 30-6 UT 129 DK	RIO ARRIBA	NM	30	N	7	W	25	P	G	A724988	216600	BASIN::DAKOTA	11	10/14/99		10/25/99	10/25/99
300393080900C01	SAN JUAN 30-6 UT 129M DK	RIO ARRIBA	NM	30	N	7	W	25	J	G	A724988	216600	BASIN::DAKOTA	11	6/1/10		6/29/10	
300393080900C02	SAN JUAN 30-6 UT 129M MV	RIO ARRIBA	NM	30	N	7	W	25	J	G	A728853	216600	BLANCO::MESAVERDE	11	6/1/10		6/29/10	
300392570000S01	SAN JUAN 30-6 UT 12A MV	RIO ARRIBA	NM	30	N	6	W	26	D	G	A728853	216600	BLANCO::MESAVERDE	11	8/27/97		9/16/97	9/16/97
300390773700S01	SAN JUAN 30-6 UT 13 MV	RIO ARRIBA	NM	30	N	6	W	32	G	G	A728853	216600	BLANCO::MESAVERDE	11	12/13/55		3/16/56	3/16/56
300392644800S01	SAN JUAN 30-6 UT 135 P&A	RIO ARRIBA	NM	30	N	6	W	27	O	G	A724991	216600	BASIN::DAKOTA	71	10/23/00		11/9/00	11/9/00
300392650700S01	SAN JUAN 30-6 UT 138 DK	RIO ARRIBA	NM	30	N	6	W	18	I	G	A724989	216600	BASIN::DAKOTA	11	11/16/01		11/26/01	11/26/01
300392650900S01	SAN JUAN 30-6 UT 139 DK	RIO ARRIBA	NM	30	N	6	W	19	F	G	A728852	216600	BASIN::DAKOTA	11	11/2/00		11/20/00	11/20/00
300392167000S01	SAN JUAN 30-6 UT 13A MV	RIO ARRIBA	NM	30	N	6	W	32	J	G	A728853	216600	BLANCO::MESAVERDE	11	1/16/79		4/1/79	4/1/79
300393083300C01	SAN JUAN 30-6 UT 13M DK	RIO ARRIBA	NM	30	N	6	W	32	J	G	A714739	216600	BASIN::DAKOTA	11	7/6/10		7/6/10	7/6/10
300393083300C02	SAN JUAN 30-6 UT 13M MV	RIO ARRIBA	NM	30	N	6	W	32	J	G	A728853	216600	BLANCO::MESAVERDE	11	7/6/10		7/6/10	7/6/10
300390771500S01	SAN JUAN 30-6 UT 14 MV	RIO ARRIBA	NM	30	N	6	W	32	N	G	A728853	216600	BLANCO::MESAVERDE	11	2/4/57		2/4/57	2/4/57
300392947100S01	SAN JUAN 30-6 UT 140 PC	RIO ARRIBA	NM	30	N	7	W	28	A	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	8/22/05		9/1/05	9/1/05
300392769100S01	SAN JUAN 30-6 UT 141 PC	RIO ARRIBA	NM	30	N	7	W	33	G	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	8/20/05		9/1/05	9/1/05
300392613200S01	SAN JUAN 30-6 UT 144 PC	RIO ARRIBA	NM	30	N	7	W	27	M	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	6/16/99		7/13/99	7/13/99
300392677200S01	SAN JUAN 30-6 UT 145 DK	RIO ARRIBA	NM	30	N	6	W	22	E	G	A728852	216600	BASIN::DAKOTA	11	11/29/01		12/3/01	12/3/01
300393079400S01	SAN JUAN 30-6 UT 147 DK	RIO ARRIBA	NM	30	N	7	W	25	C	G	A714889	216600	BASIN::DAKOTA	11	3/24/10		1/26/11	
300393078800C01	SAN JUAN 30-6 UT 147M DK	RIO ARRIBA	NM	30	N	7	W	25	C	G	A724988	216600	BASIN::DAKOTA	11	6/21/10		1/26/11	
300393078800C02	SAN JUAN 30-6 UT 147M MV	RIO ARRIBA	NM	30	N	7	W	25	C	G	A728853	216600	BLANCO::MESAVERDE	11	6/21/10		1/26/11	
300393081600C01	SAN JUAN 30-6 UT 147N DK	RIO ARRIBA	NM	30	N	7	W	25	L	G	A724988	216600	BASIN::DAKOTA	11	11/21/10		11/21/10	12/1/10
300393081600C02	SAN JUAN 30-6 UT 147N MV	RIO ARRIBA	NM	30	N	7	W	25	L	G	A728853	216600	BLANCO::MESAVERDE	11	11/21/10		11/21/10	12/1/10
300392231300S01	SAN JUAN 30-6 UT 14A MV	RIO ARRIBA	NM	30	N	6	W	32	D	G	A728853	216600	BLANCO::MESAVERDE	11	9/15/80		7/1/81	7/1/81
300393083200C01	SAN JUAN 30-6 UT 14M DK	RIO ARRIBA	NM	30	N	6	W	32	C	G	A714738	216600	BASIN::DAKOTA	11	7/1/10		6/22/10	6/22/10
300393083200C02	SAN JUAN 30-6 UT 14M MV	RIO ARRIBA	NM	30	N	6	W	32	C	G	A728853	216600	BLANCO::MESAVERDE	11	7/1/10		6/22/10	6/22/10
300390775700S01	SAN JUAN 30-6 UT 15 MV	RIO ARRIBA	NM	30	N	7	W	29	L	G	A728853	216600	BLANCO::MESAVERDE	11	11/3/55		11/11/55	11/11/55
300392190200S01	SAN JUAN 30-6 UT 15A MV	RIO ARRIBA	NM	30	N	7	W	29	O	G	A728853	216600	BLANCO::MESAVERDE	11	8/7/79		2/1/80	2/1/80
300392681600S01	SAN JUAN 30-6 UT 15B MV	RIO ARRIBA	NM	30	N	7	W	29	N	G	A728853	216600	BLANCO::MESAVERDE	11	5/16/02		5/17/02	5/17/02
300393106200C01	SAN JUAN 30-6 UT 15C DK	RIO ARRIBA	NM	30	N	7	W	29	P	G	A715935	216600	BASIN::DAKOTA	11	1/24/12		1/24/12	1/24/12
300393106200C02	SAN JUAN 30-6 UT 15C MCS	RIO ARRIBA	NM	30	N	7	W	29	P	G	A717659	216600	BASIN::MANCOS	11	1/24/12		1/24/12	1/24/12
300393106200C03	SAN JUAN 30-6 UT 15C MV	RIO ARRIBA	NM	30	N	7	W	29	P	G	A728853	216600	BLANCO::MESAVERDE	11	1/24/12		1/24/12	1/24/12
300390776400S01	SAN JUAN 30-6 UT 16 MV	RIO ARRIBA	NM	30	N	6	W	26	H	G	A728853	216600	BLANCO::MESAVERDE	11	4/21/56		5/3/56	5/3/56

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN		RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsrv Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392567100S01	SAN JUAN 30-6 UT 16A MV	RIO ARRIBA	NM	30	N	6	W	26	I	G	A728853	216600	BLANCO::MESAVERDE	11	8/16/97		8/27/97	8/27/97
300390783300S01	SAN JUAN 30-6 UT 17 MV	RIO ARRIBA	NM	30	N	6	W	18	N	G	A728853	216600	BLANCO::MESAVERDE	11	9/20/57		10/3/57	10/3/57
300392567000C01	SAN JUAN 30-6 UT 17A DK	RIO ARRIBA	NM	30	N	6	W	18	E	G	A728852	216600	BASIN::DAKOTA	11	11/20/97		12/15/97	12/15/97
300392567000C02	SAN JUAN 30-6 UT 17A MV	RIO ARRIBA	NM	30	N	6	W	18	E	G	A728853	216600	BLANCO::MESAVERDE	11	11/20/97		12/15/97	12/15/97
300390785600S01	SAN JUAN 30-6 UT 18 MV	RIO ARRIBA	NM	30	N	6	W	18	A	G	A728853	216600	BLANCO::MESAVERDE	11	8/28/57		9/12/57	9/12/57
300392197700S01	SAN JUAN 30-6 UT 18A MV	RIO ARRIBA	NM	30	N	6	W	18	I	G	A728853	216600	BLANCO::MESAVERDE	11	9/20/79		3/1/80	3/1/80
300392699900C01	SAN JUAN 30-6 UT 1A DK	RIO ARRIBA	NM	30	N	6	W	9	O	G	A724999	216600	BASIN::DAKOTA	11	9/13/02		10/7/02	10/7/02
300392699900C01	SAN JUAN 30-6 UT 1A DK	RIO ARRIBA	NM	30	N	6	W	9	O	G	A724999	216600	BASIN::DAKOTA	11	9/13/02		10/7/02	10/7/02
300392699900C02	SAN JUAN 30-6 UT 1A MV	RIO ARRIBA	NM	30	N	6	W	9	O	G	A728853	216600	BLANCO::MESAVERDE	11	9/13/02		10/7/02	10/7/02
300393062500C01	SAN JUAN 30-6 UT 1M DK	RIO ARRIBA	NM	30	N	6	W	10	D	G	A724999	216600	BASIN::DAKOTA	11	7/22/11		9/15/11	9/15/11
300393062500C02	SAN JUAN 30-6 UT 1M MV	RIO ARRIBA	NM	30	N	6	W	10	D	G	A728853	216600	BLANCO::MESAVERDE	11	7/22/11		9/15/11	9/15/11
300390785700S01	SAN JUAN 30-6 UT 24 MV	RIO ARRIBA	NM	30	N	6	W	16	B	G	A728853	216600	BLANCO::MESAVERDE	11	4/6/57		4/18/57	4/18/57
300392206600S01	SAN JUAN 30-6 UT 24A MV	RIO ARRIBA	NM	30	N	6	W	16	O	G	A728853	216600	BLANCO::MESAVERDE	11	5/19/80		9/1/80	9/1/80
300392687000S01	SAN JUAN 30-6 UT 24B MV	RIO ARRIBA	NM	30	N	6	W	16	I	G	A728853	216600	BLANCO::MESAVERDE	11	7/23/03		7/25/03	7/25/03
300390780400S01	SAN JUAN 30-6 UT 25 MV	RIO ARRIBA	NM	30	N	6	W	19	H	G	A728853	216600	BLANCO::MESAVERDE	11	5/30/58		6/16/58	6/16/58
300392561800S01	SAN JUAN 30-6 UT 25A MV	RIO ARRIBA	NM	30	N	6	W	19	P	G	A728853	216600	BLANCO::MESAVERDE	11	4/12/97		4/21/97	4/21/97
300390779000S01	SAN JUAN 30-6 UT 26 MV	RIO ARRIBA	NM	30	N	6	W	19	M	G	A728853	216600	BLANCO::MESAVERDE	11	5/9/58		5/21/58	5/21/58
300392193900S01	SAN JUAN 30-6 UT 26A MV	RIO ARRIBA	NM	30	N	6	W	19	F	G	A728853	216600	BLANCO::MESAVERDE	11	8/30/79		5/1/80	5/1/80
300392585000C01	SAN JUAN 30-6 UT 27A DK	RIO ARRIBA	NM	30	N	6	W	23	O	G	A724969	216600	BASIN::DAKOTA	11	2/17/99		4/15/99	4/15/99
300392585000C01	SAN JUAN 30-6 UT 27A DK	RIO ARRIBA	NM	30	N	6	W	23	O	G	A724969	216600	BASIN::DAKOTA	11	2/17/99		4/15/99	4/15/99
300392585000C02	SAN JUAN 30-6 UT 27A MV	RIO ARRIBA	NM	30	N	6	W	23	O	G	A728853	216600	BLANCO::MESAVERDE	11	2/17/99		4/15/99	4/15/99
300390774200S01	SAN JUAN 30-6 UT 28 MV	RIO ARRIBA	NM	30	N	6	W	33	B	G	A728853	216600	BLANCO::MESAVERDE	11	4/3/58		6/16/58	6/16/58
300392169200S01	SAN JUAN 30-6 UT 28A MV	RIO ARRIBA	NM	30	N	6	W	33	J	G	A728853	216600	BLANCO::MESAVERDE	11	1/15/79		4/1/79	4/1/79
300390789900S01	SAN JUAN 30-6 UT 29 MV	RIO ARRIBA	NM	30	N	6	W	12	B	G	A728853	216600	BLANCO::MESAVERDE	11	5/7/59		5/14/59	5/14/59
300392560700S01	SAN JUAN 30-6 UT 29A MV	RIO ARRIBA	NM	30	N	6	W	12	J	G	A728853	216600	BLANCO::MESAVERDE	11	1/16/97		1/28/97	1/28/97
300393057500C01	SAN JUAN 30-6 UT 2A DK	RIO ARRIBA	NM	30	N	6	W	9	E	G	A712621	216600	BASIN::DAKOTA	11	7/1/11		7/1/11	7/1/11
300393057500C02	SAN JUAN 30-6 UT 2A MV	RIO ARRIBA	NM	30	N	6	W	9	E	G	A728853	216600	BLANCO::MESAVERDE	11	7/1/11		7/1/11	7/1/11
300396009801S01	SAN JUAN 30-6 UT 3 MV	RIO ARRIBA	NM	30	N	6	W	24	M	G	A728853	216600	BLANCO::MESAVERDE	11	8/11/53		8/11/53	8/11/53
300392567900C01	SAN JUAN 30-6 UT 30A DK	RIO ARRIBA	NM	30	N	6	W	20	J	G	A724960	216600	BASIN::DAKOTA	11	9/21/97		10/15/97	10/15/97
300392567900C02	SAN JUAN 30-6 UT 30A MV	RIO ARRIBA	NM	30	N	6	W	20	J	G	A728853	216600	BLANCO::MESAVERDE	11	9/21/97		10/15/97	10/15/97
30039256100S01	SAN JUAN 30-6 UT 30R MV	RIO ARRIBA	NM	30	N	6	W	20	A	G	A728853	216600	BLANCO::MESAVERDE	11	9/20/93		3/1/94	3/18/94
300390771200C01	SAN JUAN 30-6 UT 31 DK	RIO ARRIBA	NM	30	N	6	W	33	N	G	A725003	216600	BASIN::DAKOTA	11	7/2/59		9/9/59	9/9/59
300390771200C01	SAN JUAN 30-6 UT 31 DK	RIO ARRIBA	NM	30	N	6	W	33	N	G	A725003	216600	BASIN::DAKOTA	11	7/2/59		9/9/59	9/9/59
300390771200C02	SAN JUAN 30-6 UT 31 MV	RIO ARRIBA	NM	30	N	6	W	33	N	G	A728853	216600	BLANCO::MESAVERDE	11	7/2/59		7/22/59	7/22/59
300392562000S01	SAN JUAN 30-6 UT 31A MV	RIO ARRIBA	NM	30	N	6	W	33	F	G	A728853	216600	BLANCO::MESAVERDE	11	4/26/97		5/9/97	5/9/97
300392637500S01	SAN JUAN 30-6 UT 31Y DK	RIO ARRIBA	NM	30	N	6	W	33	D	G	A728852	216600	BASIN::DAKOTA	11	10/16/00		10/23/00	10/23/00
300390788700S01	SAN JUAN 30-6 UT 32 MV	RIO ARRIBA	NM	30	N	6	W	7	H	G	A728853	216600	BLANCO::MESAVERDE	11	10/16/59		10/27/59	10/27/59
300392197600S01	SAN JUAN 30-6 UT 32A MV	RIO ARRIBA	NM	30	N	6	W	7	J	G	A728853	216600	BLANCO::MESAVERDE	11	10/2/79		12/1/79	12/1/79
300390786900S01	SAN JUAN 30-6 UT 33 MV	RIO ARRIBA	NM	30	N	6	W	8	N	G	A728853	216600	BLANCO::MESAVERDE	11	9/22/60		10/29/60	10/29/60
300392565600S01	SAN JUAN 30-6 UT 33A MV	RIO ARRIBA	NM	30	N	6	W	8	E	G	A728853	216600	BLANCO::MESAVERDE	11	11/5/97		11/21/97	11/21/97
300392642900C01	SAN JUAN 30-6 UT 33B DK	RIO ARRIBA	NM	30	N	6	W	8	D	G	A728852	216600	BASIN::DAKOTA	11	11/25/01		11/30/01	11/30/01
300392642900C02	SAN JUAN 30-6 UT 33B MV	RIO ARRIBA	NM	30	N	6	W	8	D	G	A728853	216600	BLANCO::MESAVERDE	11	8/19/02		8/22/02	8/22/02
300390786600S01	SAN JUAN 30-6 UT 34 MV	RIO ARRIBA	NM	30	N	6	W	10	M	G	A728853	216600	BLANCO::MESAVERDE	11	7/28/60		8/13/60	8/13/60
300392581200C01	SAN JUAN 30-6 UT 34A DK	RIO ARRIBA	NM	30	N	6	W	10	C	G	A728852	216600	BASIN::DAKOTA	11	8/5/98		9/3/98	9/3/98
300392581200C02	SAN JUAN 30-6 UT 34A MV	RIO ARRIBA	NM	30	N	6	W	10	C	G	A728853	216600	BLANCO::MESAVERDE	11	8/6/98		8/31/98	8/31/98
300392641000S01	SAN JUAN 30-6 UT 34B MV	RIO ARRIBA	NM	30	N	6	W	10	K	G	A728853	216600	BLANCO::MESAVERDE	11	11/16/01		11/21/01	11/21/01
300392995200S01	SAN JUAN 30-6 UT 34E DK	RIO ARRIBA	NM	30	N	6	W	10	K	G	A728852	216600	BASIN::DAKOTA	11	11/11/06		4/30/07	5/1/07
300393057700C01	SAN JUAN 30-6 UT 34N DK	RIO ARRIBA	NM	30	N	6	W	10	D	G	A728852	216600	BASIN::DAKOTA	11	7/4/11		7/26/11	7/26/11
300393057700C02	SAN JUAN 30-6 UT 34N MV	RIO ARRIBA	NM	30	N	6	W	10	D	G	A728853	216600	BLANCO::MESAVERDE	11	7/4/11		7/26/11	7/26/11
300392651300S01	SAN JUAN 30-6 UT 35A MV	RIO ARRIBA	NM	30	N	6	W	24	J	G	A728853	216600	BLANCO::MESAVERDE	11	1/4/01		1/30/01	1/30/01

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300393087100C01	SAN JUAN 30-6 UT 35B DK	RIO ARRIBA	NM	30	N	6	W	24	J	G	A714751	216600	BASIN::DAKOTA	11	10/25/10	12/1/10
300393087100C02	SAN JUAN 30-6 UT 35B MV	RIO ARRIBA	NM	30	N	6	W	24	J	G	A728853	216600	BLANCO::MESAVERDE	11	10/25/10	12/1/10
300390788600S01	SAN JUAN 30-6 UT 36 MV	RIO ARRIBA	NM	30	N	6	W	8	G	G	A728853	216600	BLANCO::MESAVERDE	11	8/6/61	8/16/61
300392568300C01	SAN JUAN 30-6 UT 36A DK	RIO ARRIBA	NM	30	N	6	W	8	P	G	A728852	216600	BASIN::DAKOTA	11	9/21/97	10/21/97
300392568300C02	SAN JUAN 30-6 UT 36A MV	RIO ARRIBA	NM	30	N	6	W	8	P	G	A728853	216600	BLANCO::MESAVERDE	11	9/21/97	10/21/97
300393052400C01	SAN JUAN 30-6 UT 36N DK	RIO ARRIBA	NM	30	N	6	W	8	H	G	A728852	216600	BASIN::DAKOTA	11	7/21/09	
300393052400C02	SAN JUAN 30-6 UT 36N MV	RIO ARRIBA	NM	30	N	6	W	8	H	G	A728853	216600	BLANCO::MESAVERDE	11	7/21/09	
300390789500S01	SAN JUAN 30-6 UT 37 MV	RIO ARRIBA	NM	30	N	6	W	10	B	G	A728853	216600	BLANCO::MESAVERDE	11	7/23/61	9/1/61
300392577700C01	SAN JUAN 30-6 UT 37A DK	RIO ARRIBA	NM	30	N	6	W	10	I	G	A728852	216600	BASIN::DAKOTA	11	7/27/98	8/13/98
300392577700C02	SAN JUAN 30-6 UT 37A MV	RIO ARRIBA	NM	30	N	6	W	10	I	G	A728853	216600	BLANCO::MESAVERDE	11	7/27/98	8/10/98
300390911000S01	SAN JUAN 30-6 UT 38 MV	RIO ARRIBA	NM	30	N	7	W	27	M	G	A728853	216600	BLANCO::MESAVERDE	11	10/25/52	10/25/52
300392567300S01	SAN JUAN 30-6 UT 38A MV	RIO ARRIBA	NM	30	N	7	W	27	E	G	A728853	216600	BLANCO::MESAVERDE	11	9/16/97	9/24/97
300392678000S01	SAN JUAN 30-6 UT 38B MV	RIO ARRIBA	NM	30	N	7	W	27	F	G	A728853	216600	BLANCO::MESAVERDE	11	8/26/02	8/28/02
300392689900S01	SAN JUAN 30-6 UT 38C MV	RIO ARRIBA	NM	30	N	7	W	27	K	G	A728853	216600	BLANCO::MESAVERDE	11	7/15/02	7/17/02
300390785800S01	SAN JUAN 30-6 UT 39 MV	RIO ARRIBA	NM	30	N	6	W	13	B	G	A728853	216600	BLANCO::MESAVERDE	11	6/2/55	6/16/55
300392581100C01	SAN JUAN 30-6 UT 39A DK	RIO ARRIBA	NM	30	N	6	W	13	J	G	A728852	216600	BASIN::DAKOTA	11	8/24/98	9/18/98
300392581100C02	SAN JUAN 30-6 UT 39A MV	RIO ARRIBA	NM	30	N	6	W	13	J	G	A728853	216600	BLANCO::MESAVERDE	11	8/24/98	9/18/98
300393064700C01	SAN JUAN 30-6 UT 39M DK	RIO ARRIBA	NM	30	N	6	W	13	G	G	A728852	216600	BASIN::DAKOTA	11	9/2/09	8/24/09
300393064700C02	SAN JUAN 30-6 UT 39M MV	RIO ARRIBA	NM	30	N	6	W	13	G	G	A728853	216600	BLANCO::MESAVERDE	11	9/2/09	8/24/09
300393083400C01	SAN JUAN 30-6 UT 39N DK	RIO ARRIBA	NM	30	N	6	W	13	J	G	A728852	216600	BASIN::DAKOTA	11	9/13/10	9/13/10
300393083400C02	SAN JUAN 30-6 UT 39N MV	RIO ARRIBA	NM	30	N	6	W	13	J	G	A728853	216600	BLANCO::MESAVERDE	11	9/13/10	9/13/10
300392580500C01	SAN JUAN 30-6 UT 3A DK	RIO ARRIBA	NM	30	N	6	W	24	D	G	A728852	216600	BASIN::DAKOTA	11	6/22/98	7/21/98
300392580500C02	SAN JUAN 30-6 UT 3A MV	RIO ARRIBA	NM	30	N	6	W	24	D	G	A728853	216600	BLANCO::MESAVERDE	11	6/22/98	7/21/98
300393085100C01	SAN JUAN 30-6 UT 3M DK	RIO ARRIBA	NM	30	N	6	W	24	D	G	A728852	216600	BASIN::DAKOTA	11	8/8/10	9/29/10
300393085100C02	SAN JUAN 30-6 UT 3M MV	RIO ARRIBA	NM	30	N	6	W	24	D	G	A728853	216600	BLANCO::MESAVERDE	11	6/3/10	9/29/10
300393096500C01	SAN JUAN 30-6 UT 3N DK	RIO ARRIBA	NM	30	N	6	W	24	J	G	A728852	216600	BASIN::DAKOTA	11	10/14/10	11/15/10
300393096500C02	SAN JUAN 30-6 UT 3N MV	RIO ARRIBA	NM	30	N	6	W	24	J	G	A728853	216600	BLANCO::MESAVERDE	11	10/14/10	
300392393400S01	SAN JUAN 30-6 UT 400 FC	RIO ARRIBA	NM	30	N	7	W	14	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/12/85	12/14/85
300392393400S01	SAN JUAN 30-6 UT 400 FC	RIO ARRIBA	NM	30	N	7	W	14	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/12/85	12/14/85
300392940300S01	SAN JUAN 30-6 UT 400S FC	RIO ARRIBA	NM	30	N	7	W	14	F	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/23/05	6/10/05
300392940300S01	SAN JUAN 30-6 UT 400S FC	RIO ARRIBA	NM	30	N	7	W	14	F	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/23/05	6/10/05
300392436600S01	SAN JUAN 30-6 UT 401R FC	RIO ARRIBA	NM	30	N	7	W	13	N	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/28/89	3/28/89
300392436600S01	SAN JUAN 30-6 UT 401R FC	RIO ARRIBA	NM	30	N	7	W	13	N	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/28/89	3/28/89
300392940200S01	SAN JUAN 30-6 UT 401S FC	RIO ARRIBA	NM	30	N	7	W	13	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/16/05	6/16/05
300392940200S01	SAN JUAN 30-6 UT 401S FC	RIO ARRIBA	NM	30	N	7	W	13	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/16/05	6/16/05
300392401500S01	SAN JUAN 30-6 UT 402 FC	RIO ARRIBA	NM	30	N	7	W	15	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	4/17/86	5/7/86
300392401500S01	SAN JUAN 30-6 UT 402 FC	RIO ARRIBA	NM	30	N	7	W	15	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	4/17/86	5/7/86
300392471700S01	SAN JUAN 30-6 UT 403 FC	RIO ARRIBA	NM	30	N	6	W	9	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/10/90	12/5/90
300392471700S01	SAN JUAN 30-6 UT 403 FC	RIO ARRIBA	NM	30	N	6	W	9	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/10/90	12/5/90
300392776300S01	SAN JUAN 30-6 UT 403S FC	RIO ARRIBA	NM	30	N	6	W	9	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	11/24/06	10/9/12
300392776300S01	SAN JUAN 30-6 UT 403S FC	RIO ARRIBA	NM	30	N	6	W	9	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	11/24/06	10/9/12
300392524100S01	SAN JUAN 30-6 UT 404R FC	RIO ARRIBA	NM	30	N	7	W	23	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	2/14/93	6/1/93
300392524100S01	SAN JUAN 30-6 UT 404R FC	RIO ARRIBA	NM	30	N	7	W	23	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	2/14/93	6/1/93
300392768800S01	SAN JUAN 30-6 UT 404S FC	RIO ARRIBA	NM	30	N	7	W	23	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	3/7/05	12/13/11
300392768800S01	SAN JUAN 30-6 UT 404S FC	RIO ARRIBA	NM	30	N	7	W	23	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	3/7/05	12/13/11
300392458900S01	SAN JUAN 30-6 UT 405 FC	RIO ARRIBA	NM	30	N	6	W	9	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/22/89	3/29/90
300392458900S01	SAN JUAN 30-6 UT 405 FC	RIO ARRIBA	NM	30	N	6	W	9	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/22/89	3/29/90
300392933800S01	SAN JUAN 30-6 UT 405S FC	RIO ARRIBA	NM	30	N	6	W	9	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/28/04	11/16/04
300392933800S01	SAN JUAN 30-6 UT 405S FC	RIO ARRIBA	NM	30	N	6	W	9	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/28/04	11/16/04
300392448400S01	SAN JUAN 30-6 UT 406R FC	RIO ARRIBA	NM	30	N	7	W	15	F	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/2/89	9/1/89

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN		RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392448400\$01	SAN JUAN 30-6 UT 406R FC	RIO ARRIBA	NM	30	N	7	W	15	F	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/2/89		9/1/89	9/1/89
300392452700\$01	SAN JUAN 30-6 UT 407 FC	RIO ARRIBA	NM	30	N	6	W	16	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/15/89		12/6/89	12/6/89
300392452700\$01	SAN JUAN 30-6 UT 407 FC	RIO ARRIBA	NM	30	N	6	W	16	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/15/89		12/6/89	12/6/89
300392452600\$01	SAN JUAN 30-6 UT 408 FC	RIO ARRIBA	NM	30	N	6	W	16	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/26/89		12/6/89	12/6/89
300392452600\$01	SAN JUAN 30-6 UT 408 FC	RIO ARRIBA	NM	30	N	6	W	16	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/26/89		12/6/89	12/6/89
300392694300\$01	SAN JUAN 30-6 UT 408S FC	RIO ARRIBA	NM	30	N	6	W	16	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/17/02		10/6/03	10/6/03
300392694300\$01	SAN JUAN 30-6 UT 408S FC	RIO ARRIBA	NM	30	N	6	W	16	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/17/02		10/6/03	10/6/03
300392418600\$01	SAN JUAN 30-6 UT 409 FC	RIO ARRIBA	NM	30	N	7	W	25	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/20/87		2/10/88	2/10/88
300392418600\$01	SAN JUAN 30-6 UT 409 FC	RIO ARRIBA	NM	30	N	7	W	25	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/20/87		2/10/88	2/10/88
300392583500\$01	SAN JUAN 30-6 UT 40A DK	RIO ARRIBA	NM	30	N	6	W	12	E	G	A728852	216600	BASIN::DAKOTA	11	1/3/99		1/22/99	1/22/99
300392583500\$02	SAN JUAN 30-6 UT 40A MV	RIO ARRIBA	NM	30	N	6	W	12	E	G	A728853	216600	BLANCO::MESAVERDE	11	1/3/99		1/22/99	1/22/99
300393087300\$01	SAN JUAN 30-6 UT 40N DK	RIO ARRIBA	NM	30	N	6	W	11	A	G	A728852	216600	BASIN::DAKOTA	11	4/23/10		7/16/10	7/16/10
300393087300\$02	SAN JUAN 30-6 UT 40N MV	RIO ARRIBA	NM	30	N	6	W	11	A	G	A728853	216600	BLANCO::MESAVERDE	11	4/23/10		7/16/10	7/16/10
300390787400\$01	SAN JUAN 30-6 UT 40X MV	RIO ARRIBA	NM	30	N	6	W	12	M	G	A728853	216600	BLANCO::MESAVERDE	11	6/25/57		8/20/57	8/20/57
300391820100\$01	SAN JUAN 30-6 UT 41 MV	RIO ARRIBA	NM	30	N	6	W	13	M	G	A728853	216600	BLANCO::MESAVERDE	11	7/14/57		8/20/57	8/20/57
300392460200\$01	SAN JUAN 30-6 UT 410 FC	RIO ARRIBA	NM	30	N	6	W	26	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/22/90		9/27/90	9/27/90
300392460200\$01	SAN JUAN 30-6 UT 410 FC	RIO ARRIBA	NM	30	N	6	W	26	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/22/90		9/27/90	9/27/90
300392941700\$01	SAN JUAN 30-6 UT 410S FC	RIO ARRIBA	NM	30	N	6	W	26	P	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/17/05		10/10/05	10/10/05
300392941700\$01	SAN JUAN 30-6 UT 410S FC	RIO ARRIBA	NM	30	N	6	W	26	P	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/17/05		10/10/05	10/10/05
300392418900\$01	SAN JUAN 30-6 UT 411 FC	RIO ARRIBA	NM	30	N	7	W	27	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/28/87		12/28/87	12/28/87
300392418900\$01	SAN JUAN 30-6 UT 411 FC	RIO ARRIBA	NM	30	N	7	W	27	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/28/87		12/28/87	12/28/87
300392725900\$01	SAN JUAN 30-6 UT 411S FC	RIO ARRIBA	NM	30	N	7	W	27	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/5/03		7/21/03	7/21/03
300392725900\$01	SAN JUAN 30-6 UT 411S FC	RIO ARRIBA	NM	30	N	7	W	27	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/5/03		7/21/03	7/21/03
300392415300\$01	SAN JUAN 30-6 UT 412 FC	RIO ARRIBA	NM	30	N	7	W	24	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/19/88		1/27/88	1/27/88
300392415300\$01	SAN JUAN 30-6 UT 412 FC	RIO ARRIBA	NM	30	N	7	W	24	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/19/88		1/27/88	1/27/88
300392775600\$01	SAN JUAN 30-6 UT 412S FC	RIO ARRIBA	NM	30	N	7	W	24	P	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/22/04		11/16/04	11/16/04
300392775600\$01	SAN JUAN 30-6 UT 412S FC	RIO ARRIBA	NM	30	N	7	W	24	P	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/22/04		11/16/04	11/16/04
300392439600\$01	SAN JUAN 30-6 UT 413R FC	RIO ARRIBA	NM	30	N	7	W	23	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/19/89		5/23/89	5/23/89
300392439600\$01	SAN JUAN 30-6 UT 413R FC	RIO ARRIBA	NM	30	N	7	W	23	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/19/89		5/23/89	5/23/89
300392768100\$01	SAN JUAN 30-6 UT 413S FC	RIO ARRIBA	NM	30	N	7	W	23	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/13/04		6/14/04	6/14/04
300392768100\$01	SAN JUAN 30-6 UT 413S FC	RIO ARRIBA	NM	30	N	7	W	23	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/13/04		6/14/04	6/14/04
300392415400\$01	SAN JUAN 30-6 UT 414 FC	RIO ARRIBA	NM	30	N	7	W	35	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/7/87		1/1/88	1/1/88
300392415400\$01	SAN JUAN 30-6 UT 414 FC	RIO ARRIBA	NM	30	N	7	W	35	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/7/87		1/1/88	1/1/88
300392730500\$01	SAN JUAN 30-6 UT 414S FC	RIO ARRIBA	NM	30	N	7	W	35	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	61	6/16/03		7/21/03	7/21/03
300392730500\$01	SAN JUAN 30-6 UT 414S FC	RIO ARRIBA	NM	30	N	7	W	35	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	61	6/16/03		7/21/03	7/21/03
300392418800\$01	SAN JUAN 30-6 UT 415 FC	RIO ARRIBA	NM	30	N	7	W	26	N	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/23/87		12/7/87	12/7/87
300392418800\$01	SAN JUAN 30-6 UT 415 FC	RIO ARRIBA	NM	30	N	7	W	26	N	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/23/87		12/7/87	12/7/87
300392773800\$01	SAN JUAN 30-6 UT 415S FC	RIO ARRIBA	NM	30	N	7	W	26	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	3/25/05	12/20/12	4/6/05	4/6/05
300392773800\$01	SAN JUAN 30-6 UT 415S FC	RIO ARRIBA	NM	30	N	7	W	26	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	3/25/05	12/20/12	4/6/05	4/6/05
300392418300\$01	SAN JUAN 30-6 UT 416 FC	RIO ARRIBA	NM	30	N	7	W	24	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/3/87		12/4/87	12/4/87
300392418300\$01	SAN JUAN 30-6 UT 416 FC	RIO ARRIBA	NM	30	N	7	W	24	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/3/87		12/4/87	12/4/87
300392418500\$01	SAN JUAN 30-6 UT 417 FC	RIO ARRIBA	NM	30	N	7	W	25	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/7/87		12/7/87	12/7/87
300392418500\$01	SAN JUAN 30-6 UT 417 FC	RIO ARRIBA	NM	30	N	7	W	25	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/7/87		12/7/87	12/7/87
300392418700\$01	SAN JUAN 30-6 UT 418 FC	RIO ARRIBA	NM	30	N	7	W	26	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/28/87		12/28/87	12/28/87
300392418700\$01	SAN JUAN 30-6 UT 418 FC	RIO ARRIBA	NM	30	N	7	W	26	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/28/87		12/28/87	12/28/87
300392417700\$01	SAN JUAN 30-6 UT 419 FC	RIO ARRIBA	NM	30	N	7	W	11	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/4/87		12/4/87	12/4/87
300392417700\$01	SAN JUAN 30-6 UT 419 FC	RIO ARRIBA	NM	30	N	7	W	11	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/4/87		12/4/87	12/4/87
300392943800\$01	SAN JUAN 30-6 UT 419S FC	RIO ARRIBA	NM	30	N	7	W	11	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/10/05		6/21/05	6/21/05
300392943800\$01	SAN JUAN 30-6 UT 419S FC	RIO ARRIBA	NM	30	N	7	W	11	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/10/05		6/21/05	6/21/05
300392583600\$01	SAN JUAN 30-6 UT 41A DK	RIO ARRIBA	NM	30	N	6	W	13	F	G	A728852	216600	BASIN::DAKOTA	11	9/3/98		9/29/98	9/29/98

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392583600C02	SAN JUAN 30-6 UT 41A MV	RIO ARRIBA	NM	30	N	6	W	13	F	G	A728853	216600			9/24/98	9/24/98
300393060000C01	SAN JUAN 30-6 UT 41M DK	RIO ARRIBA	NM	30	N	6	W	13	L	G	A728852	216600			6/16/09	6/16/09
300393060000C02	SAN JUAN 30-6 UT 41M MV	RIO ARRIBA	NM	30	N	6	W	13	L	G	A728853	216600			6/16/09	6/16/09
300390783100S01	SAN JUAN 30-6 UT 42 MV	RIO ARRIBA	NM	30	N	6	W	14	M	G	A728853	216600			11/1/56	11/1/56
300392417800S01	SAN JUAN 30-6 UT 420 FC	RIO ARRIBA	NM	30	N	7	W	12	G	G	A728855	216600			1/1/88	1/1/88
300392417800S01	SAN JUAN 30-6 UT 420 FC	RIO ARRIBA	NM	30	N	7	W	12	G	G	A728855	216600			1/1/88	1/1/88
300392944900S01	SAN JUAN 30-6 UT 420S FC	RIO ARRIBA	NM	30	N	7	W	12	I	G	A728855	216600			7/15/05	7/15/05
300392944900S01	SAN JUAN 30-6 UT 420S FC	RIO ARRIBA	NM	30	N	7	W	12	I	G	A728855	216600			7/15/05	7/15/05
300392422100S01	SAN JUAN 30-6 UT 421 FC	RIO ARRIBA	NM	30	N	7	W	34	G	G	A728855	216600			8/12/88	8/12/88
300392422100S01	SAN JUAN 30-6 UT 421 FC	RIO ARRIBA	NM	30	N	7	W	34	G	G	A728855	216600			8/12/88	8/12/88
300392426100S01	SAN JUAN 30-6 UT 422 FC	RIO ARRIBA	NM	30	N	7	W	27	M	G	A728855	216600			10/3/90	10/3/90
300392426100S01	SAN JUAN 30-6 UT 422 FC	RIO ARRIBA	NM	30	N	7	W	27	M	G	A728855	216600			10/3/90	10/3/90
300392730600S01	SAN JUAN 30-6 UT 422S FC	RIO ARRIBA	NM	30	N	7	W	27	E	G	A728855	216600			7/29/03	7/29/03
300392730600S01	SAN JUAN 30-6 UT 422S FC	RIO ARRIBA	NM	30	N	7	W	27	E	G	A728855	216600			7/29/03	7/29/03
300392445900S01	SAN JUAN 30-6 UT 423 FC	RIO ARRIBA	NM	30	N	7	W	28	A	G	A728855	216600			10/3/90	10/3/90
300392445900S01	SAN JUAN 30-6 UT 423 FC	RIO ARRIBA	NM	30	N	7	W	28	A	G	A728855	216600			10/3/90	10/3/90
300392940700S01	SAN JUAN 30-6 UT 423S FC	RIO ARRIBA	NM	30	N	7	W	28	P	G	A728855	216600			3/19/08	3/19/08
300392940700S01	SAN JUAN 30-6 UT 423S FC	RIO ARRIBA	NM	30	N	7	W	28	P	G	A728855	216600			3/19/08	3/19/08
300392425000S01	SAN JUAN 30-6 UT 424 FC	RIO ARRIBA	NM	30	N	7	W	33	K	G	A728855	216600			5/5/92	5/5/92
300392425000S01	SAN JUAN 30-6 UT 424 FC	RIO ARRIBA	NM	30	N	7	W	33	K	G	A728855	216600			5/5/92	5/5/92
300392940600S01	SAN JUAN 30-6 UT 424S FC	RIO ARRIBA	NM	30	N	7	W	33	E	G	A728855	216600			3/17/06	3/17/06
300392940600S01	SAN JUAN 30-6 UT 424S FC	RIO ARRIBA	NM	30	N	7	W	33	E	G	A728855	216600			3/17/06	3/17/06
300392423800S01	SAN JUAN 30-6 UT 425 FC	RIO ARRIBA	NM	30	N	7	W	33	H	G	A728855	216600			5/5/92	5/5/92
300392423800S01	SAN JUAN 30-6 UT 425 FC	RIO ARRIBA	NM	30	N	7	W	33	H	G	A728855	216600			5/5/92	5/5/92
300392730700S01	SAN JUAN 30-6 UT 425S FC	RIO ARRIBA	NM	30	N	7	W	33	I	G	A728855	216600			6/19/03	6/19/03
300392730700S01	SAN JUAN 30-6 UT 425S FC	RIO ARRIBA	NM	30	N	7	W	33	I	G	A728855	216600			6/19/03	6/19/03
300392424800S01	SAN JUAN 30-6 UT 426 FC	RIO ARRIBA	NM	30	N	7	W	34	K	G	A728855	216600			4/28/89	4/28/89
300392424800S01	SAN JUAN 30-6 UT 426 FC	RIO ARRIBA	NM	30	N	7	W	34	K	G	A728855	216600			4/28/89	4/28/89
300392730400S01	SAN JUAN 30-6 UT 426S FC	RIO ARRIBA	NM	30	N	7	W	34	F	G	A728855	216600			6/12/03	6/12/03
300392730400S01	SAN JUAN 30-6 UT 426S FC	RIO ARRIBA	NM	30	N	7	W	34	F	G	A728855	216600			6/12/03	6/12/03
300392426200S01	SAN JUAN 30-6 UT 427 FC	RIO ARRIBA	NM	30	N	7	W	35	H	G	A728855	216600			1/17/89	1/17/89
300392426200S01	SAN JUAN 30-6 UT 427 FC	RIO ARRIBA	NM	30	N	7	W	35	H	G	A728855	216600			1/17/89	1/17/89
300392438100S01	SAN JUAN 30-6 UT 428 FC	RIO ARRIBA	NM	30	N	7	W	28	N	G	A728855	216600			5/7/92	5/7/92
300392438100S01	SAN JUAN 30-6 UT 428 FC	RIO ARRIBA	NM	30	N	7	W	28	N	G	A728855	216600			5/7/92	5/7/92
300392429700S01	SAN JUAN 30-6 UT 429 FC	RIO ARRIBA	NM	30	N	7	W	32	A	G	A728855	216600			5/7/92	5/7/92
300392429700S01	SAN JUAN 30-6 UT 429 FC	RIO ARRIBA	NM	30	N	7	W	32	A	G	A728855	216600			5/7/92	5/7/92
300392954100S01	SAN JUAN 30-6 UT 429S FC	RIO ARRIBA	NM	30	N	7	W	32	J	G	A728855	216600			3/17/06	3/17/06
300392954100S01	SAN JUAN 30-6 UT 429S FC	RIO ARRIBA	NM	30	N	7	W	32	J	G	A728855	216600			3/17/06	3/17/06
300392580300C01	SAN JUAN 30-6 UT 42A DK	RIO ARRIBA	NM	30	N	6	W	14	F	G	A728852	216600			7/13/98	7/13/98
300392580300C02	SAN JUAN 30-6 UT 42A MV	RIO ARRIBA	NM	30	N	6	W	14	F	G	A728853	216600			7/7/98	7/7/98
300392677000S02	SAN JUAN 30-6 UT 42M MV	RIO ARRIBA	NM	30	N	6	W	14	L	G	A728853	216600			6/17/02	6/17/02
300392677000S01	SAN JUAN 30-6 UT 42M TA	RIO ARRIBA	NM	30	N	6	W	14	L	G	A728852	216600				
300390786000S01	SAN JUAN 30-6 UT 43 MV	RIO ARRIBA	NM	30	N	6	W	14	A	G	A728853	216600			8/18/58	8/18/58
300392422400S01	SAN JUAN 30-6 UT 430 FC	RIO ARRIBA	NM	30	N	6	W	8	G	G	A728855	216600			2/1/89	2/1/89
300392422400S01	SAN JUAN 30-6 UT 430 FC	RIO ARRIBA	NM	30	N	6	W	8	G	G	A728855	216600			2/1/89	2/1/89
300392773500S01	SAN JUAN 30-6 UT 430S FC	RIO ARRIBA	NM	30	N	6	W	8	I	G	A728855	216600			12/15/04	12/15/04
300392773500S01	SAN JUAN 30-6 UT 430S FC	RIO ARRIBA	NM	30	N	6	W	8	I	G	A728855	216600			12/15/04	12/15/04
300392422600S01	SAN JUAN 30-6 UT 431 FC	RIO ARRIBA	NM	30	N	6	W	10	M	G	A728855	216600			3/1/89	3/1/89
300392422600S01	SAN JUAN 30-6 UT 431 FC	RIO ARRIBA	NM	30	N	6	W	10	M	G	A728855	216600			3/1/89	3/1/89
300392771300S01	SAN JUAN 30-6 UT 431S FC	RIO ARRIBA	NM	30	N	6	W	10	F	G	A728855	216600			9/24/04	9/24/04

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE	
300392771300S01	SAN JUAN 30-6 UT 431S FC	RIO ARRIBA	NM	30	N	6	W 10	F	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	9/16/04	11/13/12	9/24/04	9/24/04
300392422500S01	SAN JUAN 30-6 UT 432 FC	RIO ARRIBA	NM	30	N	6	W 10	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/15/88		3/27/89	3/27/89
300392422500S01	SAN JUAN 30-6 UT 432 FC	RIO ARRIBA	NM	30	N	6	W 10	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/15/88		3/27/89	3/27/89
300392756600S01	SAN JUAN 30-6 UT 432S FC	RIO ARRIBA	NM	30	N	6	W 10	I	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/24/04		8/5/04	8/5/04
300392756600S01	SAN JUAN 30-6 UT 432S FC	RIO ARRIBA	NM	30	N	6	W 10	I	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/24/04		8/5/04	8/5/04
300392424100S01	SAN JUAN 30-6 UT 433 FC	RIO ARRIBA	NM	30	N	6	W 11	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/29/88		2/1/89	2/1/89
300392424100S01	SAN JUAN 30-6 UT 433 FC	RIO ARRIBA	NM	30	N	6	W 11	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/29/88		2/1/89	2/1/89
300392944800S01	SAN JUAN 30-6 UT 433S FC	RIO ARRIBA	NM	30	N	6	W 11	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	7/11/05	11/13/12	7/19/05	7/19/05
300392944800S01	SAN JUAN 30-6 UT 433S FC	RIO ARRIBA	NM	30	N	6	W 11	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	-72	7/11/05	11/13/12	7/19/05	7/19/05
300392426000S01	SAN JUAN 30-6 UT 434 FC	RIO ARRIBA	NM	30	N	6	W 12	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/25/88		2/10/89	2/10/89
300392426000S01	SAN JUAN 30-6 UT 434 FC	RIO ARRIBA	NM	30	N	6	W 12	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/25/88		2/10/89	2/10/89
300392761900S01	SAN JUAN 30-6 UT 434S FC	RIO ARRIBA	NM	30	N	6	W 12	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/22/04		7/20/04	7/20/04
300392761900S01	SAN JUAN 30-6 UT 434S FC	RIO ARRIBA	NM	30	N	6	W 12	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/22/04		7/20/04	7/20/04
300392431900S01	SAN JUAN 30-6 UT 435 FC	RIO ARRIBA	NM	30	N	6	W 13	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/3/88		2/2/89	2/2/89
300392431900S01	SAN JUAN 30-6 UT 435 FC	RIO ARRIBA	NM	30	N	6	W 13	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/3/88		2/2/89	2/2/89
300392779200S01	SAN JUAN 30-6 UT 435S FC	RIO ARRIBA	NM	30	N	6	W 13	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	11/22/04	11/26/12	5/3/05	5/3/05
300392779200S01	SAN JUAN 30-6 UT 435S FC	RIO ARRIBA	NM	30	N	6	W 13	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	11/22/04	11/26/12	5/3/05	5/3/05
300392422700S01	SAN JUAN 30-6 UT 436 FC	RIO ARRIBA	NM	30	N	6	W 15	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/25/88		4/6/89	4/6/89
300392422700S01	SAN JUAN 30-6 UT 436 FC	RIO ARRIBA	NM	30	N	6	W 15	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/25/88		4/6/89	4/6/89
300392949400S01	SAN JUAN 30-6 UT 436S FC	RIO ARRIBA	NM	30	N	6	W 15	I	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/19/05		8/11/05	8/11/00
300392949400S01	SAN JUAN 30-6 UT 436S FC	RIO ARRIBA	NM	30	N	6	W 15	I	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/19/05		8/11/05	8/11/00
300392427500S01	SAN JUAN 30-6 UT 437 FC	RIO ARRIBA	NM	30	N	6	W 11	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/16/88		4/1/89	4/1/89
300392427500S01	SAN JUAN 30-6 UT 437 FC	RIO ARRIBA	NM	30	N	6	W 11	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/16/88		4/1/89	4/1/89
300392766400S01	SAN JUAN 30-6 UT 437S FC	RIO ARRIBA	NM	30	N	6	W 11	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/25/04		10/7/04	10/7/04
300392766400S01	SAN JUAN 30-6 UT 437S FC	RIO ARRIBA	NM	30	N	6	W 11	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/25/04		10/7/04	10/7/04
300392430200S01	SAN JUAN 30-6 UT 438 FC	RIO ARRIBA	NM	30	N	6	W 12	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/14/88		4/1/89	4/1/89
300392430200S01	SAN JUAN 30-6 UT 438 FC	RIO ARRIBA	NM	30	N	6	W 12	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/14/88		4/1/89	4/1/89
300392775200S01	SAN JUAN 30-6 UT 438S FC	RIO ARRIBA	NM	30	N	6	W 12	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/23/04		1/24/05	1/24/05
300392775200S01	SAN JUAN 30-6 UT 438S FC	RIO ARRIBA	NM	30	N	6	W 12	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/23/04		1/24/05	1/24/05
300392424200S01	SAN JUAN 30-6 UT 439 FC	RIO ARRIBA	NM	30	N	6	W 14	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/29/88		2/2/89	2/2/89
300392424200S01	SAN JUAN 30-6 UT 439 FC	RIO ARRIBA	NM	30	N	6	W 14	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/29/88		2/2/89	2/2/89
300392583700C01	SAN JUAN 30-6 UT 43A DK	RIO ARRIBA	NM	30	N	6	W 14	I	G	A728852	216600	BASIN::DAKOTA	11	1/30/99		2/19/99	2/19/99
300392583700C02	SAN JUAN 30-6 UT 43A MV	RIO ARRIBA	NM	30	N	6	W 14	I	G	A728853	216600	BLANCO::MESAVERDE	11	1/30/99		2/17/99	2/17/99
300393077600C01	SAN JUAN 30-6 UT 43M DK	RIO ARRIBA	NM	30	N	6	W 14	F	G	A728852	216600	BASIN::DAKOTA	11	7/14/11		7/14/11	8/12/11
300393077600C02	SAN JUAN 30-6 UT 43M MV	RIO ARRIBA	NM	30	N	6	W 14	F	G	A728853	216600	BLANCO::MESAVERDE	11	7/14/11		7/14/11	8/12/11
300393095800C01	SAN JUAN 30-6 UT 43N DK	RIO ARRIBA	NM	30	N	6	W 14	J	G	A728852	216600	BASIN::DAKOTA	11	7/29/11		8/30/11	8/30/11
300393095800C02	SAN JUAN 30-6 UT 43N MV	RIO ARRIBA	NM	30	N	6	W 14	J	G	A728853	216600	BLANCO::MESAVERDE	11	7/29/11		8/30/11	8/30/11
300390783700S01	SAN JUAN 30-6 UT 44 MV	RIO ARRIBA	NM	30	N	6	W 15	N	G	A728853	216600	BLANCO::MESAVERDE	11	6/26/58		8/18/58	8/18/58
300392424300S01	SAN JUAN 30-6 UT 440 FC	RIO ARRIBA	NM	30	N	6	W 15	N	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/12/88		3/28/89	3/28/89
300392424300S01	SAN JUAN 30-6 UT 440 FC	RIO ARRIBA	NM	30	N	6	W 15	N	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	8/12/88		3/28/89	3/28/89
300392424700S01	SAN JUAN 30-6 UT 441 FC	RIO ARRIBA	NM	30	N	6	W 31	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/9/88		12/17/88	12/17/88
300392424700S01	SAN JUAN 30-6 UT 441 FC	RIO ARRIBA	NM	30	N	6	W 31	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/9/88		12/17/88	12/17/88
300392764300S01	SAN JUAN 30-6 UT 441S FC	RIO ARRIBA	NM	30	N	6	W 31	I	G	A728855	216600	BASIN::FRUITLAND COAL	11	9/12/08		10/15/08	10/15/08
300392764300S01	SAN JUAN 30-6 UT 441S FC	RIO ARRIBA	NM	30	N	6	W 31	I	G	A728855	216600	BASIN::FRUITLAND COAL	11	9/12/08		10/15/08	10/15/08
300392446000S01	SAN JUAN 30-6 UT 442 FC	RIO ARRIBA	NM	30	N	6	W 14	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/6/89		7/24/90	7/24/90
300392446000S01	SAN JUAN 30-6 UT 442 FC	RIO ARRIBA	NM	30	N	6	W 14	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/6/89		7/24/90	7/24/90
300392769300S01	SAN JUAN 30-6 UT 442S FC	RIO ARRIBA	NM	30	N	6	W 14	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/30/04		12/7/04	12/7/04
300392769300S01	SAN JUAN 30-6 UT 442S FC	RIO ARRIBA	NM	30	N	6	W 14	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/30/04		12/7/04	12/7/04
300392429600S01	SAN JUAN 30-6 UT 444 FC	RIO ARRIBA	NM	30	N	6	W 36	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/25/90		8/30/90	8/30/90
300392429600S01	SAN JUAN 30-6 UT 444 FC	RIO ARRIBA	NM	30	N	6	W 36	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/25/90		8/30/90	8/30/90

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392725800S01	SAN JUAN 30-6 UT 444S FC	RIO ARRIBA	NM	30	N	6	W 36	C	G	A728855	216600	11	5/9/03		5/22/03	5/22/03
300392725800S01	SAN JUAN 30-6 UT 444S FC	RIO ARRIBA	NM	30	N	6	W 36	C	G	A728855	216600	11	5/9/03		5/22/03	5/22/03
300392433500S01	SAN JUAN 30-6 UT 445 FC	RIO ARRIBA	NM	30	N	6	W 13	L	G	A728855	216600	11	3/4/90		7/24/90	7/24/90
300392433500S01	SAN JUAN 30-6 UT 445 FC	RIO ARRIBA	NM	30	N	6	W 13	L	G	A728855	216600	11	3/4/90		7/24/90	7/24/90
300392779300S01	SAN JUAN 30-6 UT 445S FC	RIO ARRIBA	NM	30	N	6	W 13	C	G	A728855	216600	11	12/13/04		1/7/05	1/7/05
300392779300S01	SAN JUAN 30-6 UT 445S FC	RIO ARRIBA	NM	30	N	6	W 13	C	G	A728855	216600	11	12/13/04		1/7/05	1/7/05
300392459000S01	SAN JUAN 30-6 UT 446 FC	RIO ARRIBA	NM	30	N	6	W 35	N	G	A728855	216600	11	3/18/90		7/28/90	7/28/90
300392459000S01	SAN JUAN 30-6 UT 446 FC	RIO ARRIBA	NM	30	N	6	W 35	N	G	A728855	216600	11	3/18/90		7/28/90	7/28/90
300392774100S01	SAN JUAN 30-6 UT 446S FC	RIO ARRIBA	NM	30	N	6	W 35	C	G	A728855	216600	11	10/8/04		11/4/04	11/4/04
300392774100S01	SAN JUAN 30-6 UT 446S FC	RIO ARRIBA	NM	30	N	6	W 35	C	G	A728855	216600	11	10/8/04		11/4/04	11/4/04
300392463400S01	SAN JUAN 30-6 UT 447 FC	RIO ARRIBA	NM	30	N	7	W 31	G	G	A728855	216600	11	7/20/90		10/17/90	10/17/90
300392463400S01	SAN JUAN 30-6 UT 447 FC	RIO ARRIBA	NM	30	N	7	W 31	G	G	A728855	216600	11	7/20/90		10/17/90	10/17/90
300393092300C02	SAN JUAN 30-6 UT 447S FC	RIO ARRIBA	NM	30	N	7	W 31	I	G	A728855	216600	11	3/26/11		5/27/11	5/27/11
300393092300C02	SAN JUAN 30-6 UT 447S FC	RIO ARRIBA	NM	30	N	7	W 31	I	G	A728855	216600	11	3/26/11		5/27/11	5/27/11
300393092300C01	SAN JUAN 30-6 UT 447S PC	RIO ARRIBA	NM	30	N	7	W 31	I	G	A728854	216600	11	3/26/11		5/27/11	5/27/11
300392563700C01	SAN JUAN 30-6 UT 44A DK	RIO ARRIBA	NM	30	N	6	W 15	C	G	A728852	216600	11	9/5/97		10/15/97	10/15/97
300392563700C02	SAN JUAN 30-6 UT 44A MV	RIO ARRIBA	NM	30	N	6	W 15	C	G	A728853	216600	11	9/5/97		10/15/97	10/15/97
300390785200S01	SAN JUAN 30-6 UT 45 MV	RIO ARRIBA	NM	30	N	6	W 15	G	G	A728853	216600	11	8/2/57		8/20/57	8/20/57
300392423300S01	SAN JUAN 30-6 UT 450 FC	RIO ARRIBA	NM	30	N	6	W 7	K	G	A728855	216600	11	7/18/88		11/19/88	11/19/88
300392423300S01	SAN JUAN 30-6 UT 450 FC	RIO ARRIBA	NM	30	N	6	W 7	K	G	A728855	216600	11	7/18/88		11/19/88	11/19/88
300392771100S01	SAN JUAN 30-6 UT 450S FC	RIO ARRIBA	NM	30	N	6	W 7	F	G	A728855	216600	11	11/5/04		11/22/04	11/22/04
300392771100S01	SAN JUAN 30-6 UT 450S FC	RIO ARRIBA	NM	30	N	6	W 7	F	G	A728855	216600	11	11/5/04		11/22/04	11/22/04
300392423200S01	SAN JUAN 30-6 UT 451 FC	RIO ARRIBA	NM	30	N	6	W 7	H	G	A728855	216600	11	7/22/88		3/1/89	3/1/89
300392423200S01	SAN JUAN 30-6 UT 451 FC	RIO ARRIBA	NM	30	N	6	W 7	H	G	A728855	216600	11	7/22/88		3/1/89	3/1/89
300392765600S01	SAN JUAN 30-6 UT 451S FC	RIO ARRIBA	NM	30	N	6	W 7	J	G	A728855	216600	11	5/20/04		6/17/04	6/17/04
300392765600S01	SAN JUAN 30-6 UT 451S FC	RIO ARRIBA	NM	30	N	6	W 7	J	G	A728855	216600	11	5/20/04		6/17/04	6/17/04
300392427400S01	SAN JUAN 30-6 UT 452 FC	RIO ARRIBA	NM	30	N	6	W 8	N	G	A728855	216600	11	9/28/88		1/1/89	1/1/89
300392427400S01	SAN JUAN 30-6 UT 452 FC	RIO ARRIBA	NM	30	N	6	W 8	N	G	A728855	216600	11	9/28/88		1/1/89	1/1/89
300392425400S01	SAN JUAN 30-6 UT 453 FC	RIO ARRIBA	NM	30	N	6	W 17	K	G	A728855	216600	11	8/10/88		6/27/89	6/27/89
300392425400S01	SAN JUAN 30-6 UT 453 FC	RIO ARRIBA	NM	30	N	6	W 17	K	G	A728855	216600	11	8/10/88		6/27/89	6/27/89
300392423400S01	SAN JUAN 30-6 UT 454 FC	RIO ARRIBA	NM	30	N	6	W 17	A	G	A728855	216600	11	7/20/88		1/4/89	1/4/89
300392423400S01	SAN JUAN 30-6 UT 454 FC	RIO ARRIBA	NM	30	N	6	W 17	A	G	A728855	216600	11	7/20/88		1/4/89	1/4/89
300392940500S01	SAN JUAN 30-6 UT 454S FC	RIO ARRIBA	NM	30	N	6	W 17	J	G	A728855	216600	11	9/8/05		10/7/05	10/7/05
300392940500S01	SAN JUAN 30-6 UT 454S FC	RIO ARRIBA	NM	30	N	6	W 17	J	G	A728855	216600	11	9/8/05		10/7/05	10/7/05
300392424500S01	SAN JUAN 30-6 UT 455 FC	RIO ARRIBA	NM	30	N	6	W 18	N	G	A728855	216600	11	8/25/88		11/9/88	11/9/88
300392424500S01	SAN JUAN 30-6 UT 455 FC	RIO ARRIBA	NM	30	N	6	W 18	N	G	A728855	216600	11	8/25/88		11/9/88	11/9/88
300392943900S01	SAN JUAN 30-6 UT 455S FC	RIO ARRIBA	NM	30	N	6	W 18	D	G	A728855	216600	11	8/31/05		9/27/05	9/27/05
300392943900S01	SAN JUAN 30-6 UT 455S FC	RIO ARRIBA	NM	30	N	6	W 18	D	G	A728855	216600	11	8/31/05		9/27/05	9/27/05
300392424400S01	SAN JUAN 30-6 UT 456 FC	RIO ARRIBA	NM	30	N	6	W 18	A	G	A728855	216600	11	8/4/88		11/13/88	11/13/88
300392424400S01	SAN JUAN 30-6 UT 456 FC	RIO ARRIBA	NM	30	N	6	W 18	A	G	A728855	216600	11	8/4/88		11/13/88	11/13/88
300392423500S01	SAN JUAN 30-6 UT 457 FC	RIO ARRIBA	NM	30	N	6	W 19	M	G	A728855	216600	11	7/11/88		1/30/89	1/30/89
300392423500S01	SAN JUAN 30-6 UT 457 FC	RIO ARRIBA	NM	30	N	6	W 19	M	G	A728855	216600	11	7/11/88		1/30/89	1/30/89
300392769400S01	SAN JUAN 30-6 UT 457S FC	RIO ARRIBA	NM	30	N	6	W 19	F	G	A728855	216600	11	10/27/04		12/1/04	12/1/04
300392769400S01	SAN JUAN 30-6 UT 457S FC	RIO ARRIBA	NM	30	N	6	W 19	F	G	A728855	216600	11	10/27/04		12/1/04	12/1/04
300392428800S01	SAN JUAN 30-6 UT 458 FC	RIO ARRIBA	NM	30	N	6	W 19	H	G	A728855	216600	11	10/21/88		10/29/89	10/29/89
300392428800S01	SAN JUAN 30-6 UT 458 FC	RIO ARRIBA	NM	30	N	6	W 19	H	G	A728855	216600	11	10/21/88		10/29/89	10/29/89
300392428900S01	SAN JUAN 30-6 UT 459 FC	RIO ARRIBA	NM	30	N	6	W 20	L	G	A728855	216600	11	10/7/88		10/30/89	10/30/89
300392428900S01	SAN JUAN 30-6 UT 459 FC	RIO ARRIBA	NM	30	N	6	W 20	L	G	A728855	216600	11	10/7/88		10/30/89	10/30/89
300392193700S01	SAN JUAN 30-6 UT 45A MV	RIO ARRIBA	NM	30	N	6	W 15	I	G	A728853	216600	11	6/17/80		9/1/80	9/1/80
300390788900S01	SAN JUAN 30-6 UT 46 MV	RIO ARRIBA	NM	30	N	6	W 11	H	G	A728853	216600	11	7/20/58		8/14/58	8/14/58

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TFMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN		RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392424900S01	SAN JUAN 30-6 UT 460 FC	RIO ARRIBA	NM	30	N	6	W	20	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/15/88		2/13/89	2/13/89
300392424900S01	SAN JUAN 30-6 UT 460 FC	RIO ARRIBA	NM	30	N	6	W	20	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/15/88		2/13/89	2/13/89
300392768400S01	SAN JUAN 30-6 UT 460S FC	RIO ARRIBA	NM	30	N	6	W	20	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	2/14/05		4/12/05	4/12/05
300392768400S01	SAN JUAN 30-6 UT 460S FC	RIO ARRIBA	NM	30	N	6	W	20	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	2/14/05		4/12/05	4/12/05
300392437900S01	SAN JUAN 30-6 UT 461 FC	RIO ARRIBA	NM	30	N	7	W	11	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/18/89		12/29/89	12/29/89
300392437900S01	SAN JUAN 30-6 UT 461 FC	RIO ARRIBA	NM	30	N	7	W	11	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/18/89		12/29/89	12/29/89
300392773300S01	SAN JUAN 30-6 UT 461S FC	RIO ARRIBA	NM	30	N	7	W	11	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/12/04		10/26/04	10/26/04
300392773300S01	SAN JUAN 30-6 UT 461S FC	RIO ARRIBA	NM	30	N	7	W	11	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/12/04		10/26/04	10/26/04
300392439500S01	SAN JUAN 30-6 UT 462 FC	RIO ARRIBA	NM	30	N	7	W	12	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/14/89		7/6/89	7/6/89
300392439500S01	SAN JUAN 30-6 UT 462 FC	RIO ARRIBA	NM	30	N	7	W	12	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/14/89		7/6/89	7/6/89
300392940400S01	SAN JUAN 30-6 UT 462S FC	RIO ARRIBA	NM	30	N	7	W	12	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	6/20/05	8/3/12	7/8/05	7/8/05
300392940400S01	SAN JUAN 30-6 UT 462S FC	RIO ARRIBA	NM	30	N	7	W	12	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	6/20/05	8/3/12	7/8/05	7/8/05
300392438000S01	SAN JUAN 30-6 UT 463 FC	RIO ARRIBA	NM	30	N	7	W	13	H	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/28/89		8/23/89	8/23/89
300392774000S01	SAN JUAN 30-6 UT 463S FC	RIO ARRIBA	NM	30	N	7	W	13	I	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/20/04		11/24/04	11/24/04
300392774000S01	SAN JUAN 30-6 UT 463S FC	RIO ARRIBA	NM	30	N	7	W	13	I	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/20/04		11/24/04	11/24/04
300392423700S01	SAN JUAN 30-6 UT 464 FC	RIO ARRIBA	NM	30	N	7	W	14	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/30/88		1/1/89	1/1/89
300392423700S01	SAN JUAN 30-6 UT 464 FC	RIO ARRIBA	NM	30	N	7	W	14	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/30/88		1/1/89	1/1/89
300392429200S01	SAN JUAN 30-6 UT 465 FC	RIO ARRIBA	NM	30	N	7	W	15	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/9/88		10/12/88	10/12/88
300392429200S01	SAN JUAN 30-6 UT 465 FC	RIO ARRIBA	NM	30	N	7	W	15	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/9/88		10/12/88	10/12/88
300393020500S01	SAN JUAN 30-6 UT 465S FC	RIO ARRIBA	NM	30	N	7	W	15	J	G	A728855	216600	BASIN::FRUITLAND COAL	11	11/9/07		12/18/07	12/18/07
300393020500S01	SAN JUAN 30-6 UT 465S FC	RIO ARRIBA	NM	30	N	7	W	15	J	G	A728855	216600	BASIN::FRUITLAND COAL	11	11/9/07		12/18/07	12/18/07
300392435000S01	SAN JUAN 30-6 UT 466 FC	RIO ARRIBA	NM	30	N	7	W	22	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/21/88		12/21/88	12/21/88
300392435000S01	SAN JUAN 30-6 UT 466 FC	RIO ARRIBA	NM	30	N	7	W	22	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/21/88		12/21/88	12/21/88
300392941100S01	SAN JUAN 30-6 UT 466S FC	RIO ARRIBA	NM	30	N	7	W	22	P	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	2/9/06		5/24/06	5/24/06
300392941100S01	SAN JUAN 30-6 UT 466S FC	RIO ARRIBA	NM	30	N	7	W	22	P	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	2/9/06		5/24/06	5/24/06
300392443800S01	SAN JUAN 30-6 UT 468 FC	RIO ARRIBA	NM	30	N	7	W	36	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/16/89		9/29/89	9/29/89
300392443800S01	SAN JUAN 30-6 UT 468 FC	RIO ARRIBA	NM	30	N	7	W	36	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/16/89		9/29/89	9/29/89
300392749500S01	SAN JUAN 30-6 UT 468S FC	RIO ARRIBA	NM	30	N	7	W	36	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	5/7/04		6/11/04	6/11/04
300392749500S01	SAN JUAN 30-6 UT 468S FC	RIO ARRIBA	NM	30	N	7	W	36	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	5/7/04		6/11/04	6/11/04
300392581000C01	SAN JUAN 30-6 UT 46A DK	RIO ARRIBA	NM	30	N	6	W	11	I	G	A724979	216600	BASIN::DAKOTA	11	8/16/98		9/18/98	9/18/98
300392581000C01	SAN JUAN 30-6 UT 46A DK	RIO ARRIBA	NM	30	N	6	W	11	I	G	A724979	216600	BASIN::DAKOTA	11	8/16/98		9/18/98	9/18/98
300392581000C02	SAN JUAN 30-6 UT 46A MV	RIO ARRIBA	NM	30	N	6	W	11	I	G	A728853	216600	BLANCO::MESAVERDE	11	8/16/98		9/14/98	9/14/98
300392687600S01	SAN JUAN 30-6 UT 46B MV	RIO ARRIBA	NM	30	N	6	W	11	B	G	A728853	216600	BLANCO::MESAVERDE	11	7/25/03		7/30/03	7/20/03
300390772900S01	SAN JUAN 30-6 UT 47 MV	RIO ARRIBA	NM	30	N	7	W	32	H	G	A728853	216600	BLANCO::MESAVERDE	11	1/15/55		1/25/55	1/25/55
300392447100S01	SAN JUAN 30-6 UT 470 FC	RIO ARRIBA	NM	30	N	6	W	21	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/27/89		5/9/90	5/9/90
300392447100S01	SAN JUAN 30-6 UT 470 FC	RIO ARRIBA	NM	30	N	6	W	21	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/27/89		5/9/90	5/9/90
300392451200S01	SAN JUAN 30-6 UT 471 FC	RIO ARRIBA	NM	30	N	6	W	21	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/22/89		5/9/90	5/9/90
300392451200S01	SAN JUAN 30-6 UT 471 FC	RIO ARRIBA	NM	30	N	6	W	21	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/22/89		5/9/90	5/9/90
300392756700S01	SAN JUAN 30-6 UT 471S FC	RIO ARRIBA	NM	30	N	6	W	21	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/16/04		5/21/04	5/21/04
300392756700S01	SAN JUAN 30-6 UT 471S FC	RIO ARRIBA	NM	30	N	6	W	21	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	3/16/04		5/21/04	5/21/04
300392447700S01	SAN JUAN 30-6 UT 472 FC	RIO ARRIBA	NM	30	N	6	W	22	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/23/89		7/25/90	7/25/90
300392447700S01	SAN JUAN 30-6 UT 472 FC	RIO ARRIBA	NM	30	N	6	W	22	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/23/89		7/25/90	7/25/90
300392447600S01	SAN JUAN 30-6 UT 473 FC	RIO ARRIBA	NM	30	N	6	W	22	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/7/89		4/26/90	4/26/90
300392447600S01	SAN JUAN 30-6 UT 473 FC	RIO ARRIBA	NM	30	N	6	W	22	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/7/89		4/26/90	4/26/90
300392943600S01	SAN JUAN 30-6 UT 473S FC	RIO ARRIBA	NM	30	N	6	W	22	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	7/26/05	11/30/12	8/18/05	8/18/05
300392943600S01	SAN JUAN 30-6 UT 473S FC	RIO ARRIBA	NM	30	N	6	W	22	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	7/26/05	11/30/12	8/18/05	8/18/05
300392446400S01	SAN JUAN 30-6 UT 474 FC	RIO ARRIBA	NM	30	N	6	W	27	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/2/89		4/27/90	4/27/90
300392446400S01	SAN JUAN 30-6 UT 474 FC	RIO ARRIBA	NM	30	N	6	W	27	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/2/89		4/27/90	4/27/90
300392448700S01	SAN JUAN 30-6 UT 475 FC	RIO ARRIBA	NM	30	N	6	W	27	L	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	2/2/90		4/28/90	4/28/90

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON P5 - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392448700S01	SAN JUAN 30-6 UT 475 FC	RIO ARRIBA	NM	30	N	6	W 27	L	G	A728855	216600	11	2/2/90		4/28/90	4/28/90
300392761800S01	SAN JUAN 30-6 UT 475S FC	RIO ARRIBA	NM	30	N	6	W 27	D	G	A728855	216600	72	3/26/05	11/9/12	3/31/05	3/31/05
300392761800S01	SAN JUAN 30-6 UT 475S FC	RIO ARRIBA	NM	30	N	6	W 27	D	G	A728855	216600	72	3/26/05	11/9/12	3/31/05	3/31/05
300392446901S01	SAN JUAN 30-6 UT 476 FC	RIO ARRIBA	NM	30	N	6	W 28	A	G	A728855	216600	11	1/18/90		2/8/90	2/8/90
300392446901S01	SAN JUAN 30-6 UT 476 FC	RIO ARRIBA	NM	30	N	6	W 28	A	G	A728855	216600	11	1/18/90		2/8/90	2/8/90
300392768500S01	SAN JUAN 30-6 UT 476S FC	RIO ARRIBA	NM	30	N	6	W 28	J	G	A728855	216600	11	11/11/04		12/17/04	12/17/04
300392768500S01	SAN JUAN 30-6 UT 476S FC	RIO ARRIBA	NM	30	N	6	W 28	J	G	A728855	216600	11	11/11/04		12/17/04	12/17/04
300392449200S01	SAN JUAN 30-6 UT 477 FC	RIO ARRIBA	NM	30	N	6	W 28	M	G	A728855	216600	11	3/14/90		7/24/90	7/24/90
300392449200S01	SAN JUAN 30-6 UT 477 FC	RIO ARRIBA	NM	30	N	6	W 28	M	G	A728855	216600	11	3/14/90		7/24/90	7/24/90
300392749700S01	SAN JUAN 30-6 UT 477S FC	RIO ARRIBA	NM	30	N	6	W 28	F	G	A728855	216600	11	3/26/04		4/8/04	4/8/04
300392749700S01	SAN JUAN 30-6 UT 477S FC	RIO ARRIBA	NM	30	N	6	W 28	F	G	A728855	216600	11	3/26/04		4/8/04	4/8/04
300392447000S01	SAN JUAN 30-6 UT 478 FC	RIO ARRIBA	NM	30	N	6	W 29	A	G	A728855	216600	11	2/23/90		5/14/90	5/14/90
300392447000S01	SAN JUAN 30-6 UT 478 FC	RIO ARRIBA	NM	30	N	6	W 29	A	G	A728855	216600	11	2/23/90		5/14/90	5/14/90
300392749400S01	SAN JUAN 30-6 UT 478S FC	RIO ARRIBA	NM	30	N	6	W 29	O	G	A728855	216600	11	3/4/04		5/18/04	5/18/04
300392749400S01	SAN JUAN 30-6 UT 478S FC	RIO ARRIBA	NM	30	N	6	W 29	O	G	A728855	216600	11	3/4/04		5/18/04	5/18/04
300392460000S01	SAN JUAN 30-6 UT 479 FC	RIO ARRIBA	NM	30	N	6	W 29	K	G	A728855	216600	11	2/12/90		6/8/90	6/8/90
300392460000S01	SAN JUAN 30-6 UT 479 FC	RIO ARRIBA	NM	30	N	6	W 29	K	G	A728855	216600	11	2/12/90		6/8/90	6/8/90
300392941200S01	SAN JUAN 30-6 UT 479S FC	RIO ARRIBA	NM	30	N	6	W 29	F	G	A728855	216600	11	1/28/06		2/17/06	2/17/06
300392941200S01	SAN JUAN 30-6 UT 479S FC	RIO ARRIBA	NM	30	N	6	W 29	F	G	A728855	216600	11	1/28/06		2/17/06	2/17/06
300392559300S01	SAN JUAN 30-6 UT 47A MV	RIO ARRIBA	NM	30	N	7	W 32	J	G	A728853	216600	11	12/22/96		1/17/97	1/17/97
300392625900C01	SAN JUAN 30-6 UT 47B DK	RIO ARRIBA	NM	30	N	7	W 32	B	G	A728852	216600	11	4/18/01		4/26/01	4/26/01
300392625900C02	SAN JUAN 30-6 UT 47B MV	RIO ARRIBA	NM	30	N	7	W 32	B	G	A728853	216600	11	9/8/01		9/11/01	9/11/01
300392625900D03	SAN JUAN 30-6 UT 47B PC	RIO ARRIBA	NM	30	N	7	W 32	B	G	A721156	216600	71	9/8/01			
300393059800C01	SAN JUAN 30-6 UT 47M DK	RIO ARRIBA	NM	30	N	7	W 32	I	G	A728852	216600	11	8/8/09		8/8/09	
300393059800C02	SAN JUAN 30-6 UT 47M MV	RIO ARRIBA	NM	30	N	7	W 32	I	G	A728853	216600	11	8/8/09		8/8/09	
300392448800S01	SAN JUAN 30-6 UT 480 FC	RIO ARRIBA	NM	30	N	6	W 30	A	G	A728855	216600	11	3/1/90		6/19/90	6/19/90
300392448800S01	SAN JUAN 30-6 UT 480 FC	RIO ARRIBA	NM	30	N	6	W 30	A	G	A728855	216600	11	3/1/90		6/19/90	6/19/90
300392446800S01	SAN JUAN 30-6 UT 481 FC	RIO ARRIBA	NM	30	N	6	W 30	K	G	A728855	216600	11	2/11/90		4/26/90	4/26/90
300392446800S01	SAN JUAN 30-6 UT 481 FC	RIO ARRIBA	NM	30	N	6	W 30	K	G	A728855	216600	11	2/11/90		4/26/90	4/26/90
300392771200S01	SAN JUAN 30-6 UT 481S FC	RIO ARRIBA	NM	30	N	6	W 30	C	G	A728855	216600	11	2/14/05		3/19/05	3/19/05
300392771200S01	SAN JUAN 30-6 UT 481S FC	RIO ARRIBA	NM	30	N	6	W 30	C	G	A728855	216600	11	2/14/05		3/19/05	3/19/05
300392461300S01	SAN JUAN 30-6 UT 482 FC	RIO ARRIBA	NM	30	N	6	W 31	N	G	A728855	216600	11	5/19/90		11/16/90	11/16/90
300392461300S01	SAN JUAN 30-6 UT 482 FC	RIO ARRIBA	NM	30	N	6	W 31	N	G	A728855	216600	11	5/19/90		11/16/90	11/16/90
300392447300S01	SAN JUAN 30-6 UT 483 FC	RIO ARRIBA	NM	30	N	6	W 34	H	G	A728855	216600	11	3/26/90		10/18/90	10/18/90
300392447300S01	SAN JUAN 30-6 UT 483 FC	RIO ARRIBA	NM	30	N	6	W 34	H	G	A728855	216600	11	3/26/90		10/18/90	10/18/90
300392760700S01	SAN JUAN 30-6 UT 483S FC	RIO ARRIBA	NM	30	N	6	W 34	P	G	A728855	216600	11	4/29/04		6/25/04	6/25/04
300392760700S01	SAN JUAN 30-6 UT 483S FC	RIO ARRIBA	NM	30	N	6	W 34	P	G	A728855	216600	11	4/29/04		6/25/04	6/25/04
300392447200S01	SAN JUAN 30-6 UT 484 FC	RIO ARRIBA	NM	30	N	6	W 34	N	G	A728855	216600	11	3/26/90		8/1/90	8/1/90
300392447200S01	SAN JUAN 30-6 UT 484 FC	RIO ARRIBA	NM	30	N	6	W 34	N	G	A728855	216600	11	3/26/90		8/1/90	8/1/90
300392765300S01	SAN JUAN 30-6 UT 484S FC	RIO ARRIBA	NM	30	N	6	W 34	D	G	A728855	216600	11	4/18/05		4/28/05	4/28/05
300392765300S01	SAN JUAN 30-6 UT 484S FC	RIO ARRIBA	NM	30	N	6	W 34	D	G	A728855	216600	11	4/18/05		4/28/05	4/28/05
300392481400S01	SAN JUAN 30-6 UT 485 FC	RIO ARRIBA	NM	30	N	7	W 36	G	G	A728855	216600	11	10/19/90		4/4/91	4/4/91
300392481400S01	SAN JUAN 30-6 UT 485 FC	RIO ARRIBA	NM	30	N	7	W 36	G	G	A728855	216600	11	10/19/90		4/4/91	4/4/91
300392749800S01	SAN JUAN 30-6 UT 485S FC	RIO ARRIBA	NM	30	N	7	W 36	J	G	A728855	216600	11	4/9/04		6/4/04	6/4/04
300392749800S01	SAN JUAN 30-6 UT 485S FC	RIO ARRIBA	NM	30	N	7	W 36	J	G	A728855	216600	11	4/9/04		6/4/04	6/4/04
300392498000S01	SAN JUAN 30-6 UT 486 FC	RIO ARRIBA	NM	30	N	6	W 23	H	G	A728855	216600	11	2/5/91		1/7/92	1/7/92
300392498000S01	SAN JUAN 30-6 UT 486 FC	RIO ARRIBA	NM	30	N	6	W 23	H	G	A728855	216600	11	2/5/91		1/7/92	1/7/92
300392776000S01	SAN JUAN 30-6 UT 486S FC	RIO ARRIBA	NM	30	N	6	W 23	O	G	A728855	216600	11	9/11/04		10/13/04	10/13/04
300392776000S01	SAN JUAN 30-6 UT 486S FC	RIO ARRIBA	NM	30	N	6	W 23	O	G	A728855	216600	11	9/11/04		10/13/04	10/13/04
300392502300S01	SAN JUAN 30-6 UT 487 FC	RIO ARRIBA	NM	30	N	6	W 23	N	G	A728855	216600	11	1/21/91		8/1/91	8/1/91

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PC - PERM ABANDON

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392502300S01	SAN JUAN 30-6 UT 487 FC	RIO ARRIBA	NM	30	N	6	W 23	N	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/21/91		8/1/91	8/1/91
300392486700S01	SAN JUAN 30-6 UT 488 FC	RIO ARRIBA	NM	30	N	6	W 24	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/27/91		1/8/92	1/8/92
300392486700S01	SAN JUAN 30-6 UT 488 FC	RIO ARRIBA	NM	30	N	6	W 24	A	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/27/91		1/8/92	1/8/92
300392775900S01	SAN JUAN 30-6 UT 488S FC	RIO ARRIBA	NM	30	N	6	W 24	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	10/11/04		10/27/04	10/27/04
300392775900S01	SAN JUAN 30-6 UT 488S FC	RIO ARRIBA	NM	30	N	6	W 24	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	10/11/04		10/27/04	10/27/04
300392492600S01	SAN JUAN 30-6 UT 489 FC	RIO ARRIBA	NM	30	N	6	W 24	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/14/91		8/15/91	8/15/91
300392492600S01	SAN JUAN 30-6 UT 489 FC	RIO ARRIBA	NM	30	N	6	W 24	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/14/91		8/15/91	8/15/91
300392775800S01	SAN JUAN 30-6 UT 489S FC	RIO ARRIBA	NM	30	N	6	W 24	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	10/18/04		11/18/04	11/18/04
300392775800S01	SAN JUAN 30-6 UT 489S FC	RIO ARRIBA	NM	30	N	6	W 24	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	10/18/04		11/18/04	11/18/04
300393072400C01	SAN JUAN 30-6 UT 48M DK	RIO ARRIBA	NM	30	N	6	W 27	L	G	A728852	216600	BASIN::DAKOTA	11	10/7/09		9/28/09	9/28/09
300393072400C02	SAN JUAN 30-6 UT 48M MV	RIO ARRIBA	NM	30	N	6	W 27	L	G	A728853	216600	BLANCO::MESAVERDE	11	10/7/09		9/28/09	9/28/09
300392527300S01	SAN JUAN 30-6 UT 48R MV	RIO ARRIBA	NM	30	N	6	W 27	L	G	A728853	216600	BLANCO::MESAVERDE	11	9/14/93		3/21/94	3/21/94
300392486800S01	SAN JUAN 30-6 UT 490 FC	RIO ARRIBA	NM	30	N	6	W 25	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/7/91		7/17/91	7/17/91
300392486800S01	SAN JUAN 30-6 UT 490 FC	RIO ARRIBA	NM	30	N	6	W 25	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	1/7/91		7/17/91	7/17/91
300392771900S01	SAN JUAN 30-6 UT 490S FC	RIO ARRIBA	NM	30	N	6	W 25	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/1/04		10/13/04	10/13/04
300392771900S01	SAN JUAN 30-6 UT 490S FC	RIO ARRIBA	NM	30	N	6	W 25	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/1/04		10/13/04	10/13/04
300392486900S01	SAN JUAN 30-6 UT 491 FC	RIO ARRIBA	NM	30	N	6	W 25	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/31/90		7/17/91	7/17/91
300392486900S01	SAN JUAN 30-6 UT 491 FC	RIO ARRIBA	NM	30	N	6	W 25	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/31/90		7/17/91	7/17/91
300392773900S01	SAN JUAN 30-6 UT 491S FC	RIO ARRIBA	NM	30	N	6	W 25	F	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/23/04		10/8/04	10/8/04
300392773900S01	SAN JUAN 30-6 UT 491S FC	RIO ARRIBA	NM	30	N	6	W 25	F	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	9/23/04		10/8/04	10/8/04
300392488900S01	SAN JUAN 30-6 UT 492 FC	RIO ARRIBA	NM	30	N	6	W 26	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/14/90		12/31/91	12/31/91
300392488900S01	SAN JUAN 30-6 UT 492 FC	RIO ARRIBA	NM	30	N	6	W 26	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/14/90		12/31/91	12/31/91
300392481500S01	SAN JUAN 30-6 UT 493 FC	RIO ARRIBA	NM	30	N	6	W 32	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/8/90		11/26/91	11/26/91
300392481500S01	SAN JUAN 30-6 UT 493 FC	RIO ARRIBA	NM	30	N	6	W 32	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/8/90		11/26/91	11/26/91
300392749600S01	SAN JUAN 30-6 UT 493S FC	RIO ARRIBA	NM	30	N	6	W 32	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	4/16/04		5/6/04	5/6/04
300392749600S01	SAN JUAN 30-6 UT 493S FC	RIO ARRIBA	NM	30	N	6	W 32	D	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	4/16/04		5/6/04	5/6/04
300392483100S01	SAN JUAN 30-6 UT 494 FC	RIO ARRIBA	NM	30	N	6	W 33	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/25/90		5/29/91	5/29/91
300392483100S01	SAN JUAN 30-6 UT 494 FC	RIO ARRIBA	NM	30	N	6	W 33	B	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/25/90		5/29/91	5/29/91
300392957800S01	SAN JUAN 30-6 UT 494S FC	RIO ARRIBA	NM	30	N	6	W 33	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	1/21/06	11/6/12	2/9/06	2/9/06
300392957800S01	SAN JUAN 30-6 UT 494S FC	RIO ARRIBA	NM	30	N	6	W 33	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	72	1/21/06	11/6/12	2/9/06	2/9/06
300392483200S01	SAN JUAN 30-6 UT 495 FC	RIO ARRIBA	NM	30	N	6	W 33	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/5/90		5/29/91	5/29/91
300392483200S01	SAN JUAN 30-6 UT 495 FC	RIO ARRIBA	NM	30	N	6	W 33	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/5/90		5/29/91	5/29/91
300392948900S01	SAN JUAN 30-6 UT 495S FC	RIO ARRIBA	NM	30	N	6	W 33	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/2/05		12/19/05	12/19/05
300392948900S01	SAN JUAN 30-6 UT 495S FC	RIO ARRIBA	NM	30	N	6	W 33	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/2/05		12/19/05	12/19/05
300392487000S01	SAN JUAN 30-6 UT 496 FC	RIO ARRIBA	NM	30	N	6	W 35	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/23/90		7/18/91	7/18/91
300392487000S01	SAN JUAN 30-6 UT 496 FC	RIO ARRIBA	NM	30	N	6	W 35	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	12/23/90		7/18/91	7/18/91
300392770800S01	SAN JUAN 30-6 UT 496S FC	RIO ARRIBA	NM	30	N	6	W 35	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/15/04		11/4/04	11/4/04
300392770800S01	SAN JUAN 30-6 UT 496S FC	RIO ARRIBA	NM	30	N	6	W 35	J	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	10/15/04		11/4/04	11/4/04
300392496000S01	SAN JUAN 30-6 UT 497 FC	RIO ARRIBA	NM	30	N	7	W 29	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/5/91		12/3/91	12/3/91
300392496000S01	SAN JUAN 30-6 UT 497 FC	RIO ARRIBA	NM	30	N	7	W 29	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	6/5/91		12/3/91	12/3/91
300392940100C02	SAN JUAN 30-6 UT 497S FC	RIO ARRIBA	NM	30	N	7	W 29	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/11/06		7/21/06	7/21/06
300392940100C02	SAN JUAN 30-6 UT 497S FC	RIO ARRIBA	NM	30	N	7	W 29	O	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	7/11/06		7/21/06	7/21/06
300392940100C01	SAN JUAN 30-6 UT 497S PC	RIO ARRIBA	NM	30	N	7	W 29	O	G	A728854	216600	UNKNOWN::PICTURED CLIFFS	11	7/11/06		7/21/06	7/21/06
300392494800S01	SAN JUAN 30-6 UT 499 FC	RIO ARRIBA	NM	30	N	7	W 30	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	12/19/90		8/28/91	8/28/91
300392494800S01	SAN JUAN 30-6 UT 499 FC	RIO ARRIBA	NM	30	N	7	W 30	K	G	A728855	216600	BASIN CB::FRUITLAND COAL	41	12/19/90		8/28/91	8/28/91
300392194100S01	SAN JUAN 30-6 UT 49A MV	RIO ARRIBA	NM	30	N	6	W 27	O	G	A728853	216600	BLANCO::MESAVERDE	11	8/5/80		12/1/80	12/1/80
300392033000S01	SAN JUAN 30-6 UT 49R MV	RIO ARRIBA	NM	30	N	6	W 27	B	G	A728853	216600	BLANCO::MESAVERDE	11	8/24/70		9/1/70	9/1/70
300392169300S01	SAN JUAN 30-6 UT 4A MV	RIO ARRIBA	NM	30	N	6	W 35	J	G	A728853	216600	BLANCO::MESAVERDE	11	1/2/79		4/1/79	4/1/79
300392032300S01	SAN JUAN 30-6 UT 4R MV	RIO ARRIBA	NM	30	N	6	W 35	G	G	A728853	216600	BLANCO::MESAVERDE	11	8/10/70		9/1/70	9/1/70
300390771600S01	SAN JUAN 30-6 UT 5 MV	RIO ARRIBA	NM	30	N	6	W 35	N	G	A728853	216600	BLANCO::MESAVERDE	11	9/2/70		3/25/53	3/25/53

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300390778900S01	SAN JUAN 30-6 UT 50 MV	RIO ARRIBA	NM	30	N	6	W	22	M	G	A728853	216600	BLANCO::MESAVERDE	11	12/8/52	1/6/53
300392481600S01	SAN JUAN 30-6 UT 501 FC	RIO ARRIBA	NM	30	N	6	W	32	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/17/90	11/20/91
300392481600S01	SAN JUAN 30-6 UT 501 FC	RIO ARRIBA	NM	30	N	6	W	32	G	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	11/17/90	11/20/91
300392560500S01	SAN JUAN 30-6 UT 50A MV	RIO ARRIBA	NM	30	N	6	W	22	E	G	A728853	216600	BLANCO::MESAVERDE	11	12/3/96	5/27/97
300390777300S01	SAN JUAN 30-6 UT 51 MV	RIO ARRIBA	NM	30	N	6	W	30	B	G	A728853	216600	BLANCO::MESAVERDE	11	8/10/70	10/13/52
300392221300S01	SAN JUAN 30-6 UT 51A MV	RIO ARRIBA	NM	30	N	6	W	30	P	G	A728853	216600	BLANCO::MESAVERDE	11	9/15/80	9/1/81
300393099600C01	SAN JUAN 30-6 UT 51B DK	RIO ARRIBA	NM	30	N	6	W	30	P	G	A714960	216600	BASIN::DAKOTA	11	3/8/12	4/12/12
300393099600C02	SAN JUAN 30-6 UT 51B MCS	RIO ARRIBA	NM	30	N	6	W	30	P	G	A717574	216600	BASIN::MANCOS	11	3/8/12	4/1/12
300393099600C03	SAN JUAN 30-6 UT 51B MV	RIO ARRIBA	NM	30	N	6	W	30	P	G	A728853	216600	BLANCO::MESAVERDE	11	3/8/12	4/1/12
300390779600S01	SAN JUAN 30-6 UT 52 MV	RIO ARRIBA	NM	30	N	6	W	21	K	G	A728853	216600	BLANCO::MESAVERDE	11	7/28/53	9/15/53
300392562500S01	SAN JUAN 30-6 UT 52A MV	RIO ARRIBA	NM	30	N	6	W	21	D	G	A728853	216600	BLANCO::MESAVERDE	11	5/1/97	5/9/97
300390774700S01	SAN JUAN 30-6 UT 53 MV	RIO ARRIBA	NM	30	N	6	W	29	M	G	A728853	216600	BLANCO::MESAVERDE	11	7/16/53	9/14/53
300392221200S01	SAN JUAN 30-6 UT 53A MV	RIO ARRIBA	NM	30	N	6	W	29	F	G	A728853	216600	BLANCO::MESAVERDE	11	12/22/80	3/1/81
300393074400C01	SAN JUAN 30-6 UT 53B DK	RIO ARRIBA	NM	30	N	6	W	29	M	G	A711776	216600	BASIN::DAKOTA	11	7/15/10	7/22/10
300393074400C02	SAN JUAN 30-6 UT 53B MV	RIO ARRIBA	NM	30	N	6	W	29	M	G	A728853	216600	BLANCO::MESAVERDE	11	7/15/10	7/22/10
300390780500D01	SAN JUAN 30-6 UT 54 MV	RIO ARRIBA	NM	30	N	6	W	21	H	G	A728853	216600	BLANCO::MESAVERDE	11	1/5/58	1/13/58
300392194000S01	SAN JUAN 30-6 UT 54A MV	RIO ARRIBA	NM	30	N	6	W	21	J	G	A728853	216600	BLANCO::MESAVERDE	11	5/14/80	10/1/80
300390776600S01	SAN JUAN 30-6 UT 55 MV	RIO ARRIBA	NM	30	N	6	W	29	H	G	A728853	216600	BLANCO::MESAVERDE	11	4/21/58	6/16/58
300392561900S01	SAN JUAN 30-6 UT 55A MV	RIO ARRIBA	NM	30	N	6	W	29	I	G	A728853	216600	BLANCO::MESAVERDE	11	4/21/97	4/30/97
300390773601S01	SAN JUAN 30-6 UT 56 MV	RIO ARRIBA	NM	30	N	6	W	34	H	G	A728853	216600	BLANCO::MESAVERDE	11	10/6/52	10/27/52
300392167100S01	SAN JUAN 30-6 UT 56A MV	RIO ARRIBA	NM	30	N	6	W	34	P	G	A728853	216600	BLANCO::MESAVERDE	11	1/9/79	6/1/79
300390775801S01	SAN JUAN 30-6 UT 57 MV	RIO ARRIBA	NM	30	N	6	W	30	K	G	A728853	216600	BLANCO::MESAVERDE	11	7/23/53	7/23/53
300392224100S01	SAN JUAN 30-6 UT 57A MV	RIO ARRIBA	NM	30	N	6	W	30	C	G	A728853	216600	BLANCO::MESAVERDE	11	12/18/80	4/1/81
300390771900S01	SAN JUAN 30-6 UT 58 MV	RIO ARRIBA	NM	30	N	6	W	31	N	G	A728853	216600	BLANCO::MESAVERDE	11	9/1/53	9/1/53
300392527400S01	SAN JUAN 30-6 UT 58B MV	RIO ARRIBA	NM	30	N	6	W	31	C	G	A728853	216600	BLANCO::MESAVERDE	11	9/21/93	3/14/94
300393080200C01	SAN JUAN 30-6 UT 58C DK	RIO ARRIBA	NM	30	N	6	W	31	C	G	A714421	216600	BASIN::DAKOTA	11	12/1/10	12/15/10
300393080200C02	SAN JUAN 30-6 UT 58C MV	RIO ARRIBA	NM	30	N	6	W	31	C	G	A728853	216600	BLANCO::MESAVERDE	11	12/1/10	12/15/10
300393080300C01	SAN JUAN 30-6 UT 58M DK	RIO ARRIBA	NM	30	N	6	W	31	N	G	A714420	216600	BASIN::DAKOTA	11	12/16/10	12/16/10
300393080300C02	SAN JUAN 30-6 UT 58M MV	RIO ARRIBA	NM	30	N	6	W	31	N	G	A728853	216600	BLANCO::MESAVERDE	11	12/16/10	12/16/10
300390777100S01	SAN JUAN 30-6 UT 59 MV	RIO ARRIBA	NM	30	N	6	W	28	A	G	A728853	216600	BLANCO::MESAVERDE	11	12/20/52	12/20/52
300392194200S01	SAN JUAN 30-6 UT 59A MV	RIO ARRIBA	NM	30	N	6	W	28	A	G	A728853	216600	BLANCO::MESAVERDE	11	5/14/80	9/1/80
300392559500S01	SAN JUAN 30-6 UT 5A MV	RIO ARRIBA	NM	30	N	6	W	35	F	G	A728853	216600	BLANCO::MESAVERDE	11	11/22/96	12/5/96
300390773800S01	SAN JUAN 30-6 UT 60 MV	RIO ARRIBA	NM	30	N	6	W	31	A	G	A728853	216600	BLANCO::MESAVERDE	11	12/20/55	12/29/55
300392195100S01	SAN JUAN 30-6 UT 60A MV	RIO ARRIBA	NM	30	N	6	W	31	I	G	A728853	216600	BLANCO::MESAVERDE	11	8/14/79	10/1/79
300392689800C01	SAN JUAN 30-6 UT 60B DK	RIO ARRIBA	NM	30	N	6	W	31	B	G	A725004	216600	BASIN::DAKOTA	11	9/27/04	10/12/04
300392689800C01	SAN JUAN 30-6 UT 60B DK	RIO ARRIBA	NM	30	N	6	W	31	B	G	A725004	216600	BASIN::DAKOTA	11	9/27/04	10/12/04
300392689800C02	SAN JUAN 30-6 UT 60B MV	RIO ARRIBA	NM	30	N	6	W	31	B	G	A728853	216600	BLANCO::MESAVERDE	11	9/27/04	10/12/04
300390771400S01	SAN JUAN 30-6 UT 61 MV	RIO ARRIBA	NM	30	N	6	W	34	N	G	A728853	216600	BLANCO::MESAVERDE	11	4/30/57	6/2/57
300392571100S01	SAN JUAN 30-6 UT 61A MV	RIO ARRIBA	NM	30	N	6	W	34	E	G	A728853	216600	BLANCO::MESAVERDE	11	10/16/97	11/3/97
300392567200C01	SAN JUAN 30-6 UT 62A DK	RIO ARRIBA	NM	30	N	6	W	28	E	G	A728852	216600	BASIN::DAKOTA	11	10/20/97	11/3/97
300392567200C02	SAN JUAN 30-6 UT 62A MV	RIO ARRIBA	NM	30	N	6	W	28	E	G	A728853	216600	BLANCO::MESAVERDE	11	10/20/97	11/3/97
300390775000S01	SAN JUAN 30-6 UT 62X MV	RIO ARRIBA	NM	30	N	6	W	28	M	G	A728853	216600	BLANCO::MESAVERDE	11	5/17/57	6/4/57
300390784101S01	SAN JUAN 30-6 UT 63 MV	RIO ARRIBA	NM	30	N	7	W	15	L	G	A728853	216600	BLANCO::MESAVERDE	11	8/4/52	8/4/52
300392192400S01	SAN JUAN 30-6 UT 63A MV	RIO ARRIBA	NM	30	N	7	W	15	C	G	A728853	216600	BLANCO::MESAVERDE	11	8/28/79	11/1/79
300392573400D01	SAN JUAN 30-6 UT 64A DK	RIO ARRIBA	NM	30	N	7	W	11	O	G	A724962	216600	BASIN::DAKOTA	11	11/7/97	12/3/97
300392573400D02	SAN JUAN 30-6 UT 64A MV	RIO ARRIBA	NM	30	N	7	W	11	O	G	A728853	216600	BLANCO::MESAVERDE	11	11/7/97	12/3/97
300392192200S01	SAN JUAN 30-6 UT 65A MV	RIO ARRIBA	NM	30	N	7	W	13	C	G	A728853	216600	BLANCO::MESAVERDE	11	8/30/79	11/1/79
300392032000S01	SAN JUAN 30-6 UT 65R MV	RIO ARRIBA	NM	30	N	7	W	13	L	G	A728853	216600	BLANCO::MESAVERDE	11	9/8/70	12/1/70
300392192300S01	SAN JUAN 30-6 UT 66A MV	RIO ARRIBA	NM	30	N	7	W	14	F	G	A728853	216600	BLANCO::MESAVERDE	11	9/24/79	11/1/79
300392540000S01	SAN JUAN 30-6 UT 66R MV	RIO ARRIBA	NM	30	N	7	W	14	M	G	A728853	216600	BLANCO::MESAVERDE	11	10/12/94	1/17/95

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE	
300390789000S01	SAN JUAN 30-6 UT 67 MV	RIO ARRIBA	NM	30	N	7	W	12	H	G	A728853	216600	BLANCO::MESAVERDE	11	9/30/56		10/10/56	10/10/56
300392571200S01	SAN JUAN 30-6 UT 67A MV	RIO ARRIBA	NM	30	N	7	W	12	I	G	A728853	216600	BLANCO::MESAVERDE	11	10/28/97		11/14/97	11/14/97
300390775300S01	SAN JUAN 30-6 UT 68 MV	RIO ARRIBA	NM	30	N	6	W	25	M	G	A728853	216600	BLANCO::MESAVERDE	11	9/7/54		9/16/54	9/16/54
300392567400S01	SAN JUAN 30-6 UT 68A MV	RIO ARRIBA	NM	30	N	6	W	25	F	G	A728853	216600	BLANCO::MESAVERDE	11	9/28/97		10/8/97	10/8/97
300390785300S01	SAN JUAN 30-6 UT 69 MV	RIO ARRIBA	NM	30	N	7	W	14	H	G	A728853	216600	BLANCO::MESAVERDE	11	5/5/53		5/19/53	5/19/53
300392561100S01	SAN JUAN 30-6 UT 69A MV	RIO ARRIBA	NM	30	N	7	W	14	I	G	A728853	216600	BLANCO::MESAVERDE	11	1/4/97		6/9/97	6/9/97
300390775500S01	SAN JUAN 30-6 UT 7 MV	RIO ARRIBA	NM	30	N	7	W	30	K	G	A728853	216600	BLANCO::MESAVERDE	11	9/17/55		9/17/55	9/17/55
300390787200S01	SAN JUAN 30-6 UT 70 MV	RIO ARRIBA	NM	30	N	7	W	12	M	G	A728853	216600	BLANCO::MESAVERDE	11	9/4/55		9/4/55	9/4/55
300392192100S01	SAN JUAN 30-6 UT 70A MV	RIO ARRIBA	NM	30	N	7	W	12	E	G	A728853	216600	BLANCO::MESAVERDE	11	9/27/79		11/1/79	11/1/79
300390786200S01	SAN JUAN 30-6 UT 71 MV	RIO ARRIBA	NM	30	N	7	W	13	H	G	A728853	216600	BLANCO::MESAVERDE	11	10/17/55		10/26/55	10/26/55
300392542400C01	SAN JUAN 30-6 UT 71A DK	RIO ARRIBA	NM	30	N	7	W	13	J	G	A728852	216600	BASIN::DAKOTA	11	9/29/94		1/24/95	1/24/95
300392542400C02	SAN JUAN 30-6 UT 71A MV	RIO ARRIBA	NM	30	N	7	W	13	J	G	A728853	216600	BLANCO::MESAVERDE	11	9/28/94		1/24/95	1/24/95
300392612000S01	SAN JUAN 30-6 UT 71E DK	RIO ARRIBA	NM	30	N	7	W	13	L	G	A728852	216600	BASIN::DAKOTA	11	9/30/99		10/8/99	10/8/99
300392192600S01	SAN JUAN 30-6 UT 72A MV	RIO ARRIBA	NM	30	N	7	W	22	P	G	A728853	216600	BLANCO::MESAVERDE	11	8/22/79		1/1/80	1/1/80
300390781001S01	SAN JUAN 30-6 UT 74 MV	RIO ARRIBA	NM	30	N	7	W	23	A	G	A728853	216600	BLANCO::MESAVERDE	11	3/21/53		4/2/53	4/2/53
300392544700S01	SAN JUAN 30-6 UT 74A MV	RIO ARRIBA	NM	30	N	7	W	23	J	G	A728853	216600	BLANCO::MESAVERDE	11	10/29/94		1/18/95	1/18/95
300392676200S01	SAN JUAN 30-6 UT 74B MV	RIO ARRIBA	NM	30	N	7	W	23	P	G	A728853	216600	BLANCO::MESAVERDE	11	6/17/02		6/19/02	6/19/02
300390779700S01	SAN JUAN 30-6 UT 75 MV	RIO ARRIBA	NM	30	N	7	W	23	K	G	A728853	216600	BLANCO::MESAVERDE	11	3/6/53		3/18/53	3/18/53
300392544600S01	SAN JUAN 30-6 UT 75A MV	RIO ARRIBA	NM	30	N	7	W	23	D	G	A728853	216600	BLANCO::MESAVERDE	11	10/21/94		1/18/95	1/18/95
300390781100S01	SAN JUAN 30-6 UT 76 MV	RIO ARRIBA	NM	30	N	7	W	24	H	G	A728853	216600	BLANCO::MESAVERDE	11	5/3/53		6/10/53	6/10/53
300392567500D01	SAN JUAN 30-6 UT 76A DK	RIO ARRIBA	NM	30	N	7	W	24	O	G	A728852	216600	BASIN::DAKOTA	11	10/4/97		10/30/97	10/30/97
300392567500D02	SAN JUAN 30-6 UT 76A MV	RIO ARRIBA	NM	30	N	7	W	24	O	G	A728853	216600	BLANCO::MESAVERDE	11	10/4/97		10/30/97	10/30/97
300392600400S01	SAN JUAN 30-6 UT 76E DK	RIO ARRIBA	NM	30	N	7	W	24	H	G	A728852	216600	BASIN::DAKOTA	11	3/18/99		6/8/99	6/8/99
300390779800S01	SAN JUAN 30-6 UT 77 MV	RIO ARRIBA	NM	30	N	7	W	24	K	G	A728853	216600	BLANCO::MESAVERDE	11	4/4/53		4/29/53	4/29/53
300392573800C01	SAN JUAN 30-6 UT 77A DK	RIO ARRIBA	NM	30	N	7	W	24	E	G	A728852	216600	BASIN::DAKOTA	11	10/15/97		11/15/97	11/15/97
300392573800C02	SAN JUAN 30-6 UT 77A MV	RIO ARRIBA	NM	30	N	7	W	24	E	G	A728853	216600	BLANCO::MESAVERDE	11	10/15/97		11/13/97	11/13/97
300393100100C01	SAN JUAN 30-6 UT 77M DK	RIO ARRIBA	NM	30	N	7	W	24	M	G	A728852	216600	BASIN::DAKOTA	11	9/26/11		9/27/11	9/27/11
300393100100C02	SAN JUAN 30-6 UT 77M MV	RIO ARRIBA	NM	30	N	7	W	24	M	G	A728853	216600	BLANCO::MESAVERDE	11	9/26/11		9/27/11	9/27/11
300390777700S01	SAN JUAN 30-6 UT 78 MV	RIO ARRIBA	NM	30	N	7	W	25	A	G	A728853	216600	BLANCO::MESAVERDE	11	6/14/53		6/14/53	6/14/53
300392192700S01	SAN JUAN 30-6 UT 78A MV	RIO ARRIBA	NM	30	N	7	W	25	J	G	A728853	216600	BLANCO::MESAVERDE	11	9/20/79		5/1/80	5/1/80
300390775900S01	SAN JUAN 30-6 UT 79 MV	RIO ARRIBA	NM	30	N	7	W	25	L	G	A728853	216600	BLANCO::MESAVERDE	11	7/18/53		8/5/53	8/5/53
300392546900S01	SAN JUAN 30-6 UT 79A MV	RIO ARRIBA	NM	30	N	7	W	25	C	G	A728853	216600	BLANCO::MESAVERDE	11	11/5/94		3/22/95	3/22/95
300392170000S01	SAN JUAN 30-6 UT 7A MV	RIO ARRIBA	NM	30	N	7	W	30	F	G	A728853	216600	BLANCO::MESAVERDE	11	10/3/78		5/1/79	5/1/79
300390772600S01	SAN JUAN 30-6 UT 8 MV	RIO ARRIBA	NM	30	N	7	W	31	K	G	A728853	216600	BLANCO::MESAVERDE	11	7/26/55		8/2/55	8/2/55
300392563400C01	SAN JUAN 30-6 UT 80A DK	RIO ARRIBA	NM	30	N	6	W	17	C	G	A724963	216600	BASIN::DAKOTA	11	10/4/97		10/28/97	10/28/97
300392563400C02	SAN JUAN 30-6 UT 80A MV	RIO ARRIBA	NM	30	N	6	W	17	C	G	A728853	216600	BLANCO::MESAVERDE	11	10/4/97		10/28/97	10/28/97
300390785500S01	SAN JUAN 30-6 UT 81 MV	RIO ARRIBA	NM	30	N	6	W	17	A	G	A728853	216600	BLANCO::MESAVERDE	11	11/19/55		12/7/55	12/7/55
300392193800S01	SAN JUAN 30-6 UT 81A MV	RIO ARRIBA	NM	30	N	6	W	17	J	G	A728853	216600	BLANCO::MESAVERDE	11	10/4/79		6/1/80	6/1/80
300390779400S01	SAN JUAN 30-6 UT 82 MV	RIO ARRIBA	NM	30	N	6	W	20	L	G	A728853	216600	BLANCO::MESAVERDE	11	12/19/57		1/13/58	1/13/58
300392565700C01	SAN JUAN 30-6 UT 82A DK	RIO ARRIBA	NM	30	N	6	W	20	E	G	A728852	216600	BASIN::DAKOTA	11	9/11/97		10/15/97	10/15/97
300392565700C02	SAN JUAN 30-6 UT 82A MV	RIO ARRIBA	NM	30	N	6	W	20	E	G	A728853	216600	BLANCO::MESAVERDE	11	9/11/97		10/15/97	10/15/97
300390786100S01	SAN JUAN 30-6 UT 83 MV	RIO ARRIBA	NM	30	N	7	W	15	A	G	A728853	216600	BLANCO::MESAVERDE	11	7/23/53		8/5/53	8/5/53
300392560600S01	SAN JUAN 30-6 UT 83A MV	RIO ARRIBA	NM	30	N	7	W	15	J	G	A728853	216600	BLANCO::MESAVERDE	11	11/14/96		11/22/96	11/22/96
300390787300S01	SAN JUAN 30-6 UT 84 MV	RIO ARRIBA	NM	30	N	7	W	11	M	G	A728853	216600	BLANCO::MESAVERDE	11	6/30/53		7/1/53	7/1/53
300392265100S01	SAN JUAN 30-6 UT 84A MV	RIO ARRIBA	NM	30	N	7	W	11	E	G	A728853	216600	BLANCO::MESAVERDE	11	1/4/82		4/1/82	4/1/82
300390784200S01	SAN JUAN 30-6 UT 85 MV	RIO ARRIBA	NM	30	N	6	W	16	L	G	A728853	216600	BLANCO::MESAVERDE	11	10/11/54		9/18/62	9/18/62
300392559900S01	SAN JUAN 30-6 UT 85A MV	RIO ARRIBA	NM	30	N	6	W	16	E	G	A728853	216600	BLANCO::MESAVERDE	11	2/25/97		3/7/97	3/7/97
300390773200S01	SAN JUAN 30-6 UT 86 MV	RIO ARRIBA	NM	30	N	7	W	36	G	G	A728853	216600	BLANCO::MESAVERDE	11	1/21/56		2/10/56	2/10/56
300392230300S01	SAN JUAN 30-6 UT 86A MV	RIO ARRIBA	NM	30	N	7	W	36	J	G	A728853	216600	BLANCO::MESAVERDE	11	11/13/80		11/1/81	11/1/81
300393087000C01	SAN JUAN 30-6 UT 86B DK	RIO ARRIBA	NM	30	N	7	W	36	P	G	A714475	216600	BASIN::DAKOTA	11	11/19/10		1/24/11	1/24/11

PRODUCTION STATUS

11 - FLOWING WELL
41 - SHUT IN
59 - SOLD
61 - TEMP ABANDON

71 - PERM ABANDON ZONE
72 - PERM ABANDON WELL
PA - PLUG ABANDON
PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN		RGE		SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300393087000C02	SAN JUAN 30-6 UT 86B MV	RIO ARRIBA	NM	30	N	7	W	36	P	G	A728853	216600	BLANCO::MESAVERDE	11	11/19/10		1/24/11	1/24/11
300392230400S01	SAN JUAN 30-6 UT 87A MV	RIO ARRIBA	NM	30	N	7	W	36	D	G	A728853	216600	BLANCO::MESAVERDE	11	12/1/80		3/1/81	3/1/81
300392683500S01	SAN JUAN 30-6 UT 87B MV	RIO ARRIBA	NM	30	N	7	W	36	N	G	A728853	216600	BLANCO::MESAVERDE	11	2/8/03		2/11/03	2/11/03
300390787900S01	SAN JUAN 30-6 UT 88 MV	RIO ARRIBA	NM	30	N	6	W	7	K	G	A728853	216600	BLANCO::MESAVERDE	11	4/16/53		4/17/53	4/17/53
300392221100S01	SAN JUAN 30-6 UT 88A MV	RIO ARRIBA	NM	30	N	6	W	7	F	G	A728853	216600	BLANCO::MESAVERDE	11	12/23/80		3/1/81	3/1/81
300390773000S01	SAN JUAN 30-6 UT 89 MV	RIO ARRIBA	NM	30	N	6	W	36	G	G	A728853	216600	BLANCO::MESAVERDE	11	7/1/53		7/1/53	7/1/53
300392167300C01	SAN JUAN 30-6 UT 89A MV	RIO ARRIBA	NM	30	N	6	W	36	O	G	A728853	216600	BLANCO::MESAVERDE	11	1/25/79		6/5/79	6/5/79
300392167300C02	SAN JUAN 30-6 UT 89A PC	RIO ARRIBA	NM	30	N	6	W	36	O	G	A728854	216600	GOBERNADOR::PICTURED CLIF	11	1/11/84		6/5/79	6/5/79
300392170100S01	SAN JUAN 30-6 UT 8A MV	RIO ARRIBA	NM	30	N	7	W	31	C	G	A728853	216600	BLANCO::MESAVERDE	11	7/31/78		7/31/78	7/31/78
300392636900S01	SAN JUAN 30-6 UT 8B MV	RIO ARRIBA	NM	30	N	7	W	31	F	G	A728853	216600	BLANCO::MESAVERDE	11	5/1/01		5/4/01	
300390776500S01	SAN JUAN 30-6 UT 9 MV	RIO ARRIBA	NM	30	N	7	W	30	G	G	A728853	216600	BLANCO::MESAVERDE	11	11/7/55		11/14/55	11/14/55
300390772300S01	SAN JUAN 30-6 UT 90 MV	RIO ARRIBA	NM	30	N	6	W	36	L	G	A728853	216600	BLANCO::MESAVERDE	11	7/10/53		7/23/53	7/23/53
300392560000S01	SAN JUAN 30-6 UT 90A MV	RIO ARRIBA	NM	30	N	6	W	36	E	G	A728853	216600	BLANCO::MESAVERDE	11	2/20/97		3/3/97	3/3/97
300392626500D01	SAN JUAN 30-6 UT 91R MV	RIO ARRIBA	NM	30	N	7	W	28	O	G	A728853	216600	BLANCO::MESAVERDE	11	6/15/01		6/18/01	
300392626500D02	SAN JUAN 30-6 UT 91R PC	RIO ARRIBA	NM	30	N	7	W	28	O	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	6/15/01		6/21/01	6/21/01
300392540900D01	SAN JUAN 30-6 UT 92A MV	RIO ARRIBA	NM	30	N	7	W	33	I	G	A728853	216600	BLANCO::MESAVERDE	11	9/13/94		1/19/95	1/19/95
300392540900D02	SAN JUAN 30-6 UT 92A PC	RIO ARRIBA	NM	30	N	7	W	33	I	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	9/13/94		1/24/95	1/24/95
300392687400C01	SAN JUAN 30-6 UT 92B DK	RIO ARRIBA	NM	30	N	7	W	33	O	G	A728852	216600	BASIN::DAKOTA	11	10/17/02		10/22/02	10/22/02
300392687400C02	SAN JUAN 30-6 UT 92B MV	RIO ARRIBA	NM	30	N	7	W	33	O	G	A728853	216600	BLANCO::MESAVERDE	11	10/17/02		10/22/02	10/22/02
300393068600C01	SAN JUAN 30-6 UT 92M DK	RIO ARRIBA	NM	30	N	7	W	33	G	G	A728852	216600	BASIN::DAKOTA	11	12/9/09		12/1/09	12/1/09
300393068600C02	SAN JUAN 30-6 UT 92M MV	RIO ARRIBA	NM	30	N	7	W	33	G	G	A728853	216600	BLANCO::MESAVERDE	11	12/9/09		12/1/09	12/1/09
300393074500C01	SAN JUAN 30-6 UT 92N DK	RIO ARRIBA	NM	30	N	7	W	33	G	G	A728852	216600	BASIN::DAKOTA	11	12/23/09		12/14/09	12/14/09
300393074500C02	SAN JUAN 30-6 UT 92N MV	RIO ARRIBA	NM	30	N	7	W	33	G	G	A728853	216600	BLANCO::MESAVERDE	11	12/23/09		12/14/09	12/14/09
300390772501S01	SAN JUAN 30-6 UT 93 MV	RIO ARRIBA	NM	30	N	7	W	33	K	G	A728853	216600	BLANCO::MESAVERDE	11	9/6/53		9/29/53	9/29/53
300392580600S01	SAN JUAN 30-6 UT 93A MV	RIO ARRIBA	NM	30	N	7	W	33	E	G	A728853	216600	BLANCO::MESAVERDE	11	7/15/98		7/29/98	7/29/98
300392689300C01	SAN JUAN 30-6 UT 93B DK	RIO ARRIBA	NM	30	N	7	W	33	F	G	A728852	216600	BASIN::DAKOTA	11	6/20/03		6/27/03	6/27/03
300392689300C02	SAN JUAN 30-6 UT 93B MV	RIO ARRIBA	NM	30	N	7	W	33	F	G	A728853	216600	BLANCO::MESAVERDE	11	6/20/03		6/27/03	6/27/03
300392689300C03	SAN JUAN 30-6 UT 93B PC	RIO ARRIBA	NM	30	N	7	W	33	F	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	6/20/03		6/27/03	6/27/03
300392689400C01	SAN JUAN 30-6 UT 93M DK	RIO ARRIBA	NM	30	N	7	W	33	M	G	A728852	216600	BASIN::DAKOTA	11	6/28/03		7/9/03	7/9/03
300392689400C02	SAN JUAN 30-6 UT 93M MV	RIO ARRIBA	NM	30	N	7	W	33	M	G	A728853	216600	BLANCO::MESAVERDE	11	6/28/03		7/9/03	7/9/03
300392689400C03	SAN JUAN 30-6 UT 93M PC	RIO ARRIBA	NM	30	N	7	W	33	M	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	6/28/03		7/9/03	7/9/03
300391824100S01	SAN JUAN 30-6 UT 94 MV	RIO ARRIBA	NM	30	N	7	W	28	N	G	A728853	216600	BLANCO::MESAVERDE	11	10/25/52		5/25/53	5/25/53
300392265400S01	SAN JUAN 30-6 UT 94A MV	RIO ARRIBA	NM	30	N	7	W	28	F	G	A728853	216600	BLANCO::MESAVERDE	11	1/4/82		4/1/82	4/1/82
300392626600C01	SAN JUAN 30-6 UT 94B DK	RIO ARRIBA	NM	30	N	7	W	28	L	G	A728852	216600	BASIN::DAKOTA	11	11/18/00		2/21/01	2/21/01
300392626600C02	SAN JUAN 30-6 UT 94B MV	RIO ARRIBA	NM	30	N	7	W	28	L	G	A728853	216600	BLANCO::MESAVERDE	11	11/18/00		2/21/01	2/21/01
300392626600D03	SAN JUAN 30-6 UT 94B PC	RIO ARRIBA	NM	30	N	7	W	28	L	G	A728854	216600	LA JARA CNYN::PICTURED CL	11	11/18/00		2/23/01	2/23/01
300392689500C01	SAN JUAN 30-6 UT 94M DK	RIO ARRIBA	NM	30	N	7	W	28	E	G	A728852	216600	BASIN::DAKOTA	11	7/10/02		7/12/02	7/12/02
300392689500C02	SAN JUAN 30-6 UT 94M MV	RIO ARRIBA	NM	30	N	7	W	28	E	G	A728853	216600	BLANCO::MESAVERDE	11	7/10/02		7/12/02	7/12/02
300392169900S01	SAN JUAN 30-6 UT 95A MV	RIO ARRIBA	NM	30	N	7	W	26	D	G	A728853	216600	BLANCO::MESAVERDE	11	1/24/79		11/1/79	11/1/79
300392980700C01	SAN JUAN 30-6 UT 95B DK	RIO ARRIBA	NM	30	N	7	W	26	C	G	A734270	216600	BASIN::DAKOTA	11	2/22/07		2/22/07	3/8/07
300392980700C01	SAN JUAN 30-6 UT 95B DK	RIO ARRIBA	NM	30	N	7	W	26	C	G	A734270	216600	BASIN::DAKOTA	11	2/22/07		2/22/07	3/8/07
300392980700C02	SAN JUAN 30-6 UT 95B MV	RIO ARRIBA	NM	30	N	7	W	26	C	G	A728853	216600	BLANCO::MESAVERDE	11	2/22/07		2/22/07	3/8/07
300393092200C01	SAN JUAN 30-6 UT 95P DK	RIO ARRIBA	NM	30	N	7	W	26	M	G	A716429	216600	BASIN::DAKOTA	11	3/21/11		4/12/11	4/12/11
300393092200C02	SAN JUAN 30-6 UT 95P MV	RIO ARRIBA	NM	30	N	7	W	26	M	G	A728853	216600	BLANCO::MESAVERDE	11	3/21/11		4/12/11	4/12/11
300392527500S01	SAN JUAN 30-6 UT 95X MV	RIO ARRIBA	NM	30	N	7	W	26	N	G	A728853	216600	BLANCO::MESAVERDE	11	8/25/93		3/3/94	3/3/94
300390777200S01	SAN JUAN 30-6 UT 96 MV	RIO ARRIBA	NM	30	N	7	W	26	B	G	A728853	216600	BLANCO::MESAVERDE	11	11/24/53		11/24/53	11/24/53
300392568000S01	SAN JUAN 30-6 UT 96A MV	RIO ARRIBA	NM	30	N	7	W	26	I	G	A728853	216600	BLANCO::MESAVERDE	11	9/6/97		9/16/97	9/16/97
300392701100C01	SAN JUAN 30-6 UT 96B DK	RIO ARRIBA	NM	30	N	7	W	26	H	G	A725000	216600	BASIN::DAKOTA	11	10/18/02		10/22/02	10/22/02
300392701100C01	SAN JUAN 30-6 UT 96B DK	RIO ARRIBA	NM	30	N	7	W	26	H	G	A725000	216600	BASIN::DAKOTA	11	10/18/02		10/22/02	10/22/02
300392701100C02	SAN JUAN 30-6 UT 96B MV	RIO ARRIBA	NM	30	N	7	W	26	H	G	A728853	216600	BLANCO::MESAVERDE	11	10/18/02		10/22/02	10/22/02

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300393083600C01	SAN JUAN 30-6 UT 96N DK	RIO ARRIBA	NM	30	N	7	W	26	H	G	A725000	216600	BASIN::DAKOTA	11	11/30/10	11/30/10
300393083600C01	SAN JUAN 30-6 UT 96N DK	RIO ARRIBA	NM	30	N	7	W	26	H	G	A725000	216600	BASIN::DAKOTA	11	11/30/10	11/30/10
300393083600C02	SAN JUAN 30-6 UT 96N MV	RIO ARRIBA	NM	30	N	7	W	26	H	G	A728853	216600	BLANCO::MESAVERDE	11	11/30/10	11/30/10
300390776700S01	SAN JUAN 30-6 UT 97 MV	RIO ARRIBA	NM	30	N	7	W	27	G	G	A728853	216600	BLANCO::MESAVERDE	11	12/18/54	1/5/55
300392544800S01	SAN JUAN 30-6 UT 97A MV	RIO ARRIBA	NM	30	N	7	W	27	J	G	A728853	216600	BLANCO::MESAVERDE	11	10/5/94	5/3/95
300393068500C01	SAN JUAN 30-6 UT 97B DK	RIO ARRIBA	NM	30	N	7	W	27	J	G	A713487	216600	BASIN::DAKOTA	11	3/18/11	3/18/11
300393068500C02	SAN JUAN 30-6 UT 97B MV	RIO ARRIBA	NM	30	N	7	W	27	J	G	A728853	216600	BLANCO::MESAVERDE	11	3/18/11	3/18/11
300393094400C01	SAN JUAN 30-6 UT 97M DK	RIO ARRIBA	NM	30	N	7	W	27	J	G	A715004	216600	BASIN::DAKOTA	11	3/15/11	3/25/11
300393094400C02	SAN JUAN 30-6 UT 97M MV	RIO ARRIBA	NM	30	N	7	W	27	J	G	A728853	216600	BLANCO::MESAVERDE	11	3/15/11	3/25/11
300390773301S01	SAN JUAN 30-6 UT 98 MV	RIO ARRIBA	NM	30	N	7	W	34	G	G	A728853	216600	BLANCO::MESAVERDE	11	5/12/55	5/19/55
300392190500S01	SAN JUAN 30-6 UT 98A MV	RIO ARRIBA	NM	30	N	7	W	34	J	G	A728853	216600	BLANCO::MESAVERDE	11	8/3/79	9/1/79
300393077900C01	SAN JUAN 30-6 UT 98B DK	RIO ARRIBA	NM	30	N	7	W	34	G	G	A713487	216600	BASIN::DAKOTA	11	6/24/10	7/3/10
300393077900C02	SAN JUAN 30-6 UT 98B MV	RIO ARRIBA	NM	30	N	7	W	34	G	G	A728853	216600	BLANCO::MESAVERDE	11	6/24/10	7/3/10
300393074600C01	SAN JUAN 30-6 UT 98M DK	RIO ARRIBA	NM	30	N	7	W	34	G	G	A713487	216600	BASIN::DAKOTA	11	6/17/10	6/17/10
300393074600C02	SAN JUAN 30-6 UT 98M MV	RIO ARRIBA	NM	30	N	7	W	34	G	G	A728853	216600	BLANCO::MESAVERDE	11	6/17/10	6/17/10
300390772001S01	SAN JUAN 30-6 UT 99 MV	RIO ARRIBA	NM	30	N	7	W	34	M	G	A728853	216600	BLANCO::MESAVERDE	11	4/12/55	5/19/55
300392190400C01	SAN JUAN 30-6 UT 99A MV	RIO ARRIBA	NM	30	N	7	W	34	F	G	A728853	216600	BLANCO::MESAVERDE	11	7/30/79	9/1/79
300392190400C02	SAN JUAN 30-6 UT 99A PC	RIO ARRIBA	NM	30	N	7	W	34	F	G	A728854	216600	TAPACITO::PICTURED CLIFFS	11	10/4/01	10/6/01
300392769500C01	SAN JUAN 30-6 UT 99B DK	RIO ARRIBA	NM	30	N	7	W	34	E	G	A728852	216600	BASIN::DAKOTA	11	8/17/05	8/25/05
300392769500C02	SAN JUAN 30-6 UT 99B MV	RIO ARRIBA	NM	30	N	7	W	34	E	G	A728853	216600	BLANCO::MESAVERDE	11	8/17/05	8/25/05
300392687500C01	SAN JUAN 30-6 UT 99C DK	RIO ARRIBA	NM	30	N	7	W	34	N	G	A728852	216600	BASIN::DAKOTA	11	5/23/03	6/2/03
300392687500C02	SAN JUAN 30-6 UT 99C MV	RIO ARRIBA	NM	30	N	7	W	34	N	G	A728853	216600	BLANCO::MESAVERDE	11	5/23/03	6/2/03
300392190300S01	SAN JUAN 30-6 UT 9A MV	RIO ARRIBA	NM	30	N	7	W	30	P	G	A728853	216600	BLANCO::MESAVERDE	11	8/14/79	2/1/80
300393083800C01	SAN JUAN 30-6 UT 9B DK	RIO ARRIBA	NM	30	N	7	W	30	G	G	A714288	216600	BASIN::DAKOTA	11	6/14/10	8/12/10
300393083800C02	SAN JUAN 30-6 UT 9B MV	RIO ARRIBA	NM	30	N	7	W	30	G	G	A728853	216600	BLANCO::MESAVERDE	11	6/14/10	
300392447500S01	SAN JUAN 30-6 UT COM 467	RIO ARRIBA	NM	30	N	7	W	22	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/9/90	9/20/90
300392447500S01	SAN JUAN 30-6 UT COM 467	RIO ARRIBA	NM	30	N	7	W	22	M	G	A728855	216600	BASIN CB::FRUITLAND COAL	11	5/9/90	9/20/90
300392940800S01	SAN JUAN 30-6 UT COM 467S	RIO ARRIBA	NM	30	N	7	W	22	F	G	A728855	216600	BASIN::FRUITLAND COAL	11	2/20/06	3/16/06
300392940800S01	SAN JUAN 30-6 UT COM 467S	RIO ARRIBA	NM	30	N	7	W	22	F	G	A728855	216600	BASIN::FRUITLAND COAL	11	2/20/06	3/16/06
300390778800S01	SAN JUAN 30-6 UT COM 73	RIO ARRIBA	NM	30	N	7	W	22	M	G	A728853	216600	BLANCO::MESAVERDE	11	8/6/54	8/24/54
300392265200S01	SAN JUAN 30-6 UT COM 73A	RIO ARRIBA	NM	30	N	7	W	22	F	G	A728853	216600	BLANCO::MESAVERDE	11	1/4/82	4/1/82
300392533800S01	SAN JUAN 30-6 UT NP 498R	RIO ARRIBA	NM	30	N	7	W	30	G	G	A721121	216600	BASIN CB::FRUITLAND COAL	11	12/31/93	1/29/96
300392490700S01	SAN JUAN 30-6 UT NP 500 F	RIO ARRIBA	NM	30	N	7	W	31	K	G	A721124	216600	BASIN CB::FRUITLAND COAL	11	1/12/91	3/30/93
300392490700S01	SAN JUAN 30-6 UT NP 500 F	RIO ARRIBA	NM	30	N	7	W	31	K	G	A721124	216600	BASIN CB::FRUITLAND COAL	11	1/12/91	3/30/93
300392453000S01	SAN JUAN 30-6 UT POW 1 FC	RIO ARRIBA	NM	30	N	7	W	24	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	PM	3/13/90	
300392453000S01	SAN JUAN 30-6 UT POW 1 FC	RIO ARRIBA	NM	30	N	7	W	24	E	G	A728855	216600	BASIN CB::FRUITLAND COAL	PM	3/13/90	
300392533100S01	SAN JUAN 30-6 UT POW 2 FC	RIO ARRIBA	NM	30	N	6	W	33	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	PM	5/22/94	
300392533100S01	SAN JUAN 30-6 UT POW 2 FC	RIO ARRIBA	NM	30	N	6	W	33	C	G	A728855	216600	BASIN CB::FRUITLAND COAL	PM	5/22/94	
300392350100S01	SAN JUAN 30-6 UT SWD 112Y	RIO ARRIBA	NM	30	N	6	W	26	A	S	A068946	216600	UNK::MORRISON ENTRADA	31	9/26/86	9/24/86
300392393400S01	SAN JUAN 30-6(FC) 400 JCV	RIO ARRIBA	NM	30	N	7	W	14	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94
300392400000S01	SAN JUAN 30-6(FC) 401 JCV	RIO ARRIBA	NM	30	N	7	W	13	L	G	A705781	30274	BASIN CB::FRUITLAND COAL	PM		1/1/94
300392436600S01	SAN JUAN 30-6(FC) 401RUCV	RIO ARRIBA	NM	30	N	7	W	13	N	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94
300392401500S01	SAN JUAN 30-6(FC) 402 JCV	RIO ARRIBA	NM	30	N	7	W	15	K	G	A705781	30274	BASIN CB::FRUITLAND COAL	41		1/1/94
300392471700S01	SAN JUAN 30-6(FC) 403 JCV	RIO ARRIBA	NM	30	N	6	W	9	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		12/1/90
300392776300S01	SAN JUAN 30-6(FC) 403S	RIO ARRIBA	NM	30	N	6	W	9	O	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	11/24/06	7/19/07
300392417900S01	SAN JUAN 30-6(FC) 404 JCV	RIO ARRIBA	NM	30	N	7	W	23	B	G	A705781	30274	BASIN CB::FRUITLAND COAL	PS		1/1/94
300392524100S01	SAN JUAN 30-6(FC) 404RUCV	RIO ARRIBA	NM	30	N	7	W	23	B	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		6/1/93
300392768800	SAN JUAN 30-6(FC) 404S	RIO ARRIBA	NM	30	N	7	W	23	O	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		
300392458900S01	SAN JUAN 30-6(FC) 405 JCV	RIO ARRIBA	NM	30	N	6	W	9	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		3/29/90
300392933800	SAN JUAN 30-6(FC) 405S	RIO ARRIBA	NM	30	N	6	W	9	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	2/1/04	

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392402700S01	SAN JUAN 30-6(FC) 406 JCV	RIO ARRIBA	NM	30	N	7	W	15	F	G	A705781	30274			1/1/94	1/1/94
300392448400S01	SAN JUAN 30-6(FC) 406RJC	RIO ARRIBA	NM	30	N	7	W	15	F	G	A705781	30274			1/1/94	1/1/94
300392452700S01	SAN JUAN 30-6(FC) 407 JCV	RIO ARRIBA	NM	30	N	6	W	16	H	G	A705781	30274			1/1/94	12/6/89
300392452600S01	SAN JUAN 30-6(FC) 408 JCV	RIO ARRIBA	NM	30	N	6	W	16	L	G	A705781	30274			1/1/94	12/1/89
300392694300	SAN JUAN 30-6(FC) 408S	RIO ARRIBA	NM	30	N	6	W	16	E	G	A705781	1542298000				
300392418600S01	SAN JUAN 30-6(FC) 409 JCV	RIO ARRIBA	NM	30	N	7	W	25	L	G	A705781	30274			1/1/94	1/1/94
	SAN JUAN 30-6(FC) 409S	RIO ARRIBA	NM	30	N	7	W	25		G	A705781	30274				
300392460200S01	SAN JUAN 30-6(FC) 410 JCV	RIO ARRIBA	NM	30	N	6	W	26	A	G	A705781	30274			1/1/94	9/27/90
300392418900S01	SAN JUAN 30-6(FC) 411 JCV	RIO ARRIBA	NM	30	N	7	W	27	A	G	A705781	30274			1/1/94	1/1/94
300392725900	SAN JUAN 30-6(FC) 411S	RIO ARRIBA	NM	30	N	7	W	27	J	G	A705781	1542298000				
300392415300S01	SAN JUAN 30-6(FC) 412 JCV	RIO ARRIBA	NM	30	N	7	W	24	A	G	A705781	30274			1/1/94	1/1/94
300392775600	SAN JUAN 30-6(FC) 412S	RIO ARRIBA	NM	30	n	7	w	24	P	G	A705781	30274				
300392415900S01	SAN JUAN 30-6(FC) 413 JCV	RIO ARRIBA	NM	30	N	7	W	23	K	G	A705781	30274			1/1/94	1/1/94
300392439600S01	SAN JUAN 30-6(FC) 413RJC	RIO ARRIBA	NM	30	N	7	W	23	K	G	A705781	30274			1/1/94	1/1/94
300392768100	SAN JUAN 30-6(FC) 413S	RIO ARRIBA	NM	30	N	7	W	23	C	G	A705781	1542298000				
300392415400S01	SAN JUAN 30-6(FC) 414 JCV	RIO ARRIBA	NM	30	N	7	W	35	K	G	A705781	30274			1/1/94	1/1/94
300392730500	SAN JUAN 30-6(FC) 414S	RIO ARRIBA	NM	30	N	7	W	35	E	G	A705781	1542298000				
300392418800S01	SAN JUAN 30-6(FC) 415 JCV	RIO ARRIBA	NM	30	N	7	W	26	N	G	A705781	30274			1/1/94	1/1/94
300392773800	SAN JUAN 30-6(FC) 415S	RIO ARRIBA	NM	30	n	7	w	26	D	G	A705781	30274				
300392418300S01	SAN JUAN 30-6(FC) 416 JCV	RIO ARRIBA	NM	30	N	7	W	24	K	G	A705781	30274			1/1/94	1/1/94
30039296050000	SAN JUAN 30-6(FC) 416S	RIO ARRIBA	NM	30	N	7	W	24		G	A705781	30274				
300392418500S01	SAN JUAN 30-6(FC) 417 JCV	RIO ARRIBA	NM	30	N	7	W	25	H	G	A705781	30274			1/1/94	1/1/94
	SAN JUAN 30-6(FC) 417S	RIO ARRIBA	NM	30	N	7	W	25		G	A705781	30274				
300392418700S01	SAN JUAN 30-6(FC) 418 JCV	RIO ARRIBA	NM	30	N	7	W	26	B	G	A705781	30274			1/1/94	1/1/94
	SAN JUAN 30-6(FC) 418S	RIO ARRIBA	NM	28	n	6	w	28	C	G	A705781	30274				
300392417700S01	SAN JUAN 30-6(FC) 419 JCV	RIO ARRIBA	NM	30	N	7	W	11	H	G	A705781	30274			1/1/94	1/1/94
300392417800S01	SAN JUAN 30-6(FC) 420 JCV	RIO ARRIBA	NM	30	N	7	W	12	G	G	A705781	30274			1/1/94	1/1/94
300392422100S01	SAN JUAN 30-6(FC) 421 JCV	RIO ARRIBA	NM	30	N	7	W	34	G	G	A705781	30274			1/1/94	1/1/94
300392426100S01	SAN JUAN 30-6(FC) 422 JCV	RIO ARRIBA	NM	30	N	7	W	27	M	G	A705781	30274			1/1/94	10/3/90
300392730600	SAN JUAN 30-6(FC) 422S	RIO ARRIBA	NM	30	N	7	W	27	E	G	A705781	1542298000				
300392445900S01	SAN JUAN 30-6(FC) 423JCV	RIO ARRIBA	NM	30	N	7	W	28	A	G	A705781	30274			1/1/94	10/3/90
300392425000S01	SAN JUAN 30-6(FC) 424JCV	RIO ARRIBA	NM	30	N	7	W	33	K	G	A705781	30274			1/1/94	5/5/92
300392423800S01	SAN JUAN 30-6(FC) 425JCV	RIO ARRIBA	NM	30	N	7	W	33	H	G	A705781	30274			1/1/94	5/5/92
300392730700	SAN JUAN 30-6(FC) 425S	RIO ARRIBA	NM	30	N	7	W	33	I	G	A705781	1542298000				
300392424800S01	SAN JUAN 30-6(FC) 426 JCV	RIO ARRIBA	NM	30	N	7	W	34	K	G	A705781	30274			1/1/94	1/1/94
300392730400	SAN JUAN 30-6(FC) 426S	RIO ARRIBA	NM	30	N	7	W	34	F	G	A705781	1542298000				
300392426200S01	SAN JUAN 30-6(FC) 427 JCV	RIO ARRIBA	NM	30	N	7	W	35	H	G	A705781	30274			1/1/94	1/1/94
300392730000	SAN JUAN 30-6(FC) 427S	RIO ARRIBA	NM	30	n	7	w	35	O	G	A705781	30274				
300392438100S01	SAN JUAN 30-6(FC) 428JCV	RIO ARRIBA	NM	30	N	7	W	28	N	G	A705781	30274			1/1/94	5/7/92
300392429700S01	SAN JUAN 30-6(FC) 429JCV	RIO ARRIBA	NM	30	N	7	W	32	A	G	A705781	30274			1/1/94	5/7/92
300392422400S01	SAN JUAN 30-6(FC) 430 JCV	RIO ARRIBA	NM	30	N	6	W	8	G	G	A705781	30274			1/1/94	1/1/94
300392773500	SAN JUAN 30-6(FC) 430S	RIO ARRIBA	NM	30	N	6	W	8	I	G	A705781	30274				
300392422600S01	SAN JUAN 30-6(FC) 431 JCV	RIO ARRIBA	NM	30	N	6	W	10	M	G	A705781	30274			1/1/94	1/1/94
300392771300	SAN JUAN 30-6(FC) 431S	RIO ARRIBA	NM	30	N	6	W	10	F	G	A705781	30274				
300392422500	SAN JUAN 30-6(FC) 432 JCV	RIO ARRIBA	NM	30	N	6	W	10	B	G	A705781	30274			1/1/94	1/1/94
300392756600	SAN JUAN 30-6(FC) 432S	RIO ARRIBA	NM	30	N	6	W	10	I	G	A705781	1542298000				
300392424100S01	SAN JUAN 30-6(FC) 433 JCV	RIO ARRIBA	NM	30	N	6	W	11	L	G	A705781	30274			1/1/94	1/1/94
300392426000S01	SAN JUAN 30-6(FC) 434 JCV	RIO ARRIBA	NM	30	N	6	W	12	M	G	A705781	30274			1/1/94	1/1/94
300392761900	SAN JUAN 30-6(FC) 434S	RIO ARRIBA	NM	30	N	6	W	12	E	G	A705781	1542298000				
300392431900S01	SAN JUAN 30-6(FC) 435 JCV	RIO ARRIBA	NM	30	N	6	W	13	G	G	A705781	30274			1/1/94	1/1/94

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392779200	SAN JUAN 30-6(FC) 435S	RIO ARRIBA	NM	30	N	6	W 13	O	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392422700S01	SAN JUAN 30-6(FC) 436 JCV	RIO ARRIBA	NM	30	N	6	W 15	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392427500S01	SAN JUAN 30-6(FC) 437 JCV	RIO ARRIBA	NM	30	N	6	W 11	H	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392766400	SAN JUAN 30-6(FC) 437S	RIO ARRIBA	NM	30	N	7	W 11	J	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392430200S01	SAN JUAN 30-6(FC) 438 JCV	RIO ARRIBA	NM	30	N	6	W 12	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392775200	SAN JUAN 30-6(FC) 438S	RIO ARRIBA	NM	30	N	6	W 12	O	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392424200S01	SAN JUAN 30-6(FC) 439 JCV	RIO ARRIBA	NM	30	N	6	W 14	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392424300S01	SAN JUAN 30-6(FC) 440 JCV	RIO ARRIBA	NM	30	N	6	W 15	N	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392424700S01	SAN JUAN 30-6(FC) 441 JCV	RIO ARRIBA	NM	30	N	6	W 31	A	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392764300S01	SAN JUAN 30-6(FC) 441SDUP	RIO ARRIBA	NM	30	N	6	W 31	I	G	A705781	30274	BASIN CB::FRUITLAND COAL	99			
300392446000S01	SAN JUAN 30-6(FC) 442 JCV	RIO ARRIBA	NM	30	N	6	W 14	A	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	7/1/90
300392769300	SAN JUAN 30-6(FC) 442S	RIO ARRIBA	NM	30	N	6	W 14	J	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392431700S01	SAN JUAN 30-6(FC) 443 JCV	RIO ARRIBA	NM	30	N	6	W 36	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	10/1/90
300392728400	SAN JUAN 30-6(FC) 443S	RIO ARRIBA	NM	30	N	6	W 36	O	G	A705781	1542298000	BASIN CB::FRUITLAND COAL	11			
300392429600S01	SAN JUAN 30-6(FC) 444 JCV	RIO ARRIBA	NM	30	N	6	W 36	L	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	8/1/90
300392725800	SAN JUAN 30-6(FC) 444S	RIO ARRIBA	NM	30	N	6	W 36	C	G	A705781	1542298000	BASIN CB::FRUITLAND COAL	11			
300392433500S01	SAN JUAN 30-6(FC) 445 JCV	RIO ARRIBA	NM	30	N	6	W 13	L	G	A705781	30274	BASIN CB::FRUITLAND COAL	11	3/4/90	1/1/94	7/1/90
300392779300	SAN JUAN 30-6(FC) 445S	RIO ARRIBA	NM	30	N	6	W 13	C	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392459000S01	SAN JUAN 30-6(FC) 446 JCV	RIO ARRIBA	NM	30	N	6	W 35	N	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	7/28/90
300392774100	SAN JUAN 30-6(FC) 446S	RIO ARRIBA	NM	30	N	6	W 35	C	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392463400S01	SAN JUAN 30-6(FC) 447 JCV	RIO ARRIBA	NM	30	N	7	W 31	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	10/17/90
300392423300S01	SAN JUAN 30-6(FC) 450 JCV	RIO ARRIBA	NM	30	N	6	W 7	K	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392771100	SAN JUAN 30-6(FC) 450S	RIO ARRIBA	NM	30	N	6	W 7	F	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392423200S01	SAN JUAN 30-6(FC) 451 JCV	RIO ARRIBA	NM	30	N	6	W 7	H	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392765600	SAN JUAN 30-6(FC) 451S	RIO ARRIBA	NM	30	N	6	W 7	J	G	A705781	1542298000	BASIN CB::FRUITLAND COAL	11			
300392427400S01	SAN JUAN 30-6(FC) 452 JCV	RIO ARRIBA	NM	30	N	6	W 8	N	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392766600	SAN JUAN 30-6(FC) 452S	RIO ARRIBA	NM	30	N	6	W 8	E	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392425400S01	SAN JUAN 30-6(FC) 453 JCV	RIO ARRIBA	NM	30	N	6	W 17	K	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392423400S01	SAN JUAN 30-6(FC) 454 JCV	RIO ARRIBA	NM	30	N	6	W 17	A	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392424500S01	SAN JUAN 30-6(FC) 455 JCV	RIO ARRIBA	NM	30	N	6	W 18	N	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392424400S01	SAN JUAN 30-6(FC) 456 JCV	RIO ARRIBA	NM	30	N	6	W 18	A	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392423500S01	SAN JUAN 30-6(FC) 457 JCV	RIO ARRIBA	NM	30	N	6	W 19	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392769400	SAN JUAN 30-6(FC) 457S	RIO ARRIBA	NM	30	N	6	W 19	F	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392428800S01	SAN JUAN 30-6(FC) 458 JCV	RIO ARRIBA	NM	30	N	6	W 19	H	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392428900S01	SAN JUAN 30-6(FC) 459 JCV	RIO ARRIBA	NM	30	N	6	W 20	L	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392424900S01	SAN JUAN 30-6(FC) 460 JCV	RIO ARRIBA	NM	30	N	6	W 20	B	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392768400	SAN JUAN 30-6(FC) 460S	RIO ARRIBA	NM	30	N	6	W 20	J	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392437900S01	SAN JUAN 30-6(FC) 461 JCV	RIO ARRIBA	NM	30	N	7	W 11	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	12/19/89
300392773300	SAN JUAN 30-6(FC) 461S	RIO ARRIBA	NM	30	N	7	W 11	E	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392439500S01	SAN JUAN 30-6(FC) 462 JCV	RIO ARRIBA	NM	30	N	7	W 12	M	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392438000S01	SAN JUAN 30-6(FC) 463 JCV	RIO ARRIBA	NM	30	N	7	W 13	H	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392774000	SAN JUAN 30-6(FC) 463S	RIO ARRIBA	NM	30	N	7	W 13	I	G	A705781	30274	BASIN CB::FRUITLAND COAL	11			
300392423700S01	SAN JUAN 30-6(FC) 464 JCV	RIO ARRIBA	NM	30	N	7	W 14	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
	SAN JUAN 30-6(FC) 464S	RIO ARRIBA	NM	30	N	7	W 14		G	A705781	30274	BASIN CB::FRUITLAND COAL	99			
300392429200S01	SAN JUAN 30-6(FC) 465 JCV	RIO ARRIBA	NM	30	N	7	W 15	J	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300393020500S01	SAN JUAN 30-6(FC) 465S	RIO ARRIBA	NM	30	N	7	W 15		G	A705781	30274	BASIN CB::FRUITLAND COAL	41			
300392435000S01	SAN JUAN 30-6(FC) 466 JCV	RIO ARRIBA	NM	30	N	7	W 22	B	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392443800S01	SAN JUAN 30-6(FC) 468JCV	RIO ARRIBA	NM	30	N	7	W 36	K	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94
300392749500	SAN JUAN 30-6(FC) 468S	RIO ARRIBA	NM	30	N	7	W 36	D	G	A705781	1542298000	BASIN CB::FRUITLAND COAL	11			
300392447100S01	SAN JUAN 30-6(FC) 470 JCV	RIO ARRIBA	NM	30	N	6	W 21	G	G	A705781	30274	BASIN CB::FRUITLAND COAL	11		1/1/94	1/1/94

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392451200S01	SAN JUAN 30-6(FC) 471 JCV	RIO ARRIBA	NM	30	N	6	W	21	K	G	A705781	30274			1/1/94	5/1/90
300392756700	SAN JUAN 30-6(FC) 471S	RIO ARRIBA	NM	30	N	6	W	21	D	G	A705781	1542298000				
300392447700S01	SAN JUAN 30-6(FC) 472 JCV	RIO ARRIBA	NM	30	N	6	W	22	A	G	A705781	30274			1/1/94	1/1/94
300392447600S01	SAN JUAN 30-6(FC) 473 JCV	RIO ARRIBA	NM	30	N	6	W	22	M	G	A705781	30274			1/1/94	1/1/94
300392446400S01	SAN JUAN 30-6(FC) 474 JCV	RIO ARRIBA	NM	30	N	6	W	27	B	G	A705781	30274			1/1/94	1/1/94
300392448700S01	SAN JUAN 30-6(FC) 475 JCV	RIO ARRIBA	NM	30	N	6	W	27	L	G	A705781	30274			1/1/94	4/1/90
300392761800	SAN JUAN 30-6(FC) 475S	RIO ARRIBA	NM	30	N	6	W	27	D	G	A705781	30274				
300392446900S01	SAN JUAN 30-6(FC) 476 JCV	RIO ARRIBA	NM	30	N	6	W	28	A	G	A705781	30274			1/1/94	1/1/94
300392768500	SAN JUAN 30-6(FC) 476S	RIO ARRIBA	NM	30	N	6	W	28	J	G	A705781	30274				
300392449200S01	SAN JUAN 30-6(FC) 477 JCV	RIO ARRIBA	NM	30	N	6	W	28	M	G	A705781	30274			1/1/94	1/1/94
300392749700	SAN JUAN 30-6(FC) 477S	RIO ARRIBA	NM	30	N	6	W	28	F	G	A705781	1542298000				
300392447000S01	SAN JUAN 30-6(FC) 478 JCV	RIO ARRIBA	NM	30	N	6	W	29	A	G	A705781	30274			1/1/94	1/1/94
300392749400	SAN JUAN 30-6(FC) 478S	RIO ARRIBA	NM	30	N	6	W	29	O	G	A705781	1542298000				
300392460000S01	SAN JUAN 30-6(FC) 479 JCV	RIO ARRIBA	NM	30	N	6	W	29	K	G	A705781	30274			1/1/94	6/19/90
300392448800S01	SAN JUAN 30-6(FC) 480 JCV	RIO ARRIBA	NM	30	N	6	W	30	A	G	A705781	30274			1/1/94	1/1/94
300392446800S01	SAN JUAN 30-6(FC) 481 JCV	RIO ARRIBA	NM	30	N	6	W	30	K	G	A705781	30274			1/1/94	1/1/94
300392771200	SAN JUAN 30-6(FC) 481S	RIO ARRIBA	NM	30	N	6	W	30	C	G	A705781	30274				
300392461300S01	SAN JUAN 30-6(FC) 482 JCV	RIO ARRIBA	NM	30	N	6	W	31	N	G	A705781	30274			1/1/94	1/1/94
	SAN JUAN 30-6(FC) 482S	RIO ARRIBA	NM	30	N	6	W	31		G	A705781	30274				
300392447300S01	SAN JUAN 30-6(FC) 483 JCV	RIO ARRIBA	NM	30	N	6	W	34	H	G	A705781	30274			1/1/94	1/1/94
300392760700	SAN JUAN 30-6(FC) 483S	RIO ARRIBA	NM	30	N	6	W	34	P	G	A705781	1542298000				
300392447200S01	SAN JUAN 30-6(FC) 484 JCV	RIO ARRIBA	NM	30	N	6	W	34	N	G	A705781	30274			1/1/94	1/1/94
300392765300	SAN JUAN 30-6(FC) 484S	RIO ARRIBA	NM	30	N	6	W	34	D	G	A705781	30274				
300392481400S01	SAN JUAN 30-6(FC) 485 JCV	RIO ARRIBA	NM	30	N	7	W	36	G	G	A705781	30274			1/1/94	4/4/91
300392749800	SAN JUAN 30-6(FC) 485S	RIO ARRIBA	NM	30	N	7	W	36	J	G	A705781	1542298000				
300392498000S01	SAN JUAN 30-6(FC) 486 JCV	RIO ARRIBA	NM	30	N	6	W	23	H	G	A705781	30274			1/1/94	1/7/92
300392776000	SAN JUAN 30-6(FC) 486S	RIO ARRIBA	NM	30	N	6	W	33	O	G	A705781	30274				
300392502300S01	SAN JUAN 30-6(FC) 487 JCV	RIO ARRIBA	NM	30	N	6	W	23	N	G	A705781	30274			1/1/94	8/8/91
300392486700S01	SAN JUAN 30-6(FC) 488 JCV	RIO ARRIBA	NM	30	N	6	W	24	E	G	A705781	30274			1/1/94	1/8/92
300392775900	SAN JUAN 30-6(FC) 488S	RIO ARRIBA	NM	30	N	6	W	24	J	G	A705781	30274				
300392492600S01	SAN JUAN 30-6(FC) 489 JCV	RIO ARRIBA	NM	30	N	6	W	24	K	G	A705781	30274			1/1/94	8/15/91
300392775800	SAN JUAN 30-6(FC) 489S	RIO ARRIBA	NM	30	N	6	W	24	D	G	A705781	30274				
300392486800S01	SAN JUAN 30-6(FC) 490 JCV	RIO ARRIBA	NM	30	N	6	W	25	G	G	A705781	30274			1/1/94	7/17/91
300392771900	SAN JUAN 30-6(FC) 490S	RIO ARRIBA	NM	30	N	6	W	25	O	G	A705781	30274				
300392486900S01	SAN JUAN 30-6(FC) 491 JCV	RIO ARRIBA	NM	30	N	6	W	25	M	G	A705781	30274			1/1/94	7/17/91
300392773900	SAN JUAN 30-6(FC) 491S	RIO ARRIBA	NM	30	N	6	W	25	F	G	A705781	30274				
300392488900S01	SAN JUAN 30-6(FC) 492JCV	RIO ARRIBA	NM	30	N	6	W	26	K	G	A705781	30274			1/1/94	12/31/91
300392481500S01	SAN JUAN 30-6(FC) 493JCV	RIO ARRIBA	NM	30	N	6	W	32	M	G	A705781	30274			1/1/94	11/26/91
300392749600	SAN JUAN 30-6(FC) 493S	RIO ARRIBA	NM	30	N	6	W	32	D	G	A705781	1542298000				
300392483100S01	SAN JUAN 30-6(FC) 494JCV	RIO ARRIBA	NM	30	N	6	W	33	B	G	A705781	30274			1/1/94	4/29/91
300392957800	SAN JUAN 30-6(FC) 494S	RIO ARRIBA	NM	30	N	6	W	33		G	A705781	30274				
300392483200S01	SAN JUAN 30-6(FC) 495JCV	RIO ARRIBA	NM	30	N	6	W	33	K	G	A705781	30274			1/1/94	5/29/91
300392948900	SAN JUAN 30-6(FC) 495S	RIO ARRIBA	NM	30	N	6	W	33	C	G	A705781	30274				
300392487000S01	SAN JUAN 30-6(FC) 496 JCV	RIO ARRIBA	NM	30	N	6	W	35	G	G	A705781	30274			1/1/94	7/18/91
300392770800	SAN JUAN 30-6(FC) 496S	RIO ARRIBA	NM	30	N	6	W	35	J	G	A705781	30274				
300392496000S01	SAN JUAN 30-6(FC) 497 JCV	RIO ARRIBA	NM	30	N	7	W	29	M	G	A705781	30274			1/1/94	12/3/91
300392494800S01	SAN JUAN 30-6(FC) 499 JCV	RIO ARRIBA	NM	30	N	7	W	30	K	G	A705781	30274			1/1/94	8/28/91
300392481600S01	SAN JUAN 30-6(FC) 501JCV	RIO ARRIBA	NM	30	N	6	W	32	G	G	A705781	30274			1/1/94	11/20/91
300392760600	SAN JUAN 30-6(FC) 501S	RIO ARRIBA	NM	30	N	6	W	32	J	G	A705781	30274		2/1/04	4/23/04	
300392633400	SAN JUAN 30-6(FC)136 UNIT	RIO ARRIBA	NM	30	N	6	W	11	C	G	A705781	30274		11/3/04		

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TFMP ABANDON	PS - PERM SHUT-IN

SAN JUAN 30-6 UNIT
STATUS OF WELLS REPORT 02/08/13

API	WELL NAME	CTY	ST	TWN	RGE	SEC	UNIT LETTER	COMP TYPE	Lse ID	Oper ID	Rsvr Name	PROD STAT	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALE DATE
300392699900	SJ 30-6 1A DK 000001A	RIO ARRIBA	NM	30	N	6	W	9	O	G	A655396	30274				
300392699900	SJ 30-6 1A DK 000001A	RIO ARRIBA	NM	30	N	6	W	9	O	G	A655396	30274				
300392612400	SJ 30-6 UN 129 DK000129	RIO ARRIBA	NM	30	N	7	W	25	P	G	A655352	30274				
300392585000	SJ 30-6 UN 27A DK000027A	RIO ARRIBA	NM	30	N	6	W	23	O	G	A655331	30274				
300392585000	SJ 30-6 UN 27A DK000027A	RIO ARRIBA	NM	30	N	6	W	23	O	G	A655331	30274				
30039268700S01	SJ30-6 24B DK 000024B	RIO ARRIBA	NM						I	G	A655395	86645				
300392663500	SJ30-6U 114 114M 000114M	RIO ARRIBA	NM	30	N	6	W	11	K	G	A655337	30274				
300392663500	SJ30-6U 114 114M 000114M	RIO ARRIBA	NM	30	N	6	W	11	K	G	A655337	30274				

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN