



553

ConocoPhillips
San Juan Business Unit
Land Department
P.O. Box 4289
Farmington, NM 87499-4289

February 28, 2013

Burlington Resources Oil & Gas Co LP
"A subsidiary of ConocoPhillips Company"

Bureau of Land Management
Farmington Resource Area
6251 College Blvd, Ste A
Farmington, NM 87402

Oil Conservation Division
State of New Mexico
1220 S Saint Francis Dr
Santa Fe, NM 87505

**RE: 2013 Plan of Development
SAN JUAN 28-5 UNIT 14-08-001-949
RIO ARRIBA COUNTY, NEW MEXICO**

Ladies and Gentlemen:

The following Participating Areas currently exist in the SAN JUAN 28-5 UNIT:

FORMATION	EXPANSION	EFFECTIVE DATE
DAKOTA	021	01-OCT-99
FRUITLAND COAL	INITIAL	14-OCT-89
MESAVERDE	028	01-NOV-98
PICTURED CLIFFS	001	01-MAY-81

The **2012 Plan of Development** (or amendments thereto) provided for the following activity:

WELL NAME	FORMATION	TYPE	DEDICATION	STATUS
SAN JUAN 28-5 UNIT 16A	MESAVERDE	NEW DRILL - SINGLE	N2 016-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 37A	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	NSP 024-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 42P	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	S2 031-028N-005W	CARRYOVER
SAN JUAN 28-5 Unit 44C	MESAVERDE	NEW DRILL - SINGLE	S2 027-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 56N	MESAVERDE / DAKOTA / MANCOS	NEW DRILL - TRIMINGLE	S2 032-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 59N	MESAVERDE	NEW DRILL - SINGLE	N2 030-028N-005W	COMPLETED
SAN JUAN 28-5 UNIT 64N	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	N2 028-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 67P	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	S2 021-028N-005W	COMPLETED
SAN JUAN 28-5 UNIT 69N	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	MV-N2 033-028N-005W DK-E2 033-028N-005W	COMPLETED
SAN JUAN 28-5 UNIT 72P	MESAVERDE	NEW DRILL - SINGLE	S2 035-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 74N	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	MV-NSP 036-028N-005W DK-NSP 036-028N-005W	COMPLETED
SAN JUAN 28-5 UNIT 77P	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	N2 027-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 92N	MESAVERDE / DAKOTA / MANCOS	NEW DRILL - TRIMINGLE	MV-S2 024-028N-005W DK-W2 024-028N-005W MC-W2 024-028N-005W	CARRYOVER

SAN JUAN 28-5 UNIT
2013 PLAN OF DEVELOPMENT

SAN JUAN 28-5 UNIT 92P	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	MV-N2 024-028N-005W DK-W2 024-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 97C	MESAVERDE	NEW DRILL - SINGLE	S2 014-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 98C was San Juan 28-5 31N	MESAVERDE	NEW DRILL - SINGLE	S2 013-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 98N	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	NSP 024-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 103N	MESAVERDE	NEW DRILL - SINGLE	MV- N2 023-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 104B	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	MV-N2 025-028N-005W DK-NSP 025-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT 233H	FRUITLAND COAL	NEW DRILL - SINGLE	SW4 008-028N-005W	CARRYOVER
SAN JUAN 28-5 UNIT NP 219	FRUITLAND SAND	RECOMPLETION	NSP 030-028N-005W	CARRYOVER

Pursuant to Section 10 of the SAN JUAN 28-5 UNIT Agreement, Burlington Resources Oil & Gas Company LP, as Unit Operator, hereby submits the **2013 Plan of Development** as follows:

WELLNAME	FORMATION	TYPE	DEDICATION
SAN JUAN 28-5 UNIT 16A	MESAVERDE	NEW DRILL - SINGLE	N2 016-028N-005W
SAN JUAN 28-5 UNIT 37A	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	S2 024-028N-005W
SAN JUAN 28-5 UNIT 42P	MESAVERDE / DAKOTA	NEW DRILL— COMMINGLE	S2 031-028N-005W
SAN JUAN 28-5 Unit 44C	MESAVERDE	NEW DRILL— SINGLE	S2 027-028N-005W
SAN JUAN 28-5 UNIT 56N	MESAVERDE / DAKOTA / MANCOS	NEW DRILL - TRIMINGLE	S2 031-028N-005W
SAN JUAN 28-5 UNIT 64N	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	N2 028-028N-005W
SAN JUAN 28-5 UNIT 72P	MESAVERDE	NEW DRILL - SINGLE	S2 035-028N-005W
SAN JUAN 28-5 UNIT 77P	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	N2 027-028N-005W
SAN JUAN 28-5 UNIT 92N	MESAVERDE / DAKOTA / MANCOS	NEW DRILL - TRIMINGLE	MV-S2 024-028N-005W DK-W2 024-028N-005W MC-W2 024-028N-005W
SAN JUAN 28-5 UNIT 97C	MESAVERDE	NEW DRILL - SINGLE	S2 014-028N-005W
SAN JUAN 28-5 UNIT 98C Was San Juan 28-5 31N	MESAVERDE	NEW DRILL - SINGLE	S2 013-028N-005W
SAN JUAN 28-5 UNIT 98N	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	NSP 024-028N-005W
SAN JUAN 28-5 UNIT 103N	MESAVERDE	NEW DRILL - SINGLE	MV-N2 023-028N-005W
SAN JUAN 28-5 UNIT 104B	MESAVERDE / DAKOTA	NEW DRILL - COMMINGLE	MV-N2 025-028N-005W DK-NSP 025-028N-005W
SAN JUAN 28-5 UNIT NP 219	FRUITLAND SAND	RECOMPLETION	NE4 030-028N-005W

SAN JUAN 28-5 UNIT
2013 PLAN OF DEVELOPMENT

The working interest owners are being furnished a copy of this letter, well status listing and enclosed map. Burlington, as Unit Operator, will drill any offset wells required to prevent drainage of unitized substances and any other wells deemed necessary by the working interest owners or Unit Operator.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of the attached approval page to the undersigned.

Please contact me at (505) 324-6180 if there are any questions regarding this letter.

Sincerely,



Vanessa Thompson, RPL
Land Supervisor, SE


VT/ld
xc: San Juan 28-5 Unit, 3.0 (2013)
San Juan 28-5 Unit Working Interest Owners

SAN JUAN 28-5 UNIT
2013 PLAN OF DEVELOPMENT

SAN JUAN 28-5 UNIT
2013 PLAN OF DEVELOPMENT APPROVALS

Bureau of Land Management

Date



New Mexico Oil Conservation Division


3/5/2013
Date

SAN JUAN 28-5 UNIT
2013 PLAN OF DEVELOPMENT

WORKING INTEREST OWNERS SAN JUAN 28-5 UNIT

NAVATEX ENERGY LP
BARTON RESOURCES LLC
BP AMERICA PRODUCTION COMPANY
BURLINGTON RESOURCES O&G CO LP
CHARLES W GAY
CONOCOPHILLIPS COMPANY
DUGAN PRODUCTION CORP
J&M RAYMOND LTD
JABCO LLP
LANGDON D HARRISON REVOC TRUST B
LORRAYN GAY HACKER
MAR OIL & GAS CORPORATION
MCELVAIN OIL COMPANY
PROVIDENCE MINERALS LLC
RIO ARIBAGAS LTD
RIO ARriba LIMITED PARTNERSHIP
RUTH ZIMMERMAN TRUST
T H MCELVAIN OIL AND GAS PROP
TAMACAM LLC
THOMAS P TINNIN
TINMIL A NM LLC
VAUGHAN-MCELVAIN ENERGY INC
XTO ENERGY INC

R5W


$${}_{28}^{28}\text{N}$$

San Juan 28-5 Unit

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

API	WELL NAME	CTY	ST	TWN	RGE	SEC	Unit Letter	Lse ID	Oper ID	Rsvr Name	Production Status	COMP TYPE	COMP DATE	ABANDON DATE	INITIAL PROD DATE	FIRST SALES DATE
300392782301N01	SAN JUAN 28-5 31B NU DK	RIO ARRIBA	NM					A730265	216600	BASIN::DAKOTA	11	G				
300392782301N01	SAN JUAN 28-5 31B UT DK	RIO ARRIBA	NM					A728816	216600	BASIN::DAKOTA	11	G				
300392985300N02	SAN JUAN 28-5 31M NU DK	RIO ARRIBA	NM	28	N	5	W	12	O	A730265	216600	BASIN::DAKOTA	11	G	11/19/07	3/13/08 3/13/08
300392985300N01	SAN JUAN 28-5 31M UT DK	RIO ARRIBA	NM	28	N	5	W	12	O	A728816	216600	BASIN::DAKOTA	11	G	11/19/07	11/19/07
300392967600C01	SAN JUAN 28-5 34M MV	RIO ARRIBA	NM	28	N	5	W	18		A655170	30274	BLANCO::MESAVERDE	11	G	12/1/05	
3.00393E+11	SAN JUAN 28-5 35N MV	RIO ARRIBA	NM	28	N	5	W	19		A655170	30274	BLANCO::MESAVERDE	11	G		
3.00393E+11	SAN JUAN 28-5 58N MV	RIO ARRIBA	NM	28	N	5	W	30		A655170	30274	BLANCO::MESAVERDE	11	G		
300392959200C01	SAN JUAN 28-5 70P MV	RIO ARRIBA	NM	28	N	5	W	34		A655170	30274	BLANCO::MESAVERDE	11	G	12/1/05	
300392782200S01	SAN JUAN 28-5 81N MV	RIO ARRIBA	NM	28	N	5	W	25	M	A655170	30274	BLANCO::MESAVERDE	41	G	11/18/06	
3.00393E+11	SAN JUAN 28-5 81P MV	RIO ARRIBA	NM	28	N	5	W	26		A655170	30274	BLANCO::MESAVERDE	11	G		
300393081900C01	SAN JUAN 28-5 UNIT 73P DK	RIO ARRIBA	NM	28	N	5	W	35	J	A728816	216600	BASIN::DAKOTA	11	G	8/20/10	8/20/10 11/9/10
300393081900C02	SAN JUAN 28-5 UNIT 73P MV	RIO ARRIBA	NM	28	N	5	W	35	J	A710933	216600	BLANCO::MESAVERDE	11	G	8/20/10	8/20/10 11/9/10
300392010600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	27		A720764	216600	BASIN::DAKOTA	99	G	8/14/68	
300390732100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	28		A720764	216600	BASIN::DAKOTA	99	G	2/25/63	
300392023700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	7		A720764	216600	BASIN::DAKOTA	99	G	8/7/69	
300392018700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	26		A720764	216600	BASIN::DAKOTA	99	G	8/8/69	
300392627600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	28		A720764	216600	BASIN::DAKOTA	99	G	7/19/02	7/23/02 7/23/02
300390722800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	32		A720764	216600	BASIN::DAKOTA	99	G	10/9/62	
300392562100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	35		A720764	216600	BASIN::DAKOTA	99	G	11/7/97	
300392775400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	36		A720764	216600	BASIN::DAKOTA	99	G	10/5/04	
300392695600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	23		A720764	216600	BASIN::DAKOTA	99	G	2/18/03	2/21/03
300392010800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	17		A720764	216600	BASIN::DAKOTA	99	G	9/24/68	
300392955500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	26		A720764	216600	BASIN::DAKOTA	99	G	12/19/05	
300392757100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM							A720764	216600	BASIN::DAKOTA	99	G		
300392004100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	36		A720764	216600	BASIN::DAKOTA	99	G	8/2/67	
300392596900S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	25		A720764	216600	BASIN::DAKOTA	99	G	1/13/99	
300392024200S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	16		A720764	216600	BASIN::DAKOTA	99	G	9/2/69	
300392701900S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	17		A720764	216600	BASIN::DAKOTA	99	G	5/12/03	
300392381500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	21		A720764	216600	BASIN::DAKOTA	99	G	12/26/85	
300390729500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	29		A720764	216600	BASIN::DAKOTA	99	G	12/16/62	
300390728600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	30		A720764	216600	BASIN::DAKOTA	99	G	10/30/62	
300392047200S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	9		A720764	216600	BASIN::DAKOTA	99	G	7/19/72	
300392564600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	29		A720764	216600	BASIN::DAKOTA	99	G	5/28/97	
300392592700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	16		A720764	216600	BASIN::DAKOTA	99	G	4/7/99	
300392002600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	21		A720764	216600	BASIN::DAKOTA	99	G	6/21/67	
300392564500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	28		A720764	216600	BASIN::DAKOTA	99	G	7/20/97	
300392097100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	25		A720764	216600	BASIN::DAKOTA	99	G	11/22/77	
300392087600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	15		A720764	216600	BASIN::DAKOTA	99	G	12/11/74	
300392383700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	18		A720764	216600	BASIN::DAKOTA	99	G	10/23/85	
300392566500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	35		A720764	216600	BASIN::DAKOTA	99	G	7/24/97	
300392006400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	33		A720764	216600	BASIN::DAKOTA	99	G	9/28/67	
300392021700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	26		A720764	216600	BASIN::DAKOTA	99	G	7/2/69	
300392568100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W			A720764	216600	BASIN::DAKOTA	99	G	7/14/97	
300390735800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	20		A720764	216600	BASIN::DAKOTA	99	G	12/30/62	
300392383400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	8		A720764	216600	BASIN::DAKOTA	99	G	10/29/85	
300392592800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	13		A720764	216600	BASIN::DAKOTA	99	G	11/13/98	
300392383600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W			A720764	216600	BASIN::DAKOTA	99	G	11/14/85	
300392186400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	10		A720764	216600	BASIN::DAKOTA	99	G	11/20/79	
300390726100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	31		A720764	216600	BASIN::DAKOTA	99	G	1/1/63	
300392010500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	25		A720764	216600	BASIN::DAKOTA	99	G	8/14/68	
300390742700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	18		A720764	216600	BASIN::DAKOTA	99	G	12/12/62	
300392625400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	33		A720764	216600	BASIN::DAKOTA	99	G	7/20/00	

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
 41 - SHUT IN 72 - PERM ABANDON WELL
 59 - SOLD PA - PLUG ABANDON
 61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392957000S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	19		A720764	216600	BASIN::DAKOTA	99	G	1/6/06	1/13/06	1/13/06
300392379400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	21		A720764	216600	BASIN::DAKOTA	99	G	1/20/86		
300392385700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	9		A720764	216600	BASIN::DAKOTA	99	G	10/22/85		
300392664200S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	31		A720764	216600	BASIN::DAKOTA	99	G	5/15/02	5/16/02	5/16/02
300392559600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	19		A720764	216600	BASIN::DAKOTA	99	G	1/9/97		
300392023600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	22		A720764	216600	BASIN::DAKOTA	99	G	8/8/69		
300392757200S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	34		A720764	216600	BASIN::DAKOTA	99	G	1/14/05		
300392942000S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	26		A720764	216600	BASIN::DAKOTA	99	G	11/30/05		
300390729400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	27		A720764	216600	BASIN::DAKOTA	99	G	9/26/60		
300392595600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	14		A720764	216600	BASIN::DAKOTA	99	G	12/1/98		
300392383300S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	7		A720764	216600	BASIN::DAKOTA	99	G	11/14/85		
300392972600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	27		A720764	216600	BASIN::DAKOTA	99	G	8/2/06	8/25/06	8/25/06
300392035800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	8		A720764	216600	BASIN::DAKOTA	99	G	4/6/71		
300390724000S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	31		A720764	216600	BASIN::DAKOTA	99	G	7/11/60		
300392186600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	23		A720764	216600	BASIN::DAKOTA	99	G	10/17/79		
300392769600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM							A720764	216600	BASIN::DAKOTA	99	G	3/28/05	4/8/05	4/8/05
300392063500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	14		A720764	216600	BASIN::DAKOTA	99	G	10/5/73		
300392583100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	33		A720764	216600	BASIN::DAKOTA	99	G	6/22/98		
300392590800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	13		A720764	216600	BASIN::DAKOTA	99	G	7/8/99		
300392261300S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	19		A720764	216600	BASIN::DAKOTA	99	G	11/12/81		
300390727600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	32		A720764	216600	BASIN::DAKOTA	99	G	6/30/60		
300392010700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	21		A720764	216600	BASIN::DAKOTA	99	G	9/17/68		
300390740300S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	18		A720764	216600	BASIN::DAKOTA	99	G	7/23/59		
300392005600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	34		A720764	216600	BASIN::DAKOTA	99	G	9/7/67		
300392595700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	25	N	5	W	23		A720764	216600	BASIN::DAKOTA	99	G	7/1/99		
300392959200S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	34		A720764	216600	BASIN::DAKOTA	99	G	6/2/06	5/19/06	5/19/06
300392559700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	30		A720764	216600	BASIN::DAKOTA	99	G	1/22/97		
300392047100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	22		A720764	216600	BASIN::DAKOTA	99	G	7/10/72		
300392558900S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	28		A720764	216600	BASIN::DAKOTA	99	G	12/20/96		
300392943700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	30		A720764	216600	BASIN::DAKOTA	99	G	11/18/05	1/10/06	1/10/06
300392003600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	35		A720764	216600	BASIN::DAKOTA	99	G	8/17/67		
300392385500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	12		A720764	216600	BASIN::DAKOTA	99	G	10/21/85		
300392777000S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	7		A720764	216600	BASIN::DAKOTA	99	G	12/7/04		
300392566300S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	35		A720764	216600	BASIN::DAKOTA	99	G	7/14/97		
300398238100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	20		A720764	216600	BASIN::DAKOTA	99	G	11/13/62		
300392770400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	19		A720764	216600	BASIN::DAKOTA	99	G	2/7/05		
300392686700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	22		A720764	216600	BASIN::DAKOTA	99	G	2/27/03	3/8/03	3/8/03
300392562600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	32		A720764	216600	BASIN::DAKOTA	99	G	4/6/97		
300392630800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM							A720764	216600	BASIN::DAKOTA	99	G	6/26/02	7/3/02	7/3/02
300392003700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	34		A720764	216600	BASIN::DAKOTA	99	G	7/20/67		
300392564000S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	27		A720764	216600	BASIN::DAKOTA	99	G	4/28/03	5/7/03	5/7/03
300392036000S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	16		A720764	216600	BASIN::DAKOTA	99	G	4/23/71		
300392618100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	24		A720764	216600	BASIN::DAKOTA	99	G	8/28/99		
300392036400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	23		A720764	216600	BASIN::DAKOTA	99	G	5/20/71	9/13/71	9/13/71
300392006300S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	35		A720764	216600	BASIN::DAKOTA	99	G	9/14/67		
300392381300S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	20		A720764	216600	BASIN::DAKOTA	99	G	10/7/85		
300392180400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	13		A720764	216600	BASIN::DAKOTA	99	G	1/2/79		
300390735600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	19		A720764	216600	BASIN::DAKOTA	99	G	12/14/59		
300392384600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	14		A720764	216600	BASIN::DAKOTA	99	G	10/25/85		
300392047500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	15		A720764	216600	BASIN::DAKOTA	99	G	7/19/72		
300392769200S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	21		A720764	216600	BASIN::DAKOTA	99	G	8/30/04		
300392565500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	34		A720764	216600	BASIN::DAKOTA	99	G	7/29/97		
300392186500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	11		A720764	216600	BASIN::DAKOTA	99	G	10/15/79		
300390734100S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	29		A720764	216600	BASIN::DAKOTA	99	G	12/8/62		

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PFRM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392563900S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	15		A720764	216600	BASIN::DAKOTA	99	G	7/23/97		
300390730900S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	28		A720764	216600	BASIN::DAKOTA	99	G	12/29/62		
300392384700S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	18		A720764	216600	BASIN::DAKOTA	99	G	10/16/85		
300392381400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	20		A720764	216600	BASIN::DAKOTA	99	G	10/2/85		
300392261600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	30		A720764	216600	BASIN::DAKOTA	99	G	10/18/81		
300392385600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	15		A720764	216600	BASIN::DAKOTA	99	G	12/9/85		
300392625500S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	32		A720764	216600	BASIN::DAKOTA	99	G	10/1/00		
300392563000S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	31		A720764	216600	BASIN::DAKOTA	99	G	4/15/97		
300392625300S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	34		A720764	216600	BASIN::DAKOTA	99	G	9/9/00		
300392593600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	27		A720764	216600	BASIN::DAKOTA	99	G	3/17/99		
300392981900S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	33		A720764	216600	BASIN::DAKOTA	99	G	11/7/06	11/9/06	11/9/06
300392386400S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	11		A720764	216600	BASIN::DAKOTA	99	G	11/7/85		
300392967600S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	18		A720764	216600	BASIN::DAKOTA	99	G	5/10/06	5/16/06	5/16/06
300392002800S01	SAN JUAN 28-5 UNIT SPORR	RIO ARRIBA	NM	28	N	5	W	35		A720764	216600	BASIN::DAKOTA	99	G	6/21/67		
300392385600C01	SAN JUAN 28-5 UT 88M DK	RIO ARRIBA	NM	28	N	5	W	15	E	A728816	216600	BASIN::DAKOTA	11	G	12/9/85	2/10/86	2/10/86
300390733000S01	SAN JUAN 28-5 UT 1 MV	RIO ARRIBA	NM	28	N	5	W	29	G	A710933	216600	BLANCO::MESAVERDE	11	G	9/21/53	10/29/55	10/29/55
300390733000S01	SAN JUAN 28-5 UT 1 MV	RIO ARRIBA	NM	28	N	5	W	29	G	A710933	216600	BLANCO::MESAVERDE	11	G	9/21/53	10/29/55	10/29/55
300390741700S01	SAN JUAN 28-5 UT 10 MV	RIO ARRIBA	NM	28	N	5	W	15	K	A710933	216600	BLANCO::MESAVERDE	11	G	1/16/56	5/16/56	5/16/56
300392180400S01	SAN JUAN 28-5 UT 101 DK	RIO ARRIBA	NM	28	N	5	W	13	K	A728816	216600	BASIN::DAKOTA	11	G	1/2/79	5/1/79	5/1/79
300392590800C01	SAN JUAN 28-5 UT 101M DK	RIO ARRIBA	NM	28	N	5	W	13	D	A728816	216600	BASIN::DAKOTA	11	G	7/8/99	7/29/99	7/29/99
300392590800C02	SAN JUAN 28-5 UT 101M MV	RIO ARRIBA	NM	28	N	5	W	13	D	A710933	216600	BLANCO::MESAVERDE	11	G	7/8/99	7/29/99	7/29/99
300393064100C01	SAN JUAN 28-5 UT 101P DK	RIO ARRIBA	NM	28	N	5	W	14	H	A728816	216600	BASIN::DAKOTA	11	G	8/10/10	9/24/10	9/24/10
300393064100C02	SAN JUAN 28-5 UT 101P MV	RIO ARRIBA	NM	28	N	5	W	14	H	A710933	216600	BLANCO::MESAVERDE	11	G	8/10/10	9/24/10	9/24/10
300392186500C01	SAN JUAN 28-5 UT 102 DK	RIO ARRIBA	NM	28	N	5	W	11	P	A728816	216600	BASIN::DAKOTA	11	G	10/15/79	6/1/80	6/1/80
300392186500C02	SAN JUAN 28-5 UT 102 MV	RIO ARRIBA	NM	28	N	5	W	11	P	A710933	216600	BLANCO::MESAVERDE	11	G	11/3/05	11/4/05	11/4/05
300392385500C01	SAN JUAN 28-5 UT 102E DK	RIO ARRIBA	NM	28	N	5	W	12	O	A728816	216600	BASIN::DAKOTA	11	G	10/21/85	11/6/85	1/10/08
300392385500C02	SAN JUAN 28-5 UT 102E MV	RIO ARRIBA	NM	28	N	5	W	12	O	A710933	216600	BLANCO::MESAVERDE	11	G	7/20/99	7/29/99	1/10/08
300392985501C01	SAN JUAN 28-5 UT 102N DK	RIO ARRIBA	NM	28	N	5	W	12	O	A728816	216600	BASIN::DAKOTA	11	G	10/29/07	10/25/07	1/17/08
300392985501C02	SAN JUAN 28-5 UT 102N MV	RIO ARRIBA	NM	28	N	5	W	12	O	A710933	216600	BLANCO::MESAVERDE	11	G	10/29/07	10/25/07	1/17/08
300392186600S01	SAN JUAN 28-5 UT 103 DK	RIO ARRIBA	NM	28	N	5	W	23	H	A728816	216600	BASIN::DAKOTA	72	G	10/17/79	11/15/10	12/5/79
300392595700C01	SAN JUAN 28-5 UT 103M DK	RIO ARRIBA	NM	28	N	5	W	23	O	A728816	216600	BASIN::DAKOTA	11	G	7/1/99	7/15/99	7/15/99
300392595700C02	SAN JUAN 28-5 UT 103M MV	RIO ARRIBA	NM	28	N	5	W	23	O	A710933	216600	BLANCO::MESAVERDE	11	G	7/1/99	7/15/99	7/15/99
300392593100S01	SAN JUAN 28-5 UT 107 MV	RIO ARRIBA	NM	28	N	5	W	12	M	A710933	216600	BLANCO::MESAVERDE	11	G	10/5/98	11/4/98	11/4/98
300390724300S01	SAN JUAN 28-5 UT 11 MV	RIO ARRIBA	NM	28	N	5	W	33	K	A710933	216600	BLANCO::MESAVERDE	11	G	3/28/57	11/12/57	11/12/57
300390724300S01	SAN JUAN 28-5 UT 11 MV	RIO ARRIBA	NM	28	N	5	W	33	K	A710933	216600	BLANCO::MESAVERDE	11	G	3/28/57	11/12/57	11/12/57
300392218700S01	SAN JUAN 28-5 UT 11A MV	RIO ARRIBA	NM	28	N	5	W	33	I	A710933	216600	BLANCO::MESAVERDE	11	G	2/5/81	12/30/81	12/30/81
300392218700S01	SAN JUAN 28-5 UT 11A MV	RIO ARRIBA	NM	28	N	5	W	33	I	A710933	216600	BLANCO::MESAVERDE	11	G	2/5/81	12/30/81	12/30/81
300390746100S01	SAN JUAN 28-5 UT 12 MV	RIO ARRIBA	NM	28	N	5	W	7	L	A710933	216600	BLANCO::MESAVERDE	11	G	7/18/56	3/15/57	3/15/57
300390746100S01	SAN JUAN 28-5 UT 12 MV	RIO ARRIBA	NM	28	N	5	W	7	L	A710933	216600	BLANCO::MESAVERDE	11	G	7/18/56	3/15/57	3/15/57
300392186300S01	SAN JUAN 28-5 UT 12A MV	RIO ARRIBA	NM	28	N	5	W	7	J	A710933	216600	BLANCO::MESAVERDE	11	G	9/18/79	11/12/79	11/12/79
300390745700S01	SAN JUAN 28-5 UT 13 MV	RIO ARRIBA	NM	28	N	5	W	9	M	A710933	216600	BLANCO::MESAVERDE	11	G	9/1/56	3/14/57	3/14/57
300390738000S01	SAN JUAN 28-5 UT 14 MV	RIO ARRIBA	NM	28	N	5	W	20	H	A710933	216600	BLANCO::MESAVERDE	11	G	8/9/56	3/14/57	3/14/57
300392220500S01	SAN JUAN 28-5 UT 14A MV	RIO ARRIBA	NM	28	N	5	W	20	E	A710933	216600	BLANCO::MESAVERDE	11	G	2/23/81	4/1/81	4/1/81
300390723100S01	SAN JUAN 28-5 UT 15 MV	RIO ARRIBA	NM	28	N	5	W	34	M	A710933	216600	BLANCO::MESAVERDE	11	G	6/23/56	11/12/57	11/12/57
300390723100S01	SAN JUAN 28-5 UT 15 MV	RIO ARRIBA	NM	28	N	5	W	34	M	A710933	216600	BLANCO::MESAVERDE	11	G	6/23/56	11/12/57	11/12/57
300392218800S01	SAN JUAN 28-5 UT 15A MV	RIO ARRIBA	NM	28	N	5	W	34	O	A710933	216600	BLANCO::MESAVERDE	11	G	2/26/81	12/31/81	12/31/81
300392218800S01	SAN JUAN 28-5 UT 15A MV	RIO ARRIBA	NM	28	N	5	W	34	O	A710933	216600	BLANCO::MESAVERDE	11	G	2/26/81	12/31/81	12/31/81
300390743900S01	SAN JUAN 28-5 UT 16 MV	RIO ARRIBA	NM	28	N	5	W	16	A	A710933	216600	BLANCO::MESAVERDE	11	G	10/8/57	1/24/58	1/24/58
300390736400S01	SAN JUAN 28-5 UT 17 MV	RIO ARRIBA	NM	28	N	5	W	20	K	A710933	216600	BLANCO::MESAVERDE	11	G	6/5/57	6/29/57	6/29/57
300392223100S01	SAN JUAN 28-5 UT 17A MV	RIO ARRIBA	NM	28	N	5	W	20	P	A710933	216600	BLANCO::MESAVERDE	11	G	3/10/81	4/24/81	4/24/81
300390744500S01	SAN JUAN 28-5 UT 18 MV	RIO ARRIBA	NM	28	N	5	W	11	M	A710933	216600	BLANCO::MESAVERDE	11	G	7/24/57	12/1/57	12/1/57
300392386500S01	SAN JUAN 28-5 UT 18A MV	RIO ARRIBA	NM	28	N	5	W	11	O	A710933	216600	BLANCO::MESAVERDE	11	G	10/23/85	11/4/85	11/4/85
300390746600S01	SAN JUAN 28-5 UT 19 MV	RIO ARRIBA	NM	28	N	5	W	10	L	A710933	216600	BLANCO::MESAVERDE	11	G	11/5/57	1/28/58	1/28/58
300392383500S01	SAN JUAN 28-5 UT 19A MV	RIO ARRIBA	NM	28	N	5	W	10	O	A710933	216600	BLANCO::MESAVERDE	11	G	10/23/85	11/14/85	11/14/85

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300390740600S01	SAN JUAN 28-5 UT 2 MV	RIO ARRIBA	NM	28	N	5	W	14	M	A710933	216600	BLANCO::MESAVERDE	11	G	2/20/54	12/8/54	12/8/54
300390731000S01	SAN JUAN 28-5 UT 20 MV	RIO ARRIBA	NM	28	N	5	W	30	L	A710933	216600	BLANCO::MESAVERDE	11	G	5/9/57	6/28/57	6/28/57
300390731000S01	SAN JUAN 28-5 UT 20 MV	RIO ARRIBA	NM	28	N	5	W	30	L	A710933	216600	BLANCO::MESAVERDE	11	G	5/9/57	6/28/57	6/28/57
300392680700S01	SAN JUAN 28-5 UT 2015 FC	RIO ARRIBA	NM	28	N	5	W	15	F	A723386	216600	BASIN CB::FRUITLAND COAL	11	G	2/19/02	2/25/02	2/25/02
300392451700S01	SAN JUAN 28-5 UT 202 FC	RIO ARRIBA	NM	28	N	5	W	16	H	A728819	216600	BASIN CB::FRUITLAND COAL	11	G	10/14/89	12/28/89	12/28/89
300390723900S01	SAN JUAN 28-5 UT 21 MV	RIO ARRIBA	NM	28	N	5	W	35	L	A710933	216600	BLANCO::MESAVERDE	11	G	4/13/57	7/1/57	7/1/57
300390723900S01	SAN JUAN 28-5 UT 21 MV	RIO ARRIBA	NM	28	N	5	W	35	L	A710933	216600	BLANCO::MESAVERDE	11	G	4/13/57	7/1/57	7/1/57
300390736000S01	SAN JUAN 28-5 UT 22 MV	RIO ARRIBA	NM	28	N	5	W	21	M	A710933	216600	BLANCO::MESAVERDE	11	G	4/13/57	10/21/57	10/21/57
300390733100S01	SAN JUAN 28-5 UT 23 MV	RIO ARRIBA	NM	28	N	5	W	28	H	A710933	216600	BLANCO::MESAVERDE	11	G	7/5/57	8/1/57	8/1/57
300390733100S01	SAN JUAN 28-5 UT 23 MV	RIO ARRIBA	NM	28	N	5	W	28	H	A710933	216600	BLANCO::MESAVERDE	11	G	7/5/57	8/1/57	8/1/57
300392663900S01	SAN JUAN 28-5 UT 23B MV	RIO ARRIBA	NM	28	N	5	W	28	G	A710933	216600	BLANCO::MESAVERDE	11	G	6/14/01	6/23/01	6/23/01
300392663900S01	SAN JUAN 28-5 UT 23B MV	RIO ARRIBA	NM	28	N	5	W	28	G	A710933	216600	BLANCO::MESAVERDE	11	G	6/14/01	6/23/01	6/23/01
300390727700S01	SAN JUAN 28-5 UT 24 MV	RIO ARRIBA	NM	28	N	5	W	34	A	A710933	216600	BLANCO::MESAVERDE	11	G	3/27/57	7/9/57	7/9/57
300390727700S01	SAN JUAN 28-5 UT 24 MV	RIO ARRIBA	NM	28	N	5	W	34	A	A710933	216600	BLANCO::MESAVERDE	11	G	3/27/57	7/9/57	7/9/57
300392552300S01	SAN JUAN 28-5 UT 245 FC	RIO ARRIBA	NM	28	N	5	W	22	B	A723403	216600	BASIN CB::FRUITLAND COAL	11	G	10/25/95	2/6/96	2/6/96
300390741800S01	SAN JUAN 28-5 UT 25 MV	RIO ARRIBA	NM	28	N	5	W	13	K	A710933	216600	BLANCO::MESAVERDE	11	G	9/10/57	11/21/57	11/21/57
300390743000S01	SAN JUAN 28-5 UT 26 MV	RIO ARRIBA	NM	28	N	5	W	14	H	A710933	216600	BLANCO::MESAVERDE	11	G	7/21/58	11/11/58	11/15/58
300390744200S01	SAN JUAN 28-5 UT 27 MV	RIO ARRIBA	NM	28	N	5	W	15	B	A710933	216600	BLANCO::MESAVERDE	11	G	2/19/58	6/3/58	6/3/58
300390742800S01	SAN JUAN 28-5 UT 28 MV	RIO ARRIBA	NM	28	N	5	W	17	H	A710933	216600	BLANCO::MESAVERDE	11	G	2/17/58	6/2/58	6/2/58
300392377300S01	SAN JUAN 28-5 UT 28A MV	RIO ARRIBA	NM	28	N	5	W	17	D	A710933	216600	BLANCO::MESAVERDE	11	G	9/13/85	11/1/85	11/1/85
300390743600S01	SAN JUAN 28-5 UT 29 MV	RIO ARRIBA	NM	28	N	5	W	18	B	A710933	216600	BLANCO::MESAVERDE	11	G	3/8/58	5/29/58	5/29/58
300392222900C01	SAN JUAN 28-5 UT 29A MV	RIO ARRIBA	NM	28	N	5	W	18	D	A710933	216600	BLANCO::MESAVERDE	11	G	2/3/81	4/7/81	4/7/81
300392222900C02	SAN JUAN 28-5 UT 29A PC	RIO ARRIBA	NM	28	N	5	W	18	D	A721125	216600	TAPACITO::PICTURED CLIFFS	11	G	2/18/81	4/28/81	4/28/81
300393060800S01	SAN JUAN 28-5 UT 2C MV	RIO ARRIBA	NM	28	N	5	W	14	H	A710933	216600	BLANCO::MESAVERDE	11	G	8/11/10	10/7/10	10/7/10
300390729801S01	SAN JUAN 28-5 UT 3 MV	RIO ARRIBA	NM	28	N	5	W	26	M	A710933	216600	BLANCO::MESAVERDE	11	G	1/1/54	5/14/56	5/14/56
300390729801S01	SAN JUAN 28-5 UT 3 MV	RIO ARRIBA	NM	28	N	5	W	26	M	A710933	216600	BLANCO::MESAVERDE	11	G	1/1/54	5/14/56	5/14/56
300390739600S01	SAN JUAN 28-5 UT 30 MV	RIO ARRIBA	NM	28	N	5	W	22	B	A710933	216600	BLANCO::MESAVERDE	11	G	8/1/58	11/11/58	11/11/58
300392372900S01	SAN JUAN 28-5 UT 30A MV	RIO ARRIBA	NM	28	N	5	W	22	D	A710933	216600	BLANCO::MESAVERDE	11	G	10/3/85	11/6/85	11/6/85
300390743200S01	SAN JUAN 28-5 UT 31 MV	RIO ARRIBA	NM	28	N	5	W	13	G	A710933	216600	BLANCO::MESAVERDE	11	G	8/22/58	11/24/58	11/24/58
300392782301C01	SAN JUAN 28-5 UT 31B DK	RIO ARRIBA	NM	28	N	5	W	12	O	A728816	216600	BASIN::DAKOTA	11	G	11/12/07	2/14/08	2/14/08
300392782301C02	SAN JUAN 28-5 UT 31B MV	RIO ARRIBA	NM	28	N	5	W	12	O	A710933	216600	BLANCO::MESAVERDE	11	G	11/12/07		2/14/08
300392985300C01	SAN JUAN 28-5 UT 31M DK	RIO ARRIBA	NM	28	N	5	W	12	O	A728816	216600	BASIN::DAKOTA	11	G	11/19/07	11/19/07	3/13/08
300392985300C02	SAN JUAN 28-5 UT 31M MV	RIO ARRIBA	NM	28	N	5	W	12	O	A710933	216600	BLANCO::MESAVERDE	11	G	11/19/07	11/19/07	3/13/08
300390732500S01	SAN JUAN 28-5 UT 32 MV	RIO ARRIBA	NM	28	N	5	W	30	G	A710933	216600	BLANCO::MESAVERDE	11	G	10/22/58	1/3/59	1/3/59
300390732500S01	SAN JUAN 28-5 UT 32 MV	RIO ARRIBA	NM	28	N	5	W	30	G	A710933	216600	BLANCO::MESAVERDE	11	G	10/22/58	1/3/59	1/3/59
300390741300S02	SAN JUAN 28-5 UT 33 MV	RIO ARRIBA	NM	28	N	5	W	17	L	A710933	216600	BLANCO::MESAVERDE	11	G	6/8/59	9/26/59	9/26/59
300392381200S01	SAN JUAN 28-5 UT 33A MV	RIO ARRIBA	NM	28	N	5	W	17	J	A710933	216600	BLANCO::MESAVERDE	11	G	10/3/85	5/26/87	5/26/87
300392702000C01	SAN JUAN 28-5 UT 33M DK	RIO ARRIBA	NM	28	N	5	W	17	P	A728816	216600	BASIN::DAKOTA	11	G	3/7/03	3/20/03	3/20/03
300392702000C02	SAN JUAN 28-5 UT 33M MV	RIO ARRIBA	NM	28	N	5	W	17	P	A710933	216600	BLANCO::MESAVERDE	11	G	3/7/03	3/20/03	3/20/03
300390740300C01	SAN JUAN 28-5 UT 34 DK	RIO ARRIBA	NM	28	N	5	W	18	M	A728816	216600	BASIN::DAKOTA	11	G	7/23/59	9/30/59	9/30/59
300390740300C02	SAN JUAN 28-5 UT 34 MV	RIO ARRIBA	NM	28	N	5	W	18	M	A710933	216600	BLANCO::MESAVERDE	11	G	7/23/59	9/24/59	9/24/59
300390740300C02	SAN JUAN 28-5 UT 34 MV	RIO ARRIBA	NM	28	N	5	W	18	M	A710933	216600	BLANCO::MESAVERDE	11	G	7/23/59	9/24/59	9/24/59
300392223000S01	SAN JUAN 28-5 UT 34A MV	RIO ARRIBA	NM	28	N	5	W	18	O	A710933	216600	BLANCO::MESAVERDE	11	G	1/27/81	10/28/81	10/28/81
300392223000S01	SAN JUAN 28-5 UT 34A MV	RIO ARRIBA	NM	28	N	5	W	18	O	A710933	216600	BLANCO::MESAVERDE	11	G	1/27/81	10/28/81	10/28/81
300392384700S01	SAN JUAN 28-5 UT 34E DK	RIO ARRIBA	NM	28	N	5	W	18	O	A728816	216600	BASIN::DAKOTA	11	G	10/16/85	11/7/85	11/7/85
300392967600C01	SAN JUAN 28-5 UT 34M DK	RIO ARRIBA	NM	28	N	5	W	18	P	A728816	216600	BASIN::DAKOTA	11	G	5/10/06	5/16/06	5/16/06
300392967600C02	SAN JUAN 28-5 UT 34M MV	RIO ARRIBA	NM	28	N	5	W	18	P	A710933	216600	BLANCO::MESAVERDE	11	G	5/10/06	5/16/06	5/16/06
300392967600C02	SAN JUAN 28-5 UT 34M MV	RIO ARRIBA	NM	28	N	5	W	18	P	A710933	216600	BLANCO::MESAVERDE	11	G	5/10/06	5/16/06	5/16/06
300390735600C01	SAN JUAN 28-5 UT 35 DK	RIO ARRIBA	NM	28	N	5	W	19	M	A728816	216600	BASIN::DAKOTA	11	G	12/14/59	4/21/60	4/21/60
300390735600C02	SAN JUAN 28-5 UT 35 MV	RIO ARRIBA	NM	28	N	5	W	19	M	A710933	216600	BLANCO::MESAVERDE	11	G	12/14/59	6/6/60	6/6/60
300390735600C02	SAN JUAN 28-5 UT 35 MV	RIO ARRIBA	NM	28	N	5	W	19	M	A710933	216600	BLANCO::MESAVERDE	11	G	12/14/59	6/6/60	6/6/60
300392559600C01	SAN JUAN 28-5 UT 35M DK	RIO ARRIBA	NM	28	N	5	W	19	J	A728816	216600	BASIN::DAKOTA	11	G	1/9/97	3/6/97	3/6/97
300392559600C02	SAN JUAN 28-5 UT 35M MV	RIO ARRIBA	NM	28	N	5	W	19	J	A710933	216600	BLANCO::MESAVERDE	11	G	1/9/97	3/6/97	3/6/97
300392559600C02	SAN JUAN 28-5 UT 35M MV	RIO ARRIBA	NM	28	N	5	W	19	J	A710933	216600	BLANCO::MESAVERDE	11	G	1/9/97	3/6/97	3/6/97

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - PERM ABANDON 85 - PERM SHUT IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392957000C01	SAN JUAN 28-5 UT 35N DK	RIO ARRIBA	NM	28	N	5	W	19	P	A728816	216600	BASIN::DAKOTA	11	G	1/6/06	1/13/06	1/13/06
300392957000C02	SAN JUAN 28-5 UT 35N MV	RIO ARRIBA	NM	28	N	5	W	19	P	A710933	216600	BLANCO::MESAVERDE	11	G	1/6/06	1/13/06	1/13/06
300392957000C02	SAN JUAN 28-5 UT 35N MV	RIO ARRIBA	NM	28	N	5	W	19	P	A710933	216600	BLANCO::MESAVERDE	11	G	1/6/06	1/13/06	1/13/06
300396007400S01	SAN JUAN 28-5 UT 36 MV	RIO ARRIBA	NM	28	N	5	W	26	G	A710933	216600	BLANCO::MESAVERDE	11	G	4/25/59	7/25/59	7/25/59
300390736800S01	SAN JUAN 28-5 UT 37 MV	RIO ARRIBA	NM	28	N	5	W	24	L	A710933	216600	BLANCO::MESAVERDE	11	G	5/21/59	7/25/59	7/25/59
300390722900S01	SAN JUAN 28-5 UT 38 MV	RIO ARRIBA	NM	28	N	5	W	32	M	A710933	216600	BLANCO::MESAVERDE	11	G	4/15/59	7/16/59	7/16/59
300390722900S01	SAN JUAN 28-5 UT 38 MV	RIO ARRIBA	NM	28	N	5	W	32	M	A710933	216600	BLANCO::MESAVERDE	11	G	4/15/59	7/16/59	7/16/59
300392223300D01	SAN JUAN 28-5 UT 38A MV	RIO ARRIBA	NM	28	N	5	W	32	O	A710933	216600	BLANCO::MESAVERDE	11	G	2/11/81	7/6/81	7/6/81
300392223300D01	SAN JUAN 28-5 UT 38A MV	RIO ARRIBA	NM	28	N	5	W	32	O	A710933	216600	BLANCO::MESAVERDE	11	G	2/11/81	7/6/81	7/6/81
300392223300D02	SAN JUAN 28-5 UT 38A PC	RIO ARRIBA	NM	28	N	5	W	32	O	A721126	216600	TAPACITO::PICTURED CLIFFS	11	G	2/11/81	7/6/81	7/6/81
300392223300D02	SAN JUAN 28-5 UT 38A PC	RIO ARRIBA	NM	28	N	5	W	32	O	A721126	216600	TAPACITO::PICTURED CLIFFS	11	G	2/11/81	7/6/81	7/6/81
300390739700S01	SAN JUAN 28-5 UT 39 MV	RIO ARRIBA	NM	28	N	5	W	24	A	A710933	216600	BLANCO::MESAVERDE	11	G	7/30/60	9/21/60	9/21/60
300398238200S01	SAN JUAN 28-5 UT 40 MV	RIO ARRIBA	NM	28	N	5	W	27	B	A710933	216600	BLANCO::MESAVERDE	11	G	5/30/60	7/29/60	7/29/60
300398238200S01	SAN JUAN 28-5 UT 40 MV	RIO ARRIBA	NM	28	N	5	W	27	B	A710933	216600	BLANCO::MESAVERDE	11	G	5/30/60	7/29/60	7/29/60
300390727600C01	SAN JUAN 28-5 UT 41 DK	RIO ARRIBA	NM	28	N	5	W	32	A	A728816	216600	BASIN::DAKOTA	11	G	6/30/60	9/16/60	9/16/60
300390727600C02	SAN JUAN 28-5 UT 41 MV	RIO ARRIBA	NM	28	N	5	W	32	A	A710933	216600	BLANCO::MESAVERDE	11	G	6/30/60	9/8/60	9/8/60
300390727600C02	SAN JUAN 28-5 UT 41 MV	RIO ARRIBA	NM	28	N	5	W	32	A	A710933	216600	BLANCO::MESAVERDE	11	G	6/30/60	9/8/60	9/8/60
300392562600C01	SAN JUAN 28-5 UT 41M DK	RIO ARRIBA	NM	28	N	5	W	32	D	A728816	216600	BASIN::DAKOTA	11	G	4/6/97	7/30/97	7/30/97
300392562600C02	SAN JUAN 28-5 UT 41M MV	RIO ARRIBA	NM	28	N	5	W	32	D	A710933	216600	BLANCO::MESAVERDE	11	G	4/6/97	4/16/97	4/16/97
300392562600C02	SAN JUAN 28-5 UT 41M MV	RIO ARRIBA	NM	28	N	5	W	32	D	A710933	216600	BLANCO::MESAVERDE	11	G	4/6/97	4/16/97	4/16/97
300392766500C01	SAN JUAN 28-5 UT 41N DK	RIO ARRIBA	NM	28	N	5	W	32	F	A728816	216600	BASIN::DAKOTA	11	G	8/2/04	8/20/04	8/20/04
300392766500C02	SAN JUAN 28-5 UT 41N MV	RIO ARRIBA	NM	28	N	5	W	32	F	A710933	216600	BLANCO::MESAVERDE	11	G	8/2/04	8/20/04	8/20/04
300392766500C02	SAN JUAN 28-5 UT 41N MV	RIO ARRIBA	NM	28	N	5	W	32	F	A710933	216600	BLANCO::MESAVERDE	11	G	8/2/04	8/20/04	8/20/04
300390724000C01	SAN JUAN 28-5 UT 42 DK	RIO ARRIBA	NM	28	N	5	W	31	K	A728816	216600	BASIN::DAKOTA	11	G	7/11/60	10/14/60	10/14/60
300390724000C02	SAN JUAN 28-5 UT 42 MV	RIO ARRIBA	NM	28	N	5	W	31	K	A710933	216600	BLANCO::MESAVERDE	11	G	7/11/60	10/4/60	10/4/60
300390724000C02	SAN JUAN 28-5 UT 42 MV	RIO ARRIBA	NM	28	N	5	W	31	K	A710933	216600	BLANCO::MESAVERDE	11	G	7/11/60	10/4/60	10/4/60
300392563000C01	SAN JUAN 28-5 UT 42M DK	RIO ARRIBA	NM	28	N	5	W	31	I	A728816	216600	BASIN::DAKOTA	11	G	4/15/97	4/21/97	4/21/97
300392563000C02	SAN JUAN 28-5 UT 42M MV	RIO ARRIBA	NM	28	N	5	W	31	I	A710933	216600	BLANCO::MESAVERDE	11	G	4/15/97	4/21/97	4/21/97
300392563000C02	SAN JUAN 28-5 UT 42M MV	RIO ARRIBA	NM	28	N	5	W	31	I	A710933	216600	BLANCO::MESAVERDE	11	G	4/15/97	4/21/97	4/21/97
300392770500C01	SAN JUAN 28-5 UT 42N DK	RIO ARRIBA	NM	28	N	5	W	31	J	A728816	216600	BASIN::DAKOTA	11	G	6/25/07	6/22/07	7/12/07
300392770500C02	SAN JUAN 28-5 UT 42N MV	RIO ARRIBA	NM	28	N	5	W	31	J	A710933	216600	BLANCO::MESAVERDE	11	G	6/25/07	6/10/07	6/12/07
300390730600S01	SAN JUAN 28-5 UT 43 MV	RIO ARRIBA	NM	28	N	5	W	25	N	A710933	216600	BLANCO::MESAVERDE	11	G	5/21/61	9/6/61	9/6/61
300390730600S01	SAN JUAN 28-5 UT 43 MV	RIO ARRIBA	NM	28	N	5	W	25	N	A710933	216600	BLANCO::MESAVERDE	11	G	5/21/61	9/6/61	9/6/61
300390729400C01	SAN JUAN 28-5 UT 44 DK	RIO ARRIBA	NM	28	N	5	W	27	M	A728816	216600	BASIN::DAKOTA	11	G	9/26/60	12/4/60	12/4/60
300390729400C02	SAN JUAN 28-5 UT 44 MV	RIO ARRIBA	NM	28	N	5	W	27	M	A710933	216600	BLANCO::MESAVERDE	11	G	9/26/60	12/4/60	12/4/60
300390729400C02	SAN JUAN 28-5 UT 44 MV	RIO ARRIBA	NM	28	N	5	W	27	M	A710933	216600	BLANCO::MESAVERDE	11	G	9/26/60	12/4/60	12/4/60
300392564001C01	SAN JUAN 28-5 UT 44M DK	RIO ARRIBA	NM	28	N	5	W	27	I	A728816	216600	BASIN::DAKOTA	11	G	4/28/03	5/7/03	5/7/03
300392564001C02	SAN JUAN 28-5 UT 44M MV	RIO ARRIBA	NM	28	N	5	W	27	I	A710933	216600	BLANCO::MESAVERDE	11	G	7/8/97	7/8/97	7/8/97
300392564001C02	SAN JUAN 28-5 UT 44M MV	RIO ARRIBA	NM	28	N	5	W	27	I	A710933	216600	BLANCO::MESAVERDE	11	G	7/8/97	7/8/97	7/8/97
300392972600C01	SAN JUAN 28-5 UT 44N DK	RIO ARRIBA	NM	28	N	5	W	27	O	A728816	216600	BASIN::DAKOTA	11	G	8/2/06	8/25/06	8/25/06
300392972600C02	SAN JUAN 28-5 UT 44N MV	RIO ARRIBA	NM	28	N	5	W	27	O	A710933	216600	BLANCO::MESAVERDE	11	G	8/2/06	8/25/06	8/25/06
300392972600C02	SAN JUAN 28-5 UT 44N MV	RIO ARRIBA	NM	28	N	5	W	27	O	A710933	216600	BLANCO::MESAVERDE	11	G	8/2/06	8/25/06	8/25/06
300392006300S01	SAN JUAN 28-5 UT 45 DK	RIO ARRIBA	NM	28	N	5	W	35	G	A728816	216600	BASIN::DAKOTA	11	G	9/14/67	11/2/67	11/2/67
300392566500C01	SAN JUAN 28-5 UT 45M DK	RIO ARRIBA	NM	28	N	5	W	36	E	A728816	216600	BASIN::DAKOTA	11	G	7/24/97	7/30/97	7/30/97
300392566500C02	SAN JUAN 28-5 UT 45M MV	RIO ARRIBA	NM	28	N	5	W	36	E	A710933	216600	BLANCO::MESAVERDE	11	G	7/5/97	7/16/97	7/16/97
300392566500C02	SAN JUAN 28-5 UT 45M MV	RIO ARRIBA	NM	28	N	5	W	36	E	A710933	216600	BLANCO::MESAVERDE	11	G	7/5/97	7/16/97	7/16/97
300392775400C01	SAN JUAN 28-5 UT 45N DK	RIO ARRIBA	NM	28	N	5	W	36	C	A728816	216600	BASIN::DAKOTA	11	G	10/5/04	10/19/04	10/19/04
300392775400C02	SAN JUAN 28-5 UT 45N MV	RIO ARRIBA	NM	28	N	5	W	36	C	A710933	216600	BLANCO::MESAVERDE	11	G	10/5/04	10/19/04	10/19/04
300392775400C02	SAN JUAN 28-5 UT 45N MV	RIO ARRIBA	NM	28	N	5	W	36	C	A710933	216600	BLANCO::MESAVERDE	11	G	10/5/04	10/19/04	10/19/04
300390734200S01	SAN JUAN 28-5 UT 46 MV	RIO ARRIBA	NM	28	N	5	W	25	G	A710933	216600	BLANCO::MESAVERDE	11	G	11/29/60	3/9/61	3/9/61
300390734200S01	SAN JUAN 28-5 UT 46 MV	RIO ARRIBA	NM	28	N	5	W	25	G	A710933	216600	BLANCO::MESAVERDE	11	G	11/29/60	3/9/61	3/9/61
300390728000S01	SAN JUAN 28-5 UT 47 MV	RIO ARRIBA	NM	28	N	5	W	36	B	A710933	216600	BLANCO::MESAVERDE	11	G	11/21/60	3/17/61	3/17/61
300390728000S01	SAN JUAN 28-5 UT 47 MV	RIO ARRIBA	NM	28	N	5	W	36	B	A710933	216600	BLANCO::MESAVERDE	11	G	11/21/60	3/17/61	3/17/61
300390736101S01	SAN JUAN 28-5 UT 48 MV	RIO ARRIBA	NM	28	N	5	W	22	M	A710933	216600	BLANCO::MESAVERDE	11	G	7/19/61	10/30/61	10/31/61

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392379500S01	SAN JUAN 28-5 UT 48A MV	RIO ARRIBA	NM	28	N	5	W	22	J	A710933	216600	BLANCO::MESAVERDE	11	G	10/3/85	11/11/85	11/11/85
300390738600S01	SAN JUAN 28-5 UT 49 MV	RIO ARRIBA	NM	28	N	5	W	23	H	A710933	216600	BLANCO::MESAVERDE	11	G	9/4/61	12/15/61	12/15/61
300392051100S01	SAN JUAN 28-5 UT 4R MV	RIO ARRIBA	NM	28	N	5	W	19	G	A710933	216600	BLANCO::MESAVERDE	11	G	10/30/72	1/9/73	1/9/73
300392051100S01	SAN JUAN 28-5 UT 4R MV	RIO ARRIBA	NM	28	N	5	W	19	G	A710933	216600	BLANCO::MESAVERDE	11	G	10/30/72	1/9/73	1/9/73
300390729700S01	SAN JUAN 28-5 UT 50 MV	RIO ARRIBA	NM	28	N	5	W	28	M	A710933	216600	BLANCO::MESAVERDE	11	G	5/3/61	8/15/61	8/15/61
300390729700S01	SAN JUAN 28-5 UT 50 MV	RIO ARRIBA	NM	28	N	5	W	28	M	A710933	216600	BLANCO::MESAVERDE	11	G	5/3/61	8/15/61	8/15/61
300390725700S01	SAN JUAN 28-5 UT 51 MV	RIO ARRIBA	NM	28	N	5	W	31	H	A710933	216600	BLANCO::MESAVERDE	11	G	8/15/61	11/21/61	11/21/61
300390725700S01	SAN JUAN 28-5 UT 51 MV	RIO ARRIBA	NM	28	N	5	W	31	H	A710933	216600	BLANCO::MESAVERDE	11	G	8/15/61	11/21/61	11/21/61
300392223200C01	SAN JUAN 28-5 UT 51A MV	RIO ARRIBA	NM	28	N	5	W	31	C	A710933	216600	BLANCO::MESAVERDE	11	G	4/16/81	9/18/81	9/18/81
300392223200C01	SAN JUAN 28-5 UT 51A MV	RIO ARRIBA	NM	28	N	5	W	31	C	A710933	216600	BLANCO::MESAVERDE	11	G	4/16/81	9/18/81	9/18/81
300392223200C02	SAN JUAN 28-5 UT 51A PC	RIO ARRIBA	NM	28	N	5	W	31	C	A728818	216600	TAPACITO::PICTURED CLIFFS	11	G	4/16/81	9/18/81	9/18/81
300392586900S01	SAN JUAN 28-5 UT 52R MV	RIO ARRIBA	NM	28	N	5	W	33	B	A710933	216600	BLANCO::MESAVERDE	11	G	8/28/98	10/6/98	10/6/98
300392586900S01	SAN JUAN 28-5 UT 52R MV	RIO ARRIBA	NM	28	N	5	W	33	B	A710933	216600	BLANCO::MESAVERDE	11	G	8/28/98	10/6/98	10/6/98
300390725900S01	SAN JUAN 28-5 UT 53 MV	RIO ARRIBA	NM	28	N	5	W	35	G	A710933	216600	BLANCO::MESAVERDE	11	G	5/26/61	8/22/61	8/22/61
300390725900S01	SAN JUAN 28-5 UT 53 MV	RIO ARRIBA	NM	28	N	5	W	35	G	A710933	216600	BLANCO::MESAVERDE	11	G	5/26/61	8/22/61	8/22/61
300390735800C01	SAN JUAN 28-5 UT 54 DK	RIO ARRIBA	NM	28	N	5	W	20	M	A728816	216600	BASIN::DAKOTA	11	G	12/30/62	4/1/63	4/1/63
300390735800C02	SAN JUAN 28-5 UT 54 MV	RIO ARRIBA	NM	28	N	5	W	20	M	A710933	216600	BLANCO::MESAVERDE	11	G	1/30/11	2/26/11	2/26/11
300392381300C01	SAN JUAN 28-5 UT 54E DK	RIO ARRIBA	NM	28	N	5	W	20	C	A728816	216600	BASIN::DAKOTA	11	G	10/7/85	10/31/85	10/31/85
300392381300C02	SAN JUAN 28-5 UT 54E GL	RIO ARRIBA	NM	28	N	5	W	20	C	A725808	216600	MUNOZ CANYON::GALLUP	11	G	5/12/98	5/22/98	5/22/98
300392381300C02	SAN JUAN 28-5 UT 54E GL	RIO ARRIBA	NM	28	N	5	W	20	C	A725808	216600	MUNOZ CANYON::GALLUP	11	G	5/12/98	5/22/98	5/22/98
300393041600C01	SAN JUAN 28-5 UT 54F DK	RIO ARRIBA	NM	28	N	5	W	20	F	A728816	216600	BASIN::DAKOTA	11	G	5/14/08	5/28/08	5/28/08
300393041600C02	SAN JUAN 28-5 UT 54F MV	RIO ARRIBA	NM	28	N	5	W	20	F	A710933	216600	BLANCO::MESAVERDE	11	G	5/14/08	5/28/08	5/28/08
300390736900S01	SAN JUAN 28-5 UT 55 MV	RIO ARRIBA	NM	28	N	5	W	23	L	A710933	216600	BLANCO::MESAVERDE	11	G	8/18/62	12/14/62	12/14/62
300390722800S01	SAN JUAN 28-5 UT 56 DK	RIO ARRIBA	NM	28	N	5	W	32	N	A728816	216600	BASIN::DAKOTA	11	G	10/9/62	2/14/63	2/14/63
300392625500C01	SAN JUAN 28-5 UT 56M DK	RIO ARRIBA	NM	28	N	5	W	32	I	A728816	216600	BASIN::DAKOTA	11	G	10/1/00	11/10/00	11/10/00
300392625500C02	SAN JUAN 28-5 UT 56M MV	RIO ARRIBA	NM	28	N	5	W	32	I	A710933	216600	BLANCO::MESAVERDE	11	G	10/1/00	11/10/00	11/10/00
300392625500C02	SAN JUAN 28-5 UT 56M MV	RIO ARRIBA	NM	28	N	5	W	32	I	A710933	216600	BLANCO::MESAVERDE	11	G	10/1/00	11/10/00	11/10/00
300392261300C01	SAN JUAN 28-5 UT 57M DK	RIO ARRIBA	NM	28	N	5	W	19	F	A728816	216600	BASIN::DAKOTA	11	G	11/12/81	7/1/82	7/1/82
300392261300C02	SAN JUAN 28-5 UT 57M MV	RIO ARRIBA	NM	28	N	5	W	19	F	A710933	216600	BLANCO::MESAVERDE	11	G	11/12/81	6/1/82	6/1/82
300392261300C02	SAN JUAN 28-5 UT 57M MV	RIO ARRIBA	NM	28	N	5	W	19	F	A710933	216600	BLANCO::MESAVERDE	11	G	11/12/81	6/1/82	6/1/82
300392770400C01	SAN JUAN 28-5 UT 57N DK	RIO ARRIBA	NM	28	N	5	W	19	H	A728816	216600	BASIN::DAKOTA	11	G	2/7/05	2/16/05	2/16/05
300392770400C02	SAN JUAN 28-5 UT 57N MV	RIO ARRIBA	NM	28	N	5	W	19	H	A710933	216600	BLANCO::MESAVERDE	11	G	2/7/05	2/16/05	2/16/05
300392770400C02	SAN JUAN 28-5 UT 57N MV	RIO ARRIBA	NM	28	N	5	W	19	H	A710933	216600	BLANCO::MESAVERDE	11	G	2/7/05	2/16/05	2/16/05
300393040400C01	SAN JUAN 28-5 UT 57P DK	RIO ARRIBA	NM	28	N	5	W	19	D	A728816	216600	BASIN::DAKOTA	11	G	4/21/08	4/21/08	10/1/08
300393040400C02	SAN JUAN 28-5 UT 57P MV	RIO ARRIBA	NM	28	N	5	W	19	D	A710933	216600	BLANCO::MESAVERDE	11	G	4/21/08	4/21/08	10/1/08
300390728600C01	SAN JUAN 28-5 UT 58 DK	RIO ARRIBA	NM	28	N	5	W	30	M	A728816	216600	BASIN::DAKOTA	11	G	10/30/62	2/15/63	2/15/63
300390728600C02	SAN JUAN 28-5 UT 58 MV	RIO ARRIBA	NM	28	N	5	W	30	M	A710933	216600	BLANCO::MESAVERDE	11	G	9/12/05	9/14/05	9/14/05
300390728600C02	SAN JUAN 28-5 UT 58 MV	RIO ARRIBA	NM	28	N	5	W	30	M	A710933	216600	BLANCO::MESAVERDE	11	G	9/12/05	9/14/05	9/14/05
300392559700C01	SAN JUAN 28-5 UT 58M DK	RIO ARRIBA	NM	28	N	5	W	30	I	A728816	216600	BASIN::DAKOTA	11	G	1/22/97	3/3/97	3/3/97
300392559700C02	SAN JUAN 28-5 UT 58M MV	RIO ARRIBA	NM	28	N	5	W	30	I	A710933	216600	BLANCO::MESAVERDE	11	G	1/22/97	3/3/97	3/3/97
300392559700C02	SAN JUAN 28-5 UT 58M MV	RIO ARRIBA	NM	28	N	5	W	30	I	A710933	216600	BLANCO::MESAVERDE	11	G	1/22/97	3/3/97	3/3/97
300392943700C01	SAN JUAN 28-5 UT 58N DK	RIO ARRIBA	NM	28	N	5	W	30	O	A728816	216600	BASIN::DAKOTA	11	G	11/18/05	1/10/06	1/10/06
300392943700C02	SAN JUAN 28-5 UT 58N MV	RIO ARRIBA	NM	28	N	5	W	30	O	A710933	216600	BLANCO::MESAVERDE	11	G	11/18/05	1/10/06	1/10/06
300392943700C02	SAN JUAN 28-5 UT 58N MV	RIO ARRIBA	NM	28	N	5	W	30	O	A710933	216600	BLANCO::MESAVERDE	11	G	11/18/05	1/10/06	1/10/06
300398238300S01	SAN JUAN 28-5 UT 59 DK	RIO ARRIBA	NM	28	N	5	W	30	G	A728816	216600	BASIN::DAKOTA	11	G	11/8/62	2/19/63	2/19/63
300392261600C01	SAN JUAN 28-5 UT 59M DK	RIO ARRIBA	NM	28	N	5	W	30	C	A728816	216600	BASIN::DAKOTA	11	G	10/18/81	1/21/82	1/21/82
300392261600C02	SAN JUAN 28-5 UT 59M MV	RIO ARRIBA	NM	28	N	5	W	30	C	A710933	216600	BLANCO::MESAVERDE	11	G	5/11/81	1/21/82	1/21/82
300392261600C02	SAN JUAN 28-5 UT 59M MV	RIO ARRIBA	NM	28	N	5	W	30	C	A710933	216600	BLANCO::MESAVERDE	11	G	5/11/81	1/21/82	1/21/82
300393063400S01	SAN JUAN 28-5 UT 59N MV	RIO ARRIBA	NM	28	N	5	W	30	C	A710933	216600	BLANCO::MESAVERDE	11	G	7/10/12	7/10/12	7/10/12
300390741601S01	SAN JUAN 28-5 UT 6 MV	RIO ARRIBA	NM	28	N	5	W	16	K	A710933	216600	BLANCO::MESAVERDE	11	G	12/3/54	12/20/54	12/20/54
300390734100C01	SAN JUAN 28-5 UT 60 DK	RIO ARRIBA	NM	28	N	5	W	29	A	A728816	216600	BASIN::DAKOTA	11	G	12/8/62	3/28/63	3/28/63
300390734100C02	SAN JUAN 28-5 UT 60 MV	RIO ARRIBA	NM	28	N	5	W	29	A	A710933	216600	BLANCO::MESAVERDE	11	G	9/29/05	10/7/05	10/7/05
300390734100C02	SAN JUAN 28-5 UT 60 MV	RIO ARRIBA	NM	28	N	5	W	29	A	A710933	216600	BLANCO::MESAVERDE	11	G	9/29/05	10/7/05	10/7/05
300392564600C01	SAN JUAN 28-5 UT 60M DK	RIO ARRIBA	NM	28	N	5	W	29	E	A728816	216600	BASIN::DAKOTA	11	G	5/28/97	6/6/97	6/6/97

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392564600C02	SAN JUAN 28-5 UT 60M MV	RIO ARRIBA	NM	28	N	5	W	29	E	A710933	216600	BLANCO::MESAVERDE	11	G	5/28/97	6/6/97	6/6/97
300392564600C02	SAN JUAN 28-5 UT 60M MV	RIO ARRIBA	NM	28	N	5	W	29	E	A710933	216600	BLANCO::MESAVERDE	11	G	5/28/97	6/6/97	6/6/97
300390742700C01	SAN JUAN 28-5 UT 61 DK	RIO ARRIBA	NM	28	N	5	W	18	H	A728816	216600	BASIN::DAKOTA	11	G	12/12/62	4/2/63	4/2/63
300390742700C02	SAN JUAN 28-5 UT 61 MV	RIO ARRIBA	NM	28	N	5	W	18	H	A710933	216600	BLANCO::MESAVERDE	11	G	5/3/00	5/11/00	5/11/00
300392383700C01	SAN JUAN 28-5 UT 61E DK	RIO ARRIBA	NM	28	N	5	W	18	E	A728816	216600	BASIN::DAKOTA	11	G	10/23/85	11/6/85	11/6/85
300392383700C02	SAN JUAN 28-5 UT 61E GL	RIO ARRIBA	NM	28	N	5	W	18	E	A725807	216600	MUNOZ CANYON::GALLUP	11	G	5/18/98	6/1/98	6/1/98
300392986200C01	SAN JUAN 28-5 UT 61M DK	RIO ARRIBA	NM	28	N	5	W	18	F	A728816	216600	BASIN::DAKOTA	11	G	1/7/08	1/23/08	1/23/08
300392986200C02	SAN JUAN 28-5 UT 61M MV	RIO ARRIBA	NM	28	N	5	W	18	F	A710933	216600	BLANCO::MESAVERDE	11	G	1/7/08	1/23/08	1/23/08
300390726100C01	SAN JUAN 28-5 UT 62 DK	RIO ARRIBA	NM	28	N	5	W	31	G	A728816	216600	BASIN::DAKOTA	11	G	1/1/63	4/8/63	4/8/63
300390726100C02	SAN JUAN 28-5 UT 62 MV	RIO ARRIBA	NM	28	N	5	W	31	G	A710933	216600	BLANCO::MESAVERDE	11	G	5/26/00	6/8/00	6/8/00
300390726100C02	SAN JUAN 28-5 UT 62 MV	RIO ARRIBA	NM	28	N	5	W	31	G	A710933	216600	BLANCO::MESAVERDE	11	G	5/26/00	6/8/00	6/8/00
300393015400S01	SAN JUAN 28-5 UT 62E DK	RIO ARRIBA	NM	28	N	5	W	31	A	A728816	216600	BASIN::DAKOTA	11	G	5/17/08	8/19/08	8/19/08
300392664200C01	SAN JUAN 28-5 UT 62M DK	RIO ARRIBA	NM	28	N	5	W	31	E	A728816	216600	BASIN::DAKOTA	11	G	5/15/02	5/16/02	5/16/02
300392664200C02	SAN JUAN 28-5 UT 62M MV	RIO ARRIBA	NM	28	N	5	W	31	E	A710933	216600	BLANCO::MESAVERDE	11	G	5/15/02	5/16/02	5/16/02
300392664200C02	SAN JUAN 28-5 UT 62M MV	RIO ARRIBA	NM	28	N	5	W	31	E	A710933	216600	BLANCO::MESAVERDE	11	G	5/15/02	5/16/02	5/16/02
300398238100C01	SAN JUAN 28-5 UT 63 DK	RIO ARRIBA	NM	28	N	5	W	20	B	A728816	216600	BASIN::DAKOTA	11	G	11/13/62	3/27/63	3/27/63
300398238100C02	SAN JUAN 28-5 UT 63 MV	RIO ARRIBA	NM	28	N	5	W	20	B	A710933	216600	BLANCO::MESAVERDE	11	G	10/25/05	10/26/05	10/26/05
300392381400C01	SAN JUAN 28-5 UT 63E DK	RIO ARRIBA	NM	28	N	5	W	20	J	A728816	216600	BASIN::DAKOTA	11	G	10/2/85	11/13/85	11/13/85
300392381400C02	SAN JUAN 28-5 UT 63E GL	RIO ARRIBA	NM	28	N	5	W	20	J	A725810	216600	MUNOZ CANYON::GALLUP	11	G	2/8/00	2/16/00	2/16/00
300393043300C01	SAN JUAN 28-5 UT 63M DK	RIO ARRIBA	NM	28	N	5	W	20	O	A728816	216600	BASIN::DAKOTA	11	G	5/6/08	5/20/08	5/20/08
300393043300C02	SAN JUAN 28-5 UT 63M MV	RIO ARRIBA	NM	28	N	5	W	20	O	A710933	216600	BLANCO::MESAVERDE	11	G	5/6/08	5/20/08	5/20/08
300390732100S01	SAN JUAN 28-5 UT 64 DK	RIO ARRIBA	NM	28	N	5	W	28	H	A728816	216600	BASIN::DAKOTA	11	G	2/25/63	4/10/63	4/10/63
300392558900C01	SAN JUAN 28-5 UT 64M DK	RIO ARRIBA	NM	28	N	5	W	28	D	A728816	216600	BASIN::DAKOTA	11	G	12/20/96	1/15/97	1/15/97
300392558900C02	SAN JUAN 28-5 UT 64M MV	RIO ARRIBA	NM	28	N	5	W	28	D	A710933	216600	BLANCO::MESAVERDE	11	G	12/21/96	1/15/97	1/15/97
300392558900C02	SAN JUAN 28-5 UT 64M MV	RIO ARRIBA	NM	28	N	5	W	28	D	A710933	216600	BLANCO::MESAVERDE	11	G	12/21/96	1/15/97	1/15/97
300390730900S01	SAN JUAN 28-5 UT 65 DK	RIO ARRIBA	NM	28	N	5	W	28	K	A728816	216600	BASIN::DAKOTA	11	G	12/29/62	4/3/63	4/3/63
300392564500C01	SAN JUAN 28-5 UT 65M DK	RIO ARRIBA	NM	28	N	5	W	28	O	A728816	216600	BASIN::DAKOTA	11	G	7/20/97	7/29/97	7/29/97
300392564500C02	SAN JUAN 28-5 UT 65M MV	RIO ARRIBA	NM	28	N	5	W	28	O	A710933	216600	BLANCO::MESAVERDE	11	G	7/20/97	7/29/97	7/29/97
300392564500C02	SAN JUAN 28-5 UT 65M MV	RIO ARRIBA	NM	28	N	5	W	28	O	A710933	216600	BLANCO::MESAVERDE	11	G	7/20/97	7/29/97	7/29/97
300392627600C01	SAN JUAN 28-5 UT 65N DK	RIO ARRIBA	NM	28	N	5	W	28	I	A728816	216600	BASIN::DAKOTA	11	G	7/19/02	7/23/02	7/23/02
300392627600C02	SAN JUAN 28-5 UT 65N MV	RIO ARRIBA	NM	28	N	5	W	28	I	A710933	216600	BLANCO::MESAVERDE	11	G	7/19/02	7/23/02	7/23/02
300392627600C02	SAN JUAN 28-5 UT 65N MV	RIO ARRIBA	NM	28	N	5	W	28	I	A710933	216600	BLANCO::MESAVERDE	11	G	7/19/02	7/23/02	7/23/02
300390729500S01	SAN JUAN 28-5 UT 66 DK	RIO ARRIBA	NM	28	N	5	W	29	N	A728816	216600	BASIN::DAKOTA	11	G	12/16/62	3/28/63	3/28/63
300392568100C02	SAN JUAN 28-5 UT 66M DK	RIO ARRIBA	NM	28	N	5	W	29	I	A728816	216600	BASIN::DAKOTA	11	G	7/14/97	7/30/97	7/30/97
300392568100C01	SAN JUAN 28-5 UT 66M MV	RIO ARRIBA	NM	28	N	5	W	29	I	A710933	216600	BLANCO::MESAVERDE	11	G	7/14/97	7/30/97	7/30/97
300392568100C01	SAN JUAN 28-5 UT 66M MV	RIO ARRIBA	NM	28	N	5	W	29	I	A710933	216600	BLANCO::MESAVERDE	11	G	7/14/97	7/30/97	7/30/97
300392379400C01	SAN JUAN 28-5 UT 67M DK	RIO ARRIBA	NM	28	N	5	W	21	O	A728816	216600	BASIN::DAKOTA	11	G	1/20/86	2/17/86	2/17/86
300392379400C02	SAN JUAN 28-5 UT 67M MV	RIO ARRIBA	NM	28	N	5	W	21	O	A710933	216600	BLANCO::MESAVERDE	11	G	1/27/86	5/27/87	5/27/87
300392769200C01	SAN JUAN 28-5 UT 67N DK	RIO ARRIBA	NM	28	N	5	W	21	K	A728816	216600	BASIN::DAKOTA	11	G	8/30/04	9/7/04	9/7/04
300392769200C02	SAN JUAN 28-5 UT 67N MV	RIO ARRIBA	NM	28	N	5	W	21	K	A710933	216600	BLANCO::MESAVERDE	11	G	8/30/04	9/7/04	9/7/04
300393108100C01	SAN JUAN 28-5 UT 67P DK	RIO ARRIBA	NM	28	N	5	W	21	I	A728816	216600	BASIN::DAKOTA	11	G	9/27/12	9/28/12	9/28/12
300393108100C02	SAN JUAN 28-5 UT 67P MV	RIO ARRIBA	NM	28	N	5	W	21	I	A710933	216600	BLANCO::MESAVERDE	11	G	9/27/12	9/28/12	9/28/12
300392006400S01	SAN JUAN 28-5 UT 68 DK	RIO ARRIBA	NM	28	N	5	W	33	M	A728816	216600	BASIN::DAKOTA	11	G	9/28/67	11/2/67	11/2/67
300392583100C01	SAN JUAN 28-5 UT 68M DK	RIO ARRIBA	NM	28	N	5	W	33	D	A728816	216600	BASIN::DAKOTA	11	G	6/22/98	7/13/98	7/13/98
300392583100C02	SAN JUAN 28-5 UT 68M MV	RIO ARRIBA	NM	28	N	5	W	33	D	A710933	216600	BLANCO::MESAVERDE	11	G	6/22/98	7/13/98	7/13/98
300392583100C02	SAN JUAN 28-5 UT 68M MV	RIO ARRIBA	NM	28	N	5	W	33	D	A710933	216600	BLANCO::MESAVERDE	11	G	6/22/98	7/13/98	7/13/98
300392757500C01	SAN JUAN 28-5 UT 68N DK	RIO ARRIBA	NM	28	N	5	W	33	C	A728816	216600	BASIN::DAKOTA	11	G	8/12/04	8/30/04	8/30/04
300392757500C02	SAN JUAN 28-5 UT 68N MV	RIO ARRIBA	NM	28	N	5	W	33	C	A710933	216600	BLANCO::MESAVERDE	11	G	8/12/04	8/30/04	8/30/04
300392757500C02	SAN JUAN 28-5 UT 68N MV	RIO ARRIBA	NM	28	N	5	W	33	C	A710933	216600	BLANCO::MESAVERDE	11	G	8/12/04	8/30/04	8/30/04
300392981900C01	SAN JUAN 28-5 UT 68P DK	RIO ARRIBA	NM	28	N	5	W	33	L	A728816	216600	BASIN::DAKOTA	11	G	11/7/06	11/9/06	11/9/06
300392981900C02	SAN JUAN 28-5 UT 68P MV	RIO ARRIBA	NM	28	N	5	W	33	L	A710933	216600	BLANCO::MESAVERDE	11	G	11/7/06	11/9/06	11/9/06
300392981900C02	SAN JUAN 28-5 UT 68P MV	RIO ARRIBA	NM	28	N	5	W	33	L	A710933	216600	BLANCO::MESAVERDE	11	G	11/7/06	11/9/06	11/9/06
300392625400C01	SAN JUAN 28-5 UT 69M DK	RIO ARRIBA	NM	28	N	5	W	33	J	A728816	216600	BASIN::DAKOTA	11	G	7/20/00	7/31/00	7/31/00
300392625400C02	SAN JUAN 28-5 UT 69M MV	RIO ARRIBA	NM	28	N	5	W	33	J	A710933	216600	BLANCO::MESAVERDE	11	G	7/20/00	7/31/00	7/31/00

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392625400C02	SAN JUAN 28-5 UT 69M MV	RIO ARRIBA	NM	28	N	5	W	33	J	A710933	216600	BLANCO::MESAVERDE	11	G	7/20/00		7/31/00	7/31/00
300393107400C01	SAN JUAN 28-5 UT 69N DK	RIO ARRIBA	NM	28	N	5	W	33	B	A728816	216600	BASIN::DAKOTA	11	G	6/29/12		6/29/12	6/29/12
300393107400C02	SAN JUAN 28-5 UT 69N MV	RIO ARRIBA	NM	28	N	5	W	33	B	A710933	216600	BLANCO::MESAVERDE	11	G	6/29/12		6/29/12	6/29/12
300390746501S01	SAN JUAN 28-5 UT 7 MV	RIO ARRIBA	NM	28	N	5	W	8	K	A710933	216600	BLANCO::MESAVERDE	11	G	1/7/86		5/14/56	5/14/56
300392565500C01	SAN JUAN 28-5 UT 70M DK	RIO ARRIBA	NM	28	N	5	W	34	D	A728816	216600	BASIN::DAKOTA	11	G	7/29/97		8/8/97	8/8/97
300392565500C02	SAN JUAN 28-5 UT 70M MV	RIO ARRIBA	NM	28	N	5	W	34	D	A710933	216600	BLANCO::MESAVERDE	11	G	7/29/97		8/8/97	8/8/97
300392565500C02	SAN JUAN 28-5 UT 70M MV	RIO ARRIBA	NM	28	N	5	W	34	D	A710933	216600	BLANCO::MESAVERDE	11	G	7/29/97		8/8/97	8/8/97
300392757200C01	SAN JUAN 28-5 UT 70N DK	RIO ARRIBA	NM	28	N	5	W	34	K	A728816	216600	BASIN::DAKOTA	11	G	1/14/05		1/25/05	1/25/05
300392757200C02	SAN JUAN 28-5 UT 70N MV	RIO ARRIBA	NM	28	N	5	W	34	K	A710933	216600	BLANCO::MESAVERDE	11	G	1/14/05		1/25/05	1/25/05
300392757200C02	SAN JUAN 28-5 UT 70N MV	RIO ARRIBA	NM	28	N	5	W	34	K	A710933	216600	BLANCO::MESAVERDE	11	G	1/14/05		1/25/05	1/25/05
300392959200C01	SAN JUAN 28-5 UT 70P DK	RIO ARRIBA	NM	28	N	5	W	34	C	A728816	216600	BASIN::DAKOTA	11	G	5/18/06		5/19/06	5/19/06
300392959200C02	SAN JUAN 28-5 UT 70P MV	RIO ARRIBA	NM	28	N	5	W	34	C	A710933	216600	BLANCO::MESAVERDE	11	G	5/18/06		5/19/06	5/19/06
300392959200C02	SAN JUAN 28-5 UT 70P MV	RIO ARRIBA	NM	28	N	5	W	34	C	A710933	216600	BLANCO::MESAVERDE	11	G	5/18/06		5/19/06	5/19/06
300392625300C01	SAN JUAN 28-5 UT 71M DK	RIO ARRIBA	NM	28	N	5	W	34	I	A728816	216600	BASIN::DAKOTA	11	G	9/9/00		10/6/00	10/6/00
300392625300C02	SAN JUAN 28-5 UT 71M MV	RIO ARRIBA	NM	28	N	5	W	34	I	A710933	216600	BLANCO::MESAVERDE	11	G	9/9/00		10/6/00	10/6/00
300392625300C02	SAN JUAN 28-5 UT 71M MV	RIO ARRIBA	NM	28	N	5	W	34	I	A710933	216600	BLANCO::MESAVERDE	11	G	9/9/00		10/6/00	10/6/00
300392630800C01	SAN JUAN 28-5 UT 71N DK	RIO ARRIBA	NM	28	N	5	W	34	G	A728816	216600	BASIN::DAKOTA	11	G	6/26/02		7/3/02	7/3/02
300392630800C02	SAN JUAN 28-5 UT 71N MV	RIO ARRIBA	NM	28	N	5	W	34	G	A710933	216600	BLANCO::MESAVERDE	11	G	6/26/02		7/3/02	7/3/02
300392630800C02	SAN JUAN 28-5 UT 71N MV	RIO ARRIBA	NM	28	N	5	W	34	G	A710933	216600	BLANCO::MESAVERDE	11	G	6/26/02		7/3/02	7/3/02
300392002800S01	SAN JUAN 28-5 UT 72 DK	RIO ARRIBA	NM	28	N	5	W	35	N	A728816	216600	BASIN::DAKOTA	72	G	6/21/67	10/5/10	8/17/67	8/17/67
300392562100C01	SAN JUAN 28-5 UT 72M DK	RIO ARRIBA	NM	28	N	5	W	35	E	A728816	216600	BASIN::DAKOTA	11	G	11/7/97		12/2/97	12/2/97
300392562100C02	SAN JUAN 28-5 UT 72M MV	RIO ARRIBA	NM	28	N	5	W	35	E	A710933	216600	BLANCO::MESAVERDE	11	G	11/7/97		12/2/97	12/2/97
300392562100C02	SAN JUAN 28-5 UT 72M MV	RIO ARRIBA	NM	28	N	5	W	35	E	A710933	216600	BLANCO::MESAVERDE	11	G	11/7/97		12/2/97	12/2/97
300392626000C01	SAN JUAN 28-5 UT 72N DK	RIO ARRIBA	NM	28	N	5	W	35	F	A728816	216600	BASIN::DAKOTA	11	G	9/16/02		9/17/02	9/17/02
300392626000C02	SAN JUAN 28-5 UT 72N MV	RIO ARRIBA	NM	28	N	5	W	35	F	A710933	216600	BLANCO::MESAVERDE	11	G	9/16/02		9/17/02	9/17/02
300392626000C02	SAN JUAN 28-5 UT 72N MV	RIO ARRIBA	NM	28	N	5	W	35	F	A710933	216600	BLANCO::MESAVERDE	11	G	9/16/02		9/17/02	9/17/02
300392003600S01	SAN JUAN 28-5 UT 73 DK	RIO ARRIBA	NM	28	N	5	W	35	G	A728816	216600	BASIN::DAKOTA	11	G	8/17/67		9/22/67	9/22/67
300392566300C01	SAN JUAN 28-5 UT 73M DK	RIO ARRIBA	NM	28	N	5	W	35	O	A728816	216600	BASIN::DAKOTA	11	G	7/14/97		7/30/97	7/30/97
300392566300C02	SAN JUAN 28-5 UT 73M MV	RIO ARRIBA	NM	28	N	5	W	35	O	A710933	216600	BLANCO::MESAVERDE	11	G	7/14/97		7/30/97	7/30/97
300392566300C02	SAN JUAN 28-5 UT 73M MV	RIO ARRIBA	NM	28	N	5	W	35	O	A710933	216600	BLANCO::MESAVERDE	11	G	7/14/97		7/30/97	7/30/97
300392757100C01	SAN JUAN 28-5 UT 73N DK	RIO ARRIBA	NM	28	N	5	W	35	H	A728816	216600	BASIN::DAKOTA	11	G	8/23/04		9/3/04	9/3/04
300392757100C02	SAN JUAN 28-5 UT 73N MV	RIO ARRIBA	NM	28	N	5	W	35	H	A710933	216600	BLANCO::MESAVERDE	11	G	8/23/04		9/3/04	9/3/04
300392757100C02	SAN JUAN 28-5 UT 73N MV	RIO ARRIBA	NM	28	N	5	W	35	H	A710933	216600	BLANCO::MESAVERDE	11	G	8/23/04		9/3/04	9/3/04
300392004100S01	SAN JUAN 28-5 UT 74 DK	RIO ARRIBA	NM	28	N	5	W	36	N	A728816	216600	BASIN::DAKOTA	11	G	8/2/67		9/23/67	9/23/67
300392982000S01	SAN JUAN 28-5 UT 74E DK	RIO ARRIBA	NM	28	N	5	W	36	P	A728816	216600	BASIN::DAKOTA	11	G	9/13/08		9/23/08	9/23/08
300393057100C01	SAN JUAN 28-5 UT 74N DK	RIO ARRIBA	NM	28	N	5	W	36	G	A728816	216600	BASIN::DAKOTA	11	G	11/10/11		11/11/11	11/11/11
300393057100C02	SAN JUAN 28-5 UT 74N MV	RIO ARRIBA	NM	28	N	5	W	36	G	A710933	216600	BLANCO::MESAVERDE	11	G	11/10/11		11/11/11	11/11/11
300392010800C01	SAN JUAN 28-5 UT 75 DK	RIO ARRIBA	NM	28	N	5	W	17	G	A728816	216600	BASIN::DAKOTA	11	G	9/24/68		11/8/68	11/8/68
300392010800C02	SAN JUAN 28-5 UT 75 GL	RIO ARRIBA	NM	28	N	5	W	17	G	A725809	216600	MUNOZ CANYON::GALLUP	11	G	2/19/00		2/28/00	2/28/00
300392701900S01	SAN JUAN 28-5 UT 75M DK	RIO ARRIBA	NM	28	N	5	W	17	F	A728816	216600	BASIN::DAKOTA	71	G	5/12/03			
300392701900S02	SAN JUAN 28-5 UT 75M MV	RIO ARRIBA	NM	28	N	5	W	17	F	A710933	216600	BLANCO::MESAVERDE	11	G	5/12/03		5/14/03	5/14/03
300393039900C01	SAN JUAN 28-5 UT 75N DK	RIO ARRIBA	NM	28	N	5	W	17	B	A728816	216600	BASIN::DAKOTA	11	G	3/14/08			4/2/08
300393039900C02	SAN JUAN 28-5 UT 75N MV	RIO ARRIBA	NM	28	N	5	W	17	B	A710933	216600	BLANCO::MESAVERDE	11	G	3/14/08		4/2/08	4/2/08
300392010700C01	SAN JUAN 28-5 UT 76 DK	RIO ARRIBA	NM	28	N	5	W	21	G	A728816	216600	BASIN::DAKOTA	11	G	9/17/68		11/8/68	11/8/68
300392010700C02	SAN JUAN 28-5 UT 76 MV	RIO ARRIBA	NM	28	N	5	W	21	G	A710933	216600	BLANCO::MESAVERDE	11	G	7/5/97		7/22/97	7/22/97
300392010700C02	SAN JUAN 28-5 UT 76 MV	RIO ARRIBA	NM	28	N	5	W	21	G	A710933	216600	BLANCO::MESAVERDE	11	G	7/5/97		7/22/97	7/22/97
300392381500C01	SAN JUAN 28-5 UT 76M DK	RIO ARRIBA	NM	28	N	5	W	21	C	A728816	216600	BASIN::DAKOTA	11	G	12/26/85		2/6/86	2/6/86
300392381500C02	SAN JUAN 28-5 UT 76M MV	RIO ARRIBA	NM	28	N	5	W	21	C	A710933	216600	BLANCO::MESAVERDE	11	G	1/2/86		2/6/86	2/6/86
300393040000C01	SAN JUAN 28-5 UT 76N DK	RIO ARRIBA	NM	28	N	5	W	21	D	A728816	216600	BASIN::DAKOTA	11	G	4/15/08		4/29/08	4/29/08
300393040000C02	SAN JUAN 28-5 UT 76N MV	RIO ARRIBA	NM	28	N	5	W	21	D	A710933	216600	BLANCO::MESAVERDE	11	G	4/15/08		4/29/08	4/29/08
300392010600S01	SAN JUAN 28-5 UT 77 DK	RIO ARRIBA	NM	28	N	5	W	27	H	A728816	216600	BASIN::DAKOTA	11	G	8/14/68		11/8/68	11/8/68
300392593600C01	SAN JUAN 28-5 UT 77M DK	RIO ARRIBA	NM	28	N	5	W	27	F	A728816	216600	BASIN::DAKOTA	41	G	3/17/99		3/25/99	3/25/99
300392593600C02	SAN JUAN 28-5 UT 77M MV	RIO ARRIBA	NM	28	N	5	W	27	F	A710933	216600	BLANCO::MESAVERDE	41	G	3/17/99		3/25/99	3/25/99
300392593600C02	SAN JUAN 28-5 UT 77M MV	RIO ARRIBA	NM	28	N	5	W	27	F	A710933	216600	BLANCO::MESAVERDE	41	G	3/17/99		3/25/99	3/25/99

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TFMP ARANDON PS - PFRM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300393036300C01	SAN JUAN 28-5 UT 77N DK	RIO ARRIBA	NM	28	N	5	W	27	B	A728816	216600	BASIN::DAKOTA	11	G	11/10/08		10/20/08
300393036300C02	SAN JUAN 28-5 UT 77N MV	RIO ARRIBA	NM	28	N	5	W	27	B	A710933	216600	BLANCO::MESAVERDE	11	G	11/10/08		10/20/08
300392010500C01	SAN JUAN 28-5 UT 78 DK	RIO ARRIBA	NM	28	N	5	W	25	M	A728816	216600	BASIN::DAKOTA	11	G	8/14/68	11/1/68	11/1/68
300392010500C02	SAN JUAN 28-5 UT 78 MV	RIO ARRIBA	NM	28	N	5	W	25	M	A710933	216600	BLANCO::MESAVERDE	11	G	6/23/98	7/1/98	7/1/98
300392010500C02	SAN JUAN 28-5 UT 78 MV	RIO ARRIBA	NM	28	N	5	W	25	M	A710933	216600	BLANCO::MESAVERDE	11	G	6/23/98	7/1/98	7/1/98
300392596900C01	SAN JUAN 28-5 UT 78M DK	RIO ARRIBA	NM	28	N	5	W	25	F	A728816	216600	BASIN::DAKOTA	72	G	1/13/99	12/6/11	2/17/99
300392596900C02	SAN JUAN 28-5 UT 78M MV	RIO ARRIBA	NM	28	N	5	W	25	F	A710933	216600	BLANCO::MESAVERDE	72	G	1/13/99	12/6/11	2/17/99
300392596900C02	SAN JUAN 28-5 UT 78M MV	RIO ARRIBA	NM	28	N	5	W	25	F	A710933	216600	BLANCO::MESAVERDE	72	G	1/13/99	12/6/11	2/17/99
300393036800C01	SAN JUAN 28-5 UT 78N DK	RIO ARRIBA	NM	28	N	5	W	25	E	A728816	216600	BASIN::DAKOTA	11	G	10/27/09	11/19/09	11/19/09
300393036800C02	SAN JUAN 28-5 UT 78N MV	RIO ARRIBA	NM	28	N	5	W	25	E	A710933	216600	BLANCO::MESAVERDE	11	G	10/27/09	11/19/09	11/19/09
300392023700S01	SAN JUAN 28-5 UT 79 DK	RIO ARRIBA	NM	28	N	5	W	7	M	A728816	216600	BASIN::DAKOTA	11	G	8/7/69	9/16/69	9/16/69
300392383300S01	SAN JUAN 28-5 UT 79E DK	RIO ARRIBA	NM	28	N	5	W	7	I	A728816	216600	BASIN::DAKOTA	11	G	11/14/85	12/19/85	12/19/85
300392777000C01	SAN JUAN 28-5 UT 79N DK	RIO ARRIBA	NM	28	N	5	W	7	P	A728816	216600	BASIN::DAKOTA	11	G	12/7/04	12/15/04	12/15/04
300392777000C02	SAN JUAN 28-5 UT 79N MV	RIO ARRIBA	NM	28	N	5	W	7	P	A710933	216600	BLANCO::MESAVERDE	11	G	12/7/04	12/15/04	12/15/04
300392384500S01	SAN JUAN 28-5 UT 7A MV	RIO ARRIBA	NM	28	N	5	W	8	P	A710933	216600	BLANCO::MESAVERDE	11	G	10/29/85	11/13/85	11/13/85
300392021700S01	SAN JUAN 28-5 UT 80 DK	RIO ARRIBA	NM	28	N	5	W	26	G	A728816	216600	BASIN::DAKOTA	11	G	7/2/69	8/16/69	8/16/69
300393049000C01	SAN JUAN 28-5 UT 80M DK	RIO ARRIBA	NM	28	N	5	W	26	G	A728816	216600	BASIN::DAKOTA	11	G	6/18/09	7/20/09	7/20/09
300393049000C02	SAN JUAN 28-5 UT 80M MV	RIO ARRIBA	NM	28	N	5	W	26	G	A710933	216600	BLANCO::MESAVERDE	11	G	6/18/09	7/20/09	7/20/09
300392982600C01	SAN JUAN 28-5 UT 80N DK	RIO ARRIBA	NM	28	N	5	W	27	I	A728816	216600	BASIN::DAKOTA	11	G	11/2/06	11/22/06	11/22/06
300392982600C02	SAN JUAN 28-5 UT 80N MV	RIO ARRIBA	NM	28	N	5	W	27	I	A710933	216600	BLANCO::MESAVERDE	11	G	11/2/06	11/22/06	11/22/06
300392982600C02	SAN JUAN 28-5 UT 80N MV	RIO ARRIBA	NM	28	N	5	W	27	I	A710933	216600	BLANCO::MESAVERDE	11	G	11/2/06	11/22/06	11/22/06
300392018700S01	SAN JUAN 28-5 UT 81 DK	RIO ARRIBA	NM	28	N	5	W	26	M	A728816	216600	BASIN::DAKOTA	11	G	8/8/69	9/8/69	9/8/69
300392955500C01	SAN JUAN 28-5 UT 81M DK	RIO ARRIBA	NM	28	N	5	W	26	M	A728816	216600	BASIN::DAKOTA	11	G	12/19/05	12/29/05	12/29/05
300392955500C02	SAN JUAN 28-5 UT 81M MV	RIO ARRIBA	NM	28	N	5	W	26	M	A710933	216600	BLANCO::MESAVERDE	11	G	12/19/05	12/29/05	12/29/05
300392955500C02	SAN JUAN 28-5 UT 81M MV	RIO ARRIBA	NM	28	N	5	W	26	M	A710933	216600	BLANCO::MESAVERDE	11	G	12/19/05	12/29/05	12/29/05
300392782200C01	SAN JUAN 28-5 UT 81N DK	RIO ARRIBA	NM	28	N	5	W	25	I	A728816	216600	BASIN::DAKOTA	11	G	11/18/06	10/1/07	10/1/07
300392782200C02	SAN JUAN 28-5 UT 81N MV	RIO ARRIBA	NM	28	N	5	W	25	I	A710933	216600	BLANCO::MESAVERDE	11	G	11/18/06	10/1/07	10/1/07
300392942000C01	SAN JUAN 28-5 UT 81P DK	RIO ARRIBA	NM	28	N	5	W	26	M	A728816	216600	BASIN::DAKOTA	11	G	11/30/05	12/29/05	12/29/05
300392942000C02	SAN JUAN 28-5 UT 81P MV	RIO ARRIBA	NM	28	N	5	W	26	M	A710933	216600	BLANCO::MESAVERDE	11	G	11/30/05	12/29/05	12/29/05
300392942000C02	SAN JUAN 28-5 UT 81P MV	RIO ARRIBA	NM	28	N	5	W	26	M	A710933	216600	BLANCO::MESAVERDE	11	G	11/30/05	12/29/05	12/29/05
300392023600C01	SAN JUAN 28-5 UT 82 DK	RIO ARRIBA	NM	28	N	5	W	22	M	A728816	216600	BASIN::DAKOTA	11	G	8/8/69	9/12/69	9/12/69
300392023600C02	SAN JUAN 28-5 UT 82 GL	RIO ARRIBA	NM	28	N	5	W	22	M	A725811	216600	MUNOZ CANYON::GALLUP	11	G	1/25/00	2/2/00	2/2/00
300392686700C01	SAN JUAN 28-5 UT 82M DK	RIO ARRIBA	NM	28	N	5	W	22	F	A728816	216600	BASIN::DAKOTA	11	G	2/27/03	3/8/03	3/8/03
300392686700C02	SAN JUAN 28-5 UT 82M MV	RIO ARRIBA	NM	28	N	5	W	22	F	A710933	216600	BLANCO::MESAVERDE	11	G	2/27/03	3/8/03	3/8/03
300393036500C01	SAN JUAN 28-5 UT 82N DK	RIO ARRIBA	NM	28	N	5	W	22	N	A728816	216600	BASIN::DAKOTA	11	G	4/4/08	4/22/08	4/22/08
300393036500C02	SAN JUAN 28-5 UT 82N MV	RIO ARRIBA	NM	28	N	5	W	22	N	A710933	216600	BLANCO::MESAVERDE	11	G	4/4/08	4/22/08	4/22/08
300392024200C01	SAN JUAN 28-5 UT 83 DK	RIO ARRIBA	NM	28	N	5	W	16	M	A728816	216600	BASIN::DAKOTA	11	G	9/2/69	10/8/69	10/8/69
300392024200C02	SAN JUAN 28-5 UT 83 MV	RIO ARRIBA	NM	28	N	5	W	16	M	A710933	216600	BLANCO::MESAVERDE	11	G	8/5/11	9/21/11	9/21/11
300392592700C01	SAN JUAN 28-5 UT 83M DK	RIO ARRIBA	NM	28	N	5	W	16	C	A728816	216600	BASIN::DAKOTA	11	G	4/7/99	4/14/99	4/14/99
300392592700C02	SAN JUAN 28-5 UT 83M MV	RIO ARRIBA	NM	28	N	5	W	16	C	A710933	216600	BLANCO::MESAVERDE	11	G	4/7/99	4/14/99	4/14/99
300392036000C01	SAN JUAN 28-5 UT 84 DK	RIO ARRIBA	NM	28	N	5	W	16	G	A728816	216600	BASIN::DAKOTA	11	G	4/23/71	6/9/71	6/9/71
300392036000C02	SAN JUAN 28-5 UT 84 MV	RIO ARRIBA	NM	28	N	5	W	16	G	A710933	216600	BLANCO::MESAVERDE	11	G	10/25/05	10/26/05	10/26/05
300392383600C01	SAN JUAN 28-5 UT 84E DK	RIO ARRIBA	NM	28	N	5	W	16	O	A728816	216600	BASIN::DAKOTA	11	G	11/14/85	12/30/85	12/30/85
300392383600C02	SAN JUAN 28-5 UT 84E MV	RIO ARRIBA	NM	28	N	5	W	16	O	A710933	216600	BLANCO::MESAVERDE	11	G	8/22/97	9/4/97	9/4/97
300392035800C01	SAN JUAN 28-5 UT 85 DK	RIO ARRIBA	NM	28	N	5	W	8	J	A728816	216600	BASIN::DAKOTA	11	G	4/6/71	6/8/71	6/8/71
300392035800C02	SAN JUAN 28-5 UT 85 MV	RIO ARRIBA	NM	28	N	5	W	8	J	A710933	216600	BLANCO::MESAVERDE	11	G	5/19/00	5/19/00	5/19/00
300392383400S01	SAN JUAN 28-5 UT 85E DK	RIO ARRIBA	NM	28	N	5	W	8	L	A728816	216600	BASIN::DAKOTA	11	G	10/29/85	12/19/85	12/19/85
300392036400S01	SAN JUAN 28-5 UT 86 DK	RIO ARRIBA	NM	28	N	5	W	23	L	A728816	216600	BASIN::DAKOTA	11	G	5/20/71	9/13/71	9/13/71
300392594600C01	SAN JUAN 28-5 UT 86M DK	RIO ARRIBA	NM	28	N	5	W	23	D	A728816	216600	BASIN::DAKOTA	11	G	3/28/99	4/7/99	4/7/99
300392594600C02	SAN JUAN 28-5 UT 86M MV	RIO ARRIBA	NM	28	N	5	W	23	D	A710933	216600	BLANCO::MESAVERDE	11	G	3/28/99	4/7/99	4/7/99
300392695600C01	SAN JUAN 28-5 UT 86N DK	RIO ARRIBA	NM	28	N	5	W	23	K	A728816	216600	BASIN::DAKOTA	11	G	2/18/03	2/21/03	2/21/03
300392695600C02	SAN JUAN 28-5 UT 86N MV	RIO ARRIBA	NM	28	N	5	W	23	K	A710933	216600	BLANCO::MESAVERDE	11	G	2/18/03	2/21/03	2/21/03
300392047100S01	SAN JUAN 28-5 UT 87 DK	RIO ARRIBA	NM	28	N	5	W	22	B	A728816	216600	BASIN::DAKOTA	11	G	7/10/72	8/15/72	8/15/72
300392047500C01	SAN JUAN 28-5 UT 88 DK	RIO ARRIBA	NM	28	N	5	W	15	M	A728816	216600	BASIN::DAKOTA	11	G	7/19/72	8/18/72	8/18/72

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
41 - SHUT IN 72 - PERM ABANDON WELL
59 - SOLD PA - PLUG ABANDON
61 - TEMP ABANDON PS - PERM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392047500C02	SAN JUAN 28-5 UT 88 MV	RIO ARRIBA	NM	28	N	5	W	15	M	A710933	216600	BLANCO::MESAVERDE	11	G	12/10/10		3/2/11	3/2/11
300392385600C02	SAN JUAN 28-5 UT 88M MV	RIO ARRIBA	NM	28	N	5	W	15	E	A710933	216600	BLANCO::MESAVERDE	11	G	1/16/86		2/10/86	2/10/86
300392047200S02	SAN JUAN 28-5 UT 89 MV	RIO ARRIBA	NM	28	N	5	W	9	P	A710933	216600	BLANCO::MESAVERDE	11	G	8/15/97		8/25/97	8/25/97
300392385700C01	SAN JUAN 28-5 UT 89E DK	RIO ARRIBA	NM	28	N	5	W	9	N	A728816	216600	BASIN::DAKOTA	11	G	10/22/85		12/3/85	12/3/85
300392385700C02	SAN JUAN 28-5 UT 89E MV	RIO ARRIBA	NM	28	N	5	W	9	N	A710933	216600	BLANCO::MESAVERDE	11	G	6/14/00		6/27/00	6/27/00
300393004400S01	SAN JUAN 28-5 UT 89F DK	RIO ARRIBA	NM	28	N	5	W	10		A728816	216600	BASIN::DAKOTA	11	G	10/24/07		10/24/07	11/14/07
300392769600C01	SAN JUAN 28-5 UT 89N DK	RIO ARRIBA	NM	28	N	5	W	10	N	A728816	216600	BASIN::DAKOTA	11	G	3/28/05		4/8/05	4/8/05
300392769600C02	SAN JUAN 28-5 UT 89N MV	RIO ARRIBA	NM	28	N	5	W	10	N	A710933	216600	BLANCO::MESAVERDE	11	G	3/28/05		4/8/05	4/8/05
300390730701S01	SAN JUAN 28-5 UT 9 MV	RIO ARRIBA	NM	28	N	5	W	29	K	A710933	216600	BLANCO::MESAVERDE	11	G	7/13/55		12/7/55	12/7/55
300390730701S01	SAN JUAN 28-5 UT 9 MV	RIO ARRIBA	NM	28	N	5	W	29	K	A710933	216600	BLANCO::MESAVERDE	11	G	7/13/55		12/7/55	12/7/55
300392063500S01	SAN JUAN 28-5 UT 91 DK	RIO ARRIBA	NM	28	N	5	W	14	M	A728816	216600	BASIN::DAKOTA	11	G	10/5/73		10/24/73	10/24/73
300392384600S02	SAN JUAN 28-5 UT 91M MV	RIO ARRIBA	NM	28	N	5	W	14	E	A710933	216600	BLANCO::MESAVERDE	11	G	7/2/98		7/21/98	7/21/98
300393044600C01	SAN JUAN 28-5 UT 91N DK	RIO ARRIBA	NM	28	N	5	W	14	E	A728816	216600	BASIN::DAKOTA	11	G	8/24/09		12/9/09	12/9/09
300393044600C02	SAN JUAN 28-5 UT 91N MV	RIO ARRIBA	NM	28	N	5	W	14	E	A710933	216600	BLANCO::MESAVERDE	11	G	8/24/09		12/9/09	12/9/09
300393037200C01	SAN JUAN 28-5 UT 91P DK	RIO ARRIBA	NM	28	N	5	W	14	M	A728816	216600	BASIN::DAKOTA	11	G	4/23/09		6/16/09	6/16/09
300393037200C02	SAN JUAN 28-5 UT 91P MV	RIO ARRIBA	NM	28	N	5	W	14	M	A710933	216600	BLANCO::MESAVERDE	11	G	4/23/09		6/16/09	6/16/09
300392618100C01	SAN JUAN 28-5 UT 92M DK	RIO ARRIBA	NM	28	N	5	W	24	E	A728816	216600	BASIN::DAKOTA	11	G	8/28/99		9/16/99	9/16/99
300392618100C02	SAN JUAN 28-5 UT 92M MV	RIO ARRIBA	NM	28	N	5	W	24	E	A710933	216600	BLANCO::MESAVERDE	11	G	8/28/99		9/16/99	9/16/99
300392087600C01	SAN JUAN 28-5 UT 93 DK	RIO ARRIBA	NM	28	N	5	W	15	G	A728816	216600	BASIN::DAKOTA	11	G	12/11/74		1/14/75	1/14/75
300392087600C02	SAN JUAN 28-5 UT 93 MV	RIO ARRIBA	NM	28	N	5	W	15	G	A710933	216600	BLANCO::MESAVERDE	11	G	10/11/05		10/19/05	10/19/05
300392563900S01	SAN JUAN 28-5 UT 93M DK	RIO ARRIBA	NM	28	N	5	W	15	J	A728816	216600	BASIN::DAKOTA	61	G	7/23/97		8/8/97	8/8/97
300392563900S02	SAN JUAN 28-5 UT 93M MV	RIO ARRIBA	NM	28	N	5	W	15	J	A710933	216600	BLANCO::MESAVERDE	11	G	7/23/97		8/8/97	8/8/97
300393072200X01	SAN JUAN 28-5 UT 93N DK	RIO ARRIBA	NM	28	N	5	W	15	P	A728816	216600	BASIN::DAKOTA	71	G	11/18/10	11/18/10		
300393072200S02	SAN JUAN 28-5 UT 93N MV	RIO ARRIBA	NM	28	N	5	W	15	P	A710933	216600	BLANCO::MESAVERDE	11	G	11/18/10		11/18/10	12/14/10
300392097100C01	SAN JUAN 28-5 UT 94 DK	RIO ARRIBA	NM	28	N	5	W	25	P	A728816	216600	BASIN::DAKOTA	11	G	11/22/77		6/28/78	6/28/78
300392097100C02	SAN JUAN 28-5 UT 94 MV	RIO ARRIBA	NM	28	N	5	W	25	P	A710933	216600	BLANCO::MESAVERDE	11	G	8/7/97		8/25/97	8/25/97
300392097100C02	SAN JUAN 28-5 UT 94 MV	RIO ARRIBA	NM	28	N	5	W	25	P	A710933	216600	BLANCO::MESAVERDE	11	G	8/7/97		8/25/97	8/25/97
300392087800S01	SAN JUAN 28-5 UT 95 PC	RIO ARRIBA	NM	28	N	5	W	31	M	A728818	216600	TAPACITO::PICTURED CLIFFS	11	G	9/20/74		1/17/75	1/17/75
300392186400S01	SAN JUAN 28-5 UT 96 DK	RIO ARRIBA	NM	28	N	5	W	10	O	A728816	216600	BASIN::DAKOTA	11	G	11/20/79		3/20/80	3/20/80
300392386400S01	SAN JUAN 28-5 UT 96E DK	RIO ARRIBA	NM	28	N	5	W	11	M	A728816	216600	BASIN::DAKOTA	11	G	11/7/85		11/25/85	11/25/85
300392595600C01	SAN JUAN 28-5 UT 97M DK	RIO ARRIBA	NM	28	N	5	W	14	P	A728816	216600	BASIN::DAKOTA	11	G	12/1/98		12/10/98	12/10/98
300392595600C02	SAN JUAN 28-5 UT 97M MV	RIO ARRIBA	NM	28	N	5	W	14	P	A710933	216600	BLANCO::MESAVERDE	11	G	12/1/98		12/10/98	12/10/98
300392592800C01	SAN JUAN 28-5 UT 98M DK	RIO ARRIBA	NM	28	N	5	W	13	I	A728816	216600	BASIN::DAKOTA	11	G	11/13/98		12/1/98	12/1/98
300392592800C02	SAN JUAN 28-5 UT 98M MV	RIO ARRIBA	NM	28	N	5	W	13	I	A710933	216600	BLANCO::MESAVERDE	11	G	11/13/98		12/1/98	12/1/98
300392527000C02	SAN JUAN 28-5 UT NP 200 F	RIO ARRIBA	NM	28	N	5	W	14	H	A723387	216600	BASIN CB::FRUITLAND COAL	11	G	10/1/93		12/1/93	12/1/93
300392527000C01	SAN JUAN 28-5 UT NP 200 P	RIO ARRIBA	NM	28	N	5	W	14	H	A721129	216600	GOBERNADOR::PICTURED CLIF	11	G	10/1/93		12/1/93	12/1/93
300392447400S01	SAN JUAN 28-5 UT NP 201 F	RIO ARRIBA	NM	28	N	5	W	15	A	A723386	216600	BASIN CB::FRUITLAND COAL	11	G	8/2/89		1/17/90	1/17/90
300392438200S01	SAN JUAN 28-5 UT NP 204 F	RIO ARRIBA	NM	28	N	5	W	18	A	A723388	216600	BASIN CB::FRUITLAND COAL	11	G	7/2/89		10/5/89	10/5/89
300392536200C02	SAN JUAN 28-5 UT NP 211 F	RIO ARRIBA	NM	28	N	5	W	13	K	A723399	216600	BASIN CB::FRUITLAND COAL	11	G	8/26/94		1/9/95	1/9/95
300392536200C01	SAN JUAN 28-5 UT NP 211 P	RIO ARRIBA	NM	28	N	5	W	13	K	A721135	216600	GOBERNADOR::PICTURED CLIF	11	G	8/26/94		1/9/95	1/9/95
300392536900C02	SAN JUAN 28-5 UT NP 212 F	RIO ARRIBA	NM	28	N	5	W	15	L	A723400	216600	BASIN CB::FRUITLAND COAL	11	G	10/8/94		12/29/94	12/29/94
300392536900C01	SAN JUAN 28-5 UT NP 212 P	RIO ARRIBA	NM	28	N	5	W	15	L	A721138	216600	GOBERNADOR::PICTURED CLIF	11	G	10/8/94		12/29/94	12/29/94
300392492200S01	SAN JUAN 28-5 UT NP 219 F	RIO ARRIBA	NM	28	N	5	W	30	A	A723390	216600	BASIN CB::FRUITLAND COAL	11	G	10/23/92		11/15/93	11/15/93
300392492200S01	SAN JUAN 28-5 UT NP 219 F	RIO ARRIBA	NM	28	N	5	W	30	A	A723390	216600	BASIN CB::FRUITLAND COAL	11	G	10/23/92		11/15/93	11/15/93
300392492300S01	SAN JUAN 28-5 UT NP 223 F	RIO ARRIBA	NM	28	N	5	W	34	L	A723391	216600	BASIN CB::FRUITLAND COAL	11	G	11/20/90		1/12/93	1/12/93
300392528300C01	SAN JUAN 28-5 UT NP 227 F	RIO ARRIBA	NM	28	N	5	W	11	M	A723398	216600	BASIN CB::FRUITLAND COAL	11	G	9/26/93		1/26/94	1/26/94
300392528300C02	SAN JUAN 28-5 UT NP 227 P	RIO ARRIBA	NM	28	N	5	W	11	M	A721134	216600	GOBERNADOR::PICTURED CLIF	11	G	9/26/93		1/26/94	1/26/94
300392528700C02	SAN JUAN 28-5 UT NP 228 F	RIO ARRIBA	NM	28	N	5	W	24	A	A723397	216600	BASIN CB::FRUITLAND COAL	11	G	10/10/93		1/4/94	1/4/94
300392528700C02	SAN JUAN 28-5 UT NP 228 F	RIO ARRIBA	NM	28	N	5	W	24	A	A723397	216600	BASIN CB::FRUITLAND COAL	11	G	10/10/93		1/4/94	1/4/94
300392528700C01	SAN JUAN 28-5 UT NP 228 P	RIO ARRIBA	NM	28	N	5	W	24	A	A721133	216600	UNK::PICTURED CLIFFS	11	G	10/10/93		1/4/94	1/4/94
300392528700C01	SAN JUAN 28-5 UT NP 228 P	RIO ARRIBA	NM	28	N	5	W	24	A	A721133	216600	UNK::PICTURED CLIFFS	11	G	10/10/93		1/4/94	1/4/94
300392527100C02	SAN JUAN 28-5 UT NP 229 F	RIO ARRIBA	NM	28	N	5	W	27	M	A723392	216600	BASIN CB::FRUITLAND COAL	11	G	9/22/93		2/11/94	2/11/94
300392527100C02	SAN JUAN 28-5 UT NP 229 F	RIO ARRIBA	NM	28	N	5	W	27	M	A723392	216600	BASIN CB::FRUITLAND COAL	11	G	9/22/93		2/11/94	2/11/94
300392527100C01	SAN JUAN 28-5 UT NP 229 P	RIO ARRIBA	NM	28	N	5	W	27	M	A721127	216600	BLANCO S::PICTURED CLIFF	11	G	9/22/93		2/11/94	2/11/94

PRODUCTION STATUS

11 - FLOWING WELL 71 - PERM ABANDON ZONE
49 - SHUT IN 72 - PERM ABANDON WELL
51 - SOLD PA - PLUG ABANDON
61 - TFMF ARANDON PS - PFRM SHUT-IN

SAN JUAN 28-5 UNIT
STATUS OF WELLS REPORT 02/08/2013

300392527100C01	SAN JUAN 28-5 UT NP 229 P	RIO ARRIBA	NM	28	N	5	W	27	M	A721127	216600	BLANCO S.:PICTURED CLIFF	11	G	9/22/93		2/11/94	2/11/94
300392536400C02	SAN JUAN 28-5 UT NP 230 F	RIO ARRIBA	NM	28	N	5	W	25	B	A723396	216600	BASIN CB::FRUITLAND COAL	11	G	10/11/94		1/24/95	1/24/95
300392536400C01	SAN JUAN 28-5 UT NP 230 P	RIO ARRIBA	NM	28	N	5	W	25	B	A721132	216600	TAPACITO::PICTURED CLIFFS	11	G	10/11/94		1/24/95	1/24/95
300392527600C02	SAN JUAN 28-5 UT NP 232 F	RIO ARRIBA	NM	28	N	5	W	24	L	A723393	216600	BASIN CB::FRUITLAND COAL	11	G	10/6/93		12/6/93	12/6/93
300392527600C02	SAN JUAN 28-5 UT NP 232 F	RIO ARRIBA	NM	28	N	5	W	24	L	A723393	216600	BASIN CB::FRUITLAND COAL	11	G	10/6/93		12/6/93	12/6/93
300392527600C01	SAN JUAN 28-5 UT NP 232 P	RIO ARRIBA	NM	28	N	5	W	24	L	A721128	216600	TAPACITO::PICTURED CLIFFS	11	G	10/6/93		12/6/93	12/6/93
300392527600C01	SAN JUAN 28-5 UT NP 232 P	RIO ARRIBA	NM	28	N	5	W	24	L	A721128	216600	TAPACITO::PICTURED CLIFFS	11	G	10/6/93		12/6/93	12/6/93
300392542700C02	SAN JUAN 28-5 UT NP 235 F	RIO ARRIBA	NM	28	N	5	W	28	K	A723395	216600	BASIN CB::FRUITLAND COAL	11	G	10/13/94		3/31/95	3/31/95
300392542700C02	SAN JUAN 28-5 UT NP 235 F	RIO ARRIBA	NM	28	N	5	W	28	K	A723395	216600	BASIN CB::FRUITLAND COAL	11	G	10/13/94		3/31/95	3/31/95
300392542700C01	SAN JUAN 28-5 UT NP 235 P	RIO ARRIBA	NM	28	N	5	W	28	K	A721131	216600	TAPACITO::PICTURED CLIFFS	11	G	10/12/94		3/31/95	3/31/95
300392542700C01	SAN JUAN 28-5 UT NP 235 P	RIO ARRIBA	NM	28	N	5	W	28	K	A721131	216600	TAPACITO::PICTURED CLIFFS	11	G	10/12/94		3/31/95	3/31/95
300392536500C02	SAN JUAN 28-5 UT NP 236 F	RIO ARRIBA	NM	28	N	5	W	26	M	A723394	216600	BASIN CB::FRUITLAND COAL	11	G	10/18/94		1/24/95	1/24/95
300392536500C01	SAN JUAN 28-5 UT NP 236 P	RIO ARRIBA	NM	28	N	5	W	26	M	A721130	216600	TAPACITO::PICTURED CLIFFS	11	G	10/18/94		1/24/95	1/24/95
300392536600C02	SAN JUAN 28-5 UT NP 240 F	RIO ARRIBA	NM	28	N	5	W	32	H	A723401	216600	BASIN CB::FRUITLAND COAL	11	G	10/18/94		1/24/95	1/24/95
300392536600C02	SAN JUAN 28-5 UT NP 240 F	RIO ARRIBA	NM	28	N	5	W	32	H	A723401	216600	BASIN CB::FRUITLAND COAL	11	G	10/18/94		1/24/95	1/24/95
300392536600C01	SAN JUAN 28-5 UT NP 240 P	RIO ARRIBA	NM	28	N	5	W	32	H	A721136	216600	TAPACITO::PICTURED CLIFFS	11	G	10/18/94		1/24/95	1/24/95
300392536600C01	SAN JUAN 28-5 UT NP 240 P	RIO ARRIBA	NM	28	N	5	W	32	H	A721136	216600	TAPACITO::PICTURED CLIFFS	11	G	10/18/94		1/24/95	1/24/95

PRODUCTION STATUS

11 - FLOWING WELL	71 - PERM ABANDON ZONE
41 - SHUT IN	72 - PERM ABANDON WELL
59 - SOLD	PA - PLUG ABANDON
61 - TEMP ABANDON	PS - PERM SHUT-IN