

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-23525
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator C. W. Trainer		6. State Oil & Gas Lease No. E-2431
3. Address of Operator P. O. Box 754, Midland, Texas 79702		7. Lease Name or Unit Agreement Name Gulf State Com
4. Well Location Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>4</u> Township <u>15S</u> Range <u>15E</u> NMPM County <u>Lea</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4004.2 GL		9. OGRID Number 3474
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		10. Pool name or Wildcat Morton Wolfcamp, East
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Rig up wire line unit and go in the hole with a gauge ring to 10,505' and come out of the hole with gauge ring and go in the hole with CIBP and set at 10,454' +/- . Come out of the hole with wire line and go in the hole and dump 35' of cement on top of CIBP and come out of the hole with wire line and load hole with 2% KCL and pressure test well to 400 psig and hold for 30 minutes for approval from NMOCd for T/A.

*No chart TA not complete until
chart run!*

NOTE: This C-103 was typed out 7-19-06 but was never filed: copy attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCd guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Sheryl L. Jonas TITLE Agent for CW Trainer DATE 12/27/06

Type or print name Sheryl L. Jonas E-mail address: Sjonas4011@aol.com Telephone No. 432-683-5511

For State Use Only

APPROVED BY: Sheryl L. Jonas **FIELD REPRESENTATIVE II/STAFF MANAGER**
Conditions of Approval (if any):

OCD Ex. No. 4
Case 13846

