



San Juan Business Unit
PO Box 4289
Farmington NM 87499-4289
(505) 326-9700

February 23, 2007

Bureau of Land Management
Farmington Resource Area
1235 La Plata Highway
Farmington, NM 87401

2007 MAR 2 11 3 AM
2007 MAR 2 11 3 AM
Commissioner of Public Lands
State of New Mexico
P. O. Box 1148
Santa Fe, NM 87501-1148

Oil Conservation Division
State of New Mexico
1220 S. Saint Francis Drive
Santa Fe, NM 87505

RE: **2007 Plan of Development
Lindrith "B" Unit, I SEC. #713
Rio Arriba County, New Mexico**

Ladies and Gentlemen:

The following Participating Areas currently exist in the Lindrith Unit:

FORMATION	EXPANSION	EFFECTIVE DATE
Gallup	Initial	1/1/1986
Dakota	Fourth	11/1/1984

The 2006 Plan of Development (or amendments thereto) provided for no wells to be drilled during 2006.

Pursuant to Section 9 of the Lindrith Unit Agreement, ConocoPhillips Company, as Unit Operator, hereby submits no wells for the 2007 Plan of Development.

The working interest owners are being furnished a copy of this letter, well status listing and enclosed map. ConocoPhillips, as Unit Operator, will drill any offset wells required to prevent drainage of unitized substances and any other wells deemed necessary by the working interest owners or Unit Operator.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of this letter to the undersigned.

Please contact me at (505) 326-9760 if there are any questions regarding this letter.

Sincerely,

Linda Dean

Lindrith Unit, 3.0 (2007)

**LINDRITH UNIT
2007 PLAN OF DEVELOPMENT APPROVALS**

Bureau of Land Management

Date

Ed Martin

New Mexico Oil Conservation Division

3/5/07

Date

New Mexico Commissioner of Public Lands

Date

Lindrieth "B" Unit Wells Status as of 2/22/2007

List of Completions - San Juan																	
Well Name	Rev Name	Sec Num	Twinsp	Twinsp Dir	Ring	Ring Dir	Prod Strat	API Well Code	MMS Prod Interval	MMS Lse Agr Number	State	Lease Code	Lea ID	Oper ID	Compl Dtr	Int Prod Dt	1st Sale Dt
LINDRITH B UNIT #103 DK	LINDRITH GALLUP DAKOTA.WS	18	24	N	2	W	41	300392572200501	S01	8920007130	31778	A706737	12001	12001		1/1/1994	4/1/1998
LINDRITH B UNIT #108 DK	LINDRITH GALLUP DAKOTA.WS	15	24	N	3	W	PR	300392679100501	S01	820789130	31778	A707094	12001	12001		1/1/1994	9/15/1980
LINDRITH B UNIT #10 DK	LINDRITH GALLUP DAKOTA.WS	34	24	N	3	W	41	300392242000501	S01	820789150	31778	A706422	12001	12001	9/15/1980	2/25/2002	2/25/2002
LINDRITH B UNIT #110 DK	LINDRITH GALLUP DAKOTA.WS	15	24	N	3	W	PR	300392682000501	S01	892000713X	31778	A707094	12001	12001	11/20/2001	1/1/1994	3/12/1981
LINDRITH B UNIT #113 DK	LINDRITH GALLUP DAKOTA.WS	10	24	N	3	W	PR	300392676600501	S01	820789120	31778	A706425	12001	12001	1/1/1994	1/1/1994	1/1/1994
LINDRITH B UNIT #11 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	PR	300392253500501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	3/12/1981	
LINDRITH B UNIT #12 DK	LINDRITH GALLUP DAKOTA.WS	22	24	N	3	W	PR	300392255000501	S01	820789130	31778	A706416	12001	12001	1/1/1994	4/13/1981	
LINDRITH B UNIT #13 DK	LINDRITH GALLUP DAKOTA.WS	27	24	N	3	W	PR	300392255100501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	4/6/1981	
LINDRITH B UNIT #14 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	PR	300392255400501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	2/19/1981	
LINDRITH B UNIT #15 DK	LINDRITH GALLUP DAKOTA.WS	21	24	N	3	W	PR	300392254900501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	1/22/1981	
LINDRITH B UNIT #16 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	PR	300392271200501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	6/30/1981	
LINDRITH B UNIT #17 DK	LINDRITH GALLUP DAKOTA.WS	22	24	N	3	W	PR	300392271300501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	6/11/1981	
LINDRITH B UNIT #18 DK	LINDRITH GALLUP DAKOTA.WS	27	24	N	3	W	PR	300392271500501	S01	820789140	31778	A706421	12001	12001	1/1/1994	2/20/1980	
LINDRITH B UNIT #19 DK	LINDRITH GALLUP DAKOTA.WS	28	24	N	3	W	11	300392213700501	S01	8920007134	31778	A706416	12001	12001	1/1/1994	5/16/1981	
LINDRITH B UNIT #20 DK	LINDRITH GALLUP DAKOTA.WS	26	24	N	3	W	41	300392271400501	S01	820789140	31778	A706421	12001	12001	1/1/1994	7/16/1981	
LINDRITH B UNIT #21 DK	LINDRITH GALLUP DAKOTA.WS	15	24	N	3	W	PR	300392271100501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	10/19/1982	
LINDRITH B UNIT #21 DK	LINDRITH GALLUP DAKOTA.WS	15	24	N	3	W	11	300392303600501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	10/25/1982	
LINDRITH B UNIT #22 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	PR	300392303700501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	9/29/1983	
LINDRITH B UNIT #23 DK	LINDRITH GALLUP DAKOTA.WS	9	24	N	3	W	61	300392324100501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	9/29/1983	
LINDRITH B UNIT #24 DK	LINDRITH GALLUP DAKOTA.WS	9	24	N	3	W	31	300392324700501	S01	892000713A	31778	A706423	12001	12001	11/29/1983	1/1/1994	11/22/1983
LINDRITH B UNIT #25 DK SWD	LINDRITH GALLUP DAKOTA.WS	9	24	N	3	W	41	300392346500501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	10/31/1984	
LINDRITH B UNIT #26 DK	LINDRITH GALLUP DAKOTA.WS	10	24	N	3	W	11	300392360900501	S01	820789120	31778	A706425	12001	12001	1/1/1994	1/24/1985	
LINDRITH B UNIT #27 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	72	300392381800501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	10/31/1985	
LINDRITH B UNIT #28 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	11	300392386800501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	3/21/1986	
LINDRITH B UNIT #29 DK	LINDRITH GALLUP DAKOTA.WS	28	24	N	3	W	41	300392219800501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	3/17/1980	
LINDRITH B UNIT #2 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	11	300392385900501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	4/1/1986	
LINDRITH B UNIT #31 DK	LINDRITH GALLUP DAKOTA.WS	21	24	N	3	W	PR	300392396800501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	4/21/1986	
LINDRITH B UNIT #32 DK	LINDRITH GALLUP DAKOTA.WS	21	24	N	3	W	11	300392392400501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	3/5/1986	
LINDRITH B UNIT #33 DK	LINDRITH GALLUP DAKOTA.WS	21	24	N	3	W	71	300392378800501	S01	892000713B	31778	A706416	12001	12001	1/1/1994	12/9/1985	
LINDRITH B UNIT #34 GM	LINDRITH GALLUP DAKOTA.WS	32	25	N	2	W	PR	300392378800501	S01			A706428	12001	12001	1/1/1994	6/30/1986	
LINDRITH B UNIT #35 DK	LINDRITH GALLUP DAKOTA.WS	9	24	N	3	W	11	300392375500501	S01	892000713B	31778	A706428	12001	12001	12/12/1985	1/1/1994	12/4/1985
LINDRITH B UNIT #37 GM	LINDRITH GALLUP DAKOTA.WS	4	24	N	2	W	11	300392381600501	S01	892000713B	31778	A706428	12001	12001	1/1/1994	9/30/1986	
LINDRITH B UNIT #3 DK	LINDRITH GALLUP DAKOTA.WS	21	24	N	3	W	71	300392227800501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	5/15/1980	
LINDRITH B UNIT #40 DK	LINDRITH GALLUP DAKOTA.WS	15	24	N	3	W	PR	30039237900501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	3/13/1986	
LINDRITH B UNIT #41 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	3	W	PR	300392384000501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	2/24/1986	
LINDRITH B UNIT #42 DK	LINDRITH GALLUP DAKOTA.WS	15	24	N	3	W	PR	300392377800501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	12/22/1985	
LINDRITH B UNIT #44 DK	LINDRITH GALLUP DAKOTA.WS	21	24	N	3	W	PR	300392386000501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	4/15/1986	
LINDRITH B UNIT #45 DK	LINDRITH GALLUP DAKOTA.WS	28	24	N	3	W	11	300392387300501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	5/2/1986	
LINDRITH B UNIT #46 DK	LINDRITH GALLUP DAKOTA.WS	28	24	N	3	W	PR	300392386100501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	5/15/1986	
LINDRITH B UNIT #5 DK	LINDRITH GALLUP DAKOTA.WS	21	24	N	3	W	PR	30039238400501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	9/4/1980	
LINDRITH B UNIT #6 DK	LINDRITH GALLUP DAKOTA.WS	28	24	N	3	W	PR	3003923842400501	S01	820789140	31778	A706421	12001	12001	1/1/1994	10/15/1980	
LINDRITH B UNIT #72 GM	LINDRITH GALLUP DAKOTA.WS	8	24	N	2	W	72	300392409000501	S01			A706418	12001	12001	3/30/1987	1/1/1994	3/30/1987
LINDRITH B UNIT #73 GM	LINDRITH GALLUP DAKOTA.WS	6	24	N	2	W	PR	30039240800501	S01	820789070	31778	A706417	12001	12001	1/1/1994	8/1/1987	
LINDRITH B UNIT #78 DK	LINDRITH GALLUP DAKOTA.WS	7	24	N	2	W	11	300392506600501	S01	820789070	31778	A706426	12001	12001	1/1/1994	3/11/1993	
LINDRITH B UNIT #79 DK	LINDRITH GALLUP DAKOTA.WS	28	24	N	2	W	11	300392510500501	S01	820789080	31778	A706427	12001	12001	1/1/1994	1/6/1992	
LINDRITH B UNIT #7 DK	LINDRITH GALLUP DAKOTA.WS	8	24	N	2	W	PR	300392245000501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	12/9/1980	
LINDRITH B UNIT #82 DK	LINDRITH GALLUP DAKOTA.WS	16	24	N	2	W	PR	30039225100501	S01	820789080	31778	A706419	12001	12001	1/1/1994	4/3/1992	
LINDRITH B UNIT #84 DK	LINDRITH GALLUP DAKOTA.WS	27	24	N	2	W	72	300392317800501	S01			A706420	12001	12001	1/1/1994	11/5/1980	
LINDRITH B UNIT #8 DK	LINDRITH GALLUP DAKOTA.WS	27	24	N	3	W	11	300392242200501	S01	892000713A	31778	A706416	12001	12001	1/1/1994	11/4/1980	
LINDRITH B UNIT #9 DK	LINDRITH GALLUP DAKOTA.WS	27	24	N	3	W	11	300392242300501	S01	820789140	31778	A706421	12001	12001	1/1/1994	11/4/1980	

Lindrieth "B" Unit Wells as of 2/22/2007

Prod Stat : 11 Flowing Well
21 Pumping Well

61 Temp Abandoned
71 Perm Abandoned Well

Lindrith Unit

Well Formation

- PICTURED CLIFFS
- CHACRA
- MANCOS
- GALLUP /SD/ SH/
- GALLUP DAKOTA
- DAKOTA



Inventory Management
San Juan Business Unit
Farmington, New Mexico
2/07

